

<b>Name of Mine:</b>	<b>COWAL GOLD MINE</b>
<b>Titles/Mining Leases:</b>	<b>ML 1535</b>
<b>MOP Commencement Date:</b>	<b>October 2012</b>
<b>MOP Completion Date:</b>	<b>January 2014 - extension to 31 January 2015</b>
<b>AEMR Commencement Date:</b>	<b>23 DECEMBER 2012</b>
<b>AEMR End Date:</b>	<b>22 DECEMBER 2013</b>
<b>Name of Leaseholder:</b>	<b>BARRICK (COWAL) LIMITED</b>
<b>Name of Mine Operator (if different):</b>	<b>AS ABOVE</b>
<b>Reporting Officer:</b>	<b>GARRY PEARSON</b>
<b>Title:</b>	<b>ENVIRONMENTAL MANAGER</b>
<b>Signature:</b>	.....
<b>Date:</b>	<b>12 August 2014</b>

**DOCUMENT COPY No:**

**ISSUED TO:**

**DATE: 12 August 2014**

**Plate 1  
Lake Cowal in receding phase (23 January 2014)**



## TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>	
1	INTRODUCTION	1
1.1	CONSENTS, LEASES, LICENCES AND PERMITS	1
	1.1.1 Current List of Consents, Leases, Licences and Permits	1
	1.1.2 Approval Variations Applicable to the Subject Area	3
1.2	MINE CONTACTS	5
1.3	ACTIONS REQUIRED AT THE PREVIOUS AEMR REVIEW	5
1.4	CGM BACKGROUND	5
1.5	INDEPENDENT ENVIRONMENTAL AUDIT	6
2	OPERATIONS DURING THE REPORTING PERIOD	7
2.1	EXPLORATION	7
2.2	LAND PREPARATION	7
2.3	INFRASTRUCTURE CONSTRUCTION	7
2.4	MINING	9
2.5	MINERAL PROCESSING	9
2.6	WASTE MANAGEMENT	10
2.7	ORE AND PRODUCT STOCKPILES	11
2.8	WATER MANAGEMENT	12
2.9	HAZARDOUS MATERIAL MANAGEMENT	13
2.10	OTHER INFRASTRUCTURE MANAGEMENT	14
3	ENVIRONMENTAL MANAGEMENT AND PERFORMANCE	14
3.1	AIR QUALITY	18
	3.1.1 Reporting Requirements	18
	3.1.1.1 Development Consent	18
	3.1.1.2 Environmental Protection Licence	18
	3.1.1.3 Any Other Relevant Approvals	19
	3.1.2 Environmental Management	19
	3.1.2.1 Control Strategies	19
	3.1.2.2 Effectiveness of Control Strategies	19
	3.1.2.3 Variations from Proposed Control Strategies	20
	3.1.3 Environmental Performance	20
	3.1.3.1 Monitoring	20
	3.1.3.2 Performance Outcomes	22
	3.1.4 Reportable Incidents	24
	3.1.5 Further Improvements	25
3.2	EROSION AND SEDIMENT	26
	3.2.1 Reporting Requirements	26
	3.2.1.1 Development Consent	26
	3.2.1.2 Environment Protection Licence	26
	3.2.1.3 Any Other Relevant Approval	26
	3.2.2 Environmental Management	26
	3.2.2.1 Control Strategies	26
	3.2.2.2 Effectiveness of Control Strategies	28
	3.2.2.3 Variations from Proposed Control Strategies	28
	3.2.3 Environmental Performance	28
	3.2.3.1 Monitoring	28
	3.2.3.2 Performance Outcomes	29
	3.2.4 Reportable Incidents	29
	3.2.5 Further Improvements	29
3.3	SURFACE WATER	30
	3.3.1 Reporting Requirements	30
	3.3.1.1 Development Consent	30
	3.3.1.2 Environmental Protection Licence	30
	3.3.1.3 Any Other Relevant Approval	31
	3.3.2 Environmental Management	31
	3.3.2.1 Control Strategies	31
	3.3.2.2 Effectiveness of the Control Strategies	31

## TABLE OF CONTENTS (Continued)

	3.3.2.3	Variations from Proposed Control Strategies	31
3.3.3		Environmental Performance	31
	3.3.3.1	Monitoring	31
	3.3.3.2	Performance Outcomes	33
	3.3.3.3	Interpretation	40
3.3.4		Reportable Incidents	42
3.3.5		Further Improvements	42
3.4		GROUNDWATER	43
3.4.1		Reporting Requirements	43
	3.4.1.1	Development Consent	43
	3.4.1.2	Environmental Protection Licence	43
	3.4.1.3	Any other Relevant Approval	43
3.4.2		Environmental Management	44
	3.4.2.1	Control Strategies	44
	3.4.2.2	Effectiveness of the Control Strategies	44
	3.4.2.3	Variations from Proposed Control Strategies	44
3.4.3		Environmental Performance	44
	3.4.3.1	Monitoring	44
	3.4.3.2	Performance Outcomes	46
3.4.4		Reportable Incidents	49
3.4.5		Further Improvements	49
3.5		CYANIDE MANAGEMENT	49
3.5.1		Reporting Requirements	49
	3.5.1.1	Development Consent	49
	3.5.1.2	Environment Protection Licence	50
	3.5.1.3	Any Other Relevant Approval	50
3.5.2		Environmental Management	50
	3.5.2.1	Control Strategies	50
	3.5.2.2	Effectiveness of Control Strategies	51
	3.5.2.3	Variations from Proposed Control Strategies	51
3.5.3		Environmental Performance	51
	3.5.3.1	Monitoring	51
	3.5.3.2	Performance Outcome	52
3.5.4		Reportable Incidents	52
3.5.5		Further Improvements	53
3.6		CONTAMINATED LAND	53
3.6.1		Reporting Requirements	53
	3.6.1.1	Development Consent	53
	3.6.1.2	Environment Protection Licence	54
	3.6.1.3	Any Other Relevant Approval	54
3.6.2		Environmental Management	54
	3.6.2.1	Control Strategies	54
	3.6.2.2	Effectiveness of the Control Strategies	55
	3.6.2.3	Variations from Proposed Control Strategies	55
3.6.3		Environmental Performance	55
	3.6.3.1	Monitoring	55
	3.6.3.2	Performance Outcomes	56
3.6.4		Reportable Incidents	57
3.6.5		Further Improvements	57
3.7		FLORA	57
3.7.1		Reporting Requirements	57
	3.7.1.1	Development Consent	57
	3.7.1.2	Environment Protection Licence	59
	3.7.1.3	Any Other Relevant Approvals	59
3.7.2		Environmental Management	59
	3.7.2.1	Control Strategies	59
	3.7.2.2	Effectiveness of Control Strategies	62
	3.7.2.3	Variations from Proposed Control Strategies	62
3.7.3		Environmental Performance	62
	3.7.3.1	Monitoring	62
	3.7.3.2	Performance Outcomes	63
3.7.4		Reportable Incidents	66
3.7.5		Further Improvements	66

**TABLE OF CONTENTS (Continued)**

3.8	FAUNA	66
	3.8.1 Reporting Requirements	66
	3.8.1.1 Development Consent	66
	3.8.1.2 Environment Protection Licence	67
	3.8.1.3 Any Other Relevant Approvals	67
	3.8.2 Environmental Management	67
	3.8.2.1 Control Strategies	67
	3.8.2.2 Effectiveness of Control Strategies	68
	3.8.2.3 Variations from proposed Control Strategies	68
	3.8.3 Environmental Performance	68
	3.8.3.1 Monitoring	68
	3.8.3.2 Performance Outcomes	70
	3.8.4 Reportable Incidents	85
	3.8.5 Further Improvements	85
3.9	WEEDS AND PESTS	85
	3.9.1 Reporting Requirements	85
	3.9.1.1 Development Consent	85
	3.9.1.2 Environment Protection Licence	86
	3.9.1.3 Any Other Reporting Requirement	86
	3.9.2 Environmental Management	86
	3.9.2.1 Control Strategies	86
	3.9.2.2 Effectiveness of Control Strategies	87
	3.9.2.3 Variations from Proposed Control Strategies	87
	3.9.3 Environmental Performance	87
	3.9.3.1 Monitoring	87
	3.9.3.2 Performance Outcome	88
	3.9.4 Reportable Incidents	90
	3.9.5 Further Improvements	90
3.10	BLASTING	90
	3.10.1 Reporting Requirements	90
	3.10.1.1 Development Consent	90
	3.10.1.2 Environment Protection Licence	91
	3.10.1.3 Any Other Relevant Approval	91
	3.10.2 Environmental Management	91
	3.10.2.1 Control Strategies	91
	3.10.2.2 Effectiveness of Control Strategies	92
	3.10.2.3 Variations from Proposed Control Strategies	92
	3.10.3 Environmental Performance	92
	3.10.4 Reportable Incidents	94
	3.10.5 Further Improvements	94
3.11	OPERATIONAL NOISE	97
	3.11.1 Reporting Requirements	97
	3.11.1.1 Development Consent	97
	3.11.1.2 Environmental Protection Licence	98
	3.11.1.3 Any Other Relevant Approval	98
	3.11.2 Environmental Management	98
	3.11.2.1 Control Strategies	98
	3.11.2.2 Effectiveness of Control Strategies	99
	3.11.2.3 Variations from Proposed Strategies	99
	3.11.3 Environmental Performance	100
	3.11.3.1 Monitoring	100
	3.11.3.2 Daytime Operator-attended Noise Survey Results	100
	3.11.3.3 Evening Operator-attended Noise Survey Results	100
	3.11.3.4 Night-time Operator-attended Noise Survey Results	101
	3.11.3.5 Unattended Continuous Noise Logging	102
	3.11.3.6 Operator-attended and Unattended Traffic Noise	102
	3.11.4 Reportable Incidents	107
	3.11.5 Further Improvements	107
3.12	VISUAL, STRAY LIGHT	107
	3.12.1 Reporting Requirements	107
	3.12.1.1 Development Consent	107
	3.12.1.2 Environment Protection Licence	107
	3.12.1.3 Any other Relevant Approval	107

---

**TABLE OF CONTENTS (Continued)**

3.12.2	Environmental Management	107
3.12.2.1	Control Strategies	107
3.12.2.2	Effectiveness of Control Strategies	108
3.12.2.3	Variations from Proposed Control Strategies	108
3.12.3	Environmental Performance	109
3.12.3.1	Monitoring	109
3.12.3.2	Performance Outcomes	109
3.12.4	Reportable Incidents	110
3.12.5	Further Improvements	110
3.13	ABORIGINAL HERITAGE	110
3.13.1	Reporting Requirements	110
3.13.1.1	Development Consent	110
3.13.1.2	Environment Protection Licence	110
3.13.1.3	Any Other Relevant Approvals	110
3.13.2	Environmental Management	110
3.13.2.1	Control Strategies	110
3.13.2.2	Effectiveness of Control Strategies	113
3.13.2.3	Variations from Proposed Control Strategies	113
3.13.3	Environmental Performance	113
3.13.3.1	Monitoring	113
3.13.3.2	Performance Outcomes	113
3.13.4	Reportable Incidents	113
3.13.5	Further Improvements	113
3.14	EUROPEAN HERITAGE	114
3.14.1	Reporting Requirements	114
3.14.1.1	Development Consent	114
3.14.1.2	Environment Protection Licence	114
3.14.1.3	Any Other Relevant Approval	114
3.14.2	Environmental Management	114
3.14.2.1	Control Strategies	114
3.14.2.2	Effectiveness of Control Strategies	115
3.14.2.3	Variations from Proposed Control Strategies	115
3.14.3	Environmental Performance	115
3.14.3.1	Monitoring	115
3.14.3.2	Performance Outcomes	115
3.14.4	Reportable Incidents	115
3.14.5	Further Improvements	115
3.15	SPONTANEOUS COMBUSTION	115
3.16	BUSHFIRE	115
3.16.1	Reporting Requirements	115
3.16.1.1	Development Consent	115
3.16.1.2	Environment Protection Licence	116
3.16.1.3	Any Other Relevant Approval	116
3.16.2	Environmental Management	116
3.16.2.1	Control Strategies	116
3.16.2.2	Effectiveness of Control Strategies	116
3.16.2.3	Variations from Proposed Control Strategies	116
3.16.3	Environmental Performance	116
3.16.3.1	Monitoring	116
3.16.3.2	Performance Outcomes	117
3.16.4	Reportable Incidents	117
3.16.5	Further Improvements	117
3.17	MINE SUBSIDENCE	117
3.18	HYDROCARBON CONTAMINATION	118
3.18.1	Reporting Requirements	118
3.18.1.1	Development Consent	118
3.18.1.2	Environment Protection Licence	119
3.18.1.3	Any Other Relevant Approvals	119
3.18.2	Environmental Management	119
3.18.2.1	Control Strategies	119
3.18.2.2	Effectiveness of Control Strategies	120
3.18.2.3	Variations from Proposed Control Strategies	120
3.18.3	Environmental Performance	121

**TABLE OF CONTENTS (Continued)**

	3.18.3.1	Monitoring	121
	3.18.3.2	Performance Outcomes	121
	3.18.4	Reportable Incidents	121
	3.18.5	Further Improvements	121
3.19		METHANE DRAINAGE/VENTILATION	122
3.20		WASTE GEOCHEMISTRY	122
	3.20.1	Reporting Requirements	122
	3.20.2	Environmental Management	122
	3.20.2.1	Control Strategies	123
	3.20.2.2	Effectiveness of Control Strategies	123
	3.20.2.3	Variations from Proposed Control Strategies	123
	3.20.3	Environmental Performance	123
	3.20.4	Reportable Incidents	124
	3.20.5	Further Improvements	124
3.21		PUBLIC SAFETY	124
	3.21.1	Reporting Requirements	124
	3.21.1.1	Effectiveness of Control Strategies	125
	3.21.1.2	Variations from Proposed Control Strategies	125
	3.21.2	Environmental Performance	125
	3.21.3	Reportable Incidents	125
	3.21.4	Further Improvements	125
3.22		NATURAL HERITAGE	125
4		COMMUNITY RELATIONS	126
	4.1	COMMUNITY COMPLAINTS	126
	4.2	COMMUNITY LIAISON	150
5		REHABILITATION REPORT	153
	5.1	BUILDINGS	153
	5.2	REHABILITATION OF DISTURBED LAND	153
	5.3	OTHER INFRASTRUCTURE	164
	5.4	REHABILITATION TRIALS AND RESEARCH	165
	5.5	DEVELOPMENT OF THE FINAL REHABILITATION PLAN	172
6		ACTIVITIES PROPOSED FOR THE NEXT AEMR PERIOD	175
	6.1	ENVIRONMENTAL MANAGEMENT TARGETS AND STRATEGIES FOR THE NEXT YEAR	175
7		REFERENCES	180
8		GLOSSARY OF TERMS	187

**LIST OF TABLES**

<b><u>Table</u></b>		<b><u>Page</u></b>
Table 1	Key Consents, Leases, Licences and Permits	1
Table 2	AEMR Meeting Actions	5
Table 3	Infrastructure Construction Components during the Reporting Period	8
Table 4	Production and Waste Summary	10
Table 5	Operational Phase Wastes – Transport, Handling and Disposal	11
Table 6	Stored Water	13
Table 7	Air Quality Safeguards and Control Strategies Implemented During the Reporting Period for Dust Sources	19
Table 8	Monthly Rainfall (mm) Measured at Cowan Gold Mine in 2010, 2011, 2012 and 2013	20
Table 9	Monthly Average Meteorological Data (2013)	21
Table 10	Air Quality Impact Assessment Criteria	22
Table 11	Monthly and Mean Dust (insoluble solids) Deposition Rates (2013)	23

**TABLE OF CONTENTS (Continued)**

Table 12	Summary for the Relevant Erosion and Sediment Control Strategies/Management Measures	27
Table 13	Surface Water Monitoring Programme	32
Table 14	Summary of Surface Water Monitoring Results for the Reporting Period	33
Table 15	Summary of Lake Water Monitoring Results for the reporting period	35
Table 16	Summary of Lake Cowal Inflow Water Monitoring Results for the Reporting period	37
Table 17	Summary of Lake Cowal Sediment Monitoring Results for the Reporting Period	42
Table 18	Groundwater Monitoring Programme	45
Table 19	Bland Creek Paleochannel Production Bores - Extraction Volumes	46
Table 20	Preliminary Groundwater Model for the Cowal Mining Lease	47
Table 21	WAD cyanide Day-Night Shift Monitoring Data for Tailings Discharge - NTSF (01/01/2013 to 13/06/2013) and STSF (14/06/2013 to 31/12/2013)	52
Table 22	Summary of Soil Stripping Activities for the Reporting Period	56
Table 23	Offset Management Areas	61
Table 24	Bird Breeding Monitoring Conducted During the Reporting Period	69
Table 25	Records of Fauna Deaths and Other Incidents for the Reporting Period	71
Table 26	Bird Breeding Monitoring Results for the Reporting Period	81
Table 27	Summary of Vertebrate Pest Control Measures	87
Table 28	Blasting Impact Assessment Criteria	92
Table 29	Summary of Individual Blasts Peak Overpressure Levels Exceeding Compliance Criteria for CGM (23/12/2012 – 22/12/2013)	95
Table 30	Noise Impact Assessment Criteria dB (A) $L_{Aeq(15\text{ minute})}$	98
Table 31	Daytime Noise Emission Levels $L_{Aeq(15\text{ minute})}$	100
Table 32	Evening Noise Emission Levels $L_{Aeq(15\text{ minute})}$	101
Table 33	Night-time Noise Emission Levels $L_{Aeq(15\text{ minute})}$	102
Table 34	Operator-attended Traffic Noise Emission Survey Results (January 2013) TN1 – 140 Ungarie Road	104
Table 35	Operator-attended Traffic Noise Emission Survey Results (January 2013) TN2 – ‘Clairview’ Residence	105
Table 36	Operator-attended Traffic Noise Emission Survey Results (January 2013) TN3 – ‘Windstone’ Residence	106
Table 37	Landscape Maintenance and Monitoring Summary	109
Table 38	Summary of Major Management Measures Undertaken for Registered Sites	111
Table 39	Summary of Community Complaints during the Reporting Period	127
Table 40	Nature of Disturbance and Rehabilitation Status of Disturbed Land at the end of the Reporting Period	155
Table 41	Rehabilitation Summary	169
Table 42	Maintenance Activities on Rehabilitated Land	170
Table 43	Summary of Environmental Targets and Management Strategies for the Next Reporting Year	175

**LIST OF FIGURES**

Figure 1	CGM Location
Figure 2	Property Boundaries
Figure 3	Aerial Photograph of Cowal Gold Mine
Figure 4	Approximate Locations of Soil Stockpiles, Vegetation Screening and Landform Rehabilitation
Figure 5	CGM Water Management System
Figure 6	Dust Management Procedures
Figure 7a	Annual Wind Rose for 2013
Figure 7b	Monthly Wind Roses for January – December 2013
Figure 8	Dust, Noise, Blast, Lake and Groundwater Monitoring Locations



**TABLE OF CONTENTS (Continued)**

Figure 9	High-Volume TSP Dust Results (23 December 2012 to 22 December 2013)
Figure 10a	Insoluble Solids in Dust ( $\text{g/m}^2/\text{month}$ ), January - December 2013 for Dust Gauges DG1 to DG4
Figure 10b	Insoluble Solids in Dust ( $\text{g/m}^2/\text{month}$ ), January - December 2013 for Dust Gauges DG5 to DG8
Figure 10c	Insoluble Solids in Dust ( $\text{g/m}^2/\text{month}$ ), January - December 2013 for Dust Gauges DG9 to DG12
Figure 10d	Insoluble Solids in Dust ( $\text{g/m}^2/\text{month}$ ), January - December 2013 for Dust Gauges DG13 and DG14, McLintocks Shed and Site Office
Figure 10e	Insoluble Solids in Dust ( $\text{g/m}^2/\text{month}$ ), January – December 2013 for Dust Gauges Site 52, 15 and Lakeside
Figure 11	Erosion and Sediment Control Systems and Up-catchment Drainage Monitoring Sites
Figure 12	Surface and Groundwater Monitoring Locations – ML Area
Figure 13a	Stiff Plots Showing Major Ion Relationships in Groundwater from Selected End-member Facies in the Cowal Gold Mine Area
Figure 13b	Stiff Plots Showing Major Ion Relationships in Groundwater from Selected End-member Facies in the Cowal Gold Mine Area
Figure 14	Piper Diagram Showing Major Ion Chemistry Trends in End-member Groundwater Types in the Three Operational Areas at the Cowal Gold Mine Area
Figure 15a	Deep Groundwater Contours
Figure 15b	Shallow Groundwater Contours
Figure 16	Bores PDB 1A, 3A and 5A Standing Water Levels Measured During the Reporting Period
Figure 17	Location of Soil Stockpiles – July 2013
Figure 18	Vegetation Clearance Protocol
Figure 19	Location of Offset Areas
Figure 20	Typical Section through Perimeter Waste Emplacement and Lake Isolation System
Figure 21	Conceptual Embankment Section of Northern Waste Rock Emplacement
Figure 22	Conceptual Embankment Section of Northern Tailings Storage Facility
Figure 23	Proposed Mining and Rehabilitation – Waste Rock Emplacements – Year 1 of MOP Term (2014)
Figure 24	Proposed Mining and Rehabilitation – Tailings Storage Facilities – Year 1 of MOP Term (2014)
Figure 25	Conceptual Final Landforms and Proposed Final Land Use Areas

**LIST OF PLATES**

Plate 1	Lake Cowal in receding phase (23 January 2014)	inside cover
Plate 2	Lake Cowal Water Level (2010 – 2014)	39
Plate 3	Aerial Photograph of the Lake Protection Bund (LPB) January 2014	39
Plate 4	Freckled Duck rescued from bottom of E42 Open Pit (04 February 2014)	79
Plate 5	Northern Ends of Transects 1 and 7 for Waterbird Survey (October 2013)	83
Plate 6	TIB – Eastern Face Native Re-growth	160
Plate 7	STSF and NTSF Wall Rehabilitation	168
Plate 8	SWE - Southern Slope Trial Plots	171
Plate 9	SWE – Southern Slope Trial Direct Seeding Mix	172
Plate 10	Weeping Myall ( <i>A. Pendula</i> ) Re-growth from topsoil SWE Southern Slope Trials	172
Plate 11	New Shallower Draught Environmental Patrol Boat (March 2014)	179
Plate 12	Southern Waste Rock Emplacement South Side (May 2014)	179
Plate 13	Original south face of the 'Cowan West' Shearing Shed (2005 - 2012)	180
Plate 14	Refurbished 'Cowan West' Shearing Shed (April 2013)	180

**TABLE OF CONTENTS (Continued)**

**LIST OF APPENDICES**

Appendix A	2013 Independent Environmental Audit
Appendix B	Dust Monitoring Data
Appendix C	Surface Water, Groundwater and Biological Monitoring Report
Appendix D	Lake Waters and Sediments Sampling Data and Graphs
Appendix E	Community Environmental Monitoring and Consultative Committee Minutes

## PLANS

In accordance with Section 3 of the *Guidelines and Format for the Preparation of an Annual Environmental Management Report*: (NSW Department of Trade and Investment, Regional Infrastructure and Services [DTIRIS (Minerals), 2006]) a number of plans (including a land preparation plan, proposed mining activities plan and proposed rehabilitation plan) are required to be prepared for the Annual Environmental Management Report (AEMR). These plans are to show equivalent information to plans provided in the current CGM Mining Operations Plan (October 2012 – January 2014) (MOP). The October 2012 to January 2014 MOP was approved by the DTIRIS (Minerals) on 19 December 2012. On 4 October 2013, the Director-General of the DTIRIS-DRE granted Barrick an extension to the term of the previous Cowal Gold Mine Mining Operations Plan (October 2012 – January 2014) to 31 January 2015.

A draft Mining Operations Plan (MOP) 2014 – 2016 has been prepared by Barrick in accordance with the requirements of the Mining Lease 1535 condition 25, MCoA 2.1 and the latest NSW Department of Trade and Investment, Regional Infrastructure and Services – Division of Resources and Energy (DTIRIS-DRE) guideline - ESG3: Mining Operations Plan (MOP) Guidelines, September 2013 (the MOP Guidelines). This MOP (when approved) will replace the present MOP (2012 – 2014; extended until 31 January 2015), and describes the proposed operational mining activities beyond the currently approved CGM MOP (submission is pending MOD11 approval).

### ***Land Preparation Plan***

Disturbance areas associated with the CGM and soil stockpile areas are shown on Figure 4. Plans showing proposed land preparation areas for the next reporting period are provided as Figures 23 and 24 of this AEMR).

### ***Proposed Mining Activities Plan***

Mining operations commenced on 21 April 2005.

Figure 4 shows the layout of the open cut pit, soil stockpiles and water management structures.

Mining activities for the next reporting period have been addressed in the MOP. A summary of operations for the next reporting period is provided in Paragraph 6 of this report.

### ***Rehabilitation Plan***

Areas where rehabilitation activities have occurred during the reporting period and to date are shown on Figure 4. Plans showing proposed rehabilitation activities for the next reporting period are included in the 2014-2016 MOP and are shown on Figures 23 and 24. A conceptual view of the proposed final landform and final land use areas is shown on Figure 25.

Figures 1 to 22 provide additional plans and information relevant to this AEMR.

## 1 INTRODUCTION

This Annual Environmental Management Report (**AEMR**) has been prepared by Barrick (Cowal) Limited (**Barrick**) for the Cowal Gold Mine (**CGM**) in accordance with the conditions of the Development Consent DA 14/98 for the CGM granted on 26 February 1999 (**Development Consent**) and the Conditions of Authority for Mining Lease (**ML**) 1535 granted on 13 June 2003. This AEMR has been prepared for the period 23 December 2012 to 22 December 2013. The requirements for the AEMR are set out in the Conditions of Authority for ML 1535 and the CGM Development Consent.

As Cowal Gold Mine is in transition to using the ESG3 DRE Guidelines for a MOP, this AEMR for this reporting period has been prepared in accordance with the NSW Department of Trade and Investment, Regional Infrastructure and Services Division of Resources and Energy (**DTIRIS [DRE]**) *Guidelines and Format for Preparation of an Annual Environmental Management Report (DTIRIS, 2006)*.

This AEMR has been prepared in consultation with relevant stakeholders. A meeting regarding the 2012 AEMR was held on 2 October 2013 at the CGM. Attendees included representatives from the Environmental Protection Authority (**EPA**), the DTIRIS (DRE) and Barrick (Cowal) Limited. In addition, Barrick has been in contact with the DTIRIS (DRE) and Department of Planning and Environment (**DP&I**) regarding the development of this AEMR. No additional requirements in relation to the AEMR were requested by the DTIRIS (DRE) or the DP&I.

In accordance with Development Consent Condition 9.2(iii), copies of the AEMR will be provided to the Director-General of the DP&I, EPA, NSW Office of Water (**NoW**), DTIRIS (DRE), the NSW Dams Safety Committee (**DSC**), DPI-Fisheries, the Bland Shire Council (**BSC**) and the Community Environmental Monitoring and Consultative Committee (**CEMCC**).

### 1.1 CONSENTS, LEASES, LICENCES AND PERMITS

#### 1.1.1 Current List of Consents, Leases, Licences and Permits

The key consents, leases, licences and permits under which CGM operates are presented in Table 1.

**Table 1**  
**Key Consents, Leases, Licences and Permits**

Instrument	Relevant Authority	Date of Grant	Duration of Approval
Development Consent (DA 14/98)	DP&I	26/02/1999	Mining operations may take place until 30 June 2019. "Mining operations" includes all ore extraction, processing and transportation activities carried out on site. The Development Consent then continues in force until Barrick rehabilitates the site in accordance with the conditions of the Development Consent.
Development Consent (DA2011/64) (Eastern Saline Borefield)	Forbes Shire Council	20/12/2010	N/A
Mining Lease (ML 1535)	DTIRIS (DRE)	13/06/2003	21 years (2024).
Environment Protection Licence (EPL 11912)	EPA	23/12/2003	Until the licence is surrendered, suspended or revoked. The licence is subject to review every three years, and was last varied on 21 May 2014.
Permit #1361 under section 87(1) of the NPW Act	EPA	23/05/2002	Valid for period of exploration drilling on the lots covered by the permit.
Consent #1467 under section 90 of the NPW Act	EPA	27/11/2002	The approval lapses when the Minister for Environment acknowledges that satisfactory rehabilitation work has been completed under ML1535 or 18 years after completion of constructions works, whichever occurs first.

**Table 1 (Continued)**  
**Key Consents, Leases, Licences and Permits**

Instrument	Relevant Authority	Date of Grant	Duration of Approval
Permit #1468 under section 87(1) of the NPW Act	EPA	27/10/2003	Same as Consent #1467.
Consent #1680 under section 90 of the NPW Act	EPA	28/07/2003	The approval lapses when the Minister for Environment acknowledges that satisfactory rehabilitation work has been completed under ML1535 or 18 years after completion of construction works, whichever occurs first.
Permit #1681 under section 87(1) of the NPW Act	EPA	28/07/2003	Same as Consent #1680.
Production bore licence (Bland Creek Palaeochannel borefield) #70BL229248, #70BL229249, #70BL229250, #70BL229251	NoW and EPA	14/09/2012	WAL31864. 14 September 2015.
Production bore licences (saline groundwater supply borefield within ML 1535) #70BL232691 and #70BL232692. 70WA614090. 70AL615007.	NoW and EPA	21/03/2014	WAL36615. 14 September 2015. Upper 10% (366 units. Lachlan Alluvial Zone 7). Valid for the operation of three lake floor saline production bores when not inundated by Lake Cowl.
DA No. 2011/0064 #70BL233321 #70BL233323	FSC and NoW	20/12/2010	09 June 2016. Valid for the operation of the eastern saline borefield.
Pit dewatering bore licences #70BL230233 existing and newer. 70WA614090. 70AL615007.	NoW and EPA	21/03/2014	WAL36615. 14 September 2015. Upper 10% (366 units. Upper Lachlan Alluvial Zone 7). Replacement de-watering bore licenses as exchanged for decommissioned bores.
Pit dewatering bore licences #70BL230233 existing and newer. 70WA614090. 70AL615007.	NoW and EPA	21/03/2014	WAL36617. 14 September 2015. Lower 90% (3,294 units. Upper Lachlan Fold MDB). Replacement de-watering bore licenses as exchanged for decommissioned bores.
Monitoring and test bore licences	NoW and EPA	Various	Various.
High Security Title WAL13749 NoW Reference 70AL603333	LPI and NoW	21/12/2006	Title for allocation from Regulated River Source.
High Security Title WAL14981 NoW Reference 70WA603145 (80 Units)	LPI and NoW	15/09/2011	Title for allocation from Lachlan River Regulated Source- Water Sharing Plan. Followed WAL13749/ 70AL603333 (21/12/2006) (above).
General Security WAL13748 NoW Reference 70AL603332	LPI and NoW	21/12/2006	Title for allocation from Regulated River Source.
Surface Licence 70SL090308	NoW	12/01/2010	Surface Licence for TIB-LPB and buried borefield poly pipeline under Lake Cowl. 5-yearly renewals.

Source: Barrick (2014)

DP&I: NSW Department of Planning and Infrastructure

DTIRIS: NSW Department of Trade and Investment, Regional Infrastructure and Services – Mineral Resources and Energy

EPA: NSW Environmental Protection Authority

FSC: Forbes Shire Council

LPI: NSW Land and Property Information

NoW: NSW Office of Water

NPW Act: NSW *National Parks and Wildlife Act 1974*.

### **Mining Operations Plan (MOP)**

One MOP was applicable to the CGM during the reporting period and is described below.

#### *2012 to 2014 MOP*

The October 2012 to January 2014 MOP was approved by the DTIRIS (DRE) on 19 December 2012. On 4 October 2013, the Director-General of the DTIRIS-DRE granted Barrick an extension to the term of the previous Cowal Gold Mine Mining Operations Plan (October 2012 – January 2014) to 31 January 2015.

During the current reporting period (2012 to 2014 MOP), the footprints of the Perimeter Waste Emplacement (**PWE**), Northern Waste (rock) Emplacement (**NWE**) and Southern Waste (rock) Emplacement (**SWE**) remained unchanged. E42 Pit walls continued to lay back and deepen in Stages D, E, F and G. The outer batters of the fourth lift (third augmentation) of the Southern Tailings Storage Facility (**STSF**) were rehabilitated and tailings deposition re-commenced in mid-June 2013. The third lift of the Northern Tailings Storage Facility (**NTSF**) was filled to a safe level mid-June 2013. NTSF fourth lift (fourth augmentation) earthworks commenced early-December 2013.

A small temporary topsoil stockpile inside the TSF fenced area and remnants of the stripping area near the TSF Depot (for the large 2004-2005 topsoil stockpile relocated from Miller's Crusher area), provided the majority of the topsoil for the waste rock – topsoil cover rehabilitation method needs of the outer batters of the fourth lift (third augmentation) of the STSF (Paragraph 5.4).

The Lake Protection Bund (**LPB**) outer bund and eastern face of Pond D1 were rock armoured before Lake Cowal levels rose over the Temporary Isolation Bund (**TIB**) shortly after the near 1:100 year ARI flood event of 7 March 2012. The early-2012 Pond D1 north rehabilitation trial area was maintained in a weed free state during the reporting period. Unfortunately, due to the dry and erratic years in 2012 and 2013 there was no native pasture hay available to complete the setup of the extended trial. Native pasture hay was slashed and baled at 'Hillgrove' in November 2013.

The late-June 2013 Pond D1 north rehabilitation trial 80 metre extension area was contoured and covered with waste rock and 150 and 300 mm topsoil in preparation for final plot design treatments at the start of the next reporting period. Gypsum spreading at 10 t/ha has occurred (mid-June 2014), and native plants will be planted on the whole Pond D1 trial area (including the 80 metre extension) as soon as the native pasture hay and clean wheaten hay is spread (July 2014). (Paragraph 5.4).

#### **1.1.2 Approval Variations Applicable to the Subject Area**

##### ***Environment Protection Licence***

One s58 variation request resulted in EPL11912 variations posted in track change at:

<http://www.epa.nsw.gov.au/prpoeoapp/>

During the 2013 AEMR reporting year the computer system used by the EPA to store and process licences was upgraded. Some changes to the format of the licence may have occurred as a result of the upgrade. Conditions that were previously recorded as "not applicable" have been removed from the licence. These upgrades are not intended to change the substance of the licence. By the notice 1513100 (02 May 2013) the EPA varied EPL11912.

##### ***Development Consent***

No amendments to the CGM's Development Consent occurred during the reporting period. An application to the D-General DP&I under s75W of the EP&A Act for a 5-year extension to mine life (MOD11) was lodged by Barrick on 23 September 2013.

##### ***Amendments and Revisions to Environmental Management Plans***

A description of the relevant amendments and revisions to the EMPs required under the Development Consent is provided below.

#### *Site Water Management Plan*

In February 2012 a revised SWMP incorporating the eastern saline borefield was submitted to relevant government departments for comment in accordance with Development Consent Condition 4.1/4.2. Comments were addressed and a revised SWMP was provided to the DP&I in late February 2012. The DP&I provided review comments on the revised SWMP in August 2012. Barrick subsequently revised the SWMP to address the DP&I's comments and submitted the SWMP back to the relevant consultees for comment in May 2013.

In accordance with Development Consent Condition 4.1/4.2(b), a long-term strategy for decommissioning water management structures and a strategy for the final void was prepared during the reporting period. A request for an extension of the timing for submission of the long-term strategy, to the end-June 2013 was submitted to the DP&I on 13 November 2012. The long-term strategy has been incorporated into the revised SWMP after Barrick consulted with the DTIRIS (DRE) and the CEMCC. Barrick has consulted with NoW and EPA submitted a revised SWMP to the DP&I for approval on 8 August 2013.

#### *Surface Water, Groundwater, Meteorological and Biological Monitoring Programme*

After DP&I approval of MOD10 in July 2011, Barrick prepared an Addendum to the Meteorological and Biological Monitoring Programme (**SWGMBMP**) to include the Eastern Saline Borefield in consultation with relevant regulatory agencies in accordance with Development Consent Condition 3.2(a). The Addendum to the SWGMBMP was then submitted to the DP&I for approval in February 2012. The DP&I approved the Addendum on 14 August 2012. To maintain consistency with the revised SWMP (which was updated to address DP&I review comments provided in August 2012), Barrick commenced preparation of another Addendum to the SWGMBMP towards the end of the 2012 reporting period and submitted it to the DP&I for approval on 13 August 2013.

#### *Blast Management Plan*

The BLMP was revised (May 2010) to reflect the modification of the Development Consent conditions relevant to blasting on 10 March 2010. The DP&I provided feedback on the content of the BLMP in their letter dated 14 August 2012. Barrick subsequently prepared a revised BLMP to address the DP&I's review comments and submitted the revised BLMP to the DP&I on 11 December 2012. Barrick is currently awaiting approval of the revised BLMP.

#### *Noise Management Plan*

The NMP (July 2010) was revised to reflect the modification of the Development Consent conditions relevant to noise on 10 March 2010. The DP&I provided feedback on the content of the NMP in a letter dated 14 August 2012. Barrick subsequently prepared a revised NMP to address the DP&I's review comments and lodged the revised NMP with the DP&I on 24 December 2012. Barrick is currently awaiting approval of the revised NMP.

#### *Threatened Species Management Strategy*

The Threatened Species Management Strategy was prepared in consultation with EPA (for the Inland Forest Bat, Sloane's Froglet and Woodland birds Little Eagle, Spotted Harrier, Square-tailed Kite, Varied Sittella and White-fronted Chat). An addendum to the Strategy was submitted to the DP&I for approval in February 2011. The Strategy was amended to address DP&I comments provided on 14 August 2012. The Strategy was resubmitted to DP&I on 13 November 2012 and is currently awaiting DP&I approval.

#### *Rehabilitation and Offset Management Plan (ROMP)*

A ROMP was prepared in accordance with the Modified Development Consent approved on 10 March 2010. The ROMP was prepared in consultation with EPA, NoW and BSC and then submitted to both DRE and DP&I for approval. Subsequent to receiving DP&I review comments on 14 August 2012, Barrick continued to prepare a revised ROMP at the end of the reporting period. Barrick Revised the ROMP and submitted it to the DP&I for approval on 21 August 2013.

#### *Transport of Hazardous Material Study*

Barrick advised the DP&I Major Hazards Unit of one emergency route change during the reporting period. This was in early March 2013 when a single NaCN isotainer movement missed the train from Sydney to Dubbo. The movement occurred using the same alternate risk assessed route after Queensland flooding in early-2012 disrupted train shipments from Brisbane to Sydney (also the approved alternate route for hydrogen peroxide shipments).

## 1.2 MINE CONTACTS

Contact details for the CGM are provided below:

General Manager Alan Fearon Telephone: (02) 6975 4707 Fax: (02) 6975 4740 Email: <a href="mailto:alfearon@barrick.com">alfearon@barrick.com</a>	Environmental Manager Garry Pearson Telephone: (02) 6975 4708 Fax: (02) 6975 4740 Email: <a href="mailto:gpearson@barrick.com">gpearson@barrick.com</a>
---	---

## 1.3 ACTIONS REQUIRED AT THE PREVIOUS AEMR REVIEW

The 2012 Annual Environmental Management Report (**AEMR**) meeting was held on 02 October 2013 at the CGM. Actions arising from this meeting are included in Table 2. No additional directions were given during site visits during the reporting period.

**Table 2**  
**AEMR Meeting Actions**

Action	Responsibility	Status	Document Reference
Next Cowal MOP (ESG3 Guidelines, 2013)	Barrick/ DRE (Minerals)	<b>Ongoing</b> – Barrick will convert to ESG3 format after DRE approval of Barrick request to transition current MOP to end-January 2015 (to allow adequate time for approvals process for current DC Modification application for mine life Extension).	CGM MOP (Oct 2012 – Jan 2014)

## 1.4 CGM BACKGROUND

The CGM is owned and operated by Barrick and is located approximately 38 kilometres (km) north-east of West Wyalong, New South Wales (NSW) (Figure 1). Figure 2 provides the cadastral boundaries of properties in the vicinity of the CGM. Figure 3 provides a satellite image of the CGM (as at March 2014).

North Limited (**North**) commenced exploration along the western side of Lake Cowal in 1981. From 1981 to 1994, exploration was concentrated on the Endeavour 42 (E42) ore body to increase the size and confidence of the resource by infill and deep drilling.

North received Development Consent for the Cowal Gold Project in February 1999. North was later acquired by Rio Tinto which subsequently sold the Cowal Gold Project to Homestake Australia Limited (**Homestake**). Homestake commenced advanced drilling on E42 in late 2001. In December 2001, Barrick acquired Homestake and its operating subsidiary. Barrick continued the drilling programme. Additional drilling of the E42 ore body was undertaken between 2001 and 2005. During 2003 and 2004, the CGM underwent a detailed design phase and construction commenced on 12 January 2004. Mining operations commenced in April 2005 followed by operation of the final stage of the open pit dewatering system in June 2005.

Construction was carried out in accordance with the Development Consent. Vegetation clearance and soil stripping activities were undertaken prior to the commencement of construction of mine infrastructure. All clearance areas were subject to Development Consent Condition 3.10(B) which required Barrick to minimise the removal of trees and other vegetation to specified approved areas. Vegetation clearance activities were conducted in accordance with the Vegetation Clearance Protocol and Threatened Species Management Protocol. Details of these are provided in the Flora and Fauna Management Plan (**FFMP**) and Implementation of the Threatened Species Management Protocol (**TSMP**) (Barrick, 2003h).

The CGM was the first non-operational gold mine using cyanide in the world to be certified to the International Cyanide Management Institute Code (**ICMI Code**) for Cyanide Management (17 April 2006). The CGM was also the first gold mine using cyanide in the world to be pre-operationally and operationally certified to the ICMI Code (2 August 2007). An independent professional third-party re-certification occurred previously during February



2010 and May 2012. Cowal operations were found to have maintained full compliance to the ICMC Cyanide management Code during the previous three years.

A further independent professional re-certification audit occurred during 18-21 November 2013. Barrick (Cowal) Limited was again officially re-certified to the ICMI Code for a fourth time on 28 May 2014. Details regarding the re-certification audit are provided on the ICMI's website <http://www.cyanidecode.org/media-room/press-releases>.

## 1.5 INDEPENDENT ENVIRONMENTAL AUDIT

Condition 8.8(a) of the CGM Development Consent requires that an independent environmental audit be undertaken every three years to assess the performance of the CGM against conditions of the Development Consent and other licences and approvals and the results included in the AEMR. The CGM Independent Monitoring Panel (**IMP**) recommended in their 2007 Annual Report that "*Barrick consider continuing use of the template-based approach established by aemc for environmental auditing of operations in order to regularly and systematically update progress on each of the environmental management and monitoring components*".

An Independent Environmental Audit (**IEA**) of the CGM was conducted during 16-19 April 2013 by Trevor Brown and Robert Drury of Trevor Brown & Associates. The IEA was conducted in accordance with the Australian/New Zealand Standards AS/NZS ISO 14010:1996 – *Guidelines and General Principles for Environmental Auditing* and AS/NZS ISO 14011:1996 – *Procedures for Environmental Auditing*. The scope of the work for the compliance audit included the following:

- review of the implementation of the requirements of the Development Consent, licences and approvals for the CGM;
- conduct a site inspection and review of on-site documentation and monitoring data relevant to the audit;
- discussions with CGM staff in relation to the requirements of the Development Consent;
- assessment of the CGM against the requirements of the Development Consent; and
- preparation of the Compliance Audit Report providing assessment of compliance against each condition of the Development Consent.

A copy of the 2013 IEA is provided as Appendix A. A summary of the 2013 IEA is provided in Section 3.

## 2 OPERATIONS DURING THE REPORTING PERIOD

Sections 2.1 to 2.10 below describe the operations undertaken at the CGM during the reporting period. Activities included exploration, land preparation, infrastructure construction, mining, mineral processing, waste management, ore and product stockpiling, water management, hazardous material management and other infrastructure management.

### 2.1 EXPLORATION

A summary of the exploration, drilling and other geology related activities undertaken within ML 1535 during the reporting period is provided below.

Exploration activities undertaken during 2013 included resource definition drilling over the north-western portion of the E42 Open Pit and resource infill drilling within E46 East. The drilling north-west of E42 Open Pit was part of the geotechnical air-core drilling program. Total drilling completed within ML1535 during 2013 amounted to approximately 13,734 m (726 m air-core and 13,007 m diamond drilling). The geotechnical program consisted of eight air-core holes to an average depth of 91 m. Deeper drilling was conducted on the E46 prospect within Lake Cowal within the boundary of ML 1535 where 21 holes with depths ranging between 500-800m were completed, testing a zone of mineralization for underground mining possibilities.

The drilling during the reporting period was concentrated 28:72 both inside of the lake protection bund as well as within the lake at E46. All drill holes completed during the program as well as those drilled on the lake bed were concrete grouted throughout the entire length after the completion of each hole.

Land disturbance was minimal as a result of the exploration activities. Lake drilling was conducted from purpose built track mounted platform rigs designed to reduce impact on the ground. The rig has a self-contained fluid retention system and drip trays that prevent spillage of fluids into the lake. Rehabilitation of the drilling areas is described in detail in the October 2012 to January 2014 MOP. On 4 October 2013, the Director-General of the DTIRIS-DRE granted Barrick an extension to the term of the previous Cowal Gold Mine Mining Operations Plan (October 2012 – January 2014) to 31 January 2015.

### 2.2 LAND PREPARATION

Land preparation activities for the reporting period involved soil stripping of the following areas (Paragraph 3.6.3.2);

- Pond D1 trial area; and
- TSF Depot area.

The pre-stripped TSF Depot area received the relocated Millers Crusher Subsoil stockpile. The 80 metre extension of the Pond D1 north trial area was independently assessed as the best place to conduct further test work on 150 or 300 mm topsoil with native pasture hay, clean wheaten straw, and native seeds and tube stock species. Shaping and ripping of the soil into the waste rock layer occurred during a relatively dry growing season.

Prior to soil stripping being undertaken at a particular location, the CGM Vegetation Clearance Protocol (**VCP**), Threatened Species Management Protocol and Aboriginal Heritage Clearance requirements were implemented.

ML1535 stripped soils are either re-used or delivered directly to soil stockpiles for use in rehabilitation as shown on Figure 4. The date, location, soil type, volume and description of any ameliorants added to stockpiled materials were recorded in the CGM soils database.

### 2.3 INFRASTRUCTURE CONSTRUCTION

The construction details and the construction status of infrastructure components at the end of the reporting period are provided in Table 3. The infrastructure components are shown on Figure 3.

**Table 3**  
**Infrastructure Construction Components during the Reporting Period**

Infrastructure Component	Construction Status
Temporary Isolation Bund and Pond D1	<p>Lake Cowal has remained against the Temporary Isolation Bund (TIB) since the most recent Lake Cowal flooding event of mid-March 2012.</p> <p>Post-flood natural regeneration of native species, particularly Lignum, River Red Gum and River Cooba has been visibly significant along the length and crest of the TIB and LPB valley. Waterbird, raptor, bush bird, reptile and frog numbers have remained noticeably high.</p> <p>Works are proposed to raise the TIB by 0.5m when Lake Cowal has receded to a safe distance for earthworks to occur. These works will be detailed in the next relevant AEMR/MOP reporting period. The NoW SL for the TIB-LIB-pipeline is due for renewal in 2015.</p>
Stilling Basin Southern Upper Catchment Diversion - Lowflow Diversion	<p>Advantage of a dry period was taken and a small amount of clay-sand sediment was removed to original as-constructed survey depth. There was no change in Stilling Basin footprint. The removed clay-sand sediment was placed on the waste rock layer immediately adjacent at the south lower slope of the SWRE. The basin is yet to refill with storm water.</p>
Southern Tailings Storage Facility (STSF)	<p>Construction works on the 4<sup>th</sup> lift (3<sup>rd</sup> augmentation) were conducted during the prior reporting period. The 4<sup>th</sup> lift became operational from mid-June 2013. The 4<sup>th</sup> lift will be operational until August 2014. Gas cannons have been redeployed around the NTSF Decant (as they were around the STSF Decant during 2013), as Lake Cowal continues to recede quickly and become much shallower. Clear water seepage was noted on the north upper lift joint. Simple bench drainage trench structures were installed. Additional piezos showed that the phreatic water responded immediately. There is no structural issue. A large clay plug was inserted into the start of the Decant access road as a means of identifying whether the road or lift joints needed further design review. Lift engineering design review has resulted in a lift construction change for the 4<sup>th</sup> lift of the NTSF. Geotechnical monitoring will continue into the next reporting period (see section 3.5.1.2).</p>
Northern Tailings Storage Facility (NTSF)	<p>Outer batter rehabilitation works of the 3<sup>rd</sup> lift of the NTSF were completed in early-2013, and are functioning well. Tailings deposition into the 3<sup>rd</sup> lift of the NTSF ceased in mid-June 2013. Planning for the 4<sup>th</sup> lift planning commenced in early-2014. A saline seep developed in the north-east toe area of NTSF in mid-December 2012 and is linked to the old black-clay creek bed that runs towards the north east. A clear water seep developed in the middle of the south wall above the first Lift and has been managed safely back into the NTSF since January 2013. Simple bench drainage trench structures were installed. Additional piezos showed that the phreatic water responded immediately. There is no structural issue. A large clay plug was inserted into the start of the Decant access road as a means of identifying whether the road or lift joints needed further design review. Lift engineering design review has resulted in a lift construction change for the 4<sup>th</sup> lift of the NTSF. Geotechnical monitoring will continue into the next reporting period (see section 3.5.1.2).</p>
Southern Waste Emplacement (SWRE)	<p>The SWE has been used to store waste rock from Pit stages D, E, F and G.</p> <p>Monitoring of the rehabilitation trials on the south side of the SWE was continued. The recent wet and dry two years have not resulted in any significant erosion on the treated areas. Pre-treated seed was spread across the four top soiled trial plot sectors in October-2011. Independent investigation of tree root penetration into the waste rock oxide and sub-soil layer below the trial plots occurred.</p> <p>Substantial shaping and outer batters rehabilitation of the southern, western and northern slopes has occurred using the waste rock, gypsum treated topsoil method during the reporting period.</p>
Perimeter Waste Emplacement (PWRE)	<p>Rehabilitation of the eastern and southern outside upper two lifts occurred using the waste rock, gypsum treated topsoil method during the reporting period. The southern inside three lifts of the PWRE will be treated by the same rehabilitation method during the latter part of 2014.</p>
Northern Waste Emplacement (NWRE)	<p>The NWE continued to receive waste from the Pit stages D, E, F and G. The upper two Lifts of the NWE replicate trials adjacent to Pond D1 (Pond D1 north) were constructed in readiness for wheaten-lucerne straw and pasture hay cover treatments early in 2012 have continued to self-cover and remain stable. Due to unseasonal rainfall patterns, no native pasture hay was collected from Barrick land during 2012-2013 thus affecting the Pond D1 north trial progress. As per independent advice, a supplementary 80 metre extension area was created near the Pond D1 north trial area. Native pasture hay was slashed and baled from Barrick's 'Hillgrove' property in November 2013 and has been stockpiled ready for use. Gypsum spreading occurred in June 2014. The native pasture hay and clean wheaten straw covers will be added before mid-July 2014. The timing of native tube stock planting and seeding will be dependent on a period of suitable rainfall.</p>
Northern Upper catchment Diversion - Lowflow Drain	<p>During the reporting period the original rock bars were repaired (intense rainfall event 2011). Rock edge protection wings were added to the sides of the five substantial leaky weir rock bars. All the bars have been holding some water during the majority of the reporting period. Wildlife visitations in these areas were notable during recent dry months.</p>

**Table 3 (Continued)**  
**Infrastructure Construction Components during the Reporting Period**

Infrastructure Component	Construction Status
Lake Cowal Monitoring Equipment	<p>Lake Cowal blast monitoring stations were inundated by 0.1 - 0.5m of water just before annual maintenance and recalibration checks were due. New technology Lake loggers arrived in June 2012 for fitting onto tall tripod stations of between 2 and 4m in height. Toward the end of 2013, further enhanced logging capabilities were due to be installed at each of the stations to access meteorological conditions at each station. This has been delayed as commissioning continued on the new logger technology during the 2013 reporting period. 2014 reporting period logger equipment checks will occur soon after the next EPL variation (BM06 'east Lake' blast monitoring gauge relocation to BM08.1 'Cowel North' permanent). Light vehicle access is now available again to BM04.1 (north-east Lake).</p> <p>New tripod stations were manufactured locally in early-2012 to install duplicate, taller dust gauges alongside existing 2m tall monitors. Lake Cowal levels rose quickly and dropped slowly as waters entered from the south and east, and left the north end of the Lake system, respectively. Lake Cowal has continued to recede and become shallower during 2013 and 2014 years. Light vehicle access is now available again to DG02 (north-east Lake).</p> <p>Deployment of the locally manufactured raised dust tripods and ambient noise monitoring chairs and logger stands in the 3 to 4m deep parts of Lake Cowal occurred from May 2012. They have been used for the 2013 year six-monthly independent attended and unattended noise surveys. Light vehicle access is now available again to NO4 (north-east Lake).</p>

## 2.4 MINING

Mining operations continued throughout 2013. Material types mined included ore and waste (including mineralised material). Mostly sulphide ores were extracted with some oxide ores being stockpiled for later processing. A total of 9,944,885 tonnes of ore and 19,096,078 tonnes of waste rock was mined during the reporting period. A further 713,000 tonnes of mineralised material was also mined during the reporting period.

No expansions occurred on the NWRE, SWRE or PWRE during the reporting period. Reclamation shaping with waste rock – topsoil cover method occurred on the north-eastern end of the outer northern batter during 2013. The 80 metre extension to the rehabilitation trial plots adjacent to Pond D1 north trials were constructed using the rock-topsoil method as a basis (Section 5.4). Native pasture hay was recovered during October 2013 for the Pond D1 trials that were currently on hold at the end of the reporting period.

Waste rock mined from the open pit was stockpiled for the STSF and NTSF wall raising works and outer slope rehabilitation. Clay obtained from phase E works was stockpiled near the TSF Depot for future works. The upstream lift material was direct hauled on occasions. This process of TSF lifts will continue on an annual basis.

Mining during 2013 occurred in two separate areas Stage G and Stage F.

Mining occurred in the Stage F2 pit from RL 993m to RL 912m, representing a vertical advance of 81m. Mining occurred in the Stage G pit from RL 1,119m to RL 1,065m, representing a vertical advance of 54m.

Vertical and horizontal dewatering systems were maintained throughout the reporting period. Additional horizontal holes were drilled as mining progressed through phase E and phase G. New de-watering bores placed outside the Open Pit perimeter continued to be used for de-watering of the Open Pit wall. The NoW issued two Water Title Certificates for the Upper Lachlan Alluvial (10%) and the Upper Lachlan Fold Belt MDB (90%) portions of the de-watering operations for the E42 Open Pit (maximum of 2 ML/day; typical average < 0.5 ML/day).

A new MOP was approved during the prior reporting period. As stated in Paragraph 1.1.1, the new 2012 to 2014 MOP was approved by the DTIRIS (DRE) on 19 December 2012. On 4 October 2013, the Director-General of the DTIRIS-DRE granted Barrick an extension to the term of the previous Cowal Gold Mine Mining Operations Plan (October 2012 – January 2014) to 31 January 2015.

## 2.5 MINERAL PROCESSING

Processing continued throughout 2013. The processing plant recovered 296,883 ounces of gold during the reporting period. The maximum ore processing rate during the reporting period was approximately 7.2 Mtpa (Table 4).

Tailings were deposited into the third lift of the NTSF until June 2013, after which tailings were deposited into the fourth lift (third augmentation) of the STSF for the remainder of the year. Construction works began on the fourth lift (fourth augmentation) of the NTSF in December 2013 and have continued into the 2014 reporting period.

The October 2012 – January 2014 MOP provides further detail regarding minerals processing undertaken at the CGM. On 4 October 2013, the Director-General of the DTIRIS-DRE granted Barrick an extension to the term of the previous Cowal Gold Mine Mining Operations Plan (October 2012 – January 2014) to 31 January 2015.

## 2.6 WASTE MANAGEMENT

### *Waste Rock (including mineralised material), Ore and Processing Waste*

The CGM produced waste rock (including mineralised material), ore, processing waste and product during the reporting period. Topsoil continued to be stripped, used and spread during the reporting period in accordance with the Soil Stripping Management Plan (**SSMP**) (Barrick, 2003a) as described in Paragraph 3.6. The amount of ore and waste rock (including mineralised material), ore, processing waste and product produced is set out in Table 4. Table 21 (Paragraph 3.4.3.2) describes 2013 year topsoil stripped, spread and used.

**Table 4  
Production and Waste Summary**

	Cumulative Production		
	Start of Reporting Period	At End of Reporting Period	End of Next Reporting Period (estimated)
Waste Rock (Mt) (excluding mineralised material)	163.34	182.44	200.32
Mineralised Material (Mt)	13.71	14.42	15.10
Ore (Mt)	63.52	73.46	82.93
Processing Waste (Tailings) (Mt)	45.13	52.16	59.36
Product (oz)	1,621,180	1,918,063	2,167,063

### *Non-Mining Waste*

Non-mining waste generated at the CGM during the reporting period was transported, handled and disposed of in accordance with the Hazardous Waste and Chemical Management Plan (**HWCMP**) (Barrick, 2006c). Wastes generated during the reporting period consisted of:

- administration area domestic and packaging waste;
- sewage effluent;
- waste hydrocarbons including lubricating oils, hydraulic oils, degreasing fluids, distillate and petroleum fuels;
- used oil filters, grease and fuel/oil contaminated rags;
- vehicle batteries and light vehicle tyres;
- general waste/obsolete operational and maintenance chemicals;
- process plant trash screen oversize plastic mulch;
- scrap metals including electrical off-cuts and undersized grinding media magnet rejects; and
- spill kit recovery/ clean-up materials.

Any hazardous material or dangerous good not used or obsolete for site use is disposed of to the appropriate off-site disposal facilities by a licensed waste management contractor.

Table 5 provides a summary of operational waste types generated during the reporting period.

**Table 5  
Operational Phase Wastes – Transport, Handling and Disposal**

<b>Waste</b>	<b>Handling</b>	<b>Transport/Disposal</b>
General inert construction waste (e.g. concrete, and timber)	Waste stockpiled on-site and progressively removed/disposed.	Disposal in West Wyalong landfill/refuse facility by arrangement with BSC.
Office and packaging waste	Waste collected on-site.	Removed by contractor or BSC truck or disposal on-site in waste rock emplacements only.  Disposal to West Wyalong landfill/refuse facility by arrangement with BSC or recycling depot (e.g. cardboard, aluminium cans, plastics and paper). Cardboard bailer installed and operational since 2009 was decommissioned in 2012. Cardboard is now taken loose to recycler in West Wyalong.
Food waste	Domestic solid waste held in specific storage containers.	Removed by contractor or BSC covered vehicle. Disposal to West Wyalong landfill/refuse facility by arrangement with BSC.
Scrap metal streams	Waste was segregated and held on-site in designated areas.	Removed from site by contractor for recycling.
Used lead acid batteries	Used batteries were stored in a bunded area.	Periodically removed from site by a licensed contractor. Recycled by licensed contractor.
Degreasing fluids, distillate and petroleum fluids	Used and flammable petroleum liquid wastes stored in dedicated storage vessel(s).	Removed from site by licensed contractor for recycling/disposal.
Lubricating oils and hydraulic oils	Used and waste oils stored in dedicated storage vessel(s).	Removed from site by licensed contractor for recycling/disposal.
Used/rejected tyres	Tyre store was maintained in designated area.	On-site disposal at surveyed locations in waste rock emplacements.
Hydrocarbon tainted soils/rock.	Treated in on-site bioremediation facility.	Treated in on-site bioremediation facility.
Used oil/fuel filters	Filters stored in dedicated bins prior to removal.	Removed by licensed contractor. Disposal or recycling at licensed waste facility (material is inert by EPA Guidelines for waste classification).
Processing Plant trash screen oversize plastic mulch	Dried and boxed for disposal in WRE layer.	Not used 2008 through 2011. Commenced early 2012 to address build-up of plastic in carbon stripping circuit.
Drained/crushed oil/fuel filters	Filters stored in dedicated bins prior to removal.	Removed from site for recycling disposal via licensed contractor.
Used absorbents – free liquid	Clearly marked to avoid mixing of incompatible substances. Transferred to clearly labelled drums or similar containers.	Removed by licensed contractor. Disposal at licensed waste facility.
Liquid waste from sewage system	Contents of septic systems pumped out as required (currently). Portaloo units maintained by contractor.	Treated effluent from site sewage treatment facility disposed of via above ground pipeline to tailings storage. Solids from site sewage treatment facility pumped out and collected as required via licensed contractor. Grey water used for watering of Geology garden beds and landscaping or as TSF make-up water.

The October 2012 to January 2014 MOP provides further detail regarding waste management activities undertaken at the CGM.

## 2.7 ORE AND PRODUCT STOCKPILES

The amount of CGM ore and waste rock (including mineralised material) produced during the reporting period is set out in Table 4.

The October 2012 to January 2014 MOP provides further detail regarding ore and product stockpile management undertaken at the CGM.

## 2.8 WATER MANAGEMENT

### Groundwater

The quantity of water approved to be extracted from the Bland Creek Palaeochannel (**BCPC**) is limited by:

- a) Development Consent Condition 4.4(a) which states:
  - (a) *The maximum daily extraction of water from the Bland Creek Palaeochannel shall not exceed 15 ML/day, and not exceed 3,650 ML/year. A total extraction of 30,000 ML shall not be exceeded for the life of the mine, unless otherwise agreed by the Director-General of the DP&I, in consultation with NoW. All bores from the Bland Creek Palaeochannel borefield used for mine purposes must be metered.*

and
- b) the NoW bore water licences.

Development Consent Condition 9.2(i) (f) requires the outcome of the water budget for the year and the quantity of water used from water storages and BCPC borefield to be included in the AEMR. A summary of the volume of water extracted from the BCPC borefield is summarised in Paragraph 3.4.3.2.

A total of 1,377 megalitres (ML) of water was extracted from the BCPC borefield during the reporting period (see Table 19). No water was extracted from the eastern saline borefield during the reporting period.

The saline groundwater supply borefield on the floor of Lake Cowal within ML 1535 was commissioned in mid-2009 (Production bore licences #70BL232691 and #70BL232692 were granted by the NoW for the period 28 January 2010 to 27 January 2015). No extraction has occurred since April 2010 due to access restrictions resulting from the inundation of Lake Cowal. The production and monitoring bores on the floor of Lake Cowal remain capped. The recently received NoW Water Title Certificate for the Upper Lachlan Alluvial (10%) of E42 Pit de-watering allocation includes these two Lake floor production bores. The gravel access track was still cut by Lake water at the end of the 2013 reporting period.

Extracted water was used mainly for the treatment of sulphide ores through the processing plant. Water is also used for dust suppression and soil conditioning to achieve optimal compaction rates during TSF lift construction works.

Pond D9 held approximately 405 ML of groundwater (from the BCPC, saline groundwater de-watering/supply borefields and rainfall) and surface water (Regulated Lachlan River water) at the end of the reporting period.

The groundwater level associated with the BCPC borefield is monitored on a continuous basis by the NoW groundwater monitoring bore on Burcher Road (GW036553). Contingency measures have been developed for implementation when water levels reach either RL 137.5m AHD or RL 134m AHD. These trigger levels were developed in consultation with the NoW and other water users within the BCPC including stock and domestic users and irrigators. The trigger levels were not reached during the reporting period.

Notwithstanding, Barrick continues to assist local BCPC water users with access concerns. As per an agreement with the NoW (13 September 2006), Barrick previously supplied water to users in the West Plains and Trivalana schemes via the Barrick (Cowan) Limited BCPC borefield pipeline during the reporting period. Also as agreed with the NoW and BCPC Water Users Group, Barrick has conducted regular surveys to monitor eight monuments on the east side of Lake Cowal for any evidence of soil compaction. Both the West Plains and Trivalana schemes have since been removed from the Barrick pipeline system by mutual agreements.

Development Application No. 2011/0064 was granted by the Forbes Shire Council on 20 December 2010 for the construction and operation of the eastern saline borefield (ESB), located approximately 10 km east of Lake Cowal's eastern shoreline, for a period of five years (until 20 December 2015). The November 2011 revised SWMP (eastern saline borefield MOD10), replaced the November 2010 SWMP. The DP&I provided review comments on the revised SWMP in August 2012. Barrick has subsequently updated the revised SWMP to address the DP&I's review comments and has submitted the revised SWMP to relevant consultees. NoW summarily issued two presently unused production bore and monitoring bore piezometer licenses. The eastern

saline borefield and associated production bore licences are included in the Addendum to the SWGMBMP, approved by the DP&I in August 2012.

In accordance with Development Consent Condition 4.1/4.2(b), a long-term strategy for decommissioning water management structures and a strategy for the final void was prepared during the reporting period. A request for an extension of the timing for submission of the long-term strategy, to the end-June 2013 was submitted to the DP&I on 13 November 2012. The long-term strategy has been incorporated into the revised SWMP after Barrick consulted with the DTIRIS (DRE) and the CEMCC. Barrick is consulted with NoW and EPA submitted a revised SWMP to the DP&I for approval on 8 August 2013.

SB01 (#70BL233321) and SB02 (#70BL233323) have not been used during the 2013 reporting period due to wet regional conditions and local access issues.

The E42 open pit dewatering borefield was established external to the perimeter of the E42 Pit. A total of 11.0 ML was extracted from the open pit borefield, and a further 955.0 ML from the open pit de-watering sumps from rock wall seepage and rainfall during the reporting period. The water from the borefield was mainly used for ore treatment within the processing plant via Pond D6, dust control on E42 Pit and TSF haul roads and for soil conditioning to achieve optimal compaction rates during TSF lift construction works. During the 2013 reporting period the NoW advertised CGM's replacement vertical de-watering bores publicly, and summarily issued a Water Title Certificate for 366 Units in the Upper Lachlan Alluvial Zone 7 (includes the rested lake floor bores).

### Surface Water

A total of 1,102 ML was pumped from the Jemalong Irrigation Channel during the reporting period due to the relatively drier conditions. The Jemalong water was purchased from the regulated Lachlan River trading market.

Barrick's High Security (80 Units) and General Security (zero allocation) water access licences (High Security Title Identifier WAL14981 has a NoW Lachlan River Regulated Water Source – Water Sharing Plan Reference of 70WA603145 (previously 70AL603333), and General Security Title Identifier WAL13748 (NoW Reference of 70AL603332)), enable trade of Temporary Water. The Jemalong irrigation channel transfer at the Bore 4 intake pumping station (Figure 1) to the CGM was used for the 1,102 ML transfer during the reporting period.

Table 6 provides the volume of water contained in the water storages at the beginning and end of the reporting period. The Cowal Gold Mine water management system is conceptually shown in Figure 5.

**Table 6  
Stored Water**

	Volumes Held (ML)		
	Start of Reporting Period	End of Reporting Period	Storage Capacity
Contained Water Storage (D1, D2, D3, D4, D5 and D8B)	35	22	375
Process Water Storage (D9)	641.4	405	700
Process Water Storage (D6 + TSF Decant[s])	47	52	250

The CGM MOP (2012 - 2014) provides further detail regarding water management undertaken at the CGM.

## 2.9 HAZARDOUS MATERIAL MANAGEMENT

Hazardous Materials and Dangerous Goods were managed in accordance with the Environmental Impact Statement (EIS) and HWCMP during the reporting period (Barrick, 2006c).

Emergency response spill kits are provided at all fuel storage locations. Licensed waste contractors remove all waste oil and used engine coolant from site for recycling.

In accordance with the Chemical Management Strategy (CMS) described in the HWCMP, all raw materials/consumables brought on-site for use at the CGM are recorded in an Inventory Register which is updated and available for inspection by the appropriate authorities. Manufacturer's Safety Data Sheets (SDS) for these substances are also included in the Inventory Register. Substances that are designated as hazardous



and/or dangerous goods (**HSDG**) are also included in the Hazardous Substances Dangerous Goods Register (**HSDGR**). Fuels and oils in the Inventory Register are also included in the Fuels and Oils Register (**FOR**). The HWCMP (Barrick, 2006c) was approved by the Director-General of the DP&I on 6 March 2006. In 2009 an addendum to the HWCMP was prepared to: revise the waste classifications in accordance with the *Waste Classification Guidelines* (EPA, 2008); revise the waste tracking requirements in accordance with the amended *Protection of the Environment Operations (Waste) Regulation, 2005*; revise the proposed management measures for waste tyres generated at the CGM; and include proposed management measures for the area of historic contamination. The addendum to the HWCMP was approved by the DP&I on 15 May 2009. The CGM HWCMP was updated in accordance with Development Consent Conditions 3.2 and 5.7 to reflect changes in operational practices since the commencement of the CGM. The DP&I approved the revision on 12 May 2011.

The application and approval process for the introduction of new substances at the CGM is conducted via the ChemAlert web-based management system. The Manufacturer's Safety Data Sheet information for approved chemicals, lubricants and fuels is available to all employees via the CGM intranet using the ChemAlert 3 software package. Laminated field hardcopy information folders are also available.

Any surplus chemical substances from the operations are removed by licensed contractors to approved locations for re-use/disposal.

### **Hazard Audit**

In accordance with the Development Consent Condition 5.4 (e), a Hazard Audit is required to be conducted 12 months after the commencement of operations (and three yearly thereafter).

An audit was conducted by an independent qualified person (Dean Shewring of Pinnacle Risk Management) using DP&I Hazard Audit Guidelines (Advisory Paper No 5) in 2007. No significant findings were made. Barrick prepared a Progress Report detailing the status of the Hazard Audit's 14 recommendations during the 2010 reporting period.

The first triennial Hazard audit occurred on 19 to 23 April 2010 and was conducted by an independent qualified person (Dean Shewring of Pinnacle Risk Management). Eleven recommendations were made, which were tracked and addressed in a timely manner.

The second triennial Hazard audit occurred on 8 to 10 April 2013 and was conducted by an independent qualified person (Dean Shewring of Pinnacle Risk Management), in compliance with the Department of Planning and Infrastructure's HIPAP No. 5. Eighteen recommendations were made and are being traced in the CGM's EOR.

The October 2012 to January 2014 MOP provides further detail regarding hazardous material management undertaken at the CGM.

## **2.10 OTHER INFRASTRUCTURE MANAGEMENT**

This Paragraph is not applicable to the CGM for this reporting period. CGM is an Open Pit type mine and gold-silver ore processing and recovery plant. Mobile fleet and fixed plant assets are self-maintained on site.

## **3 ENVIRONMENTAL MANAGEMENT AND PERFORMANCE**

Environmental management at the CGM during the reporting period has been conducted under the guidance of and in accordance with the numerous EMPs prepared for the CGM required under the CGMs Development Consent.

### ***Overall Performance against Licences, Approvals and Environmental Management Plans and Effectiveness of Environmental Management***

The sixth, annual operational phase IEA was conducted for the CGM from 15 - 18 April 2013. The auditors concluded that Barrick has demonstrated general compliance with the conditions attached to the Development Consent, licences and approvals granted for the CGM. The results of the audit indicated that the overall performance against the licences, approvals and EMPs has been of a high standard. The report is attached in

Appendix A. The IEA for the eighth year of operations will be conducted during the 2014 AEMR reporting year (28 - 30 April 2014).

Barrick has complied with the commitments of the 2012 – 2014 MOP and the more recent approved current term (October 2012 – January 2014) to the extent that site conditions permitted.

The Environment Protection Licence No. 11912 Annual Environmental Return (**AER**) for the 23 December 2012 to 22 December 2013 reporting period was submitted to the EPA on 20 February 2014. The AER provides the EPA with (amongst other things) a Statement of Compliance by Barrick in relation to its monitoring obligations under Environment Protection Licence No. 11912. In its 2013 AER, Barrick identified non-compliances related to monitoring not being undertaken at some surface water, dust, groundwater and blast monitoring points. The reasons for the non-compliances were inaccessibility of monitoring points due to weather, dry bore, no seepage point, scheduling errors or logger equipment failure. There was one air blast overpressure level exceedance of condition L5.2 on 7 July 2013. However in accordance with the allowable exceedance criteria detailed in Condition 6.3(a) of the CGM's Development Consent, this individual exceedance of the air blast overpressure level was less than 5% of the total number of blasts and as a result Barrick was compliant with Condition 6.3(a). The occurrence of non-compliances is listed on the EPA website at: <http://www.environment.nsw.gov.au/prpoeoapp/>

Sections 3.1 to 3.22 describe the objectives of relevant EMPs, their management measures and discuss the environmental performance of each EMP for the reporting period. Overall, due to Barrick's substantial compliance with the EMPs, environmental management for the CGM during the reporting period has been highly effective. Reportable incidents and any further improvements to the environmental management strategies at the CGM are also discussed.

#### ***Expected Performance of Licences, Approvals and Environmental Management Plans***

Barrick has all the relevant Project Management systems, staffing and consultancy arrangements in place to enable it to be in a position of confidence regarding compliance with all relevant licences, approvals and EMPs. Barrick expects to undertake CGM activities for the next reporting year in accordance with all relevant licences, approvals and EMPs. Paragraph 6 discusses the management objectives and targets for the CGM during the next reporting period.

#### ***Independent Environmental Audit***

The Development Consent for the CGM requires an IEA of compliance. Development Consent Condition 8.8 states:

- (a) *An Independent Environmental Audit shall be completed:*
- a. *six monthly during construction;*
  - b. *12 months after the commencement of ore processing; and*
  - c. *then every three years thereafter until decommissioning of the mine and ore processing operations respectively, or as otherwise directed by the Director-General of the DP&I.*

*The Applicant shall conduct an environmental audit of the mining and infrastructure areas of the development in accordance with ISO 14010 - Guidelines and General Principles for Environmental Auditing, and ISO 14011 - Procedures for Environmental Auditing (or the current versions), and in accordance with any specifications required by the Director-General of the DP&I. Copies of the report shall be submitted by the Applicant to the Director-General of the DP&I, BSC, EPA, NoW, DTIRIS (Minerals) and CEMCC within two weeks of the report's completion for comment.*

- (i) *The audit shall:*
- *assess compliance with the requirements of this consent, licences and approvals;*
  - *in the event of any non-compliance, report on the effectiveness of the environmental management of the mine as it may relate to the area of non-compliance;*
  - *be carried out at the Applicant's expense; and*
  - *be conducted by a duly qualified independent person or team approved by the Director-General of the DP&I in consultation with BSC and CEMCC.*

- (ii) *The Director-General may, after considering any submission made by the relevant government agencies, BSC and CEMCC on the report, notify the Applicant of any requirements with regard to any recommendations in the report. The Applicant shall comply with those reasonable requirements within such time as the Director-General may require.*

As described in Section 1.5, the IMP recommended in their 2007 Annual Report that “*Barrick consider continuing use of the template-based approach established by aemc for environmental auditing of operations in order to regularly and systematically update progress on each of the environmental management and monitoring components*”.

The 2013 IEA was conducted between 15 - 18 April 2013 by Trevor Brown and Robert Drury of Trevor Brown & Associates to assess the status of the development activities undertaken during the prior year of operations. The audit generally confirmed a high degree of compliance with the Minister’s Conditions of Approval, Environment Protection Licence conditions and requirements of the conditions attached to the Mining Lease. Upon receipt, this report was distributed to the above regulatory agencies in June 2013, and is appended in the 2013 AEMR as Appendix A. The 2014 IEA was conducted during the 28 – 30 April 2014.

### **Environmental Risk Identification**

A Preliminary Hazard Analysis (**PHA**), Transport of Hazardous Materials Study (**THMS**), *Hazard and Operability Study Report, Cowal Gold Project (HAZOP)* (Pinnacle Risk Management, 2004), *Fire Safety Study, Cowal Gold Project (FSS)* (Pinnacle Risk Management, 2005), HWCMP, Final Hazard Analysis (**FHA**), Bushfire Management Plan (**BMP**), CMP, Safety Management System (**SMS**) and Emergency Response Plan (**ERP**), including the PIRMP have been completed and relevant measures implemented for the CGM. Relevant measures continue to be implemented for the CGM, as appropriate.

### **Revision of Monitoring Programmes**

Development Consent Condition 8 requires the monitoring programmes in Development Consent Conditions 8.1 to 8.6 to be revised or updated annually to reflect changing environmental requirements, significant changes in technology/operational practices and results from monitoring conducted. The monitoring programmes include:

- Meteorological monitoring (Development Consent Condition 8.1)
- Surface water (and biological), groundwater and cyanide monitoring (Development Consent Condition 8.2)
- Air quality and dust monitoring (Development Consent Condition 8.3)
- Noise and blasting monitoring (Development Consent Conditions 6.3(b) and 6.4(g) respectively)
- Fauna and flora monitoring (Development Consent Condition 8.5)
- Cultural heritage monitoring (Development Consent Condition 8.6)

As discussed in Paragraph 1.1.2, several EMPs (including monitoring programmes) were revised during the reporting period.

Comments on specific monitoring programs are set out below.

### **Surface Water, Groundwater, Meteorological and Biological Monitoring Programme (SWGMBMP) and Flora and Fauna Management Plan (FFMP)**

In accordance with Development Consent Condition 8.2(a) (ii), the SWGMBMP was revised in consultation with the EPA, NoW and DPI (Fisheries). The DP&I approved the revised SWGMBMP on 10 March 2010.

After DP&I approval of MOD10 in July 2011, Barrick prepared a revised SWGMBMP and provided it to the Independent Monitoring Panel (**IMP**) and other appropriate regulators in accordance with CGM Development Consent Condition 3.2(a) for review. The addendum to the SWGMBMP was submitted to relevant government departments. The DP&I approved the addendum on 14 August 2012.

To maintain consistency with the revised SWMP (which was updated to address DP&I review comments provided in August 2012), Barrick commenced preparation of another Addendum to the SWGMBMP towards the end of the 2012 reporting period and submitted it to the DP&I for approval on 13 August 2013.

To maintain consistency between the SWGMBMP and the FFMP, Barrick also revised the FFMP to incorporate the revised biological monitoring programme as presented in the approved SWGMBMP for the 2012 reporting period. The Threatened Species Management Strategy was prepared in consultation with former EPA (for the Inland Forest Bat, Sloane's Froglet and Woodland birds Little Eagle, Spotted Harrier, Square-tailed Kite, Varied Sittella and White-fronted Chat). The Strategy was submitted to DP&I on 13 November 2012 and is currently awaiting DP&I approval.

### ***Air Quality Monitoring Programme***

The use of galvanized brushes during sample collection ceased during 2009. Regular cleaning, maintenance and replacement of dust gauge components were also introduced as part of regular monthly monitoring activities. On the recommendation of IMP, Barrick has implemented a QA/QC programme with respect to its air quality monitoring programme, incorporating a portable duplicate station. ALS Environmental, a National Association of Testing Authorities (NATA) accredited laboratory, was the preferred laboratory for dust analysis until July 2012 at which time all depositional dust samples were sent to the National Measurement Institute (NMI) Sydney Laboratory. All duplicate depositional dust samples remain with ALS to provide a comparison between the two laboratories. ALS supplied depositional dust collection jars with a non-copper based algaecide during the reporting period. ALS has stated that the algaecide is used for clients where copper analysis is required and has been shown to cause no interference with metals detection. NMI supplied collection jars do not contain algaecide.

In 2012, Barrick successfully approached the National Measurement Institute (**NMI**), Sydney Laboratory regarding the creation of a new dust standard for Cowal operations QA/QC works. Barrick switched from ICP-AES to ICP-MS methodology with ALS, Sydney Laboratory during the 2012 reporting period to gain lower limits of reporting for metals analysis. Barrick advised the EPA and IMP of this intended change in analysis in February 2012.

### ***Blast Monitoring Programme***

The modification to the Development Consent (approved by the DP&I in March 2010) deletes Development Consent Condition 8.4 which was relevant to blast monitoring. A revised Blast Management Plan (**BLMP**) was submitted to the Director-General of the DP&I at the end of July 2010 in accordance with Development Consent Condition 6.3(b). Following the BLMP was again revised and submitted to the DP&I on 11 December 2012 and is currently awaiting DP&I approval.

Due to flood inundation in March 2012, the blast monitoring units in Lake Cowal (BM04, BM05 and BM06) were mounted upon taller tripod stands from May 2012. Enhanced logger technology has been installed in the land-based and Lake cabinets of blast monitoring units around Lake Cowal since June 2012. The new technology loggers commissioning was ongoing at the end of the current reporting period due to intermittent technical issues with the new loggers. Meteorological condition monitoring is intended to be installed at each blast logger unit during the next reporting period. BM07 was to be relocated to the Lake Protection Bund (**LPB**) during 2013 to enhance blast signalling as the mining activity in the E42 Pit becomes deeper.

Barrick will apply for a s58 to vary EPL11912 condition M7.1 during the 2014 reporting period to relocate BM06 (east Lake) to 'Cowan North' (old BM08). Barrick won't relocate until the variation is approved. Thus BM06 equipment will become operational location BM08.1 (BM08 was temporary at another location at 'Cowan North').

### ***Noise Monitoring Programme***

As reported in the AER to EPA on 21 February 2013, monitoring was undertaken by SLR Consulting Australia Pty Ltd (formerly Heggies Pty Ltd) (**SLR Consulting**) in January-February and July 2012. The control strategies implemented during the reporting period in accordance with the NMP are considered to be effective. During September 2009, noise monitoring locations NO7 ("West Lea") and NO8 ("McLintock's") were added to the NMP.

The modification to the Development Consent (approved by the DP&I in March 2010) replaces Development Consent Condition 6.4 relevant to noise monitoring and deletes Development Consent Condition 8.4. As a result, a revised NMP was submitted to the Director-General of the DP&I at the end of July 2010, in accordance with Development Consent Condition 6.4(g) and is currently awaiting approval. DP&I comments were received on 14 August 2012. The revised NMP to address the DP&I's comments was lodged with the DP&I on 24 December 2012 and Barrick is currently awaiting DP&I approval.

### ***Reporting Requirements***

Development Consent Condition 9.2(i) (c) requires the AEMR to include results of all environmental monitoring under the Development Consent and other approvals which includes interpretation and discussion by a suitably qualified person. Accordingly, the requirements of this condition are provided for each of the environmental risks in the sub-sections below.

The Development Consent and the EPL have a complaints mechanism. All complaints received during the reporting period are discussed in Paragraph 4.1.

The EPL requires that Barrick notify the EPA of incidents causing or threatening material harm to the environment. There have been no such incidents during the reporting period.

### 3.1 AIR QUALITY

#### 3.1.1 Reporting Requirements

##### 3.1.1.1 Development Consent

The reporting of air quality monitoring is required by Development Consent Condition 8.3(c), which states that the applicant shall:

*Provide all results and analysis of air quality monitoring in the AEMR including a determination of the dust deposition rate in g/m<sup>2</sup>/month, which shall be plotted in the AEMR.*

The reporting of meteorological monitoring is required by Development Consent Condition 8.1, which states:

*The Applicant shall continue meteorological monitoring by utilising and maintaining the existing weather station on-site. The data shall be particularly used for predicting noise, dust and blasting impacts on nearby residences, and bird breeding areas identified by the Applicant in consultation with EPA.*

The Dust Management Plan (**DMP**) (Barrick, 2003c) was prepared in accordance with Development Consent Condition 6.1 to establish a dust management strategy for CGM.

In accordance with the DMP, the following air quality related issues are required to be reported in the AEMR:

- Annual average dust deposition results (plotted in g/m<sup>2</sup>/month) and comparison to the EPA amenity criteria;
- Total suspended particulates (TSP) monitoring results and comparison to the EPA criteria;
- Measures employed to minimise/prevent excessive dust emissions;
- Dust related complaints and amelioration measures undertaken in the event of any confirmed exceedances of the EPA criteria;
- Review of the performance of dust control measures and the monitoring program;
- Interpretation and discussion of the air quality monitoring program results and management measures by a suitably qualified person; and
- Community Environmental Monitoring & Consultative Committee (**CEMCC**) decisions relating to CGM dust issues.

##### 3.1.1.2 Environmental Protection Licence

The EPL requires Barrick to undertake dust and Total Suspended Particulates (**TSP**) monitoring at points identified in EPL Condition P1.1. The licence also requires Barrick to undertake weather monitoring at the location identified in EPL Condition P2.1 and M8.1.

Condition R1 of the licence requires the completion of an Annual Environmental Return (**AER**) comprising of a Statement of Compliance and a Monitoring and Complaints Summary at the end of each annual reporting period. Barrick submitted an AER for the period 23 December 2012 to 22 December 2013 to the EPA on 20 February 2014.

Additionally, Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

### 3.1.1.3 Any Other Relevant Approvals

Barrick reported to the Greenhouse Challenge, Energy Efficiency Opportunities Program (**EEO**), National Greenhouse and Energy Reporting (**NGER**) Scheme and National Pollutant Inventory during the reporting period.

## 3.1.2 Environmental Management

### 3.1.2.1 Control Strategies

Air quality safeguards and control strategies were implemented at CGM during the reporting period to minimise dust emissions from mining activities and exposed areas in accordance with the Development Consent, DMP and EPL. These control strategies are summarised in Table 7.

**Table 7**  
**Air Quality Safeguards and Control Strategies Implemented During the Reporting Period for Dust Sources**

Source	Control Strategies
Disturbed Surfaces	<ul style="list-style-type: none"> <li>Disturbed surfaces were watered using water trucks to suppress dust.</li> <li>Areas for soil stripping were minimised to reduce the area of exposed ground at any one time.</li> </ul>
Access Roads	<ul style="list-style-type: none"> <li>Access roads were watered and regularly maintained.</li> <li>A dust suppressant chemical (PetroTac) was applied to 5 km of unsealed Mining Lease roads around the general Administration and Plant area to reduce dust generation.</li> <li>Site access routes are clearly marked and workplace inductions specify routes.</li> <li>The speed of vehicles travelling on unsealed surfaces is restricted.</li> </ul>
Soil Stripping	<ul style="list-style-type: none"> <li>Access tracks used for soil stripping during the loading and unloading cycle were watered.</li> <li>Soil stripping was limited to areas required for future mining operations.</li> </ul>

Dust control equipment was maintained in accordance with the site maintenance schedule based on equipment manufacturer's specifications. Data provided by the Cowal Automatic Weather Station (**AWS**) and the new Kattron system is monitored continually for potential storm activity. The CGM pit and exploration geology supervisor vehicles are equipped with lightning warning alert meters in the event of approaching storm front which have historically generated considerable local dust. Such information is utilised to make decisions regarding dust control strategies. The dust management procedures decision-making flowchart from the DMP is provided on Figure 6.

In order to improve access and reliability in collecting samples due to the effects of adverse weather conditions, wet weather access roads have been constructed and/or repaired where possible. The change in method for dust analysis in the laboratory from ICP-AES to ICP-MS in mid-2012 was based on recommendations by Dr Cattle (University of Sydney). This has resulted in greater consistency of results and lower detection limits thus improving the quality of results. The EPA and IMP have been previously notified of the change in method.

### 3.1.2.2 Effectiveness of Control Strategies

In accordance with the DMP, implementation of the control strategies at the CGM minimised dust emissions from mining activities. The control strategies implemented during the reporting period are considered effective as demonstrated by the environmental performance outcomes as discussed in Section 3.1.3.2.

As described in Section 3.1.3.1, Barrick augmented the existing dust monitoring programme during the reporting period which involved installation of duplicate dust gauges adjacent to existing dust gauges to assist with the verification of results from the CGM's existing dust monitoring programme. Samples from the trial duplicate gauges are collected at extended intervals (i.e. 3 monthly, rather than monthly for existing gauges) in an effort to obtain an increased sample size which is more adequate for laboratory analysis. The initial results of this trial are described in Appendix B. Barrick will continue to conduct this trial throughout 2014 with results reported in the next AEMR.

### 3.1.2.3 Variations from Proposed Control Strategies

The Kattron lightning tracking system was introduced to operations in early-2012 (replaced the obsolete Cowal Storm Vue system). The Mining Dispatch Control Room operators continually monitor and pass on alert levels between red, amber and yellow to other employee groups and the ERT until all clear conditions resume.

There were no other variations from the proposed control strategies during the reporting period.

### 3.1.3 Environmental Performance

#### 3.1.3.1 Monitoring

##### **Meteorological Monitoring**

A meteorological station located near the south Mining Lease boundary collected meteorological data throughout the reporting period. The station measures real-time wind speed and direction, standard deviation of wind direction, temperature (2m, 10m), barometric pressure, humidity, solar radiation and rainfall. The Cowal AWS is supported by quarterly independent maintenance and calibration as well as production of monthly data reviews by Sentinel Pty Ltd. Review of the AWS by Sentinel Pty Ltd in 2006 resulted in upgrades to the station to ensure uninterrupted collection of weather data.

Annual and monthly wind roses from the Cowal AWS are presented in Figures 7a and 7b.

Monthly total rainfall measured at the Cowal AWS is shown in Table 8. Total annual rainfall in 2013 was approximately 341.6 mm, with the highest total rainfall recorded during June (87.8 mm) and the lowest recorded in April (3.4 mm). Table 8 indicates that conditions were drier throughout 2013 compared with 2012. Lake Cowal water levels declined as a result. The Cowal AWS continued to work well and was calibrated in April, July, September and December 2013. The correlation of real time data to the reference station has been very accurate with minimal error found.

**Table 8**  
**Monthly Rainfall (mm) Measured at CGM in 2010, 2011, 2012 and 2013**

Month	Rainfall in 2010 (mm)	Rainfall in 2011 (mm)	Rainfall in 2012 (mm)	Rainfall in 2013 (mm)
January	2.8	24.4	26.6	5.20
February	95.6	138.6	129.2	26.0
March	44.6	146.2	78.0	45.4
April	50.6	20.2	15.6	3.4
May	40.0	22.0	32.6	30.4
June	22.8	29.4	29.6	87.8
July	62.2	11.8	49.8	33.4
August	34.0	41.8	19.0	18.8
September	64.2	13.8	25.0	60.4
October	94.0	31.0	16.0	7.2
November	60.2	130.4	36.4	9.0
December	111.7	135.0	27.0	14.6
<b>TOTAL</b>	<b>682.7</b>	<b>744.6</b>	<b>484.8</b>	<b>341.6</b>

The remaining monthly Cowal AWS meteorological station data for 2013 is presented in Table 9.

**Table 9  
Monthly Average Meteorological Data (2013)**

	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sept	Oct	Nov	Dec
Mean Humidity (%)	41.0	69.8	75.9	78.9	87.2	91.0	91.6	89.5	84.7	72.8	69.4	61.2
Mean Pressure (mbar)	981.7	986.7	991.6	995.4	997.7	996.2	999.6	993.9	993.2	994.1	989.8	989.7
Mean Wind Direction (°)	156.0	117.1	134.7	187.2	182.2	196.7	186.6	227.5	204.9	212.7	160.5	174.0
Mean Wind Velocity (m/s) 15min	3.8	3.7	3.5	2.5	2.6	2.7	2.6	2.8	2.9	3.8	3.8	3.6
2m Temp Max (°C)	39.7	36.5	31.6	28.0	21.6	16.7	16.2	17.8	23.9	27.0	30.4	35.9
2m Temp Min (°C)	19.4	18.5	15.5	10.4	5.7	5.6	4.8	5.2	8.4	9.4	12.1	16.4

### ***Air Quality Monitoring***

During the reporting period dust monitoring was carried out in accordance with the DMP utilising depositional (static or gravimetric) and high-volume Total Suspended Particulate (**TSP**) sampling equipment.

A network of 18 static dust deposition gauges was used throughout 2013 to collect monthly dust samples. These dust gauges are located at varying distances from the CGM open pit, and in a range of directions from the pit (Figure 8). A number of the gauges are situated near homesteads of properties that adjoin the mine site and a number within Lake Cowal near bird breeding areas. A high-volume automatic sampler (HV1) at 'Coniston' Homestead to the north of the CGM collected suspended particle data throughout 2013, operating for 24 hour periods every 6 days.

Two duplicate dust gauges (Duplicate 1, Duplicate 2) were deployed near a number of the pre-existing gauge sites for various sampling periods during the first four months of 2013. Of these 18 sites, two are located at private receivers (DG1 and DG6) and five are located within the ML (DG11, DG12, DG13, DG14 and Site 52). Selected metal concentrations of duplicate dust samples from the DG1, DG2 (December only), DG3, DG4, DG5 and DG13 locations were also measured for the September and December sampling periods. Analysis of the duplicate gauge samples aims to verify the results from the CGM's existing dust monitoring programme.

### ***Air Quality Impact Assessment Criteria***

The air quality impact assessment criteria specified in Condition 6.3(d) of the Development Consent are provided in Table 10.



**Table 10**  
**Air Quality Impact Assessment Criteria**

Pollutant	Averaging Period	Maximum Increase in Deposited Dust Level	Maximum Total Deposited Dust Level
<i>Long term impact assessment criteria for deposited dust</i>			
Deposited Dust	Annual	2 g/m <sup>2</sup> /month	4 g/m <sup>2</sup> /month
	<b>Averaging Period</b>	<b>Criterion</b>	
<i>Long term impact assessment criteria for particulate matter</i>			
Total suspended particulate (TSP) matter	Annual	90 µg/m <sup>3</sup>	
Particulate matter < 10 µm (PM <sub>10</sub> )	Annual	30 µg/m <sup>3</sup>	
<i>Short term impact assessment criterion for particulate matter</i>			
Particulate matter < 10 µm (PM <sub>10</sub> )	24 hour	50 µg/m <sup>3</sup>	

Source: EPA (2001)

Note 1: Dust is assessed as insoluble solids as defined by AS 3580.10.1-1991 (AM-19).

Note 2: Deposited dust is assessed as insoluble solids as defined by Standards Australia, AS/NZS 3580.10.1:2003: Methods for Sampling and Analysis of Ambient Air - Determination of Particulate Matter - Deposited Matter - Gravimetric Method.

Note 3: Dust emissions generated by the development shall not cause additional exceedances of the air quality impact assessment criteria listed in the above Table at any residence on privately-owned land, or on more than 25 percent of privately-owned land not located within Lake Cowal (March 2010 section 75W approval condition).

### 3.1.3.2 Performance Outcomes

#### **Total Suspended Particulates (TSP)**

On an annual average basis, the TSP data collected by the high-volume automatic sampler is well below the NSW EPA (2001) assessment criterion for TSP matter (90 µg/m<sup>3</sup>). Compared to previous years, the TSP level in 2013 (44 µg/m<sup>3</sup>) was higher than that of 2012 (34 µg/m<sup>3</sup>), 2011 (28 µg/m<sup>3</sup>), 2010 (39 µg/m<sup>3</sup>) and 2008 (43 µg/m<sup>3</sup>), but lower than that in 2009 (63 µg/m<sup>3</sup>).

In keeping with the previous years of TSP measurements at CGM, there was moderately strong seasonality in the 2013 TSP data, and this seasonality matched quite closely that of the deposited dust amounts. For the summer and autumn months of January, February, March, April and May the average TSP was around 61 µg/m<sup>3</sup>; for the winter months of June, July and August the average TSP was around 16 µg/m<sup>3</sup>; and for the spring and summer months of September, October, November and December the average TSP was around 45 µg/m<sup>3</sup>.

#### **Deposited Dust**

A summary of the dust deposition results for the reporting period is provided in Table 11. Detailed dust monitoring results (including laboratory analysis of dust results) are provided in the University of Sydney's *Interpretation and Discussion of 2013 Air Quality Monitoring Results Cowal Gold Project* in Appendix B.

**Table 11**  
**Monthly and Mean Dust (insoluble solids) Deposition Rates (2013)**

Dust gauge site	Monthly deposition of insoluble solids in dust (g/m <sup>2</sup> /month)												
	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean
<b>Private Receiver Locations</b>													
DG1	2.9	1.5	2.8	1.3	0.9	0.7	0.5	0.5	0.7	6.1	1.4	0.6	<b>1.7</b>
DG6	1.1	4.1	7.9	1.9	1.8	1.9	0.8	1.0	1.2	0.6	1.6	2.0	<b>2.2</b>
<b>Locations within Lake Cowal</b>													
DG4	0.6	0.8	2.0	0.5	0.8	0.1	0.4	0.4	1.7	0.8	0.6	1.0	<b>0.8</b>
DG5	9.2	1.6	1.2	0.5	1.3	0.1	0.5	0.4	0.8	0.8	1.0	3.0	<b>1.7</b>
<b>Locations within the ML</b>													
DG11	1.4	4.3	–	0.2	1.0	7.3	1.8	1.8	2.5	1.6	1.1	2.2	<b>2.3</b>
DG12	7.8	6.2	–	4.8	4.9	6.1	4.3	3.2	0.5	3.1	1.5	3.2	<b>4.1</b>
DG13	1.8	4.1	1.8	0.5	1.3	0.1	0.8	1.0	0.7	1.0	1.0	0.7	<b>1.2</b>
Site 52	4.2	4.3	10.7	0.5	2.8	0.3	2.0	1.8	1.2	2.1	1.9	2.8	<b>2.9</b>
DG14	-----DG14 established in Aug, 2013-----							0.8	1.6	1.2	1.2	0.6	<b>1.1</b>
<b>Other Locations</b>													
DG2	0.8	–	–	0.5	0.5	0.3	0.4	0.3	1.5	0.8	0.8	0.6	<b>0.7</b>
DG3	2.6	0.9	1.6	0.3	0.6	0.2	0.3	0.1	15.3	0.5	0.9	0.8	<b>2.0</b>
DG7	0.9	0.3	–	4.8	3.0	6.0	5.1	7.4	1.8	5.2	2.0	7.3	<b>4.0</b>
DG8	0.7	4.1	8.7	2.9	1.1	0.6	0.9	-----DG8 abandoned in Aug, 2013--				<b>2.7</b>	
DG9	0.9	–	1.2	1.7	2.3	1.6	0.6	0.6	1.6	0.6	0.7	0.6	<b>1.1</b>
DG10	3.5	1.6	–	2.4	0.8	1.5	0.6	0.5	2.6	3.5	6.4	0.4	<b>2.2</b>
I5	7.3	1.5	28.5	1.3	1.0	0.9	10.5	0.5	16.1	1.0	3.0	1.4	<b>6.1</b>
Lakeside (Barrick)	7.3	3.3	3.4	0.9	2.2	4.5	0.7	1.7	1.7	2.2	1.1	1.1	<b>2.5</b>
McLintock's Shed	3.3	2.4	2.2	2.0	3.5	5.2	1.1	1.6	0.3	0.7	1.0	13.8	<b>3.1</b>
Site Office	1.3	7.5	2.9	5.7	4.6	3.1	1.7	1.2	0.9	3.6	1.3	0.9	<b>2.9</b>
<b>Mean</b>	<b>3.2</b>	<b>3.0</b>	<b>5.8</b>	<b>1.8</b>	<b>1.9</b>	<b>2.3</b>	<b>1.8</b>	<b>1.4</b>	<b>2.9</b>	<b>2.0</b>	<b>1.6</b>	<b>2.4</b>	<b>2.4</b>

In accordance with Development Consent Condition 8.3(c), the annual average dust deposition rate has been plotted in g/m<sup>2</sup>/month as shown in Figures 10a to 10e.

In accordance with Australian Standard 3580.10.1 - 2003 extraneous organic material has been removed, where possible, from insoluble solids reporting results. Verbal confirmation has also been gained from ALS Environmental that where possible, they remove any obvious foreign material from dust samples (e.g. sticks, grass etc.). Dust monitoring procedures are outlined in the CGM procedure titled 'Depositional Dust Monitoring PROCEDURE (DOC-ENV-PRO-228070)'. The procedure has been prepared in accordance with appropriate standards and guidelines. Causes for the exceedances are provided by Dr Stephen Cattle and are described below.

Tabulated results for all dust gauges are presented in Appendix B.

There is moderate seasonality associated with the 2013 dust deposition data (Table 11). Between the months of January and March (summer/autumn) the average dust deposition rate across all gauges was 4.0 g/m<sup>2</sup>/month, between April and August (autumn/winter) the average dust deposition rate across all gauges was 1.8 g/m<sup>2</sup>/month, while between September and December (spring/summer) the average dust deposition rate across all gauges was 2.2 g/m<sup>2</sup>/month. The greater dust deposition rates earlier in the year likely reflects the relatively

dry summer experienced (only 58 mm rainfall between December 2012 and February 2013) and the lack of ground cover at that time. The lower dust deposition rates of the winter period reflect the reduced availability of wind entrainable dust particles from the soil surface when it is moist.

Overall dust deposition in 2013, and the amount of fluctuation in deposition rate between gauges, was distinctly lower than that experienced in 2012. There was a moderate correlation between monthly dust deposition and season in 2013, with the summer months being distinctly more dusty than the wetter late autumn, winter and spring months. This indicates that regional æolian processes were more prominent than isolated local processes in 2013.

Compliance with the assessment criterion of 4 g/m<sup>2</sup>/month average annual deposited dust was achieved at 13 out of 14 gauges outside the ML during 2013. Compliance was achieved at all residences and bird-breeding and native fauna areas.

For the single gauge external to the ML that exceeded the assessment criterion of 4 g/m<sup>2</sup>/month (I5), the cause of the exceedance was three sampling periods with dust deposition of more than 10 g/m<sup>2</sup>. For each of these three deposits, more than 70% of the material was combustible, suggesting a large contribution of insects, bird droppings and vegetative matter to those deposits. Exclusion of the combustible fractions of these dust deposits would result in the annual average dust deposition rate for gauge I5 dropping below the assessment criterion.

One of the four gauges located within the ML (DG12) yielded deposited dust in excess of 4 g/m<sup>2</sup>/month. Levels recorded in these gauges are not relevant to the assessment criterion.

The HVAS, located to the north of the ML area, yielded TSP levels well below the relevant NSW EPA amenity criterion. The average 2013 TSP level was higher than that of 2012, 2011, 2010 and 2008, but lower than that of 2009. As with the previous five years of TSP measurements at CGM, the 2013 data exhibited moderately strong seasonality, with measurements of TSP level conspicuously higher during the dry, hot summer months, and lower during the cool, moist winter months.

Further analysis of the dust deposition results is provided below (Cattle, 2014):

- Temporal and spatial variation in monthly dust deposition in 2013 was only moderate. Overall dust deposition in 2013, and the amount of fluctuation in deposition rate between gauges, was distinctly lower than that experienced in 2012.
- Changes in monthly dust deposition rates at each gauge were only very weakly correlated with seasonal weather conditions in 2012. Monthly dust deposition rates averaged across all gauges ranged from 2.1 to 8.5 g/m<sup>2</sup>, but for no month did relatively high rates of deposition occur for all gauges. For all of the months, different combinations of several gauges received appreciably greater dust deposits than all of the other gauges.
- Compliance with the assessment criterion of 4 g/m<sup>2</sup>/month average annual deposited dust was achieved at 13 out of 14 gauges outside the ML during 2013. Compliance was achieved at all residences and bird-breeding and native fauna areas.
- For the single gauge external to the ML that exceeded the assessment criterion of 4 g/m<sup>2</sup>/month (I5), the cause of the exceedance was three sampling periods with dust deposition of more than 10 g/m<sup>2</sup>. For each of these three deposits, more than 70% of the material was combustible, suggesting a large contribution of insects, bird droppings and vegetative matter to those deposits. Exclusion of the combustible fractions of these dust deposits would result in the annual average dust deposition rate for gauge I5 dropping below the assessment criterion.
- One of the four gauges located within the ML (DG12, near truck haul road) yielded deposited dust in excess of 4 g/m<sup>2</sup>/month. Levels recorded in these gauges are not relevant to the assessment criterion.

### 3.1.4 Reportable Incidents

No complaints were received relating to dust at the CGM during the reporting period. PetroTac treatment was continued during the reporting period and will continue into the next reporting period. PetroTac was also applied near the 'Coniston' residence to minimize production of dust related to mine traffic on the road. The DMP requires that dust-related complaints and amelioration measures undertaken in the event of any confirmed exceedances of the EPA criteria be reported in the AEMR.

### 3.1.5 Further Improvements

As described in Paragraph 3, recommendations made in the 2013 IMP report (for ongoing analysis of dust samples) will continue to be actioned during the next reporting period.

Review and interpretation of the dust monitoring data for the reporting period was conducted by Dr Stephen Cattle of the University of Sydney (2014) in accordance with requirements of the DMP. The main recommendations of Dr Cattle's analysis relevant to dust deposition and TSP monitoring are summarised below.

#### **Improvements to Dust Monitoring Program**

- Consideration should be given to piloting the use of inverted Frisbee dust traps, with anti-bird spikes affixed to the metal rims of the traps.
- Consideration should be given to modifying the range of elements measured in dust samples at six monthly intervals. In particular Aluminium (Al) and silver (Ag). In the case of Al, concentrations are conspicuously smaller in dusts and various potential dust source materials at the Project than in typical soils, and Al in soil only becomes toxic to plant roots under very acidic conditions. Soils surrounding the Project are not acidic. Consideration for inclusion of silver in six monthly metal analysis as a potential indicator for mine-derived dust.
- It is further recommended that duplicate gauges be kept in the same locations for the entire calendar year. In particular, suggested locations for *Duplicate* gauges with 2-3 month sampling periods are near *Site 52* or *DG14* (likely to receive dust from the Project), near *DG7* or *DG10* (unlikely to receive dust from the Project), and near *I5* or *DG3* (downwind of the Project, but some distance away). This combination of *Duplicate* gauge sites should provide a clearer picture of metals in 'background dust' and metals in dust contributed by the Project.

Other improvements to the air quality monitoring program that Barrick will continue to implement during the next reporting period to improve confidence in future analyses include:

- The continuing use of standardised sample collection procedures across the site monitoring program, whilst maintaining current Barrick site standards.
- Barrick will continue a QA/QC system utilising trip blanks and duplicate samples every 2-3 months, blanks and control samples during the next reporting period.
- All monitoring equipment is currently and will continue to be decontaminated each sample round using a solution of deionised water and Decon 90.
- NMI is intended to remain the as the primary supplier of laboratory data reporting for Barrick. This includes a report of analysis and quality assurance reporting.
- A review of laboratory testing procedures will continue during 2014 to ascertain the most accurate method of calculating results in accordance with Australian Standards and applicable conditions.

The University of Sydney will continue to liaise with Barrick sampling personnel on routine dust sampling methodology, as a means to reduce the likelihood of sample contamination during collection and dispatch stages.

To mitigate dust generated by vehicle movements within ML 1535, PetroTac (a water emulsified bitumen sealant) was first applied to 5 km of unsealed Mining Lease roads during October 2006. PetroTac has since been routinely applied around the general administration and workshop areas, on roads within the processing plant and on the portion of Lake Cowal Road between the two 'Coniston' farm southern entry roads (BSC approved).

Barrick will apply further PetroTac dust suppressant to unsealed roads within ML 1535 that are subject to high-frequency light vehicle use during the next reporting period.

The use of saline pit water on heavy mobile equipment haul roads in the open pit mine and waste emplacement areas to reduce dust generation will continue throughout the next reporting period.

Other dust mitigation measures employed at CGM include water sprays at the primary crusher, covered conveyors within the processing plant and maintaining minimal dust levels at the crushed ore stockpile.

The Cowal Mine CEMCC is kept informed of any public comment or complaint about dust, and external dust study

updates during quarterly meetings. The CEMCC raised no concern about dust during 2013.

## **3.2 EROSION AND SEDIMENT**

### **3.2.1 Reporting Requirements**

#### *3.2.1.1 Development Consent*

The Erosion and Sediment Control Management Plan (**ESCMP**) (Barrick, 2003d) was prepared in accordance with Development Consent Condition 3.5(a) to provide erosion and sediment control strategies for works to be undertaken throughout the life of the Project (i.e. construction and operations).

In accordance with the ESCMP, the following issues are required to be reported in the AEMR:

- surface and groundwater monitoring results;
- comparison of surface water and groundwater monitoring results with criteria in the Surface Water, Groundwater, Meteorological and Biological Monitoring Programme (**SGWMBMP**) (Barrick, 2003e);
- interpretation and discussion of the surface and groundwater monitoring program results; and
- CEMCC decisions relating to CGM ESCMP issues.

In addition, any proposed improvements to erosion and sediment control systems are required to be included in the AEMR (when monitoring indicates the need).

The ESCMP was amended to include the soil disturbance and management measures associated with the approved saline groundwater supply borefield within ML 1535. The addendum to the ESCP was approved by the DP&I on 10 March 2010. Lake Cowal filled to the TIB by August 2010 and the Lake floor saline bore has remained capped and inundated during the reporting period.

#### *3.2.1.2 Environment Protection Licence*

Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

#### *3.2.1.3 Any Other Relevant Approval*

There are no other relevant reporting requirements from approvals in relation to erosion and sediment management for the reporting period.

### **3.2.2 Environmental Management**

#### *3.2.2.1 Control Strategies*

A summary of the control strategies/management measures implemented during the reporting period in accordance with the ESCMP (Barrick, 2003d) is provided in Table 12.

The erosion and sediment control systems for the reporting period are shown in Figure 11.

**Table 12**  
**Summary of the Relevant Erosion and Sediment Control Strategies/  
Management Measures**

Project Development	Control Strategy/Management Measure
<b>Temporary Erosion and Sediment Controls Systems</b>	
Internal Mine Access Road	<ul style="list-style-type: none"> <li>• Minimisation of disturbance to watercourses that cross the road.</li> <li>• Provision of culverts and diversion of runoff from undisturbed areas.</li> <li>• Erection of sediment control barrier downslope of small, disturbed areas.</li> <li>• Provision of sediment basins for concentrated runoff areas.</li> <li>• Stabilisation of the access road surface.</li> <li>• Rapid stabilisation and revegetation of road batters.</li> </ul>
ML 1535 Fences	<ul style="list-style-type: none"> <li>• Minimising the area disturbed and restricting access to non-disturbed areas.</li> </ul>
Ore Stockpile and Process Plant Area	<ul style="list-style-type: none"> <li>• Minimising the area disturbed and restricting access to non-disturbed areas.</li> <li>• Settlement/plant runoff storage.</li> <li>• Installation of sediment control barrier.</li> <li>• Installation of runoff collections drains.</li> <li>• Dewatering of settlement storage following rainfall events.</li> <li>• Ripping and rehabilitation of hardstand areas.</li> </ul>
Soil Stockpiles	<ul style="list-style-type: none"> <li>• Use of sediment control barrier and sediment traps to minimise soil movement.</li> <li>• Use of diversion banks, channels and rip-rap structures to divert surface water around disturbed areas and control runoff velocity.</li> </ul>
Internal Mine Roads	<ul style="list-style-type: none"> <li>• Constructing all access roads at an appropriated slope along the contour, where practicable.</li> <li>• The use of spoon drains, table drains and concrete culverts to control surface runoff from access roads.</li> <li>• Ripping and rehabilitation of roads no longer required for access.</li> </ul>
Contractors' Area	<ul style="list-style-type: none"> <li>• Minimising the area disturbed and restricting access to non-disturbed areas.</li> <li>• Erection of sediment control barrier downslope of small, disturbed areas.</li> <li>• Provision of sediment basins for concentrated runoff areas.</li> <li>• Ripping and rehabilitation of hardstand areas.</li> </ul>
Borrow Pits	<ul style="list-style-type: none"> <li>• Use of temporary sediment traps and sediment control barrier filters (bales).</li> <li>• Use of temporary sediment basins.</li> </ul>
Earthworks Associated with Landscaping	<ul style="list-style-type: none"> <li>• Use of sediment control barriers and sediment traps to minimise soil movement.</li> </ul>
Up-Catchment Diversion System (UCDS)	<ul style="list-style-type: none"> <li>• Use of temporary sediment traps and sediment barrier filters (rock bars).</li> <li>• Installation of silt fences and hay bale weirs downslope of all disturbed areas.</li> <li>• Installation of rip-rap structures along UCDS.</li> <li>• Vegetation stabilisation.</li> </ul>
Internal Catchment Drainage System	<ul style="list-style-type: none"> <li>• Construction of the internal catchment drainage system as described in the ESCMP.</li> <li>• Construction of sediment retention storages to reduce non-colloidal fraction of sediment carried in runoff from large disturbed areas. Storages sized to provide flow detention and effective settlement during small to medium sized flood events (1 in 20 year 1 hour event).</li> <li>• Use of small-scale runoff controls comprising hay bales and rockfill bunds to control sediment loads in runoff from small areas. Silt control hay bale weirs installed downslope of all disturbed areas.</li> <li>• Rapid stabilisation of disturbed areas using contour banks and furrows, erosion-stable drainage paths and early revegetation or armouring of disturbed areas. Disturbed areas rapidly stabilised to reduce sediment fluxes.</li> </ul>

**Table 12 (Continued)**  
**Summary of the Relevant Erosion and Sediment Control Strategies/  
Management Measures**

Project Development	Control Strategy/Management Measure
<b>Permanent Erosion and Sediment Controls Systems</b>	
Lake Isolation System	<ul style="list-style-type: none"> <li>• Construction of the Temporary Isolation Bund and Lake Protection Bund as described in the ESCMP. Provision of clean water diversion and settlement storages for runoff control at borrow areas.</li> <li>• Stabilisation and revegetation of the batters of the Temporary Isolation Bund.</li> </ul>
Earth Mounds	<ul style="list-style-type: none"> <li>• Rapid vegetative stabilization (straw armour).</li> </ul>
Monitoring and Maintenance	<ul style="list-style-type: none"> <li>• Water quality monitoring in accordance with the SWGMBMP.</li> <li>• Maintenance of erosion and sediment control structure where necessary.</li> </ul>

### 3.2.2.2 Effectiveness of Control Strategies

In accordance with the ESCP the primary objectives of the control strategies are to:

- control the movement of sediment and salinity migration from areas disturbed by mining and construction activities; and
- maintain downstream (Lake) water quality.

The control strategies implemented during the reporting period were considered to be effective in meeting the above objectives as demonstrated by the environmental performance indicators. The environmental performance indicators are discussed in Section 3.2.3 below.

### 3.2.2.3 Variations from Proposed Control Strategies

There were no variations to the Erosion and Sediment Control strategy during the 2013 reporting period.

## 3.2.3 Environmental Performance

### 3.2.3.1 Monitoring

In accordance with the ESCMP, inspections and maintenance of erosion and sediment control structures (e.g. silt fences, hay-bales, sediment ponds and diversion structures) occurred as required during the reporting period.

As discussed in Paragraph 3.2.1.1 above, the ESCMP also requires the following to be reported in the AEMR:

- Surface and groundwater monitoring results. The surface and groundwater monitoring results are provided in Paragraph 3.3.3.2 and 3.4.3.2 respectively.
- Comparison of surface water and groundwater monitoring results with criteria in the SWGMBMP. The surface and groundwater monitoring results are discussed in Paragraph's 3.3.3.2 and 3.4.3.2 respectively.
- Interpretation and discussion of the surface and groundwater monitoring program results. The surface and groundwater monitoring results are discussed in Paragraphs 3.3.3.2 and 3.4.3.2 respectively.
- CEMCC decisions relating to CGM ESCMP issues.

There were no CEMCC decisions relating to CGM erosion and sediment control issues.

There are no additional monitoring requirements in any other approval.

No additional improvements to erosion and sediment control systems were made during the reporting period.

### 3.2.3.2 Performance Outcomes

The Cowal geotechnical department conducted monthly monitoring and assessment of structures such as all water holding facilities on site, waste dumps and the lake protection bund for sediment movement and erosion control effectiveness. In particular, analysis of the Lake Protection Bund (**LPB**) indicated that the increased rainfall experienced during 2010 and 2011 had not significantly impacted on the stability of the structure. Some erosion and sediment movement was found to be evident, the effects of which have been minimised by improved vegetative cover on all slopes on site, resulting in improved soil stability. In May 2012 Barrick sought and received relevant regulator permission to lower the level of the sediment laden PWE storm water run-off held between the LPB and Temporary Isolation Bund (**TIB**) by pumping to Pond D1 and into the Processing Plant, lest more storm activity might cause this water overflow into the immediately adjacent high level in Lake Cowal (the Lake level had decreased to about 100 mm below the top of the TIB since the March 2012 peak flood level). Lake Cowal has not been impacted due to the presence and effectiveness of the TIB, Ponds D1 and D4 and the initial vegetation covers on the adjacent lifts trapping any sediment movement.

Furthermore, water quality results as discussed in Section 3.3.3 have not indicated that any impact on Lake Cowal has occurred. Water quality monitoring results will continue to be monitored and evaluated throughout the next monitoring period.

Early in 2011, Barrick conducted repair of the eastern edge of UCDS and the installation of a concrete causeway apron, to direct water flow to causeway and additional rock weirs to prevent further erosion damage. These works were very timely given the excess water flows through this area in early-2012 and subsequent Lake level inundation of the area. De-silting of the front basin of the Southern Up Catchment Pond will occur when next dry.

Stabilisation works on the downstream and upstream slopes of the STSF and NTSF were conducted using several methods which were all more effective than topsoil alone during the heavy summer storm rains of early-2010 and in early-2012.

During 2012, further works were conducted on the Northern Diversion Channel to those completed in mid-2011.

The outer slopes of the 5 ha of the outer slopes of the 3<sup>rd</sup> Lift of the NTSF during 2011, and the 4<sup>th</sup> Lift of the STSF were completed in 2012 using the new rock-topsoil method with ongoing cover stability success.

The outer slopes of the 4<sup>th</sup> Lift of the NTSF were completed using the new rock-topsoil rehabilitation method during the 2013 reporting period.

De-silting of the front basin of the Southern Up Catchment Pond occurred when dry at the end of the 2013 reporting period. The structure was not heavily silted. The recovered material was used as topsoil near Pond D4.

As described in Paragraph 5.4, the new rock-topsoil rehabilitation treatment method continues to appear to have demonstrated greatly reduced risk of erosion loss as evidenced by independent review (DnA Environmental, 2010). The rehabilitation trial areas created during the reporting period are discussed further in Paragraph 5.4 of this report.

### 3.2.4 Reportable Incidents

No environmental incidents or complaints were reported or received relating to erosion and sediment control at the CGM during the reporting period. There were no CEMCC decisions regarding erosion and sediment issues for the reporting period.

### 3.2.5 Further Improvements

Ongoing periodic inspection and maintenance of the Up Catchment Diversion System (**UCDS**) by ongoing maintenance of erosion control structures. Distinct absence of reasonable storm flows at period ended.

Further independent confirmation and rehabilitation success monitoring works will continue during the next reporting period. Annual risk review workshops occur during each reporting period to assess the outcomes of the new rock-topsoil cross-rip erosion control method decision from the July 2008 on-site peer review workshop. The next AEMR will review the findings of the 13 March 2014 CGM Rehabilitation Risk Assessment peer review.



### 3.3 SURFACE WATER

#### 3.3.1 Reporting Requirements

##### 3.3.1.1 Development Consent

The reporting of surface water monitoring is required by Development Consent Condition 8.2 (a) (iv), which states:

- (iv) *The results and interpretation of surface and ground water monitoring (including biological monitoring) are to be provided by the Applicant in an approved form to the NoW, EPA, and DTIRIS (Fisheries) on a three monthly basis during construction and the first 12 months of ore processing operations and thereafter on an annual basis, unless otherwise agreed by the Director-General. The results are also to be contained and analysed in the Annual Environmental Management Report (Condition 9.2(a)).*

The Site Water Management Plan (**SWMP**) (Barrick, 2003b) and the SWGMBMP (Barrick, 2010) were prepared in accordance with Development Consent Conditions 4.1 and 8.2(ii), respectively, to provide management objectives for the CGM site water management system.

The revised SWMP was lodged with the DP&I in June 2010 and a further revised version was lodged on 30 November 2010 (following review comments provided by EPA, and NoW). The revised SWMP (eastern saline borefield MOD10) was submitted to DP&I in November 2011 and was again revised to address DP&I review comments provided in August 2012. Barrick has consulted with NoW and EPA regarding the revised SWMP. The revised SWMP was submitted to the DP&I for approval on 08 August 2013.

Barrick prepared a revised SWGMBMP and provided it to the IMP and other appropriate regulators in accordance with the consent condition requirements, for review. The DP&I approved the revision of the SWGMBMP on 10 March 2010 after consultation with other departments and the IMP.

An addendum to the SWGMBMP was submitted to relevant government departments after DP&I approval of MOD10 in July 2011. The addendum was approved in August 2012. A separate Addendum to the SWGMBMP has been prepared to reflect changes to the SWGMBMP as a result of revisions to the SWMP. Barrick consulted with NOW, EPA and DPI- Fisheries regarding the Addendum. The Addendum was submitted to the DP&I for approval on 13 August 2013.

In accordance with both the SWMP and the SWGMBMP the following surface water-related issues are required to be reported in the AEMR:

- surface water, groundwater and biological monitoring results;
- details of any trends observed in the monitoring data;
- details of investigations and consultation with regulatory agencies;
- review of the performance of control measures and the monitoring program; and
- interpretation and discussion of the monitoring program results and management measures by a suitably qualified person.

##### 3.3.1.2 Environmental Protection Licence

The EPL requires Barrick to undertake storm water and ambient water quality monitoring at points identified in EPL Condition P1.3.

Condition R1 of the licence requires the completion of an Annual Return comprising a Statement of Compliance and a Monitoring and Complaints Summary at the end of each annual reporting period (i.e. the AER). Barrick submitted an Annual Return for the period 23 December 2012 to 22 December 2013 to the EPA on 20 February 2014. Storm water and ambient water quality of monitoring points identified in EPL Condition P1.3 were reported. The storm water and ambient monitoring points and frequencies required by the EPL are consistent with monitoring required by the Development Consent and SWGMBMP. Additionally, Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

### 3.3.1.3 *Any Other Relevant Approval*

There are no other relevant reporting requirements for the reporting period.

## 3.3.2 **Environmental Management**

### 3.3.2.1 *Control Strategies*

The site water management system is designed to contain all potentially contaminated water and comprises the following major components as noted on Figure 11:

- (i) Up Catchment Diversion System (**UCDS**);
- (ii) Lake Isolation System (comprising the Temporary Isolation Bund (**TIB**), Lake Protection Bund (**LPB**) and Perimeter Waste (rock) Emplacement (**PWE**));
- (iii) Internal Catchment Drainage System (including the permanent catchment divide and contained water storages);
- (iv) Integrated Erosion and Sediment Control System (refer to Paragraph 3.2); and
- (v) E42 Open Pit Dewatering System.

### 3.3.2.2 *Effectiveness of the Control Strategies*

The site water management system is designed to contain all potentially contaminated water generated within the closed catchment of the ML 1535 area while diverting all other water around the perimeter of the site. The UCDS, Lake Isolation System and Internal Catchment Drainage System are designed to minimise the volume of surface water entering ML 1535 by isolating the site from Lake Cowal and the up-slope catchment above the UCDS. Surface water collected within ML 1535 is controlled using a number of water management structures which are designed to prevent discharge to Lake Cowal.

The control strategies implemented during the reporting period effectively met the above objectives as demonstrated by the environmental performance outcomes discussed in Paragraph 3.3.3.

### 3.3.2.3 *Variations from Proposed Control Strategies*

There were no variations from the proposed control strategies during the reporting period.

## 3.3.3 **Environmental Performance**

### 3.3.3.1 *Monitoring*

Surface water monitoring was conducted in accordance with the SWGMBMP and EPL. Details of the location, frequency and analytical requirements for each monitoring point are presented below in Table 13. All monitoring results for the reporting period are provided in Appendix C with a summary discussion in Paragraph 3.3.3.2.

**Table 13**  
**Surface Water Monitoring Programme**

CGM Component	Site	Monitoring Frequency	Parameter/Analyte
Up-catchment Diversion System	Up-catchment diversions north and south (UCD north and UCD south)	Weekly and following rainfall events of 20 mm or greater in a 24 hour period	Suspended Solids, EC, pH.
Internal Catchment Drainage System	Contained water storages D1 and D4	Weekly and following rainfall events of 20 mm or greater in a 24 hour period	Suspended Solids, EC, pH.
	Contained water storages D2, D3, D9 D6 and D8B	Quarterly	Oil and grease, EC, pH.
		Monthly	EC, pH, turbidity, dissolved oxygen, temperature.
	Sediment control structures	Quarterly	Biological oxygen demand, faecal indicators, total hardness, total suspended solids, total dissolved solids. Ca, Mg, K, sodium, chloride, sulphate, Total As, Cd, Mo, Ni, Pb, Sb and Zn Dissolved As, Cd, Mo, Ni, Pb, Sb and Zn.
		Monthly and following rainfall events of 20 mm or greater in a 24 hour period	Structural integrity, Suspended Solids.
	Overflow event	Suspended Solids, pH, EC.	
Open Pit/Void Water	Pit sumps	Monthly	Suspended Solids, EC, pH.
Lake Cowal Water Level	Lake Cowal gauge board	Monthly (when lake water is present)	Lake water level.
Lake Cowal Chemical Monitoring	B1, B5, P1, P2, P3	Weekly and following rainfall events of 20 mm or greater in a 24 hour period	Suspended Solids, EC, pH.
	Lake Cowal transect sampling sites (including the Lachlan floodway, irrigation channel, Bland Creek, east shore, Project and control transects [refer to Figure 8])	Monthly (when lake water is present)	EC, pH, turbidity, dissolved oxygen, temperature, and lake water level.
		Quarterly (when lake water is present)	Suspended Solids, Alkalinity, cations and anions. Total Fe, Ca, Mg, K, sodium, chloride, sulphate, total phosphate, ortho phosphate, ammonium, nitrogen as nitrate and nitrite. Total As, Cd, Mo, Ni, Pb, Sb and Zn Dissolved As, Cd, Mo, Ni, Pb, Sb and Zn.
Lake Cowal Inflow Sites	Lake inflow sites (including the Lachlan floodway, irrigation channel, Bland Creek and Sandy Creek inflow sites)	Monthly (when lake water is present)	EC, pH, turbidity, dissolved oxygen, temperature.
		Quarterly (when lake water is present)	Suspended Solids, Alkalinity, cations, anions Total Fe, Ca, Mg, K, sodium, chloride, sulphate, Total As, Cd, Mo, Ni, Pb, Sb and Zn Dissolved As, Cd, Mo, Ni, Pb, Sb and Zn.
Other Waters	Lachlan River - Jemalong Weir Stream Gauge	Continuous (data to be obtained from NoW every 6 months)	Flow.

Source: SWGMBMP Addendum (Barrick, 2013)

## 3.3.3.2 Performance Outcomes

A summary of the CGM and Lake Cowal surface water monitoring results is provided in Tables 14 and 15 respectively while detailed data is presented in Appendix C. Water quality monitoring at Lake Cowal Inflow Sites is summarised in Table 16. Lake Cowal sediment monitoring results are presented in Table 17. Unless otherwise noted, all analytical data was obtained by ALS Environmental Laboratory (Sydney, NSW).

**Table 14**  
**Summary of Surface Water Monitoring Results for the Reporting Period**

<b>Weekly Surface Water Monitoring - D1, D4, UCD North, UCD South, Pit Sumps 1, 2 &amp; 3</b>				
<b>Pond D1</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	55	6.45	9.85	8.6904
Electrical Conductivity - Field (µS/cm)	55	1952	16170	7535.6
Total Suspended Solids (mg/L)	55	5	233	42.3
<b>Pond D4*</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	35	6.52	8.78	7.96
Electrical Conductivity - Field (µS/cm)	35	2158	44500	9492.5
Total Suspended Solids (mg/L)	35	5	808	103
<b>UCD North</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	53	7.07	9.23	8.2
Electrical Conductivity - Field (µS/cm)	53	332.8	813	538.6
Total Suspended Solids (mg/L)	52	31	713	226.3
<b>UCD South</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	38	5.85	9.39	8.3
Electrical Conductivity - Field (µS/cm)	38	128.7	2459	476.6
Total Suspended Solids (mg/L)	39	12	2140	264.8
<b>Monthly Surface Water Monitoring – D5, D6 and Pit Sumps</b>				
<b>Pond D5</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	12	7.47	9.25	8.4
Electrical Conductivity - Field (µS/cm)	12	2960	30600	9731.8
Dissolved Oxygen - Field (mg/L)	10	5.34	8.82	7
Temperature (Deg C)	12	10.8	33.2	21.7
Turbidity (NTU)	11	1.8	28.4	9.4
<b>Pond D6</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	12	6.51	8.16	7.6
Electrical Conductivity - Field (µS/cm)	12	1166	23300	15230.5
Dissolved Oxygen - Field (mg/L)	11	3.41	7.08	4.9
Temperature (Deg C)	12	13.5	32.8	24.5
Turbidity (NTU)	11	11.2	205	77.2
<b>Pit Sump 1</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	12	6.63	7.96	7.11
Electrical Conductivity - Field (µS/cm)	12	5690	56300	45044.2
Total Suspended Solids (mg/L)	12	5	301	52.2
<b>Pit Sump 2</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	18	6.38	7.9	7
Electrical Conductivity - Field (µS/cm)	18	21.33	52800	35831.1
Total Suspended Solids (mg/L)	11	5	1040	258
<b>Pit Sump 3</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	8	6.6	7.68	7.0875
Electrical Conductivity - Field (µS/cm)	8	4660	52800	38140
Total Suspended Solids (mg/L)	8	5	198	44

\* Saline groundwater from Lake Floor production bores was occasionally pumped to and stored in Pond D4 from 2008-2010. Recent three wetter years has seen saline water from Subsoil Stockpile 04 on the south side of the SWE entering Pond D4 storm water inflows.

**Table 14 (Continued)**  
**Summary of Surface Water Monitoring Results for the Reporting Period**

<b>Quarterly Surface Water Monitoring – D2, D3, D8B, D9, D6</b>				
<b>Pond D2</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	4	8.22	8.91	8.53
Electrical Conductivity - Field (µS/cm)	4	1880	20630	9452.5
Oil & Grease (mg/L)	4	5	5	5
<b>Pond D3</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	4	7.23	8.75	8.0575
Electrical Conductivity - Field (µS/cm)	4	12610	54200	27177.5
Oil & Grease (mg/L)	4	5	5	5
<b>Pond D8B</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	4	8.2	8.83	8.55
Electrical Conductivity - Field (µS/cm)	4	1303	13020	4963.25
Oil & Grease (mg/L)	4	5	11	6.5
<b>Pond D9</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
pH - Field	4	7.91	8.69	8.235
Electrical Conductivity - Field (µS/cm) <sup>^</sup>	4	13140	21820	19190
Oil & Grease (mg/L)	4	5	5	5
<b>D6</b>	<b>COUNT</b>	<b>MIN</b>	<b>MAX</b>	<b>MEAN</b>
Antimony - Total	14	0.001	0.011	0.0059
Arsenic - Total	14	0.001	0.008	0.0035
Biochemical Oxygen Demand	4	2	16	9
Cadmium - Total	14	0.0001	0.006	0.0022
Calcium - Dissolved	3	159	593	434.6667
Chloride	4	1930	6680	5037.5
Coliforms	3	1	1	1
Copper - Total	14	0.05	2.76	1.1163
Enterococci	4	1	1	1
Escherichia coli	3	1	1	1
Faecal Coliform -Total	3	1	1	1
Iron - Total	14	0.05	2.08	0.4879
Lead - Total	14	0.001	0.009	0.0021
Magnesium - Dissolved	3	101	683	370.3333
Manganese - Total	14	0.185	1.02	0.5426
Mercury - Total	8	0.0001	0.0001	0.0001
Potassium - Dissolved	3	181	518	305
Selenium - Total	8	0.01	0.15	0.0375
Sodium - Dissolved	3	1230	3750	2800
Sulfates	4	997	4150	2396.75
Total Dissolved Solids	4	4500	17300	12475
Total hardness as CaCO3	3	813	4290	2607.6667
Total Suspended Solids	12	21	441	163.5
Zinc - Total	14	0.005	0.107	0.0441

<sup>^</sup> Pond D9 was used as storage for water collected from surface water runoff dams after heavy rain.

**Table 15**  
**Summary of Lake Water Monitoring Results for the Reporting Period**

Parameter	Lake Cowal Water Quality Results (November 2010) (Mean)	Lake Cowal Water Quality Results (2011) Ranges (Mean)	Lake Cowal Water Quality Results (2012) Ranges (Mean)	Lake Cowal Water Quality Results (2013) Ranges (Mean)	Lake Cowal Baseline Water Quality Results (1991 -1992)	Aquatic Ecosystems <sup>^</sup> ~
Alkalinity (mg/L)	105	64 – 142 (100)	50 – 152 (87)	113 – 178 (157)	NA	NA
Suspended Solids (mg/L)	6 - 192	5 – 184 (38)	7 – 274 (67)	66 – 472 (216)	NA	NA
Acidity – Alkalinity scale (pH)	7.03 – 8.27	7.22 – 8.82 (8.14)	5.56 – 9.78 (7.81)	7.82 – 8.43 (8.19)	8.27 – 8.67	6.5 to 8.0
Electrical Conductivity (µS/cm)	100 – 701	190 – 727 (322)	107 – 433 (236)	351 – 572 (503)	222 – 1557 <sup>1</sup>	20 to 30 µS/cm <sup>1</sup>
Turbidity (NTU)	8.2 – 211	11.5 – 144 (53.3)	7.8 – 829 (246.1)	271 – 755 (470)	22 - 224	1 to 20 <sup>2</sup>
Dissolved Oxygen (mg/L)	0.84 – 8.89	1.64 – 14.74 (9.76)	2.24 – 17.89 (8.95)	1.84 – 12.7 (9.03)	7.3 – 11.5	90 to 110 (derived from daytime measurements)
Temperature (°C)	24.9	9.6 – 29.8 (18.4)	7.5 – 28.8 (16.7)	9.8 – 27 (17.4)	NA	Not applicable
Depth (m)	0.10 – 1.20	0.6 – 2.5 (1.7)	0.5 – 3.6 (2.0)	0.4 – 2.00 (1.2)	0.2 – 2.0	Not applicable
Lake Water Level (m RL)	204.5	205.25 – 205.75	205.40 – 206.88	204.33 - 205.24	205.1	Not applicable
Total Iron (mg/L)	6.50	0.36 – 11.00 (2.50)	0.92 – 22.6 (9.55)	2.54 – 33.6 (21.49)	NA	NA (insufficient data)
Calcium (mg/L)	17	10 – 26 (19)	8 – 28 (14)	22 – 32 (26)	NA	NA
Magnesium (mg/L)	10	6 – 12 (9)	4 – 14 (7)	9 – 17 (13.4)	NA	NA
Potassium (mg/L)	15	12 – 19 (15)	12 – 19 (14)	14 – 27 (21)	NA	NA
Sodium (mg/L)	19	13 – 35 (24)	12 – 38 (22)	35 – 59 (50)	NA	NA
Chloride (mg/L)	25	19 – 41 (28)	12 – 66 (22)	36 – 61 (51)	NA	NA
Sulphate (mg/L)	3	1 – 10 (2)	1 – 10 (4)	14 -38 (21)	NA	NA
Cations (mg/L)	2.81	1.98 – 3.77 (3.02)	1.56 – 3.82 (2.11)	3.74 – 5.85 (5.13)	NA	NA
Anions (mg/L)	2.83	1.93 – 3.67 (2.91)	1.45 – 3.77 (2.00)	3.76 – 5.78 (5.02)	NA	NA

**Table 15 (Continued):  
Summary of Lake Water Monitoring Results for the Reporting Period**

Parameter	Lake Cowl Water Quality Results (November 2010)	Lake Cowl Water Quality Results (2011) Ranges (Mean)	Lake Cowl Water Quality Results (2012) Ranges (Mean)	Lake Cowl Water Quality Results (2013) Ranges (Mean)	Lake Cowl Baseline Water Quality Results (1991 -1992)	Aquatic Ecosystems <sup>^</sup> ~
Arsenic (mg/L)	0.006 (total)	<0.001 – 0.007 (0.003 <sup>3</sup> ) (total)	0.002 – 0.007 (0.004 <sup>3</sup> ) (total)	0.006 – 0.014 (0.009) (total)	0.0026 <sup>3</sup> (total)	0.008
	0.005 (dissolved)	<0.0003 – 0.006 (0.0026 <sup>3</sup> ) (dissolved)	0.001 – 0.006 (0.003 <sup>3</sup> ) (dissolved)	0.003 – 0.011 (0.007) (dissolved)	0.0016 <sup>3</sup> (dissolved)	
Cadmium (mg/L)	0.0001 (total)	<0.0001 - 0.001 (0.0001 <sup>3</sup> ) (total)	<0.0001 – 0.005 (0.0002 <sup>3</sup> ) (total)	0.0001 – 0.0002 (0.0001) (total)	0.000055 <sup>3</sup> (total)	0.0006
	0.0001 (dissolved)	<0.0001 – 0.0004 (0.0001 <sup>3</sup> ) (dissolved)	<0.0001 – <0.0001 (0.00001 <sup>3</sup> ) (dissolved)	0.0001 – 0.0002 (0.0001) (dissolved)	0.00005 <sup>3</sup> (dissolved)	
Molybdenum (mg/L)	0.001 (total)	<0.001 – 0.006 (0.0012 <sup>3</sup> ) (total)	<0.001 – 0.004 (0.001 <sup>3</sup> ) (total)	0.001 – 0.003 (0.0014) (total)	NA	NA (insufficient data)
	0.001 (dissolved)	<0.001 - 0.001 (0.001 <sup>3</sup> ) (dissolved)	<0.001 – 0.001 (0.001 <sup>3</sup> ) (dissolved)	0.001 – 0.002 (0.0014) (dissolved)	NA	
Nickel (mg/L)	0.007 (total)	<0.001 – 0.009 (0.0036 <sup>3</sup> ) (total)	<0.001 – 0.018 (0.009 <sup>3</sup> ) (total)	0.006 – 0.025 (0.018) (total)	NA	0.008
	0.004 (dissolved)	<0.001 – 0.004 (0.0023 <sup>3</sup> ) (dissolved)	<0.001 – 0.004 (0.003 <sup>3</sup> ) (dissolved)	0.002 – 0.005 (0.0035) (dissolved)	NA	
Lead (mg/L)	0.003 (total)	<0.001 – 0.004 (0.0013 <sup>3</sup> ) (total)	<0.001 – 0.009 (0.004 <sup>3</sup> ) (total)	0.003 – 0.015 (0.009) (total)	0.0029 <sup>3</sup> (total)	0.001
	0.001 (dissolved)	<0.001 - 0.001 (0.001 <sup>3</sup> ) (dissolved)	<0.001 – 0.003 (0.001 <sup>3</sup> ) (dissolved)	0.001 – 0.001 (0.001) (dissolved)	0.0005 <sup>3</sup> (dissolved)	
Antimony (mg/L)	0.001 (total)	<0.001 – 0.004 (0.0014 <sup>3</sup> ) (total)	<0.001 – <0.001 (0.001 <sup>3</sup> ) (total)	0.001 – 0.001 (0.001) (total)	NA	NA (insufficient data)
	0.001 (dissolved)	<0.001 - 0.001 (0.001 <sup>3</sup> ) (dissolved)	<0.001 – <0.001 (0.001 <sup>3</sup> ) (dissolved)	0.001 – 0.001 (0.001) (dissolved)	NA	
Zinc (mg/L)	0.012 (total)	<0.005 – 0.038 (0.0074 <sup>3</sup> ) (total)	<0.005 – 0.040 (0.016 <sup>3</sup> ) (total)	0.008 – 0.079 (0.036) (total)	0.012 <sup>3</sup> (total)	0.0024
	0.015 (dissolved)	<0.005 – 0.022 (0.0109 <sup>3</sup> ) (dissolved)	<0.005 – 0.264 (0.035 <sup>3</sup> ) (dissolved)	0.005 – 0.067 (0.018) (dissolved)	0.00306 <sup>3</sup> (dissolved)	

<sup>^</sup> Guideline values in accordance with ANZECC and ARMCANZ (2000).

~ 99% protection level trigger values for toxicants – lakes and reservoirs.

NA – Not Available.

<sup>1</sup> ANZECC and ARMCANZ (2000) notes that conductivity in lakes is generally low, but will vary depending upon catchment geology.

<sup>2</sup> ANZECC and ARMCANZ (2000) notes that lakes in catchments with highly dispersible soils will have high turbidity.

<sup>3</sup> Mean value.

**Table 16**  
**Summary of Lake Cowal Inflow Water Monitoring Results for 2010, 2011, 2012 and 2013**

Parameter	Lake Inflow Water Quality Results (November 2010 – Mean) <sup>#</sup>	Lake Inflow Water Quality Results (2011) Ranges (Mean) <sup>#</sup>	Lake Inflow Water Quality Results (2012) Ranges (Mean)	Lake Inflow Water Quality Results (2013) Ranges (Mean)	Lake Cowal Baseline Water Quality Results (1991 -1992) <sup>#</sup>	Aquatic Ecosystems <sup>^</sup> ~
Alkalinity (mg/L)	50	16 – 79 (56)	39 – 101 (67)	95 – 170 (133)	NA	NA
Suspended Solids (mg/L)	14	11 – 201 (53)	23 – 372 (124)	210 – 640 (425)	NA	NA
Acidity – Alkalinity scale (pH)	7.3	7.17 – 7.73 (7.37)	7.55 – 7.90 (7.73)	7.73 – 7.87 (7.80)	8.27 – 8.67	6.5 to 8.0
Electrical Conductivity (µS/cm)	178	126 – 348 (199)	89 – 871 (246)	365 – 551 (458)	222 – 1557 <sup>1,3</sup>	20 to 30 µS/cm <sup>1</sup>
Turbidity (NTU)	116	31 – 807 (237)	18.6 – 693 (296)	337 – 2560 (1449)	22 – 224	1 to 20 <sup>2</sup>
Total Iron (mg/L)	6.5	0.9 – 42.8 (10.7)	2.09 – 36.7 (13.68)	20.8 – 180 (100)	NA	NA
Calcium (mg/L)	9	3 – 15 (8)	5 – 23 (11.3)	10 – 29 (19.5)	NA	NA
Magnesium (mg/L)	5.5	2 – 9 (5)	3 – 16 (6.9)	6 – 15 (10.5)	NA	NA
Potassium (mg/L)	10.5	8 – 17 (12)	10 – 16 (12.6)	21 – 23 (22)	NA	NA
Sodium (mg/L)	15.5	11 – 34 (17)	14 – 45 (22.4)	48 – 51 (49.5)	NA	NA
Chloride (mg/L)	18	9 – 28 (18)	12 – 94 (31)	40 – 55 (47.5)	NA	NA
Sulphate (mg/L)	4.5	1 – 13 (5)	2 – 11 (6.2)	23 – 28 (25.5)	NA	NA



**Table 16 (continued):  
Summary of Inflow Water Quality Results for 2011, 2012 and 2013**

Parameter	Lake Inflow Water Quality Results (November 2010 – Mean <sup>#</sup> )	Lake Inflow Water Quality Results (2011) Ranges (Mean)	Lake Inflow Water Quality Results (2012) Ranges (Mean) <sup>#</sup>	Lake Inflow Water Quality Results (2013) Ranges (Mean) <sup>#</sup>	Lake Cowal Baseline Water Quality Results (1991 -1992)	Aquatic Ecosystems <sup>^</sup> ~
Cations (mg/L)	1.7	1.11 – 2.40 (1.71)	1.43 – 4.78 (2.46)	3.62 – 5.49 (4.55)	NA	NA
Anions (mg/L)	1.6	1.26 – 2.27 (1.74)	1.27 – 4.64 (2.33)	3.61 – 5.43 (4.52)	NA	NA
Arsenic (mg/L)	0.0035 <sup>3</sup> (total)	0.001 – 0.007 (0.003 <sup>3</sup> ) (total)	0.003 – 0.007 (0.004 <sup>3</sup> ) (total)	0.008 – 0.026 (0.017) (total)	0.0026 <sup>3</sup> (total)	0.008
	0.0015 <sup>3</sup> (dissolved)	<0.001 – 0.004 (0.002 <sup>3</sup> ) (dissolved)	0.001 – 0.003 (0.002 <sup>3</sup> ) (dissolved)	0.002 – 0.006 (0.004) (dissolved)	0.0016 <sup>3</sup> (dissolved)	
Cadmium (mg/L)	<0.0001 <sup>3</sup> (total)	<0.0001 - <0.001 (<0.0001 <sup>3</sup> ) (total)	<0.001 - <0.001 (0.001 <sup>3</sup> ) (total)	<0.0001 - <0.001 (<0.0001 <sup>3</sup> ) (total)	0.000055 <sup>3</sup> (total)	0.0006
	<0.0001 <sup>3</sup> (dissolved)	<0.0001 – <0.0002 (<0.0001 <sup>3</sup> ) (dissolved)	<0.001 - <0.001 (0.001 <sup>3</sup> ) (dissolved)	<0.001 - <0.001 (0.001 <sup>3</sup> ) (dissolved)	0.00005 <sup>3</sup> (dissolved)	
Molybdenum (mg/L)	<0.001 <sup>3</sup> (total)	0.001 – 0.004 (0.0015 <sup>3</sup> ) (total)	<0.001 - <0.001 (0.001 <sup>3</sup> ) (total)	<0.001 - <0.001 (0.001 <sup>3</sup> ) (total)	NA	NA (insufficient data)
	<0.001 <sup>3</sup> (dissolved)	<0.001 - <0.001 (<0.001 <sup>3</sup> ) (dissolved)	<0.001 - <0.001 (0.001 <sup>3</sup> ) (dissolved)	<0.001 - <0.001 (0.001 <sup>3</sup> ) (dissolved)	NA	
Nickel (mg/L)	0.007 <sup>3</sup> (total)	0.001 – 0.026 (0.008 <sup>3</sup> ) (total)	0.005 – 0.021 (0.011 <sup>3</sup> ) (total)	0.017 – 0.077 (0.047) (total)	NA	0.008
	0.002 – 0.003 (0.0025 <sup>3</sup> ) (dissolved)	0.002 – 0.005 (0.003 <sup>3</sup> ) (dissolved)	0.003 – 0.005 (0.004 <sup>3</sup> ) (dissolved)	0.004 – 0.004 (0.004) (dissolved)	NA	
Lead (mg/L)	0.0035 <sup>3</sup> (total)	<0.001 – 0.029 (0.006 <sup>3</sup> ) (total)	<0.001 – 0.021 (0.007 <sup>3</sup> ) (total)	0.007 – 0.097 (0.052) (total)	0.0029 <sup>3</sup> (total)	0.001
	0.001 <sup>3</sup> (dissolved)	<0.001 - 0.003 (0.002 <sup>3</sup> ) (dissolved)	<0.001 – 0.007 (0.002 <sup>3</sup> ) (dissolved)	<0.001 – 0.001 (0.001) (dissolved)	0.0005 <sup>3</sup> (dissolved)	
Antimony (mg/L)	<0.001 <sup>3</sup> (total)	<0.001 – 0.004 (0.002 <sup>3</sup> ) (total)	<0.001 - <0.001 (0.001 <sup>3</sup> ) (total)	<0.001 - <0.001 (<0.001) (total)	NA	NA (insufficient data)
	<0.001 <sup>3</sup> (dissolved)	<0.001 - <0.001 (<0.001 <sup>3</sup> ) (dissolved)	<0.001 - <0.001 (0.001 <sup>3</sup> ) (dissolved)	<0.001 - <0.001 (<0.001) (dissolved)	NA	
Zinc (mg/L)	0.015 <sup>3</sup> (total)	<0.005 – 0.074 (0.0022 <sup>3</sup> ) (total)	0.009 – 0.051 (0.024 <sup>3</sup> ) (total)	0.033 – 0.234 (0.134) (total)	0.012 <sup>3</sup> (total)	0.0024
	0.03 <sup>3</sup> (dissolved)	<0.005 – 0.219 (0.046 <sup>3</sup> ) (dissolved)	<0.005 – 0.068 (0.036 <sup>3</sup> ) (dissolved)	0.005 – 0.009 (0.007) (dissolved)	0.00306 <sup>3</sup> (dissolved)	

<sup>^</sup> Guideline values in accordance with ANZECC and ARM CANZ (2000).

~ 99% protection level trigger values for toxicants – lakes and reservoirs.

<sup>#</sup> Two readings only for December 2010

NA – Not Available.

<sup>1</sup> ANZECC and ARM CANZ (2000) notes that conductivity in lakes is generally low, but will vary depending upon catchment geology.

<sup>2</sup> ANZECC and ARM CANZ (2000) notes that lakes in catchments with highly dispersible soils will have high turbidity.

<sup>3</sup> Mean Value

During the March 2012 high rainfall events and subsequent floods the lake went from a relatively static level of around 205.3m AHD to a peak of 206.88 on the 21<sup>st</sup> of March. The lake stayed at a relatively high level for approximately one month before steadily receding back to 205.3m by the end of 2012 due to a return of average rainfall conditions. The general trend for the majority of 2013 has followed on from June 2012. With the exception of some above average rainfall in June 2013 which held lake levels steady at a depth of 204.8 m AHD. Lake levels remained steady until October 2013, before receding at a steady rate once more. Plate 2 shows lake heights since October 2010 to the time of reporting in March 2014.

**Plate 2  
Lake Cowal Water Level (2010 – 2014)**




Plate 3 below is an aerial photograph taken from the North looking South towards the open-pit. The photograph was taken 23 January 2014 and depicts vegetation cover just to the North of the open-pit that grew quickly after lake recession. Lake water at this stage abutted the perimeter Lake Protection Bund.

**Plate 3  
Aerial Photograph of the Lake Protection Bund (LPB) January 2014.**



## Interpretation

A full summary of surface water monitoring results is provided in Appendix C. A comparison of surface water results with the Australian and New Zealand Environmental Conservation Council (**ANZECC**) and Agriculture and Resource Management Council of Australia and New Zealand (**ARMCANZ**) (2000) guidelines has not been undertaken on on-site surface water ponds as they are contained inside a closed catchment in the mining lease area. The closed catchment is engineered to contain all runoff on the mining lease and physically separates mine water from offsite waters in the upstream diversion drains and Lake Cowal. A summary of the on-site water quality monitoring results and a comparison of all lake water and sediment monitoring results against relevant ANZECC and ARMCANZ (2000) guideline values (detailed in the SWGMBMP) is provided below.

Up Catchment Diversion North (**UCD North**) and Up Catchment Diversion South (**UCD South**) are stilling basins at the edges of Lake Cowal which collect upstream water flowing through diversion channels around the perimeter of the closed catchment.

**UCD North** pH and Conductivity remained within acceptable limits and fluctuated slightly during the 2013 reporting period. pH remained fairly stable whilst conductivity trended slightly upwards due to receding lake water levels. Samples are still taken from same sample point using a GPS unit and aluminium boat.

**UCD South** pH values decreased to become fairly stable from mid-2013 onwards. Conductivity fluctuated slightly throughout reporting period.

**Pond D1** pH and Conductivity remained fairly stable throughout the reporting period. Fluctuations in pH and Conductivity were due to a combination of rainfall affecting dam volume and sample location.

**Pond D4** pH remained fairly stable throughout the reporting period. Conductivity decreased to become fairly stable from mid-2013 onwards correlating with increasing dam levels.

In summary, throughout the 2013 reporting period, pH values seen in on-site water quality monitoring data has remained fairly stable. Conductivity of all sites reflected a combination of rainfall affecting dam volume and sample location.

Pit sump monitoring points are continuously destroyed and recreated due to the vertical advancement of the pit floor. When they exist, sumps continue to be sampled on a monthly basis.

## Lake Cowal Surface Water Monitoring Results

A summary of the 2013 Lake Cowal surface water monitoring results and the Lake Cowal Inflow site monitoring results compared with the baseline surface water monitoring results conducted during 1991 – 1992, the 2010, 2011 and 2012 monitoring results and the ANZECC and ARMCANZ (2000) default trigger values is provided in Tables 15 and 16.

Surface water and sediment monitoring of Lake Cowal commenced during November 2010. Monitoring was undertaken by David McMahon of DM McMahon Pty Ltd Environmental Consultants. 2011 was the first full year of Lake Water monitoring since mining production commenced in 2006.

A summary of the surface water and sediment monitoring results from David McMahon's *Surface Water and Sediment Sampling and Analysis Lake Cowal, NSW 2013* is provided below. Of the 34 lake surface water sample sites specified only 30 were able to be sampled in January 2013. Sites L10 to L13 were too shallow to access safely at that time. In April an additional two sites L9 and L14 were inaccessible, this included L9 and L14 due to low lake levels. In July 2013 another 4 sites had become inaccessible due to lower lake level, these sites included B6, L7, Sandy Creek and Bland Creek. From May to Dec 2013 all inflow sites could not be sampled due to dry and inaccessible conditions.

### pH and Electrical Conductivity

pH results ranged from 7.82 to 8.43 with a mean of 8.19. This is lower overall than the baseline water quality data collected in 1991 – 1992, and similar to the ANZECC and ARMCANZ (2000) upper level of 8.0 and 2011 results (Table 16).

EC results ranged from 351 to 572  $\mu\text{S}/\text{cm}$  with a mean of 503  $\mu\text{S}/\text{cm}$  which is mid to low range of the baseline data but higher than the ANZECC and ARMCANZ (2000) level of 30  $\mu\text{S}/\text{cm}$  for slightly disturbed ecosystems (lakes). However, ANZECC and ARMCANZ (2000) note that conductivity in lakes will vary depending on catchment geology (Table 15). These results are higher to those recorded in 2011 and 2012 due to the declining lake levels and subsequent concentration of salts.

### **Turbidity and Suspended Solids**

Turbidity results ranged from 271 to 755 mg/L NTU with a mean of 470 mg/L. No baseline data for turbidity from 1991 – 1992 is available. The turbidity results are above the ANZECC and ARMCANZ (2000) level of 20 mg/L for slightly disturbed ecosystems (lakes). ANZECC and ARMCANZ (2000) note that lakes in catchments with highly dispersive soils such as Lake Cowal will have high turbidity (Table 15). These results are well above 2010 to 2012 values.

The suspended solids results ranged from 66 to 472 mg/L with a mean of 216 mg/L which is above the 2010 to 2012 results. The ANZECC and ARMCANZ (2000) recommended guideline trigger values for toxicants do not include a trigger value for suspended solids.

### **Dissolved Oxygen**

Dissolved Oxygen results ranged from 1.84 to 12.70 mg/L with a mean of 9.03 mg/L which is similar to the 2011 and 2012 results. The ANZECC and ARMCANZ (2000) recommended a guideline range of between 90 and 110% saturation which is a different scale to what was directly measured at Lake Cowal.

### **Heavy Metals**

The mean results for dissolved heavy metals for 2013 are generally equal to or lower than the ANZECC and ARMCANZ (2000) default trigger values, with the exception of Zinc. However it should be noted that the mean dissolved zinc results for the Lake Cowal Inflow sites were also elevated above the ANZECC and ARMCANZ (2000) default trigger value for zinc and have been since monitoring commenced in 2010.

Overall, the mean 2013 results for dissolved heavy metals are consistent with the mean baseline results recorded in 1991-1992, are consistent with the Lake Cowal Inflow sites results and also consistent with the results from the 2010, 2011 and 2012 monitoring rounds.

The mean 2013 monitoring results for total heavy metals marginally exceeded ANZECC and ARMCANZ (2000) default trigger values for Nickel, Lead and Zinc, as was the case in 2011 and 2012 for Lead and Zinc.

### **Lake Cowal Sediment Monitoring Results**

A summary of 2013 Lake Cowal sediment data is presented in Table 17.

A total of 30 of the 34 lake sediment sites were sampled in Jan. Sites L10, L11, L12 and L13 were deemed too shallow to access safely. In April an additional two sites L9 and I4 could not be accessed due to the lower lake level. In July 2013 another 4 sites had also become inaccessible, these sites included B6, L7, Sandy Creek and Bland Creek. From May 2013 no inflow sites could be sampled due to inaccessibility.

The mean heavy metals results for 2013 were very similar to the mean heavy metals results for 2010, 2011 and 2012 with some minor variation noted. Mean heavy metals results were below the ANZECC and ARMCANZ (2000) sediment trigger values for extractable metals. All Total Antimony results were reported as <5mg/L (the laboratory method detection limit (MDL)), which is above the ANZECC and ARMCANZ (2000) sediment trigger value (2 mg/L). However, the 2013 mean extractable Antimony results are consistent with the 2010, 2011 and 2012 mean Antimony results and are below the ANZECC and ARMCANZ (2000) trigger level.

**Table 17**  
**Summary of Lake Cowl Sediment Monitoring Results for the Reporting Period**

Parameter	Lake Cowl Sediment Results (November 2010)	Lake Cowl Sediment Results (2011) Range (Mean)	Lake Cowl Sediment Results (2012) Range (Mean)	Lake Cowl Sediment Results (2013) Range (Mean)	Aquatic Ecosystems <sup>^</sup>
Arsenic (mg/L)	2.6 <sup>1</sup> (total)	0.02 – 5.6 (3.1) <sup>1</sup> (total)	1 – 6 (3.2) <sup>1</sup> (total)	1.9 – 5.8 (3.2) <sup>1</sup> (total)	20
	1.5 <sup>1</sup> (extractable)	<0.1 – 1.8 (1.25) <sup>1</sup> (extractable)	1 – 3.1 (1.4) <sup>1</sup> (extractable)	1 – 3.1 (1.2) <sup>1</sup> (extractable)	
Cadmium (mg/L)	1 <sup>1</sup> (total)	<1 - <1 (1) <sup>1</sup> (total)	1 – 1 (1) <sup>1</sup> (total)	1 – 1 (1) <sup>1</sup> (total)	1.5
	0.1 <sup>1</sup> (extractable)	<0.1 - <0.1 (0.1) <sup>1</sup> (extractable)	0.1 – 0.1 (0.1) <sup>1</sup> (extractable)	0.1 -0.1 (0.1) <sup>1</sup> (extractable)	
Lead (mg/L)	15 <sup>1</sup> (total)	8 – 20 (13.7) <sup>1</sup> (total)	7 – 20 (12.6) <sup>1</sup> (total)	8 – 23 (14.2) <sup>1</sup> (total)	50
	8.7 <sup>1</sup> (extractable)	3.8 – 15 (8.8) <sup>1</sup> (extractable)	4.3 – 14.5 (8.6) <sup>1</sup> (extractable)	3.5 – 13.3 (7.33) <sup>1</sup> (extractable)	
Zinc (mg/L)	31.5 <sup>1</sup> (total)	14 – 57 (32.5) <sup>1</sup> (total)	11 – 43 (23.3) <sup>1</sup> (total)	13 – 63 (33.2) <sup>1</sup> (total)	200
	3.5 <sup>1</sup> (extractable)	1 - 14.8 (3.9) <sup>1</sup> (extractable)	1.1 – 7.7 (3.6) <sup>1</sup> (extractable)	1 – 11.4 (3.4) <sup>1</sup> (extractable)	
Antimony (mg/L)	5 <sup>1</sup> (total)	<5 - <5 (5) <sup>1</sup> (total)	5 – 5 (5) <sup>1</sup> (total)	<5 -<5 (5) <sup>1</sup> (total)	2
	1 <sup>1</sup> (extractable)	<1 – 6.9 (1.1) <sup>1</sup> (extractable)	1 – 7.6 (1.1) <sup>1</sup> (extractable)	1 - 4.8 (1.18) <sup>1</sup> (extractable)	

After: NSR Environmental Consultants (1995).

<sup>^</sup> Guideline values in accordance with ANZECC and ARMCANZ (2000) recommended sediment quality guidelines.

<sup>1</sup> Mean value.

### 3.3.4 Reportable Incidents

In accordance with procedures in the SWGMBMP, should monitoring results indicate values in excess of the ANZECC and ARMCANZ (2000) default 99% protection level triggers, an investigation/review shall be conducted to assess the need to implement additional management measures.

As described in Section 3.3.3, the mean dissolved zinc result for the Lake Cowl monitoring sites was above the ANZECC and ARMCANZ (2000) default trigger value for zinc. However the mean dissolved zinc result is consistent with zinc results recorded since monitoring commenced in 2010 and consistent with the mean dissolved zinc result for the Lake Cowl Inflow sites since 2010. The baseline dissolved zinc result from 1991/1992 is also above the ANZECC and ARMCANZ (2000) default trigger value for zinc. Based on this consistency of results, no additional management measures are considered necessary.

No environmental incidents or complaints were received relating to surface water at the CGM during the reporting period. There were no CEMCC resolutions regarding surface water quality during the reporting period.

### 3.3.5 Further Improvements

Lake water and sediment monitoring data will continue to be collected during the next reporting period when the lake level remains at or above 204.5 m AHD and when safe for personnel to do so. An EPL11912 variation will be lodged in early 2014 due to lower levels in Lake Cowl during the current receding phase.

As described in Paragraph 1.1.2, a request for an extension of the timing for submission of the long-term strategies (including addressing Development Consent Condition 4.1/4.2(b) (see Items 1.2.2 and 1.4) regarding strategy for decommissioning water management structures and a strategy for the final void), to the end-June 2013 was submitted to the DP&I on 13 November 2012. The long-term strategy has been incorporated into the revised SWMP after Barrick consulted with the DTIRIS (DRE) and the CEMCC. Barrick has consulted with NoW and EPA submitted a revised SWMP to the DP&I for approval on 8 August 2013.

## 3.4 GROUNDWATER

### 3.4.1 Reporting Requirements

#### 3.4.1.1 Development Consent

The reporting of groundwater monitoring is required by Development Consent Condition 8.2 (a) (iv), which states:

- (iv) *The results and interpretation of surface and ground water monitoring (including biological monitoring) are to be provided by the Applicant in an approved form to the NoW, EPA, and NSW DPI-Fisheries on a three monthly basis during construction and the first 12 months of ore processing operations and thereafter on an annual basis, unless otherwise agreed by the Director-General. The results are also to be contained and analysed in the Annual Environmental Management Report (Condition 9.2(a)).*

The SWMP (Barrick, 2010a) and the SWGMBMP (Barrick, 2010b) were prepared in accordance with Development Consent Conditions 4.1 and 8.2 (ii) respectively to provide management objectives for the CGM site water management system.

In accordance with both the SWMP and the SWGMBMP the following groundwater related issues are required to be reported in the AEMR:

- surface water, groundwater and biological monitoring results;
- details of any trends observed in the monitoring data;
- details of investigations and consultation with regulatory agencies;
- review of the performance of control measures and the monitoring program; and
- interpretation and discussion of the monitoring program results and management measures by a suitably qualified person.

#### 3.4.1.2 Environmental Protection Licence

The CGM EPL requires Barrick to undertake groundwater quality monitoring at the points identified in EPL Condition P1.3.

Condition R1 of the licence requires the completion of an Annual Return comprising a Statement of Compliance and a Monitoring and Complaints Summary at the end of each annual reporting period (i.e. the AER). Barrick submitted an Annual Return for the period 23 December 2012 to 22 December 2013 to the EPA on 20 February 2014. The groundwater quality of monitoring points identified in EPL Condition P1.3 was reported. The groundwater monitoring points and frequencies required by the EPL are consistent with monitoring required by the Development Consent and SWGMBMP.

No groundwater bores were installed or decommissioned during the monitoring period.

#### 3.4.1.3 Any other Relevant Approval

Barrick holds various licences for monitoring bores, open pit dewatering bores and Bland Creek Palaeochannel (BCPC) production bores. Each of the four BCPC production bore licences require Barrick to provide the NoW with a return showing the meter readings of hours pumped and the extraction rate for each month during the previous 12 months. There is also an obligation to provide pumping and non-pumping levels at least quarterly (or on request to the NoW). Barrick has met all NoW reporting requirements during the reporting period. The BCPC licences daily limit of 15 ML/day was not exceeded during the reporting period.

The Eastern Saline Borefield (ESB) is located approximately 10 km east of Lake Cowal's eastern shoreline. The Forbes Shire Council (FSC) approved the development application for the ESB on 20 December 2010. NoW summarily issued two presently unused production bore and monitoring bore piezometer licenses. The eastern saline borefield and associated production bore licences are described in Paragraph 2.8. In February 2012 a revised SWMP incorporating the eastern saline borefield modification was submitted to relevant government departments for comment. Comments were collated and provided to the DP&I in February 2012. A request for an extension of the timing for submission of the long-term strategies (including addressing Development Consent Condition 4.1/4.2(b) (see Items 1.2.2 and 1.4) regarding strategy for decommissioning water management structures and a strategy for the final void), to the end-June 2013 was submitted to the DP&I on 13 November

2012. The long-term strategy has been incorporated into the revised SWMP after Barrick consulted with the DTIRIS (DRE) and the CEMCC. Barrick is consulted with NoW and EPA submitted a revised SWMP to the DP&I for approval on 8 August 2013.

### **3.4.2 Environmental Management**

#### *3.4.2.1 Control Strategies*

The SWMP and the EIS establish the following objectives for the Project site water management system including groundwater:

- Prevent the quality of any surface water (including waters within Lake Cowal) and groundwater being degraded, through the containment of all potentially contaminated water (contained water) generated within the project area and diversion of all other water around the perimeter of the site (North Limited, 1998)
- Manage the quantity of surface water and groundwater within and around the mine site through appropriate design (i.e., sizing), construction and operation of water management structures;
- Establish a monitoring, review and reporting programme that facilitates the identification of potential surface water and groundwater impacts and the development of ameliorative measures as necessary, including provision of appropriate compensation measures for landholders affected by changes to the flood regime of Nerang Cowal.

The review procedure relevant to groundwater monitoring detailed in the SWGMBMP provides:

Groundwater Monitoring: Groundwater quantity and quality data will be compared to relevant baseline data, data collected since the commencement of operations and assessment presented in the Project EIS. Where the data analysis indicates that an adverse impact is occurring to the efficiency of surrounding bores an investigation will be undertaken to determine the need and type of ameliorative measures. The scope and timeframe of the investigation will be developed in consultation with the relevant authorities. The results of the investigation will be presented to the relevant authorities and the CEMCC within the agreed timeframe.

In order to monitor important background and predicted future water level draw-downs, monitoring piezometers have been installed (Figure 11 of the SWGMBMP).

In accordance with the SWGMBMP, groundwater monitoring includes:

- monitoring of bores in aquifers potentially affected by the Project (Figure 11 of the SWGMBMP) (drawdown levels); and
- feedback from private groundwater users regarding adverse changes in groundwater quantity.

#### *3.4.2.2 Effectiveness of the Control Strategies*

The control strategies implemented during the reporting period effectively met the objectives described in Paragraph 3.4.2.1 as demonstrated by the environmental performance outcomes discussed in Paragraph 3.4.3.2.

#### *3.4.2.3 Variations from Proposed Control Strategies*

There were no variations from the control strategies during the reporting period.

### **3.4.3 Environmental Performance**

#### *3.4.3.1 Monitoring*

Groundwater monitoring was conducted in accordance with the SWGMBMP and EPL. Details of the location, frequency and analytical requirements for each monitoring point are presented in Table 18. Groundwater monitoring locations are shown in Figure 12. All monitoring results for the reporting period are provided in Appendix C with a summary discussion in Paragraph 3.4.3.2.

**Table 18  
Groundwater Monitoring Program**

Site	Monitoring Frequency	Parameters
Open pit area (PDB1A & PDB1B, PBD3A & PDB3B, and PDB5A & PDB5B).	Daily.	Bore water level.
	Monthly.	SWL, EC, pH.
	Quarterly.	Total hardness, Alkalinity, total suspended solids and anions. Chloride, sulphate, Ca, Mg, K and Na. Dissolved metals – As, Cd, Mo, Ni, Pb, Sb, Zn.
Processing plant area (PP03 & PP04).	Monthly.	SWL, EC, pH.
	Quarterly.	Total hardness, Alkalinity, total suspended solids and anions. WAD and total cyanide. Chloride, sulphate, Ca, Mg, K and Na. Dissolved metals – As, Cd, Mo, Ni, Pb, Sb, Zn.
Northern Tailings Storage Facility Area (P561A & P561B, P418 A & P418 B, MON01A & MON01B, TSFNA, TSFNB & TSFNC).	Monthly.	SWL, EC, pH.
	Quarterly.	Total hardness, Alkalinity, total suspended solids and anions. Chloride, sulphate, Ca, Mg, K and Na. Dissolved metals – As, Cd, Mo, Ni, Pb, Sb, Zn.
Southern Tailings Storage Facility Area (P412 A-R & P412 B, P414 A & P414 B, P417 A & P417 B, MON02A & MON02B).	Monthly.	SWL, EC, pH.
	Quarterly.	Total hardness, Alkalinity, total suspended solids. and anions. Chloride, sulphate, Ca, Mg, K and Na. Dissolved metals – As, Cd, Mo, Ni, Pb, Sb, Zn.
Up-gradient of the northern and southern tailings storage facilities (P558A-R, P555A-R & P555B).	Monthly.	SWL, EC, pH.
	Quarterly.	Total hardness, Alkalinity, total suspended solids. and anions. Chloride, sulphate, Ca, Mg, K and Na. Dissolved metals – As, Cd, Mo, Ni, Pb, Sb, Zn.
Northern, Southern and Perimeter Waste Rock Emplacement (External toe drain).	Monthly.	SWL, EC, pH.
	Quarterly.	Total hardness, Alkalinity, total suspended solids. and anions. Chloride, sulphate, Ca, Mg, K and Na. Dissolved metals – As, Cd, Mo, Ni, Pb, Sb, Zn.
BLPR1, BLPR2, BLPR3, BLPR4 BLPR5, BLPR6, and BLPR7.	Monthly.	SWL, EC, pH. Quantity of water extracted.
	Quarterly.	Total hardness, Alkalinity, total dissolved solids. Chloride, sulphate, Ca, Mg, K and Na. Dissolved metals: Fe, Mn.
Private registered bores 29094, 57974, 29574, and 31341.	As provided by private groundwater users.	Bore water level.
NoW piezometers 36551, 36552, 36553, 36523, 36524, 36528, 36594, 36595, 36596, 36597, 36609, 36610, 36611, 36613, 36700, and 90093.	Monthly.	Bore water level.
Above ground sections of the pipeline.	Monthly.	Visual inspection.
Tailings seepage (see above - northern and southern tailings storage facility monitoring bores).	See above -northern and southern tailings storage facility.	See above -Northern and southern tailings storage facility monitoring bores.
Saline Groundwater Supply Borefields (WB01, WB20 and PZ09, PZ10 and PZ11)	Monthly.	SWL, EC, pH. Quantity of water extracted.
	Quarterly.	Total Hardness, Alkalinity, total dissolved solids, chloride, sulphate, calcium, magnesium, potassium, sodium, iron, manganese.
Water Supply Pipeline from Saline Borefield (Above ground sections of the pipeline).	Monthly.	Visual Inspection.



3.4.3.2 *Performance Outcomes***Groundwater Monitoring Data and Annual Monitoring Report**

Stiff plots of water quality and quantity results for the Bland Creek Palaeochannel Borefield (formerly the Jemalong Borefield), Processing Plant Area bores, Pit Area bores and Tailings Storage Area bores are provided in Figures 13a,13b and Figure 14. Detailed monitoring data is provided in Appendix C. The annual report containing the results and interpretation of the groundwater monitoring programme is included in Appendix C of this report, in accordance with Development Consent Condition 8.2(a) (iv).

**Groundwater Production Bores**

Groundwater extraction from the BCPC commenced in August 2004 at bore PB4. Extraction from production bores PB1, PB2 and PB3 commenced in June 2005.

A summary of monthly extraction volumes from BCPC in 2013 data is presented in Table 19. The total volume extracted during the reporting period was 1,377 ML. This equates an average of 3.77 ML/day over the 12 month period which is within the licence limit of 15 ML/day.

**Table 19**  
**Bland Creek Paleochannel Production Bores - Extraction Volumes (2013)**

Month	Extraction Volume (ML)				
	PB1	PB2	PB3	PB4	Total
January	0.0	0.3	0.0	0.0	<b>0.3</b>
February	0.0	0.3	0.0	0.0	<b>0.3</b>
March	0.0	0.3	0.0	0.0	<b>0.3</b>
April	59.6	0.0	88.0	20.9	<b>168.5</b>
May	104.0	0.0	72.0	79.8	<b>255.8</b>
June	70.0	0.0	0.0	57.7	<b>127.7</b>
July	58.6	0.0	0.0	45.2	<b>103.8</b>
August	48.8	1.4	7.6	15.8	<b>73.6</b>
September	55.7	0.1	41.3	0.0	<b>97.1</b>
October	68.3	0.4	14.0	53.4	<b>136.1</b>
November	76.1	0.6	76.1	72.7	<b>225.5</b>
December	63.9	56.6	61.5	6.1	<b>188.1</b>
<b>ANNUAL TOTAL</b>	<b>605.0</b>	<b>59.9</b>	<b>360.4</b>	<b>351.5</b>	<b>1,377</b>

As described in Paragraph 2.8, the groundwater supply borefield within ML 1535 was commissioned in mid-2009 (Production bore licences #70BL232691 and #70BL232692 have been granted during the reporting period by NoW via Water Title Certificate WAL36615 until 14 September 2015). The groundwater supply borefield has been estimated to supply up to 0.5 ML/day. Due to ongoing inundation by Lake Cowal waters, no water was extracted from the saline groundwater supply borefield within ML 1535 during the reporting period (Paragraph 2.8).

As discussed in Paragraph 3.4.1.3, Development Application No. 2011/0064 was granted by the FSC on 20 December 2010 for the operation of the eastern saline borefield for a period of five years (until 20 December 2015) (Paragraph 2.8).

From January 2012, bores PZ01, PZ02 and PZ05 were in operation in the Eastern Saline Borefield (ESB). Since these bores were constructed with slotted pipe over their full depth, their water levels are not representative of any individual hydrogeological unit. Bores PZ09, PZ10 and PZ11 were constructed with different screen intervals. These bores were monitored for standing water levels and water quality instead of PZ01, PZ02 and PZ05 from September 2012. Bore PZ01 was decommissioned in October 2012 while bores PZ02 and PZ05, in which standing water levels have been measured (but groundwater samples are not taken), remained operational.

The following observations have been made for the Eastern Saline Borefield bores:

- All the bores show small but continuing rises in groundwater level; and
- During 2013 the groundwater level has increased between 0.7 m (bore PZ05) and 1.1 m (bore PZ02).

### Hydrogeological Setting

The geological setting of the Cowal area is dominated by Gilmore Fault Zone (**GFZ**), a structurally and lithographically complex feature which trends north-south though ML 1535 approximately 500 m west of E42 pit. It separates Late Ordovician igneous units of the Lake Cowal Volcanic Complex to the east from Siluro-Devonian sedimentary basement to the west. Siluro-Devonian sedimentary rocks also occur east of Lake Cowal Volcanic Complex on the eastern side of Lake Cowal where the basement has been deeply incised and lays host to Palaeochannel deposits of the Bland Creek Unit (part of the Lachlan Formation, inferred to be Miocene to Pliocene in age).

The entire area is covered by varying thicknesses of Tertiary and Quaternary regolith deposits, including Pleistocene Cowra alluvium across the CGM ML and thick Quaternary lacustrine sediments underlying Lake Cowal. The Cowra Formation consists of interbedded clays and sandy clays. It contains two minor clayey sand aquifers, separated and confined by clay aquitards (Hawkes, 1998; Lyons *et al.*, 2000). Early work by Hawkes (1998) and Coffey Partners (1995) identified five aquifer units across the mining lease and Jemalong or Bland Creek Paleochannel Borefield area as summarised in Table 20.

**Table 20**  
**Preliminary Groundwater Model for the Cowal Mining Lease**

Aquifer Unit	Sub-Unit and Occurrence	Hydrochemical Facies Characteristics	Intersecting Bores
Cowra Formation (Tertiary-Quaternary)	Upper Alluvial Aquifer - across mining lease and Cowal area.	Na-Mg:Cl pH: Circum-neutral TDS: 17,000 – 41,000 mg/L Low Fe: <0.5 mg/L Moderate Mn: 0.01 – 1.7 mg/L	P412B, P414B, P417B, P418B, P555B, P561B, TSFNC.
	Lower Alluvial Aquifer and saprolitic units - across mining lease and Cowal area (the saprolite-saprock is probably a distinct aquifer unit but the facies includes both).	Na-Mg:Cl Na-Mg:Cl-SO <sub>4</sub> pH: Circum-neutral TDS: 20,000 – 42,000 mg/L Low Fe (generally <0.5 mg/L) Moderate Mn, (generally <0.5 Mg/L) which increases with depth and intersection with saprolitic units e.g. P555A-R, P331	P558A-R, P555A-R, P412A, P414A, P417A, P418A, P555A, P561A, TSFNB, MON02A, MON02B, PDB1B, PDB3B, PDB4B, PDB5B.
Siluro-Devonian Sedimentary Basement	Includes Burcher Greywacke & Ootha Group Sandstone.	Na-Mg:Cl-SO <sub>4</sub> pH: Circum-neutral Moderate to high Mn and Fe	MON01A, P412A-R, P555A-R.
Lake Cowal Volcanic Complex (Late Ordovician)	Volcanic and intrusive lithologies and the overlying saprolitic horizon immediately east of the GFZ underlies alluvial sediments in the open pit area beneath Lake Cowal.	Na-Mg:Cl-SO <sub>4</sub> pH: Circum-neutral TDS: 31,000 – 43,000 mg/L. Moderate Fe: <0.5 – 1.5 mg/L High Mn: 0.2 – 8.0 mg/L High trace element composition due to mineralisation history	TSFNA, PDB1A, PDB2A, PDB3A, PDB4A, PDB5A.
Bland Creek Paleochannel		Na:Cl-HCO <sub>3</sub> TDS: 900 – 3000 mg/L pH: Circum-neutral Fe: 0.3 – 0.7 mg/L Mn: 0.07 – 0.16 mg/L	BLPR1, BLPR2, BLPR3, BLPR4, BLPR5, BLPR6, BLPR7, GW36553, GW36609.

Source: Hawkes (1998) and Coffey (1995).

### **Groundwater Levels and Quality**

Detailed groundwater monitoring data for the reporting period is presented in Appendix C. The 2013 data set was analysed by Coffey Geotechnics.

A number of dry bores exist in the vicinity of the tailings storage facilities where the piezometers do not intersect the groundwater piezometric surface. Bores P555A, P555B and P412B continued to be dry during 2013 and are expected to remain dry unless groundwater levels rise. Seven additional piezometers installed around the tailings storage facilities in late 2004 (P412A-R, P555A-R, P558A, MON01A, MON01B, MON02A, and MON02B) to augment the existing network.

The Cowal groundwater system generally shows limited response to rainfall. The main groundwater level response is to pumping for water supply and pit dewatering. From 2004 to 2013, water supply pumping has resulted in a maximum drawdown of approximately 60 m in the Bland Creek Palaeochannel borefield, and pit dewatering has resulted in a maximum drawdown of approximately 70 m in the pit area monitoring bores (Figure 15). In general, vertical hydraulic gradients within the groundwater system surrounding the mine pit are downward. Measured piezometric levels within the Transported material tend to change more slowly than those for the Saprolite and Saprock (Coffey Geotechnics, 2014).

A localised increase in groundwater levels has been observed in the vicinity of the TSF area. A separate groundwater level investigation was conducted by Coffey to further assess the change in groundwater level in this area (Coffey, 2009b). A model of the groundwater system adjacent to the Southern TSF was developed and calibrated to provide reasonable agreement with the measured groundwater levels in the area. It was concluded that increasing groundwater levels south of the Southern TSF at bores MON02A and MON02B, and northeast of the southern TSF at P412A-R, are related to the movement of seepage from the TSFs (Coffey, 2009b). The direction of seepage flow towards the E42 Open Pit is consistent with the seepage flow direction predicted in the EIS and in recent hydrogeological assessments (Coffey, 2011b and 2012). It was also assessed that groundwater level rises associated with the TSF are not expected to reach the ground surface (Coffey, 2009b).

The following observations have been made relating to the groundwater levels surrounding the TSF (Coffey, 2014):

- Most of the bores show small but continuing increases in groundwater level, possibly associated with tailings dam activities (such as loading or movement of tailings water).
- The groundwater level in bore P558A-R increased by approximately 1 m in June 2013 and then returned to its former level. The increase may have been caused by a response to rainfall; and
- The paired monitoring bores MON02A and MON02B south of the southern TSF show increasing groundwater levels since October 2006. Increases of 8.7 m (MON02A) and 8.5 m (MON02B) have been recorded between May 2006 and December 2013.

In their evaluation of the 2013 groundwater monitoring data, Coffey Geotechnics concluded (Coffey Geotechnics, 2014):

- The zone of influence of the pit dewatering after five years of mine dewatering is small (around 1 km), indicating low lateral permeability.
- There has been a localised increase in groundwater levels south of the southern TSF and groundwater chemistry has remained relatively stable at monitoring bores MON02A and MON02B. A separate groundwater level investigation was conducted by Coffey to further assess the change in groundwater level in this area (Coffey, 2009b). It was concluded that increasing groundwater levels at MON02A and MON02B south of the southern TSF and northeast of the southern TSF at P412A-R are related to the movement of seepage from the TSF. The direction of seepage flow towards the open pit is consistent with the seepage flow direction predicted in the EIS and in the recent hydrogeological assessment (Coffey, 2011b and 2012).
- Water management control measures appear to have successfully prevented groundwater contamination.

Groundwater contour surfaces for December 2012 and December 2013 are presented in Figures 15a and 15b for the Transported (Shallow) and Saprock/Saprolite (Deep) aquifers. Pumping from new pit dewatering bores in the vicinity of PDB3A is likely to have affected groundwater levels on the eastern side of the pit particularly for the Saprock aquifer (Figure 16).

The groundwater quality results and trends reported in this assessment illustrate that the water management control measures for full containment of mine site water and control of runoff from the TSF and waste rock emplacements appear to have successfully prevented groundwater contamination.

### **BCPC Settlement Monuments**

Barrick installed twelve settlement monitoring monuments on and adjacent to the BCPC borefield. The inaugural survey of the monuments commenced in August 2007. Additional surveys have been conducted in April and October 2008, June 2009, March and December 2010, June 2011, and February, August 2012 and September 2013. The monuments have shown no significant trending movement since surveys began.

#### **3.4.4 Reportable Incidents**

No environmental incidents or complaints were received relating to groundwater pollution at the CGM during the reporting period. There were no CEMCC resolutions regarding groundwater quality during the reporting period.

#### **3.4.5 Further Improvements**

As described in Paragraph 1.1.2, the revised SWMP submitted in November 2011 has been updated to address DP&I review comments provided in August 2012. The long-term water management strategy has been incorporated into the revised SWMP after Barrick consulted with the DTIRIS (DRE) and the CEMCC. Barrick has consulted with NoW and EPA submitted a revised SWMP to the DP&I for approval on 8 August 2013.

The monitoring and management measures as described in the SWGMBMP will continue to be implemented during the next reporting period.

## **3.5 CYANIDE MANAGEMENT**

### **3.5.1 Reporting Requirements**

#### *3.5.1.1 Development Consent*

The reporting of cyanide monitoring is required by Development Consent Condition 8.2(b), which states:

*The Applicant shall prior to any tailings disposal prepare a cyanide monitoring program in consultation with the EPA and DTIRIS (Minerals), and to the satisfaction of the Director-General. The plan shall include, but not be limited to, provision for:*

- *monitoring of  $CN_{WAD}$  levels of the aqueous component of the tailings slurry stream at the discharge point to tailings twice daily or as otherwise directed by the Director-General, with any increases above 20mg  $CN_{WAD}/L$  to be assessed daily to ensure compliance and reported monthly to the DTIRIS (Minerals) and EPA, unless otherwise agreed by the Director-General. If the  $CN_{WAD}$  levels of 30mg/L are exceeded in the liquid at any time, discharge to the tailings dams shall cease until  $CN_{WAD}$  levels can be achieved below the levels stated in condition 5.3(a) and such exceedance shall be reported to the EPA within 24 hours;*
- *monitoring  $CN_{WAD}$  levels in the decant water of the tailings dams twice daily or as otherwise directed by the Director-General;*
- *an onsite laboratory for quickly establishing  $CN_{WAD}$  levels in the liquid at the discharge point to tailings dams and in the decant ponds for monitoring purposes;*
- *on-line monitoring of CN (FREE) at locations where employees are operating; and*
- *establishing a monitoring regime for detection of cyanide movement beneath and adjacent to the tailings impoundments.*

*A summary of the cyanide monitoring results shall be provided to the Director-General, EPA and DTIRIS (Minerals) on a three monthly basis, unless otherwise agreed by the Director-General. All results shall be included in the AEMR.*

The CMP (Barrick, 2006e) was prepared in accordance with Development Consent Condition 5.3(b) to provide objectives for monitoring and reporting of cyanide use on-site. The CMP was prepared prior to commissioning of cyanide use on-site and was approved by the DP&I on 9 January 2006. In 2008, both the FFMP and CMP were amended to reflect changes to the Development Consent related to reporting of fauna deaths.

Barrick has continued to report monthly weak acid dissociable (CN<sub>WAD</sub>) cyanide results to the Director-General of the DP&I, EPA and DTIRIS (DRE) during the reporting period. Barrick also reported and discussed these results with the CEMCC at quarterly meetings.

An amendment to the CMP was prepared in October 2010 to reflect the June 2009 Modification which allowed the addition of a cyanide destruction method (i.e. the INCO process) as an alternative to Caro's Acid and the associated introduction of sulphur dioxide (SO<sub>2</sub>) as SMBS. The addendum to the CMP was approved by the DP&I on 24 March 2010.

As described in Paragraph 1.1.2, Barrick commenced negotiations with the EPA and DTIRIS (DRE) in September 2010 regarding a proposed change to the location at which monitoring of CN<sub>WAD</sub> levels of the aqueous component of the tailings slurry stream is undertaken at the CGM. An addendum to the CMP was subsequently prepared and approved by the Director-General of the DP&I on 20 October 2010. A variation of the EPL was also issued by EPA on 24 June 2011 to reflect this change in monitoring location to the final tailings hopper (Point 48).

### 3.5.1.2 *Environment Protection Licence*

The CGM EPL requires Barrick to undertake cyanide monitoring at the points identified in EPL Condition P1.3.

Condition R1 of the licence requires the completion of an Annual Return comprising a Statement of Compliance and a Monitoring and Complaints Summary at the end of each annual reporting period (i.e. the AER). Barrick submitted an Annual Return for the period 23 December 2012 to 22 December 2013 to the EPA on 19 February 2013. Cyanide monitoring at points identified in EPL Condition P1.3 were reported. The cyanide monitoring points and frequencies required by the EPL are consistent with monitoring required by the Development Consent and SWGMBMP. Additionally, Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

The DSC inspected the TSFs, various bunds and the Pond D9 structure in June 2007 and approved their use. Barrick continues to engage the services of Dr Neil Mattes (AECOM formerly URS Corporation) to advise in various matters of inspection, maintenance and construction of walls and dams.

### 3.5.1.3 *Any Other Relevant Approval*

There are no other relevant reporting requirements for the reporting period.

## 3.5.2 **Environmental Management**

### 3.5.2.1 *Control Strategies*

A summary of the control strategies maintained during the reporting period in accordance with the CMP is provided below:

- Containment of all tailings waters within the tailings storage facility, processing plant and processing plant dams. Maintenance of the LPB and upper catchment diversion drain systems;
- Provision of emergency containment channels alongside tailings storage pipelines to and from the tailings storage facility. Maintenance of process pipe work, equipment and leak detection equipment;
- Terrestrial fauna protection fencing and avifauna deterrent methods to minimize the potential for impacts of tailings operations;
- Use of SMBS to destruct cyanide in tailings slurry to permissible levels before the processing plant slurry discharge is pumped to the tailings storage facility (with standby Caro's Acid circuit);
- Routine monitoring and reporting of tailings facility flows, ground and surface waters, and employee work areas for cyanide levels;
- Maintenance of emergency preparedness of employees and supply chain in reporting and response capability; and
- Routine patrols of tailings and process areas to ensure the potential for spillage, dust or native fauna and flora impacts are minimised.

### 3.5.2.2 *Effectiveness of Control Strategies*

Monitoring and reporting was conducted in accordance with the CMP and resulted in the effective maintenance of WAD cyanide levels below 20 mg/L (90 percentile over six months) and below 30 mg/L at all times.

On 17 April 2006, the CGM became the first cyanide-using gold operation in the world to gain Pre-Operational Plant Certification under the International Cyanide Management Institute's (ICMI) Code for Cyanide Management. The ICMI required certification to Operational requirements within 12 months after first delivery of cyanide stock. An external independent ICMI Operational Phase Code for Cyanide Management Certification Audit was undertaken from 23 to 30 March 2007. The operation was found to be in full compliance with the Code's Principles and Standards of Practice. On 2 August 2007, the CGM became the first gold operation using cyanide to be certified pre-operationally and operationally compliant with the ICMI Code. Cowal Gold was audited for 3-yearly re-certification in September 2009 and was confirmed as fully compliant with the Code.

An independent professional third-party re-certification occurred previously during February 2010 and May 2012. Cowal operations were found to have maintained full compliance to the ICMC Cyanide management Code during the previous three years.

A further independent professional re-certification audit occurred during 18-21 November 2013. Barrick (Cowan) Limited was again officially re-certified to the ICMI Code for a fourth time on 28 May 2014. Details regarding the re-certification audit are provided on the ICMI's website <http://www.cyanidecode.org/media-room/press-releases>.

### 3.5.2.3 *Variations from Proposed Control Strategies*

There were no variations from the proposed control strategies during the reporting period.

## **3.5.3 Environmental Performance**

### 3.5.3.1 *Monitoring*

In accordance with the CMP and Development Consent Condition 8.2(b), results of WAD cyanide monitoring of decant water at the process plant were reported monthly, in writing by the Environmental Manager, to the DP&I, EPA and DTIRIS (DRE), and by quarterly presentation to the CEMCC throughout the reporting period.

Monitoring results at the process plant have remained low and are summarised in Table 21.

In accordance with Consent Condition 5.3(b)(ii), CN<sub>WAD</sub> levels of the aqueous component of the tailings slurry stream have been maintained so that they do not exceed 20 mg CN<sub>WAD</sub>/L (90 percentile over six months) and 30 mg CN<sub>WAD</sub>/L (maximum permissible limit at any time) at the process plant.

As described in Paragraph 3.5.1.2, the CMP was revised following approval of the section 75W modification to the Development Consent (i.e. the E42 Modification - Modified Request) to incorporate relocation of the automated sampler from the discharge point to the tailings storage facilities to the process plant. The revision of the CMP was approved by the DP&I on 20 October 2010.

**Table 21**  
**WAD cyanide Day-Night Shift Monitoring Data for Tailings Discharged to the NTSF (01/01/2013 to 13/06/2013) and STSF (14/06/2013 to 31/12/2013)**

NTSF	WAD Cyanide (mg/L)			Total Cyanide (mg/L)		
	Site Lab	SGS, WWy	NATA, Syd	Site Lab	SGS, WWy	NATA, Syd
<b>No. Samples Taken</b>	313	313	22	160	22	22
<b>Minimum</b>	0.10	0.26	0.01	5.06	10.49	0.69
<b>Mean</b>	7.51	6.27	4.11	15.23	21.29	4.99
<b>Maximum</b>	14.28	12.2	8.6	23.36	31.8	9.19
STSF	WAD Cyanide (mg/L)			Total Cyanide (mg/L)		
	Site Lab	SGS, WWy	NATA, Syd	Site Lab	SGS, WWy	NATA, Syd
<b>No. Samples Taken</b>	377	376	29	29	29	29
<b>Minimum</b>	0.77	0.4	1.45	6.82	11	2.01
<b>Mean</b>	7.83	6.14	5.54	15.77	19.88	5.83
<b>Maximum</b>	17.39	18.2	14.2	28.11	37.5	15.2

The current recognised international safe limit for tailings storage facility fauna usage protection is 50 mg/L WAD cyanide. Barrick internal environmental management controls and the ICMI Code for Cyanide Management requires signatories to ensure that any spillage outside a bunded area above 0.5 mg/L WAD cyanide is recorded as an incident and treated as an emergency requiring immediate surface clean up. As per the CMP, on and off-site laboratories are used to monitor reagent levels inside the fenced TSF. Approval was granted during the 2007 reporting period for use of the Picric Acid method for on-site WAD cyanide level determinations in the Plant Laboratory for cyanide destruction monitoring purposes.

### 3.5.3.2 Performance Outcome

#### **Process Plant**

As described in Section 3.5.3.1 above, monitoring results at the process plant did not exceed 20 mg CN<sub>WAD</sub>/L (90 percentile over six months) or 30 mg CN<sub>WAD</sub>/L (maximum permissible limit at any time) (Table 21).

#### **Groundwater**

A detailed summary of groundwater monitoring results is provided in Appendix C.

During the 2013 reporting period, three bores reported a total cyanide concentration above the ANZECC trigger value of 0.007 mg/L in April 2013 (0.017 mg/L in MON02A, 0.027 mg/L in P412A-R and 0.034 mg/L in P417A). The WAD cyanide results were below the LOR. Re-test results for these bores and subsequent sampling events in 2013 showed both total and WAD cyanide below the LOR.

All other groundwater results for cyanide in the monitoring period remained below the laboratory detection limit.

### 3.5.4 Reportable Incidents

As per 3.8.3.1 and Table 25, one cyanide related animal death was recorded as occurring during the reporting period. On 14 November 2013 a Silver Gull was noted looking sick near the concrete sump slurry pump below Leach Tank No. 7. The maintenance employee hosing up in the immediate area immediately notified his supervisor who called the Environmental Manager. The bird was deceased by the time the first responders arrived. The EPA, DRE and CEMCC were notified immediately by phone, whilst the bird on ice in an esky and on its way for Sydney histopathology via the West Wyalong Veterinary Clinic. Soon after, additional fauna screens were erected around the concrete bunded floor sump pumps in the Leach Circuit. Gas cannons and bird scarer speakers were in operation at the adjacent Pond D6 during the time of the death. The presence of cyanide was confirmed verbally to the Environmental Manager by the West Wyalong Veterinarian in following weeks, and in writing on 2 May 2014.

There have been no deaths of animals by cyanide in the CGM Tailings Storage Facilities area since operations began in April 2006.

### 3.5.5 Further Improvements

No additional management measures are proposed for the current reporting period. The cyanide management measures as described in the CMP will continue to be implemented during the next reporting period. As such, no further improvements are intended for the management of cyanide.

## 3.6 CONTAMINATED LAND

### 3.6.1 Reporting Requirements

#### 3.6.1.1 *Development Consent*

The HWCMP (Barrick, 2006c) prepared for the CGM in accordance with Development Consent Condition 5.7 requires that any major or emergency spills that occur during the reporting period as well as any remedial measures that have been implemented to reduce the risk of occurrence are to be reported in the AEMR. Since the construction phase was completed (i.e. April 2006), hydrocarbons and paints were no longer the major relevant substances used at CGM and are further discussed in Paragraphs 2.6, 2.9 and 3.18.2. The HWCMP (Barrick, 2006c) required revision of the plan to reflect results of pre-commissioning studies and the CMP. The revised HWCMP (Barrick, 2006c) was approved by the Director-General of the DP&I on 6 March 2006.

A prior amendment of the HWCMP was approved by the Director-General of the DP&I in January 2008 to reflect the proposed management procedures for two new waste streams generated at the CGM, viz.: trash screen oversized waste and hydrocarbon-impacted material. The amendment of the HWCMP was consistent with the variations to the EPL that were approved on 16 July 2008. Hydrocarbon impacted material will be treated at the site bioremediation area.

The HWCMP was amended to reflect the June 2009 Modification to allow the addition of a cyanide destruction method (i.e. the INCO process) as an alternative to Caro's Acid, and the associated introduction of sulphur dioxide (SO<sub>2</sub>) as sodium metabisulphite (SMBS). The addendum to the HWCMP was approved by the DP&I on 10 March 2010.

In accordance with Development Consent Conditions 3.2 ad 5.7, the HWCMP was updated/ revised to reflect changes in operational practice since the commencement of CGM. The revised HWCMP addresses aspects, recommendations and findings relating to hazardous waste and chemical management in a number of other CGM management plans that were prepared subsequent to the HWCMP. The revised HWCMP was submitted to the EPA (formerly OEH) and BSC for comment and received DP&I approval in accordance with Development Consent Condition 5.7 early during the 2011 AEMR reporting period.

Cowan Mine employees promptly report and immediately address any minor substance spillages to ground or water. Incident and hazard report records are held in the on-line Barrick Responsibility Information Management System (**RIMS**) and discussed monthly at departmental ESH, General Manager's ESH meetings and form part of ongoing and the annual Site risk reviews for Community Relations, Health, Environmental, Safety and Security (**CHES**) impact controls effectiveness.

The Monitoring Programme for Detection of Any Movement of Lake Protection Bund, Water Storage and Tailings Structures and Pit/Void Walls (**LPBMP**) (Barrick, 2003f) was prepared in accordance with Development Consent Condition 8.2(a)(v) to establish a monitoring programme for CGM to prevent the contamination of the land surrounding the CGM by providing for the detection of any movement of the Lake Protection Bund, water storage and tailings structures and E42 Open Pit/ void walls during the life of the mine, with particular emphasis on monitoring after any seismic events.

In accordance with the LPBMP, the following related issues are required to be reported in the AEMR including:

- monitoring program results;
- measures employed in response to any identified movement where necessary;



- discussion of the definition of significant movement and whether a different definition is more appropriate; and
- interpretation and discussion of LPBMP results and management measures by a suitably qualified person.

The SSMP (Barrick, 2003a) prepared in accordance with Development Consent Condition 3.5(b) requires that the effectiveness of the soil stripping methods employed and the performance of CGM activities against the objectives of the SSMP are to be reported in the AEMR. Proposed improvements to soil stripping methods and any improvements to other soil management practices are also to be reported in the AEMR.

#### 3.6.1.2 *Environment Protection Licence*

Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

#### 3.6.1.3 *Any Other Relevant Approval*

The *Protection of the Environment Operations Act, 1997 (NSW) (POEO Act)* ensures licences are specified by activity to avoid associated impact e.g. Noise, Air, Water, etc. The POEO Act also requires the notification of potential environmental harm e.g. disposal of waste, leaks and spillages. In addition, the *Contaminated Land Management Act, 1997 (NSW) (CLM Act)* imposes a duty on a person who causes contamination or who is the owner of contaminated land to notify the EPA if the person becomes aware that the land is contaminated in such a way as to present a significant risk of harm. In addition to the POEO Act and CLM Act, numerous EPA guidelines referring to contaminated land state the requirements of land holders to effectively assess, manage and prevent land pollution.

The EPA introduced new legislation during 2012 which requires the preparation and implementation of Pollution Incident Response Management Plan (PIRMP). As a result of consultation with the EPA, Barrick incorporated the relevant requirements of the PIRMP within the CGM's existing Emergency Response Plan (ERP).

### **3.6.2 Environmental Management**

#### 3.6.2.1 *Control Strategies*

Continued inductions and front line management reinforcement that Cowal Mine employees need to promptly report and immediately address any minor substance spillages to ground or water. The ERP/PIRMP details control strategies relevant to preventing and reporting spills which include:

- Control the leak/flow;
- Contain the spillage;
- Limit access to the area to only clean up personnel;
- Environmental Manager to advise statutory authorities of the incident.

The control strategies described in the HWCMP (Barrick, 2011) relevant to hydrocarbons are provided in Paragraph 3.18.

The overriding control strategy for the monitoring of any movement of the LPB and water storages at the CGM during the reporting period was to implement the LPBMP (Barrick, 2003f).

Significant movement is currently defined as (AECOM formerly URS, pers. comm., 15 August 2003):

- lateral movement greater than 20 mm since previous survey, or greater than 500 mm in total; and/or
- vertical movement greater than 20 mm since previous survey, or greater than 0.1% of total embankment height.

This definition remains the most appropriate definition for detecting significant movement.

Visual and survey assessments of the LPB and TIB are the management measures described in the LPMBP (Barrick, 2003f). The NSW DSC approved Barrick's request for the de-prescription of the LPB from the DSC Register of Dams (5 March 2007 CGP letter attached to 2006 LPB Inspection Report, Dr. N. Mattes, AECOM formerly URS Corporation).

Control strategies implemented during the reporting period relevant to soil stripping are described in the SSMP (Barrick, 2003a) and included:

- scheduling of soil stripping activities (including meteorological monitoring);
- stripping of soil quantities/depths to reflect the intended use of the stripped soil;
- conducting soil stripping activities in accordance with other relevant requirements (e.g. Section 87 permits and Section 90 consents (NSW) NPW Act), Vegetation Clearance Protocol and Threatened Species Management Protocol);
- implementing appropriate dust, erosion and sediment control measures; and
- managing soil stockpiles to optimise the retention of soil characteristics.

#### 3.6.2.2 *Effectiveness of the Control Strategies*

Incident and hazard report records are held in the on-line Barrick Responsibility Information Management System (**RIMS**) and discussed monthly at departmental ESH, GMESH meetings and form part of ongoing and the annual Site risk reviews for Community Relations, Health, Environmental, Safety and Security (**CHES**) impact controls effectiveness.

Open pit visual inspections of the Lake Protection Bund, Temporary Isolation Bund, NTSF and STSF and open pit/void walls were effective in determining the satisfactory construction of the bunds.

Monthly inspections of the waste emplacements focusing on waste dump integrity (e.g. seepage inspections) were undertaken by Barrick geotechnical personnel.

The control strategies implemented during the reporting period were considered to be effective as discussed in Paragraph 3.6.3 below.

#### 3.6.2.3 *Variations from Proposed Control Strategies*

No variations to control strategies outlined in the CGM ESH performance monitoring and review process (ISO 14001 certified), SSMP and the LPBMP occurred during the reporting period.

Top of bank survey monuments exist every 200 m at the top of the NTSF and STSF. These monuments have been re-established and resurveyed (or will be scheduled), where required, after recent earthmoving works and/or after upcoming scheduled TSF earthworks. Survey monuments at the NTST and STSF will remain at their surveyed locations. Additional survey monuments will be installed at each progressive 3-metre lift.

### **3.6.3 Environmental Performance**

#### 3.6.3.1 *Monitoring*

After an independent surveillance audit in October 2012, Cowal Mine's certification to ISO 14001 Environmental Management Systems was conferred on 12 June 2013. The next scheduled ISO 14001 independent surveillance audit will be 27-30 October 2014.

The visual assessments of the LPB, TIB and NTSF and STSF were undertaken by geotechnical engineers during the reporting period. The reporting focused on seepage, cracking, stability, depressions, vegetation growth, fauna activity and other necessary structural factors. Any issues raised were suitability managed.

Routine visual and annual written assessments and review of Barrick's survey works throughout the year were undertaken by AECOM's (formerly URS) Dam's specialist (Dr Neil Mattes) to review the NTSF, STSF and all structural walls for geotechnical engineering integrity.

Soil stripping activities were carried out during the reporting period in accordance with the SSMP. A site soil database was updated as new soil stripping was undertaken during the reporting period. The database recorded details such as soil stockpile locations, soil volumes, amelioration treatment, weed control, fertiliser application and date(s) of soil stripping.

### 3.6.3.2 Performance Outcomes

Cowel Mine's certification to ISO 14001 was conferred on 12 June 2013. CGM will conduct annual ESH controls effectiveness review workshops in mid-2014. Management of Change process addresses any new projects.

Routine visual assessments by AECOM (formerly URS) and the Cowal Geotechnical Department did not detect any movement of the Temporary Isolation Bund or Lake Protection Bund during the reporting period. No significant seismic events were recorded during the reporting period. There were three near field events of 2 to 3 ML with no damage to local infrastructure (two on 27 February and one on 01 March 2014).

Due to the Lake filling event of mid-2010, the piezometers were again measured during the reporting period. Monitoring of the Lake Protection Bund piezometers began during early-2011. No influence beyond that anticipated in the shallow aquifer response zone has occurred since the lake fill. Now in a Lake receding phase.

Late in December 2012, a seep developed at the top of the first Lift near the middle of the south side of the NTSF. It was independently assessed as non-structural. The water is clear, has no cyanide WAD in it. A saline seep developed at the end of 2012 at the north-east edge toe of the NTSF. Again the flow was clear with no cyanide WAD. EPA was informed and DRE visited site. Independent TSF Design Engineer relayed event to DSC. A TSF design review was in progress from early 2013 and has been effective in draining bench seepage down from the intermittent joint seep locations. Independent review has concluded that there is no structural integrity concern. A substantial clay plug was placed into the original floor road at the start of the STSF and the NTSF Decant crushed waste rock access road ways, to eliminate the Decant road raises as a potential source of Lift intermittent joint seep water expressions. The fourth Lift of the NTSF will be constructed as a clay wrap around internal crushed waste rock fill material. Ongoing geotechnical monitoring and review shall continue for the prior and revised Lifts design through the next reporting period.

A summary of the locations where soil stripping activities occurred during the reporting period, including the volumes of soil used for rehabilitation and for stockpiling purposes, are provided in Table 22. The soil stockpile locations as at July 2013 are shown on Figure 17.

**Table 22**  
**Summary of Soil Stripping Activities for the Reporting Period**

Location of Areas Stripped	Volume of Soil Used for Rehabilitation (m <sup>3</sup> )	Volume of Soil Stockpiled (m <sup>3</sup> )
NWRE Pond D1 north trial area 80 m extension project (from Topsoil 06)	1,100	
<b>Total</b>	1,100	

The site soil database enables records to be monitored to determine the effectiveness of soil stripping methods.

The soil management measures employed during the reporting period are considered to be effective in achieving the objectives set out in the SSMP and minimising impacts of the CGM during soil stripping. As stated above, the site soil database determines the effectiveness of soil stripping methods and will continue to be utilised during the next reporting period.

Topsoil stockpile movements were scheduled for the start of the 2014 reporting period as follows:

- 23,070 m<sup>3</sup> from Stockpile 22 for lower three southern Lifts of the SWRE (January 2014);
- 8,060 m<sup>3</sup> from Stockpile 19 for south-east outer Lifts of the SWRE (February 2014); and
- 13,700 m<sup>3</sup> from Stockpile 3 for east top two Lifts of the outer PWRE (February 2014).

The top two eastern outer Lifts of the PWRE also gained topsoil resource from a 2007 temporary stockpile that had been left in situ after the initial failures in the earlier rehabilitation method for the inner PWRE Lifts.

An aerial LiDAR survey for 3-D  $\pm$  0.1 m was conducted during the 2012 reporting period. A satellite photograph update of operations occurred at the start of the 2013 reporting period.

#### **3.6.4 Reportable Incidents**

There have been no EPA PIRMP reportable incidents relevant to contaminated land during the current reporting period (since 1 July 2012).

In accordance with the LPBMP, should visual or survey assessments indicate any significant movement of the LPB or water storages, Barrick will record this movement in the database and undertake further monitoring to verify and assess the extent and potential impacts of the movement.

As required by the DTIRIS (DRE), Barrick would then enter into discussions with the DTIRIS (DRE) and DP&I to facilitate the undertaking of a risk assessment to devise ameliorative measures depending on the severity of the problem.

No environmental incidents were reported in relation to any movements of the LPB or water storages at the CGM during the reporting period.

In accordance with Development Consent Condition 9.1, soil stripping operations will be reported in accordance with the MOP. In accordance with Development Consent Condition 9.1, the predicted annual soil stripping volumes and detailed soil stockpile locations and soil management measures have been provided in the CGM MOP (2012 - 2014), extended to 31 January 2015.

No environmental incidents or complaints were reported or received relating to air, soil or water contamination, soil stripping or soil management activities at the CGM during the reporting period.

Reportable incidents regarding hydrocarbons for the reporting period are discussed in Paragraph 3.18.

#### **3.6.5 Further Improvements**

Soil stockpile characterisation, was completed during the prior reporting period (McKenzie), and findings were included in operations management for future planning periods. Characterisation has allowed Barrick to better define the quality and volume of soil resources present and inform rehabilitation efforts now and into the future. Pending MOD11 approvals outcomes the next MOP (2014 – 2016) will describe how higher salinity subsoil and topsoil stockpiles will be ameliorated by gypsum treatment.

An aerial LiDAR survey for 3-D  $\pm$  0.1 m was conducted during the 2012 reporting period. These are scheduled for about every three years to assist routine Mine Survey and Environmental staff with planning. A satellite photograph update of operations occurs near the start of the annual reporting periods.

No other improvements are proposed for the next reporting period. Barrick will work with relevant government departments and independent professional input to ensure that operations continue to prevent the contamination of the surrounding land whilst working towards setting phased completion criteria.

### **3.7 FLORA**

#### **3.7.1 Reporting Requirements**

##### *3.7.1.1 Development Consent*

The reporting of flora monitoring is required by Development Consent Condition 8.5, which states:

*The Applicant shall monitor the effectiveness of measures outlined in the fauna management plan and Threatened Species Protocol (condition 3.4). A summary of monitoring results shall be included in the AEMR.*

The Flora and Fauna Management Plan (**FFMP**) (Barrick, 2003g) was prepared in accordance with Development Consent Condition 3.4(a). In accordance with the FFMP, the following flora related issues are required to be reported in the AEMR:

- vegetation clearance activities;
- weed and pest management;
- results of the flora monitoring program; and
- the progress of remnant vegetation and wetland enhancement programmes.

The Threatened Species Management Protocol (**TSMP**) (Barrick, 2003h) was prepared in accordance with Development Consent Condition 3.4(b).

In accordance with Development Consent Condition 8.5, a summary of the effectiveness of the measures outlined in the FFMP and TSMP are required to be included in the AEMR.

As described in Paragraph 1.1.2, a Rehabilitation and Offset Management Plan (**ROMP**) was prepared in accordance with the Modified Development Consent Condition 3.6(d) and submitted to relevant government departments for review on 30 July 2010. The ROMP was lodged with the DP&I on 9 January 2011. Barrick received comments from DP&I on the ROMP in August 2012. Barrick Revised the ROMP and submitted it to the DP&I for approval on 21 August 2013.

Development Consent Condition 3.6(d) provides:

**Rehabilitation and Offset Management Plan**

3.6(d) *The Applicant shall prepare and implement Rehabilitation and Offset Management Plan for the Project to the satisfaction of DTIRIS and the Director-General. This plan must be prepared in consultation with EPA, NoW and BSC, and be submitted to the Director-General and DTIRIS (Minerals) for approval by the end of July 2010.*

*This plan must include:*

- (i) *the rehabilitation objectives for the mine site and offset areas;*
- (ii) *a description of the short, medium, and long term measures that would be implemented to:*
  - *rehabilitate the mine site;*
  - *implement the offset strategy; and*
  - *manage the remnant vegetation and habitat on the mine site and in the offset areas;*
- (iii) *detailed performance and completion criteria for the mine site rehabilitation and implementation of the offset strategy;*
- (iv) *a detailed description of the measures that would be implemented, including the procedures to be implemented for:*
  - *progressively rehabilitating disturbed areas;*
  - *implementing revegetation and regeneration within the disturbance areas and offset areas, including establishment of canopy, sub-canopy (if relevant), understory and ground strata;*
  - *protecting vegetation and soil outside the disturbance areas;*
  - *rehabilitating creeks and drainage lines on the site (both inside and outside the disturbance areas);*
  - *managing salinity;*
  - *conserving and reusing topsoil;*
  - *undertaking pre-clearance surveys;*
  - *managing impacts on terrestrial and aquatic fauna;*
  - *landscaping the mine site to minimise visual impacts;*
  - *collecting and propagating seed for rehabilitation works;*
  - *salvaging and reusing material from the mine site for habitat enhancement;*
  - *controlling weeds and feral pests, including terrestrial and aquatic species;*
  - *managing grazing and agriculture on site;*
  - *controlling access; and*
  - *bushfire management;*
- (v) *a program to monitor the effectiveness of these measures, and progress against the performance and completion criteria;*
- (vi) *a description of the potential risks to successful rehabilitation and/or revegetation, and a description of the contingency measures that would be implemented to mitigate these risks; and*

(vii) details of who would be responsible for monitoring, reviewing, and implementing the plan.

Development Consent Conditions 3.6(a), (b) and (c) are also relevant to rehabilitation of the mine site and implementation of the offset strategy. Development Consent Conditions 3.6(a) to (c) provide:

#### **Rehabilitation and Offsets**

- 3.6(a) The Applicant shall:
- (i) progressively rehabilitate the mine site in a manner that is generally consistent with the final landform in the EA (as shown in Appendix 1);
  - (ii) maximise the salvage and beneficial use of resources in areas subject to disturbance; and
  - (iii) Implement the biodiversity offset strategy as described in the EA, and summarised in Table 1 (and shown conceptually in Appendix 2), to the satisfaction of the Director-General and DTIRIS (Minerals).

Table 1: Offset Strategy

Area	Minimum Size
Offset - Enhancement Area	110 ha
Offset - Revegetation Area	100 ha
<b>Total</b>	<b>210 ha</b>

- 3.6 (b) By the end of December 2011, the Applicant shall make suitable arrangements to provide appropriate long term security for the offset areas to the satisfaction of the Director-General.
- 3.6 (c) By the end of December 2001, the Applicant shall demonstrate that appropriate monetary bonds are, or will be, in place with applicable authorities to fully implement the offset strategy, to the satisfaction of the Director-General.

As per Consent Conditions 3.6(b) and 3.6(c), Barrick (Cowal) submitted a draft VPA to DP&I on 28 April 2014. Subject to DP&I approval the draft VPA and the proposed value for the VPA bank guarantee, the offset VPA will be finalised.

As per Consent Condition 3.6(c), Barrick (Cowal) advised the DP&I on 17 December 2010 that the offset bond (to implement the offset strategy) was currently incorporated within the CGM's ML security bond held by the DTIRIS (DRE). Barrick (Cowal) next conducted initial negotiations with OEH and DP&I regarding where a VCA or a VPA would achieve the management objectives for the offset lands. In late 2013, Barrick (Cowal) commissioned Greening Australia to calculate the cost of full implementation of the CGM's offset strategy in accordance with the requirements of Condition 3.6(c) of the CGM's Development Consent. Pending DP&I approval of the revised offset strategy costing (i.e. the amount for the VPA bank guarantee), Barrick (Cowal) will submit draft terms and conditions of the bank guarantee to DP&I for review with a view for offset VPA approval.

#### **3.7.1.2 Environment Protection Licence**

Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

#### **3.7.1.3 Any Other Relevant Approvals**

There are no other relevant reporting requirements from other approvals in relation to threatened flora for the reporting period.

### **3.7.2 Environmental Management**

#### **3.7.2.1 Control Strategies**

Flora control strategies are described in the FFMP (Barrick, 2003g). The following control strategies were implemented at the CGM during the reporting period:

- implementation of Compensatory Wetland Management Plan (**CWMP**) (Barrick, 2003i) initiatives and the remnant vegetation enhancement program;

- incorporation of flora management initiatives during operational design;
- implementation of the VCP (Figure 18);
- implementation of the TSMP;
- rehabilitation of disturbance areas;
- implementation of rehabilitation monitoring report;
- development of a ROMP (including mine site rehabilitation performance and completion criteria and a mine site rehabilitation monitoring programme and offset performance and completion criteria and an offset monitoring programme);
- assessment of rehabilitation completion criteria;
- weed management and pest control;
- flora monitoring programme;
- observance of the TSMSs for the relevant Endangered Ecological Communities (**EECs**):
  - Inland Grey Box Woodland – approved 31 August 2007;
  - Myall Woodland – approved 24 September 2007; and
  - Aquatic Ecosystems (lower Lachlan River) – approved 12 October 2007; and
- provision of information relevant to the management of native flora during employee and contractor inductions.

#### ***Mine Site Rehabilitation Monitoring Programme***

In accordance with Consent Condition 3.6(d) (v), a rehabilitation monitoring programme has been developed to monitor the effectiveness of the short, medium and long-term mine site rehabilitation measures and progress against performance and completion criteria.

The performance of the mine site rehabilitation will be monitored annually against the performance and completion criteria provided in the ROMP. The performance criteria have been developed to reflect the measures for mine site rehabilitation. This monitoring will therefore assess the effectiveness of these measures and determine the need for additional measures. The quality of revegetation will be monitored using Ecosystem Function Analysis (**EFA**), or a similar systems-based monitoring approach. EFA is a method developed by the Commonwealth Scientific and Industrial Research Organisation (**CSIRO**) which provides indicators of revegetation/rehabilitation success and allows the assessment of ecosystem sustainability through the plotting of development trajectories.

EFA monitoring of revegetated/rehabilitated areas will be used to measure the progression of the revegetation/rehabilitation towards a self-sustaining ecosystem. The mine site rehabilitation monitoring programme also includes monitoring of the:

- New Lake Foreshore;
- waste rock emplacements and tailings storage facilities;
- effectiveness of the erosion and sediment control systems; and
- fauna usage of rehabilitated areas and compensatory wetland.

Subsequent to receiving DP&I review comments on 14 August 2012, Barrick continued to prepare a revised ROMP at the end of the reporting period. Barrick Revised the ROMP and submitted it to the DP&I for approval on 21 August 2013.

### **Offset Strategy**

In accordance with Development Consent Condition 3.6 an offset strategy has been developed for the CGM and is detailed in the ROMP. The offset strategy involves the conservation and management of two designated areas located on land owned by Barrick, herein referred to as the northern and the southern offset areas (Figure 19).

The offset strategy includes:

- a description of the offset;
- objectives;
- short, medium and long-term management measures;
- performance and completion criteria; and
- a monitoring programme.

### **Management Areas**

In accordance with Development Consent Condition 3.6(a) two types of management areas have been defined in order to facilitate the management of remnant vegetation and habitat in the offset areas, namely, Offset Enhancement Areas and an Offset Revegetation Area (Table 23). The management areas are shown on Figure 19.

**Table 23**  
**Offset Management Areas**

<b>Offset Management Area</b>	<b>Description</b>	<b>Minimum Size (hectares [ha])</b>
Offset Enhancement Area (Southern Offset Area)	Enhancement through natural regeneration and management for conservation.	110
Offset Revegetation Area (Northern Offset Area)	Re-establishment of woodland in cleared agricultural land by revegetation.	100
<b>Total Area Conserved (ha)</b>		<b>210</b>

### **Offset Objectives**

The objectives for the offset areas are to:

- secure the tenure of the offset areas for long-term conservation purposes;
- enhance flora and fauna habitats within the offset areas, including increasing the area of Myall Woodland through regeneration and revegetation; and
- establish native vegetation characteristic of a Eucalypt Woodland in cleared agricultural land.

Short, medium and long-term measures will be implemented within the different management areas and are detailed in the ROMP. The flora and fauna characteristics, vegetation communities, habitat complexity and condition and threatened flora and fauna characteristics of the offset areas are described in the ROMP.

### **Offset Monitoring Programme**

In accordance with Consent Condition 3.6(d) (v), an offset monitoring programme has been developed to monitor the effectiveness of the short, medium and long-term measures proposed to implement the offset strategy and to monitor the progress against performance and completion criteria.

The performance of the offset will be monitored regularly (and at least annually) against the performance and completion criteria provided in the ROMP. The performance criteria have been developed to reflect the offset strategy measures. This monitoring will therefore assess the effectiveness of these measures and determine the need for additional measures.



The offset monitoring programme will be conducted within both the Offset Revegetation Area (Northern Offset Area) and Offset Enhancement Areas (Southern Offset Area) and will include:

- a preliminary site inspection;
- visual monitoring;
- photographic monitoring; and
- permanent flora quadrats.

As described in Paragraph 3.7.1.1, subsequent to receiving DP&I review comments on 14 August 2012, Barrick continued to prepare a revised ROMP at the end of the reporting period. Barrick Revised the ROMP and submitted it to the DP&I for approval on 21 August 2013.

DnA Environmental has developed a detailed rehabilitation and offset monitoring programme for the CGM which has been included in the revised ROMP. Pending MOD11 approvals, the 2014 AEMR will include a description of any revisions to the rehabilitation and offset area monitoring programmes and outline any changes to the performance indicators and completion criteria relevant to mine site rehabilitation and the offset areas.

### ***Offset Area Long-term Security***

As described in Section 3.7.1.1, in accordance with Consent Conditions 3.6(b) and 3.6(c), Barrick (Cowan) has been working with the DP&I to establish a VPA which will provide long-term security and protection of the CGM offset areas. As a component of the VPA, Barrick (Cowan) will commit to providing a bank guarantee, which would fund implementation of the CGM offset strategy management measures. Barrick commissioned Greening Australia in 2013 to independently calculate the full cost of implementation of the CGM Offset Strategy.

#### ***3.7.2.2 Effectiveness of Control Strategies***

Development Consent Condition 8.5 requires the effectiveness of the TSMP and FFMP to be reported in the AEMR. The control strategies implemented during the reporting period were considered to be effective in minimising impacts to threatened flora. In accordance with the CGM VCP (Figure 18), mining activities were confined to approved and delineated areas. Vehicle movements within ML 1535 were restricted to designated roads to limit the impact on any potential threatened flora. The TSMP identifies threatened flora populations and management strategies were implemented accordingly.

The results of the rehabilitation monitoring programme currently implemented to assess the effectiveness of mine site rehabilitation measures and offset strategy measures is provided in Paragraph 5.

#### ***3.7.2.3 Variations from Proposed Control Strategies***

Following approval of the revised ROMP, an assessment of rehabilitation monitoring results against approved performance and completion criteria will be provided in the next AEMR.

There are no other anticipated variations to the proposed control strategies in the next reporting period.

### **3.7.3 Environmental Performance**

#### ***3.7.3.1 Monitoring***

Monitoring and management of flora continued in accordance with the requirements of the FFMP (Barrick, 2003g) (Paragraph 3.7.1) and the ROMP, during the reporting period. Measures undertaken are discussed below.

#### ***Vegetation Clearance***

Vegetation clearance activities conducted during the reporting period were monitored and undertaken in accordance with the VCP (Figure 18).

The VCP was applied to 7 trees to the east of the SWRE to allow the relocation of a large 2004 topsoil stockpile from Miller's Crusher (on the NWRE) in January 2013. The VCP was next applied to 438 trees located within an

approved surface disturbance area north-east of the SWE between the Processing Plant HV Yard and Pond D9 in June 2013 – August 2013. Approximately 0.6 ha in wet gilgai land at the eastern end of the VCP area could not be accessed safely for WCC cultural heritage inspection works and as a result, no trees were disturbed in this area. Seven in-use nest trees at the SWRE VCP area were not cleared until May 2014 in accordance with the VCP. There were no other vegetation clearance activities undertaken during the reporting period.

### **Weed Management**

The annual weed survey of Barrick property was undertaken in December 2013 by Carnegie Natives. Weed management measures resulting from the survey will continue to be implemented during 2014.

There were no other alterations to any weed management requirements during the reporting period.

Weed management is discussed further in Paragraph 3.9.2.

### **Flora Monitoring Program**

Flora monitoring was undertaken during the reporting period in the following areas of interest:

- Compensatory Wetland;
- Rehabilitation areas and Trial areas;
- Offset Management areas;
- *Pilularia novae-hollandiae* (Austral Pillwort) habitat; and
- Remnant Vegetation Enhancement Programme areas.

Monitoring of re-vegetated and rehabilitated areas within ML1535 and the offset areas was conducted during the reporting period in accordance with the ROMP, and is discussed below.

The Australian Museum Business Services (AMBS) undertook flora surveys covering Barrick-owned land within and surrounding the CGM in two stages during the 2012 and 2013 reporting periods initially between the 25 and 26 of April 2012 and on the 5 September 2012. The aim of the flora surveys was to map and validate vegetation communities present, assess vegetation condition, and target potentially occurring threatened flora. A total of 130 full floristic survey sites were surveyed within the study area as well as 65 rapid data point sites, which recorded dominant flora species and broad condition.

A total of 451 flora species from 80 plant families have been recorded within the CGM and surrounds during surveys from 1995 to 2012. The recent survey conducted by the AMBS recorded a total of 306 vascular plant species from 69 families and 176 genera.

No threatened flora species were found during the surveys. One threatened ecological community, the Weeping Myall Woodland in the Darling Riverine Plains, Brigalow Belt South, Cobar Peneplain, Murray-Darling Depression, Riverina and NSW South Western Slopes Bioregions endangered ecological community listed under the Commonwealth *Environment Protection and Biodiversity Conservation Act 1999* (EPBC Act) and the NSW *Threatened Species Conservation Act 1995* was recorded in areas within ML 1535.

AMBS also undertook targeted surveys for threatened flora species. Targeted searches for the Austral Pillwort (*Pilularia novae-hollandiae*) were conducted in April 2013 over all major areas of gilgais and some waterways within the study area. No populations of Austral Pillwort were found.

#### **3.7.3.2 Performance Outcomes**

DnA Environmental is engaged by Barrick to conduct annual monitoring of the Compensatory Wetland (**CW**); rehabilitation area and rehabilitation trial areas; the offset areas; potential Austral Pillwort habitat and the RVEP areas. A summary of the results of DnA's monitoring programme from 2013 is provided below.

### **Compensatory Wetland**

Monitoring of regeneration in the **CW** was undertaken by DnA Environmental between the 4 to 9 November 2013. Monitoring during spring aims to capture a more accurate representation of species present in the area. Future monitoring of the CW will continue to be undertaken in spring, subject to the area not being inundated.

Due to the continued inundation of Lake Cowal only two sites CW3 and GW1 which are situated on the lake foreshore, could be accessed for monitoring since 2010. The remaining ten sites were well under water. The following summary of results therefore includes data from 2008 and 2009 from all 12 monitoring sites, but from 2010 to 2013 data was obtained from only CW3 and GW1. Comparisons between the **CW**, remaining and wetland areas could therefore not be made in the 2013 reporting period (DnA Environmental, 2013b).

Results of the 2013 monitoring included:

- In 2013 there has been a significant germination event of *Eucalyptus camaldulensis* (River Red Gum) seedlings with most being very small (2 leaf stage at Foreshore).
- Due to significant flooding again in March 2012 CWs have undergone a significant transformation due to the receding water and partial inundation of the sites and there had been substantial deposition of sand and vegetative debris resulting in a decline in total ground cover, especially at CW3;
- There has also been considerable movement of large logs and branches around site CW1 and there continued to be healthy population of skinks which inhabit the fallen branches and leaf litter indicating the importance of retaining these as critical habitat requirements and the necessity of introducing these into rehabilitation areas;
- The permanent photo points and general area photographs show a marked improvement in tree health in most areas around the Lake Cowal environment;
- The changing and highly disturbed environment as a result of the March 2012 flood waters and subsequent wave action has had a significant influence on the structure and composition of the two lake foreshore communities (DnA Environmental, 2013b).
- In 2011 and 2012, the site remained ungrazed and the most eastern side of the quadrat was under water or recently submerged, however the vegetation transect remained unaffected. Large amounts of vegetative debris have been deposited throughout the site particularly at the high water mark.

Monitoring of the CW regeneration will continue annually.

In order to limit disturbance to the CW, vehicular access continued to be limited to authorised personnel.

#### **Rehabilitation Monitoring Report and Cowal Completion Criteria**

Revegetation trials have been set up on the New Lake Foreshore in accordance with the CWMP (Barrick, 2003i). The trials are discussed in Paragraph 5.4. Also discussed in Paragraph 5.4 are the monitoring results of CGM rehabilitation areas and rehabilitation trial areas and a description of the development of detailed rehabilitation completion criteria for mine landforms.

As described in Paragraph 3.7.2.1, subsequent to receiving DP&I review comments on 14 August 2012, Barrick continued to prepare a revised ROMP at the end of the reporting period. Barrick Revised the ROMP and submitted it to the DP&I for approval on 21 August 2013. A description of the revised ROMP will be provided in the next AEMR once the revised ROMP has been approved by the DP&I.

The 2014 AEMR will include a detailed description of CGM rehabilitation area and offset area monitoring programmes and outline the performance indicators and completion criteria relevant to mine site rehabilitation and the offset areas.

#### **Offset Management Areas**

Two monitoring sites were established at each of the Offset Management Areas (Northern Offset Area and Southern Offset Area) in 2010 in accordance with Development Consent Condition 3.6(a). The Offset Areas are discussed in Paragraph 5 along with the results of the 2013 monitoring program.

#### ***Pilularia novae-hollandiae* (Austral Pillwort) Habitat**

A survey of potential habitat for the threatened species *Pilularia novae-hollandiae* (Austral Pillwort) was undertaken within ML 1535 and nearby properties by DnA Environmental from 4 to 8 November 2013. Undisturbed areas of ML 1535 and nearby properties were searched, targeting areas of potentially suitable

habitat such as gilgais, farm dams, lake foreshore, areas free of water or recently receded water and areas previously surveyed.

Lake Cowal continued to be relatively full throughout the year with hot dry weather preceding the surveys resulting in the Lake starting to recede and all gilgais drying out during the 2013 survey. There were dense swards of native and introduced grasses which provided very high levels of dead litter cover, while ground cover levels were very high and limited visual opportunities. These swards also provided high competition levels and limited opportunities for Austral Pillwort to inhabit.

The Austral Pillwort was not found during 2013 despite expanding the search areas (DnA Environmental, 2013). Suitable habitat may have been present along the receding lake foreshore; however no specimens were located during the survey (DnA Environmental, 2013).

In most cases increasing ground cover and dry gilgais habitats during 2013 are unlikely to provide conditions suitable for the establishment of this small aquatic fern (DnA Environmental, 2013).

### **Remnant Vegetation Enhancement Program (RVEP)**

RVEP monitoring has been undertaken in spring in all years with the 2013 monitoring undertaken from 4 to 9 November 2013.

In line with Barrick Cowal's Land Management Plan (LMP) permanent monitoring sites have been established to measure changes occurring within the remnant vegetation as part of the Remnant Vegetation Enhancement Program (RVEP). In the LMP, there are four main RVEOP areas (Figure 25) requiring livestock exclusion and the establishment of permanent monitoring sites, including:

- RVEP1: *Eucalyptus dwyeri* (Dwyer's Red Gum) – *Callitris glaucophylla* (White Cypress Pine) woodland on Fellman's Hill, "Hillgrove";
- RVEP 2: *Muehlenbeckia florulenta* (Lignum) area in the lake bed on "Lakeside";
- RVEP 3: *Eucalyptus camaldulensis* (River Red Gum) woodland on the northern section of "Lake Cowal" foreshores and;
- RVEP 4: *Eucalyptus camaldulensis* woodland on the southern section of "Lake Cowal" foreshores.

In 2006, four monitoring sites were established within targeted areas of remnant vegetation in RVEP 1 which have been free from livestock since 2004. RVEP2 is situated in the middle of the bed of "Lakeside" and fencing requires careful consideration and no monitoring has yet been undertaken as this area was still being grazed by livestock and since 2010 it has been under water. RVEP areas 3 and 4 were fenced off in mid-2007 and monitoring sites were established in each of these areas since 2007.

Six RVEP sites were assessed this year in 2013 and these were Hill01, Hill02, Hill03, Hill04, RVEP3 and RVEP4. The monitoring of the RVEP sites have been a simplified version of the annual rehabilitation monitoring program and did not include Landscape Function Analyses (LFA) or soil analyses but has been consistent since 2008.

Since RVEP1 has been excluded from grazing by domestic livestock, there has been an increasing number of macropods using this site, in particular a growing population of Eastern Grey Kangaroos. Due to the potentially high grazing pressure, four Kangaroo-proof enclosures were constructed in 2008 and monitoring sites were also established within these to assess the impact of the macropod grazing, if any, on the health and diversity of the remnant vegetation.

In total, there have been ten permanent monitoring quadrats established within the RVEP areas 1, 3 and 4. In six sites, the survey quadrats are 50m x 20m and are surveyed annually to monitor changes in vegetation cover, species diversity and to determine the extent of regeneration occurring within these conservation sites. In the remaining four enclosure sites in RVEP1 (Fellman's Hill), the size of the monitoring quadrats needed to be reduced to a 20x20m quadrat to fit within the enclosures.

There has been no consistent trend in changes of native floristic diversity since 2008 however the different seasonal conditions have had a major influence in all sites. The lowest floristic diversity was recorded in all sites in 2009 which was a particularly dry year while there was a peak in 2010 due to improved rainfall conditions. In 2011 dry conditions resulted in a decline in total floristic diversity and in 2012 there tended to be a slightly higher diversity across all sites despite having a very dry period preceding the monitoring event. During 2013 it was

very dry with the annual rainfall being only 341.6mm despite some heavier rainfall periods in March, June and September the Lake continued to be rapidly receding which combined with increased macropod grazing has had a significant impact on the composition and floristic diversity in most sites. During the surveys, all gilgais were dry but some sites on the lake foreshore and lake protection bunds remained partially inundated. Sites occurring within the lake were obviously under water and could not be accessed. At the time of monitoring in 2013 the water levels in Lake Cowal was approximately RL 204.7 m.

In 2010, two noxious weed species of the Bland Shire were recorded in RVEP03 and these were *Lycium ferocissimum* (African Boxthorn) and *Sclerolaena birchii* (Galvanised Burr) which are likely to have been killed as a result of the weed control program. In 2012 one small *Lycium ferocissimum* was recorded at site Hill04 within RVEP1. During 2012 and 2013 one small *Lycium ferocissimum* continued to be recorded in Hill04.

Monitoring of the RVEP areas will continue during the next reporting period.

There were no alterations to any threatened flora species reporting requirements during the reporting period.

### 3.7.4 Reportable Incidents

The FFMP requires the reporting of any incidents relating to threatened flora. No environmental incidents or complaints were reported or received at the CGM relating to threatened flora during the reporting period.

### 3.7.5 Further Improvements

Improved soil classification works prior to rehabilitation works has continued to be undertaken to ensure the optimum substrate for plant growth and establishment. These works commenced during the 2011 monitoring period and were completed during the 2012 reporting period. As described in Paragraph 3.6.5, and pending MOD11 approvals, the results from soils stockpile characterisation works will be described in the next MOP and the next AEMR and will be used to inform the CGM rehabilitation programme.

As described in Paragraph 3.7.2.3, following approval of the revised ROMP, the 2014 AEMR will also include a detailed description of the monitoring programmes for CGM rehabilitation and offset areas and outline the performance indicators and completion criteria relevant to mine site rehabilitation and the offset areas.

No further improvements to threatened flora management measures are proposed for the next reporting period.

## 3.8 FAUNA

### 3.8.1 Reporting Requirements

#### 3.8.1.1 Development Consent

The reporting of fauna monitoring is required by Development Consent Condition 8.5, which states:

*The Applicant shall monitor the effectiveness of measures outlined in the fauna management plan and Threatened Species Protocol (condition 3.4). A summary of monitoring results shall be included in the AEMR.*

The AEMR is also required to include the results of fauna monitoring and records of any wildlife/fauna deaths or other incidents due to mining operations by Conditions 3.4(a)(ii) and 9.2(i)(d) of the Development Consent.

The FFMP (Barrick, 2003g) was prepared in accordance with the Development Consent Condition 3.4(a). In accordance with the FFMP, the following fauna related issues are required to be reported in the AEMR:

- a summary of deaths or other incidents involving native fauna;
- fauna usage of tailings storages;
- results of any native fauna autopsies;
- vegetation clearance activities (discussed in Paragraph 3.7.3);
- weed and pest management (discussed in Paragraph 3.9.2);

- results of the flora and fauna monitoring programs; and
- the progress of remnant vegetation and wetland enhancement programs (discussed in Paragraph 3.7.3.2).

The FFMP and CMP were amended in 2008 to reflect changes to the Development Consent related to reporting of fauna deaths.

A TSMP (Barrick, 2003h) has been prepared in accordance with Development Consent Condition 3.4(b). In accordance with the TSMP, TSMS were prepared in consultation with the EPA during the current reporting period for the following species:

- Inland Forest Bat;
- Sloane's Froglet;
- Woodland birds including:
  - Little Eagle;
  - Spotted Harrier;
  - Square-tailed Kite;
  - Varied Sitella; and
  - White-fronted Chat.

The above TSMSs were submitted to the DP&I on 28 February 2011. The Strategy was amended to address DP&I comments provided on 14 August 2012. The Strategy was resubmitted to DP&I on 13 November 2012 and is currently awaiting DP&I approval.

In accordance with Development Consent Condition 8.5 a summary of the effectiveness of the measures outlined in the FFMP (Barrick, 2003g) and TSMP (Barrick, 2003h) is required to be included in the AEMR.

In accordance with Development Consent Condition 3.6(d)(iv) (Paragraph 3.7.1.1), the ROMP includes a description of measures that will be undertaken to manage the impacts on terrestrial and aquatic fauna and preliminary habitat assessment measures (including pre-clearance surveys) to identify roosting/nesting habitat resources that may be impacted by vegetation clearance activities.

### 3.8.1.2 *Environment Protection Licence*

Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing harm or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

### 3.8.1.3 *Any Other Relevant Approvals*

There are no other relevant reporting requirements from other approvals in relation to threatened fauna for the reporting period.

## **3.8.2 Environmental Management**

### 3.8.2.1 *Control Strategies*

The relevant control strategies for the management of threatened fauna species are described in the FFMP (Barrick, 2003g) and the ROMP (Barrick, 2010) and include:

- implementation of CWMP (Barrick, 2003i) initiatives and the remnant vegetation enhancement program (discussed in Paragraph 3.7.3.2);
- incorporation of fauna management initiatives during operational design;
- implementation of the VCP (Figure 18) (including pre-clearance surveys) (discussed in Paragraph 3.7.3.1);
- implementation of the TSMP (Barrick, 2003h);
- implementation of the Plan to Protect Fauna from Interactions with the Tailings Storage Facilities (Barrick, 2005e);
- management of impacts on terrestrial and aquatic fauna;

- rehabilitation of disturbance areas;
- weed management and pest control (discussed in Paragraph 3.7.3 and 3.9.2);
- fauna monitoring program;
- maintaining a clean, rubbish free environment to discourage scavenging;
- prohibition for the introduction of animals including domestic pets on ML 1535;
- imposing speed limits within ML 1535 to reduce the risk of fauna mortality via vehicular strike; and
- provision of information relevant to the management of native fauna during employee and contractor inductions.

### 3.8.2.2 *Effectiveness of Control Strategies*

In accordance with the FFMP, implementation of the control strategies minimised impacts on threatened fauna species during the operation of the CGM.

The number of native fauna fatalities on-site has slightly reduced compared to those reported in the previous reporting period. Paragraph 3.8.3.2 lists the fauna deaths and incidents that have occurred on ML 1535 over the reporting period. The majority of native fauna deaths that occurred during the reporting period were associated with interactions with vehicles.

No native fauna deaths occurred as a result of the VCP activities described in Paragraph 3.7.3.

Several members of the Barrick Environmental team and some local community members (sponsored by Barrick) are trained NSW Wildlife Information Rescue & Education Service (**WIRES**) members. Many Barrick employee members have been trained in handling venomous snakes by Wildlife Australia. Having locally trained snake handlers and registered WIRES members has improved the care that can be given to injured native wildlife on ML 1535 and within the local community. The Barrick Cowal Environmental Manager has been the WIRES Riverina Reptiles Coordinator for years 2010 to 2014.

A compensatory wetland habitat and fish investigation was conducted by frc Environmental during February 2013 in accordance with the CWMP and SWGMBMP. Fish communities of the survey area were species poor and were dominated by the following exotic species: eastern gambusia (*Gambusia holbrooki*), and common carp (*Cyprinus carpio*). Of the four fish species recorded in the surveys, only two were native species: common carp gudgeon (*Hypseleotris* sp.) and bony bream (*Nematalosa erebi*) (frc Environmental, 2014).

The community composition of fish in the surveys was similar to the community composition of fish recorded elsewhere in areas of the Murray-Darling Basin that experience adverse environmental conditions (i.e. ephemeral waterbodies, high water temperatures, low percent saturation of dissolved oxygen) (frc Environmental, 2014). Based on the assessments of aquatic habitat and fish communities, the Compensatory Wetland, Enhancement Wetland and the new lake foreshore areas within ML 1535 have similar habitat compared to adjacent comparative sites, and provide structure that supports feeding, shelter and reproduction for a variety of fish species (frc Environmental, 2014). The current surveys show the dominance of exotic species, which are more resilient to adverse and varied conditions, and are able to rapidly colonise newly available habitats.

### 3.8.2.3 *Variations from proposed Control Strategies*

There were no variations from the proposed control strategies.

## 3.8.3 **Environmental Performance**

### 3.8.3.1 *Monitoring*

In accordance with the FFMP, monitoring in relation to fauna was conducted during the reporting period. Activities conducted during the reporting period relating to fauna monitoring included:

- continuation of long-term monitoring of bird breeding (Table 24);
- twice daily fauna usage of the tailings storage facilities;

- regular checking of the main diesel tank and hydrogen peroxide tank concrete bund sumps after rainfall events to rescue and relocate frogs; and
- daily and weekly fauna incident inspections and field patrols.

**Table 24**  
**Bird Breeding Monitoring Conducted During the Reporting Period**

Monitoring Component	Summary
Birds	Continuation of long-term bird breeding monitoring, including: <ol style="list-style-type: none"> <li>1. Waterbird breeding surveys.</li> <li>2. Collection of environmental data including lake depth, changes in depth, Southern Oscillation Index (SOI), season, and rainfall.</li> <li>3. Statistical analysis to examine variation in the abundance of breeding birds, and the number and survival of fledglings and the mean number of breeding bird species between years, seasons, lake water cycle and climatic conditions.</li> </ol>

Twice daily monitoring of fauna usage of the tailings facilities has been undertaken since the commissioning of the facilities in April 2006. One patrol is conducted after dawn and the other in the late afternoon. The patrol includes inspection of the tailings dam fence for evidence of fauna usage (e.g. tracks or breaks in the fence) and to determine the need for any maintenance measures (e.g. fence repair). Any maintenance measures are undertaken, as soon as practicable. The fauna monitoring results are utilised to determine the requirement for modifications to the mechanisms being utilised to deter fauna from the tailings dams.

The following details and observations are recorded:

- observer details (i.e. name and position);
- date and time of inspection;
- type of species present;
- number of individuals of each species;
- location within the tailings dam (e.g. on tailings dam, beach or embankment, etc);
- behaviour and habits of individuals (e.g. flying over tailings and/or wading in the tailings facility, etc);
- visually observed fauna effects; and
- any fauna incidents and/or fauna deaths.

Weekly boundary inspections of ML 1535 were conducted by environmental and/or security personnel to identify any native fauna incidents and/or deaths.

Fauna '*incidents*' are considered to occur where the observed behaviour of native fauna indicates that a negative impact on individual(s) is occurring as a result of the presence or operation of the mine (e.g. fauna is observed trapped within the ML 1535 fence). In the event that fauna incidents are observed, the following details and observations are recorded:

- observer details (i.e. name and position);
- date and time of inspection;
- type of species;
- number of individuals of each species;
- location; and
- any other relevant details of the native fauna incident.

Any native fauna found dead in the ML 1535 area are reported to environmental personnel who coordinate collection. Dead fauna are collected for autopsy to enable the cause of death to be determined. The details and observations listed above are recorded, as well as condition of the species and surface water conditions of the Lake and surrounding area (when inundated, if relevant). Where practicable, photographs or video footage are



taken (e.g. of landscape, stance of clinically affected animal, place of death) to provide additional information for veterinarian and site investigation. If cyanide is suspected or known to be a contributor to the death of a native or feral animal, the West Wyalong Veterinarian is contacted immediately and special preservation techniques followed for the sampling process.

One cyanide related animal death was recorded as occurring during the reporting period. On 14 November 2013 a Silver Gull was noted looking sick near the concrete sump slurry pump below Leach Tank No. 7. The maintenance employee hosing up in the immediate area immediately notified his immediate supervisor who called the Environmental Manager to the scene en route. The bird was deceased by the time the first responders arrived. The EPA, DRE and CEMCC were notified immediately by phone, whilst the bird on ice in an esky and on its way for Sydney histopathology via the West Wyalong Veterinary Clinic. Soon after, additional fauna screens were erected around the concrete bunded floor sump pumps in the Leach Circuit. Gas cannons and bird scarer speakers were in operation at the adjacent Pond D6 during the time of the death. The presence of cyanide was confirmed verbally to the Environmental Manager by the West Wyalong Veterinarian in following weeks, and in writing on 02 May 2014.

There have been no deaths of animals by cyanide in the CGM Tailings Storage Facilities area since operations began in April 2006.

### ***Pest Management***

Pest Management is described in Paragraph 3.9 of this AEMR.

#### ***3.8.3.2 Performance Outcomes***

There were fifty-two WIRES rescues and relocations of native fauna that have been undertaken during the reporting period, when mining activities have been a threat to their safety.

The following page shows the list of injured animals that were taken into WIRES home care and later released at suitable habitat once rehabilitated.

The rescues and relocations to immediately adjacent suitable habitat for the 2013 reporting period included:

1	Apostlebird	1	Musk Duck
1	Barn Owl	1	Nankeen Kestrel
2	Bearded Dragon	5	Noisy Miner
1	Black Snake	5	Rabbit
1	Blue Bonnet	1	Racing Pigeon
12	Brown Snake	1	Red-naped Snake
4	Feral Cat (15.3 kg total)	1	Sacred Kingfisher
1	Goldfish	3	Snake-necked Turtle
1	Grey Kangaroo	1	Spotted Marsh Frog
1	Hare	2	Tiger Snake
1	Hoary-headed Grebe	1	Wattlebird
1	Masked Lapwing Plover	3	Welcome Swallow

All native animals rescued at the CGM are entered into the WIRES database ([www.wires.org.au](http://www.wires.org.au)).

A summary of all the reported fauna deaths during the reporting period is provided in Table 25.

**Table 25**  
**Records of Fauna Deaths and Other Incidents for the Reporting Period**

<b>Date/Time of Incident</b>	<b>03 January 2013</b>	
Location	Main Administration outside car park, Mining Lease.	
Species and number of individuals	Stubble Quail	1
Description of Incident	Employee noted a deceased bird on car park surface upon entry to site walk way.	
Outcome	Likely an off-site vehicle impact incident that fell from grill during time in car park.	
<b>Date/Time of Incident</b>	<b>04 January 2013</b>	
Location	Main Administration outside car park, Mining Lease.	
Species and number of individuals	Australian Magpie	1
Description of Incident	Employee noted a deceased bird on car park surface upon entry to site walk way.	
Outcome	Likely an off-site vehicle impact incident that fell from grill during time in car park.	
<b>Date/Time of Incident</b>	<b>04 January 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Australian Raven	1
Description of Incident	Employee noticed a recently deceased bird in tall Fleabane weeds on edge of bitumen access road just after re-entering site from routine patrol. Hot day and un-poisoned/ slashed weeds.	
Outcome	Flight path error when startled by prior approaching vehicle.	
<b>Date/Time of Incident</b>	<b>06 January 2013</b>	
Location	E42 Pit Haul truck road, Mining Lease.	
Species and number of individuals	Eurasian Coot	1
Description of Incident	One of the few Coots seen in recent times on or around the Lake in drying cycle.	
Outcome	Travel path misadventure. Black bird travelling after dark.	
<b>Date/Time of Incident</b>	<b>09 January 2013</b>	
Location	Main Plant Warehouse Yard, Mining Lease.	
Species and number of individuals	Grey-faced Heron	1
Description of Incident	Employee noted a deceased juvenile white heron on ground near the steel supplies rack.	
Outcome	Natural causes from recent hot weather. Bird likely wandered from adjacent swamp area.	
<b>Date/Time of Incident</b>	<b>16 January 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Apostlebird	1
Description of Incident	Employee noted a deceased bird on bitumen access road. Bagged and taken to Vet.	
Outcome	Injuries consistent with vehicle impact during flight path misadventure.	
<b>Date/Time of Incident</b>	<b>24 January 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Grey-crowned Babbler	1
Description of Incident	Employee noted a deceased bird on bitumen access road. Bagged and taken to Vet.	
Outcome	Injuries consistent with vehicle impact during flight path misadventure.	
<b>Date/Time of Incident</b>	<b>15 February 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Willie Wagtail	1
Description of Incident	Employee noted a deceased bird on bitumen access road. Bagged and taken to Vet.	
Outcome	Injuries consistent with vehicle impact during flight path misadventure.	

**Table 25 (Continued)**  
**Records of Fauna Deaths and Other Incidents for the Reporting Period**

<b>Date/Time of Incident</b>	<b>18 February 2013</b>	
Location	Processing Plant Leach Tank Section – concrete floor, Mining Lease.	
Species and number of individuals	Stubble Quail	1
Description of Incident	Employee noted a deceased bird on concrete floor during routine field patrol. Bagged and taken to Vet.	
Outcome	Injuries consistent with steel tank wall impact during flight path misadventure.	
<b>Date/Time of Incident</b>	<b>01 March 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Stubble Quail	1
Description of Incident	Employee noted a deceased bird on bitumen access road. Bagged and taken to Vet.	
Outcome	Injuries consistent with vehicle impact during flight path misadventure.	
<b>Date/Time of Incident</b>	<b>01 March 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Masked lapwing Plover	1
Description of Incident	Employee noted a deceased bird on bitumen access road. Bagged and taken to Vet.	
Outcome	Injuries consistent with vehicle impact during flight path misadventure.	
<b>Date/Time of Incident</b>	<b>01 March 2013</b>	
Location	Gold Room, Mining Lease.	
Species and number of individuals	Myall Snake	1
Description of Incident	Juvenile Myall snake noted deceased on concrete floor near access door whilst employee was hosing up.	
Outcome	Cause of death uncertain.	
<b>Date/Time of Incident</b>	<b>03 March 2013</b>	
Location	ML1535 Boundary fence between Gates 13 and 14, Mining Lease.	
Species and number of individuals	Emu	1
Description of Incident	Routine security patrol noted a deceased Emu stuck by left leg in top barbed wire of fence.	
Outcome	Body removed from site. Travel path misadventure by bird.	
<b>Date/Time of Incident</b>	<b>26 March 2013</b>	
Location	TSF access gravel track (Wombat Drive), Mining Lease.	
Species and number of individuals	Hoary-headed Grebe	1
Description of Incident	A deceased juvenile grebe was noted on road by employee.	
Outcome	Dry period continues. Water birds are searching for active swamp area. Death by misadventure into light vehicle area – likely dusk or dawn shift patrol.	
<b>Date/Time of Incident</b>	<b>08 April 2013 / 16:00hrs and ... 09 April 2013 / 08:00hrs</b>	
Location	NTSF east side of Decant access road in mud of Decant Pool, Mining Lease.	
Species and number of individuals	Unknown Duck ... and the next day ... Little Red Fox	1 1
Description of Incident	Little Red Fox ate what appeared to be a Duck that had flapped around in wet tailings mud until death. Body was too far out to be able to retrieve by beach road and lure. Next morning a dead Little Red Fox was seen in same spot using binoculars. Fox had walked out and back on the edge of the Decant Pool but went in at the area where the unidentified duck species had been the afternoon prior.	
Outcome	The TSF tails hopper and TSF Decant NTSF were only 1 – 10 ppm WAD CN. Death by misadventure – neither body recovered.	

**Table 25 (Continued)**  
**Records of Fauna Deaths and Other Incidents for the Reporting Period**

<b>Date/Time of Incident</b>	<b>16 April 2013</b>	
Location	TSF access gravel track (Wombat Drive), Mining Lease.	
Species and number of individuals	Myall (Curl) Snake	1
Description of Incident	A deceased adult (only grow to about 300 mm) was noted on road by employee. Swampy areas around administration have almost dried out due to lack of rain in 2013.	
Outcome	Death by misadventure into light vehicle area – likely dusk or dawn shift patrol.	
<b>Date/Time of Incident</b>	<b>17 April 2013</b>	
Location	NTSF west wall middle close to edge, Mining Lease.	
Species and number of individuals	Pied Butcherbird	1
Description of Incident	Bird found dead after major effort to get out of sticky tailings mud.	
Outcome	The TSF mud WAD CN were low at only 3 to 9 ppm.	
<b>Date/Time of Incident</b>	<b>18 April 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Grey Kangaroo	1
Description of Incident	An adult Grey was noted standing over a motionless smaller Grey on north side of bitumen access road curve adjacent to south-east corner of STSF fauna fence. Responding employees scared away the larger animal, photographed and removed the deceased, juvenile body from ML to adjacent bushland.	
Outcome	Death by misadventure into light vehicle area – just on high volume traffic at dusk.	
<b>Date/Time of Incident</b>	<b>19 April 2013</b>	
Location	RO Shed Road between Mining and Processing adjacent Pond D6, Mining Lease.	
Species and number of individuals	Hoary-headed Grebe	1
Description of Incident	A deceased juvenile grebe was noted on road by employee. Small grey bird of limited flight or walking ability on recently Petro Tac treated gravel road (bitumen spray treatment of the gravel access road to TSF area).	
Outcome	Dry period continues. Water birds are searching for active swamp area. Death by misadventure into light vehicle area – likely dusk or dawn shift patrol.	
<b>Date/Time of Incident</b>	<b>14 May 2013</b>	
Location	Mining Maintenance Workshop concrete floor, Mining Lease.	
Species and number of individuals	Welcome Swallow	1
Description of Incident	Employee reported a deceased Welcome Swallow lying on Mining Maintenance Workshop concrete floor.	
Outcome	Change in weather and lower insect numbers was suspected as cause. May have flown into Shed wall.	
<b>Date/Time of Incident</b>	<b>19 May 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Grey Kangaroo	1
Description of Incident	Duty ERO reported dragging a Grey kangaroo off the bitumen access road during the night shift and disposing of it well away into adjacent bushland.	
Outcome	Body not recovered for photographs. Mob hanging about in trees during this drought.	
<b>Date/Time of Incident</b>	<b>20 May 2013</b>	
Location	Mining Maintenance Workshop concrete floor, Mining Lease.	
Species and number of individuals	Welcome Swallow	6
Description of Incident	Employees reported six deceased Welcome Swallows lying on Mining Maintenance Workshop concrete floor. They reported seeing a Butcherbird attacking the Swallows. A Butcherbird was actively call up in the top reaches of the Shed structure as Swallows flew about.	
Outcome	Predation attacks from Butcherbird.	

**Table 25 (Continued)**  
**Records of Fauna Deaths and Other Incidents for the Reporting Period**

<b>Date/Time of Incident</b>	<b>28 May 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Pacific Black Duck	1
Description of Incident	A deceased Duck was noted on road by employee. Bagged and chilled in Env fridge.	
Outcome	Injuries consistent with vehicle impact.	
<b>Date/Time of Incident</b>	<b>30 May 2013</b>	
Location	Mining Maintenance Workshop, Mining Lease.	
Species and number of individuals	Welcome Swallow	1
Description of Incident	Employee reported a deceased Welcome Swallow lying on Mining Maintenance Workshop concrete floor.	
Outcome	Predation attacks from Butcherbird.	
<b>Date/Time of Incident</b>	<b>31 May 2013</b>	
Location	SWE tree VCP area, Mining Lease.	
Species and number of individuals	Australian Magpie	1
Description of Incident	Employee noted a freshly deceased bird on ground under where Magpies had been seen fighting moments prior. No external signs of injury.	
Outcome	Vet found haemorrhage inside the bird's stomach. Suspected mouse bait secondary kill.	
<b>Date/Time of Incident</b>	<b>04 June 2013</b>	
Location	SWE tree VCP area, Mining Lease.	
Species and number of individuals	Blue-Tongued Lizard	1
Description of Incident	Env Mgr noted a large, deceased Lizard in frosted grass. It wasn't there at end of works day prior. No external signs of injury.	
Outcome	Cold change overnight. Maybe hammering trunk identification numbers onto dead trees disturbed the Lizard.	
<b>Date/Time of Incident</b>	<b>28 June 2013</b>	
Location	Lake Foreshore, Boart Longyear Jetty, Mining Lease.	
Species and number of individuals	Feral cat	1
Description of Incident	5.0 kg Black cat rescued for lethabarb euthanasure by West Wyalong Vet.	
Outcome	Vet checked. Euthanased.	
<b>Date/Time of Incident</b>	<b>02 July 2013</b>	
Location	Ground below SAG Mill concrete ramp to Mills area, Mining Lease.	
Species and number of individuals	Welcome Swallow	1
Description of Incident	Employee found an intact, flattened bird in dusty gravel road surface. Recent death.	
Outcome	May have flown into concrete ramp and been run over by forklift later.	
<b>Date/Time of Incident</b>	<b>05 July 2013</b>	
Location	Grain Silo Parts Store, adjacent Barrick Farm Land – Grain Corp.	
Species and number of individuals	Feral cat	1
Description of Incident	4.0 kg Grey rescued for lethabarb euthanasure by West Wyalong Vet.	
Outcome	Vet checked. Euthanased.	
<b>Date/Time of Incident</b>	<b>10 July 2013</b>	
Location	Hydrogen Peroxide bulk truck unloading bay area, Mining Lease.	
Species and number of individuals	Willie Wagtail	1
Description of Incident	Employee noted a deceased bird was noted on gravel road.	
Outcome	Likely a bird fallen from a truck or vehicle grill. Not an area that Wagtails are seen.	

**Table 25 (Continued)**  
**Records of Fauna Deaths and Other Incidents for the Reporting Period**

<b>Date/Time of Incident</b>	<b>11 July 2013</b>	
Location	TSF Depot Maintenance Shed, Mining Lease.	
Species and number of individuals	Feral cat	1
Description of Incident	2.5 kg Tabby rescued for lethabarb euthanasure by West Wyalong Vet.	
Outcome	Vet checked. Euthanased.	
<b>Date/Time of Incident</b>	<b>17 July 2013</b>	
Location	Process Water Tank inside Plant, Mining Lease.	
Species and number of individuals	Goldfish (large)	1
Description of Incident	Shutdown maintenance inspection crew captured a 250 mm wild goldfish from inside drained recovered water tank and handed to Env Dept as WIRES rescue call GP/RIV2541.	
Outcome	WIRES - Euthanased.	
<b>Date/Time of Incident</b>	<b>18 July 2013</b>	
Location	TSF Depot Shed area, Mining Lease.	
Species and number of individuals	Rabbit Kittens	5
Description of Incident	Employee found rabbits unattended in cardboard box of pipe fittings. Handed to Env Dept.	
Outcome	WIRES - Euthanased.	
<b>Date/Time of Incident</b>	<b>29 July 2013</b>	
Location	Site 52 dust gauge near north end of TIB, Mining Lease.	
Species and number of individuals	Pelican	1
Description of Incident	Env employees conducting routine Lake water sampling and dust collection patrol noted a floating deceased Pelican near the Site 52 dust gauge near the TIB foreshore.	
Outcome	Returned later with appropriate collection gear and disposed boy north of ML1535.	
<b>Date/Time of Incident</b>	<b>30 July 2013</b>	
Location	Mining Maintenance Workshop, Mining Lease.	
Species and number of individuals	Welcome Swallow	1
Description of Incident	Mining Maintenance Engineer reported a deceased bird on the concrete floor. Env Dept responded.	
Outcome	Possible naturl, no recent reports of Butcherbird attacks on the native Swallows in Shed.	
<b>Date/Time of Incident</b>	<b>01 August 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Emu	1
Description of Incident	Male 40 kg Emu dislodged from road verge when it stepped out in front of a B-double delivery truck on 80 kph stretch by heavy vehicle quadruple entry gates turn-off.	
Outcome	Photographs. Instant death. Body removed from ML1535 to decompose.	
<b>Date/Time of Incident</b>	<b>12 August 2013</b>	
Location	TSF water cart stand pipe dam, Mining Lease.	
Species and number of individuals	Feral cat	1
Description of Incident	3.8 kg Black cat rescued for lethabarb euthanasure by West Wyalong Vet.	
Outcome	Vet checked. Euthanased.	
<b>Date/Time of Incident</b>	<b>28 August 2013</b>	
Location	Haul Road adjacent North Go-Line, Mining Lease.	
Species and number of individuals	Bearded Dragon	1
Description of Incident	Employee reported that a deceased Dragon was on the Haul Road near the Northern Go-Line. Environmental Officers responded to collect and bag the body.	
Outcome	Injuries consistent with being run over by a Haul Truck.	

**Table 25 (Continued)**  
**Records of Fauna Deaths and Other Incidents for the Reporting Period**

<b>Date/Time of Incident</b>	<b>28 August 2013</b>	
Location	Bitumen access road cattle grid, Mining Lease.	
Species and number of individuals	Bearded Dragon	1
Description of Incident	Employee noted a deceased dragon near cattle grid and bagged it and reported to Env Dept.	
Outcome	Injuries consistent with vehicular impact. GM included a reminder to employees about using extra caution during seasonal animal movement in the Weekly Newsletter.	
<b>Date/Time of Incident</b>	<b>28 August 2013</b>	
Location	SWE tree VCP area, Mining Lease.	
Species and number of individuals	Noisy Miner	2
Description of Incident	A small nest with two unfledged young was found in the top of a felled 20 metre tall Belah during independently supervised vegetation clearance.	
Outcome	Birds taken into WIRES Home Care (GP/RIV2552-2553).	
<b>Date/Time of Incident</b>	<b>29 August 2013</b>	
Location	SWE tree VCP area, Mining Lease.	
Species and number of individuals	Noisy Miner	3
Description of Incident	A small nest with three unfledged young was found in the top of a felled 20 metre tall Belah during independently supervised vegetation clearance.	
Outcome	Birds taken into WIRES Home Care (GP/RIV2554-2556).	
<b>Date/Time of Incident</b>	<b>24 September 2013</b>	
Location	Top of North Pit Ramp entry to E42, Mining Lease.	
Species and number of individuals	Brown Snake	1
Description of Incident	Brown snake at top of North Ramp was reported to Dispatch, and Pit Boss/ Env Mgr.	
Outcome	Heavy Vehicle (HV) impact.	
<b>Date/Time of Incident</b>	<b>04 October 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Bearded Dragon	1
Description of Incident	Deceased dragon with squashed head removed from road, bagged and take to Vet Clinic.	
Outcome	Injuries consistent with vehicular impact.	
<b>Date/Time of Incident</b>	<b>10 October 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Apostlebird	2
Description of Incident	Two deceased birds found on road centre near long grass during departure from site.	
Outcome	Injuries consistent with vehicular impact. Planned to slash verges 11 October 2013.	
<b>Date/Time of Incident</b>	<b>16 October 2013</b>	
Location	Processing Laydown Yard, Mining Lease.	
Species and number of individuals	Welcome Swallow	1
Description of Incident	Juvenile bird found desiccated and scruffy on ground. Likely fallen from nest.	
Outcome	Injuries consistent with separation from parent.	
<b>Date/Time of Incident</b>	<b>17 October 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Blue-bellied Blake Snake	1
Description of Incident	Employee noted a deceased snake on bitumen road.	
Outcome	Road verges had been slashed. Warmer weather. Injuries consistent with LV impact.	

**Table 25 (Continued)**  
**Records of Fauna Deaths and Other Incidents for the Reporting Period**

<b>Date/Time of Incident</b>	<b>20 October 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Australian Magpie	1
Description of Incident	Employee noted a deceased bird on bitumen road whilst entering site on Sunday.	
Outcome	Injuries consistent with vehicular impact. Recent strong winds – separated from parent.	
<b>Date/Time of Incident</b>	<b>21 October 2013</b>	
Location	Inside rural boundary fence, Mining Lease.	
Species and number of individuals	Grey Kangaroo	1
Description of Incident	Employee entering site noted deceased kangaroo. Head stuck in rural boundary fence.	
Outcome	Injuries consistent with misadventure. Body removed from Mine Lease.	
<b>Date/Time of Incident</b>	<b>22 October 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Bearded Dragon	1
Description of Incident	Employee noted a deceased lizard on bitumen road.	
Outcome	Injuries consistent with vehicular impact. Seasonal territorial activity on roads.	
<b>Date/Time of Incident</b>	<b>29 October 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Australian Magpie	1
Description of Incident	Employee noted a deceased bird on bitumen road.	
Outcome	Injuries consistent with vehicular impact. Recent strong winds – separated from parent.	
<b>Date/Time of Incident</b>	<b>08 November 2013</b>	
Location	Processing Plant RO Shed construction area road, Mining Lease.	
Species and number of individuals	Legless Lizard	2
Description of Incident	Employees noted deceased lizards on gravel access road during walk around inspections.	
Outcome	Injuries consistent with vehicular impact.	
<b>Date/Time of Incident</b>	<b>14 November 2013</b>	
Location	Processing Plant Leach Tank 7 sump pump area, Mining Lease.	
Species and number of individuals	Silver Gull	1
Description of Incident	Employee had hosed up sump area and noted a sick Gull walking about nearby. Employee called supervisor but the bird died soon after. Body immediately sent on ice to the West Wyalong Veterinary Clinic for Veterinarian inspection and forwarding.	
Outcome	EPA, DRE and CEMCC notified immediately by phone. Sydney Veterinary Clinic histopathology results confirmed the presence of cyanide - verbally to the Environmental Manager by the West Wyalong Veterinarian in following weeks, and in writing on 02 May 2014.	
<b>Date/Time of Incident</b>	<b>21 November 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Brown Snake	1
Description of Incident	Employee noted a writhing Brown Snake on bitumen access road. Mid body was severed. Assessed as a mortal wound and promptly euthanased with a cranial crush (WIRES Riverina call number GP/RIV2566).	
Outcome	Injuries consistent with vehicular impact. 2.0 m Brown rescued and released earlier same morning from North WRE haul road (call number GP/RIV2565).	



**Table 25 (Continued)**  
**Records of Fauna Deaths and Other Incidents for the Reporting Period**

<b>Date/Time of Incident</b>	<b>25 November 2013</b>	
Location	Front of hydrant of Process Plant Workshop footpath, Mining Lease.	
Species and number of individuals	Brown Snake	1
Description of Incident	Forklift driver noted a deceased juvenile Brown Snake on light vehicle roadway out the front of the BBQ lawn area footpath area.	
Outcome	Injuries consistent with vehicular impact.	
<b>Date/Time of Incident</b>	<b>25 November 2013</b>	
Location	Administration main car park area, Mining Lease.	
Species and number of individuals	Red-rumped Parrot	1
Description of Incident	Employee noted a deceased bird on bitumen road inside main car parking area.	
Outcome	Injuries consistent with vehicular impact.	
<b>Date/Time of Incident</b>	<b>25 November 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Australian Magpie	1
Description of Incident	Employee noted a deceased bird on bitumen road.	
Outcome	Injuries consistent with vehicular impact.	
<b>Date/Time of Incident</b>	<b>27 November 2013</b>	
Location	Boart Longyear Jetty Barge Boat bilge, Mining Lease.	
Species and number of individuals	Microbat	1
Description of Incident	An adult microbat was found deceased (advanced state), in plastic lined bilge area.	
Outcome	Injuries consistent with natural causes – hot, dry weather and reduced insect density.	
<b>Date/Time of Incident</b>	<b>12 December 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Apostlebird	1
Description of Incident	Employee noted a deceased bird on bitumen road.	
Outcome	Injuries consistent with vehicular impact.	
<b>Date/Time of Incident</b>	<b>14 December 2013</b>	
Location	Bitumen access road adjacent Pond D9, Mining Lease.	
Species and number of individuals	Brown Snake	1
Description of Incident	Employee noted a deceased snake on bitumen road.	
Outcome	Injuries consistent with vehicular impact.	
<b>Date/Time of Incident</b>	<b>16 December 2013</b>	
Location	Bitumen access road, Mining Lease.	
Species and number of individuals	Galah	1
Description of Incident	Employee noted a deceased bird on bitumen road.	
Outcome	Injuries consistent with vehicular impact.	

**Table 25 (Continued)  
Records of Fauna Deaths and Other Incidents for the Reporting Period**

<b>Date/Time of Incident</b>	<b>16 December 2013</b>	
Location	Bitumen access road near Main car park area, Mining Lease.	
Species and number of individuals	Red-rumped Parrot	1
Description of Incident	Employee noted a deceased bird on bitumen road.	
Outcome	Injuries consistent with vehicular impact.	
<b>Date/Time of Incident</b>	<b>18 December 2013</b>	
Location	Bitumen access road adjacent Pond D9, Mining Lease.	
Species and number of individuals	Cockatiel	1
Description of Incident	Employee noted a deceased bird on bitumen road.	
Outcome	Injuries consistent with vehicular impact.	

**Plate 4**

**A Freckled Duck from bottom of E42 Open Pit (*Stictonetta naevosa*) being WIRES checked.**



**(1.56 kg juvenile male. 04 February 2014 NSW WIRES Call No. GP/RIV2572).**

## **Lake Cowal Waterbird Monitoring**

Bird breeding monitoring has been conducted at Lake Cowal since 1989. The long-term monitoring of bird breeding was continued by Peter Gell from the University of Ballarat during January, August and October 2013 (potential bird breeding periods) with the results summarised in Table 26.

A summary of Professor Peter Gell's monitoring results from the 2013 reporting period is provided below.

### ***January 2013***

The first survey for 2013 was carried out between the 2 and 3 January by Peter Gell and Paul Peake. Transects 1 and 2 were surveyed on the morning of the 2nd and transects 7 and 8 on the morning of the 3rd. Waterbird breeding surveys were completed on the afternoon of 3 January. Recent rainfall was low and so the lake level had declined even further than the October survey. Even so, farm dams remained full and connected directly to the Lake and extensive areas of shallow waters existed around the lake margins. There was much less surface water across the surrounding hinterland yet Lake Nerang Cowal, while shallow, remained covered with water.

In October 2012 there was no evidence of breeding activity in the areas where colonial nesting typically occurs. On this survey, however, some nesting was observed. In the north-east section of the breeding areas, where Red Gum are mixed with Tangled Lignum, five nests of Royal Spoonbill were observed, three with large young. Also, four new Darter nests were seen along with two White Ibis nests with young. In the central section of the Lignum stand a single Royal Spoonbill nest, with eggs, was observed. Few observations of breeding activity were made during the transect surveys. A pair of Wood Duck, with five young, were observed at the northern end of transect 1 while three young Black-fronted Dotterel were seen within the sanctuary at the southern end of Transect 1.

Recent climatic conditions were very dry and so the level of Lake Cowal had fallen further since the October 2012 survey. Despite this the lake waters were deep enough for all transects to be surveyed. The reduced depth increased the extent of shallows around the margins of the lake reducing habitat for birds typical of deeper waters (e.g. Eurasian Coot and diving birds such as grebes). The shallow waters continued to provide habitat for wading birds which represented > 35% of the species observed.

Again, the highest species count was recorded on the mine site transect (T1). The species recorded around the bund wall were similar to those found on the other transects. Again, many of the other species were recorded from the sanctuary to the south of the mine attesting to the value of this reserve in supporting waterbird populations.

Colonial breeding typically commences by October each year. However, there was no evidence of colonial nesting, and limited evidence of any waterbird breeding activity. So, while the high water levels brought an expectation of extensive breeding, the fall in water level appeared sufficient to inhibit activity. The direction of water level change remains a critical predictor of colonial breeding activity. (Gell, 2013a).

**Table 26**  
**Bird Breeding Monitoring Results for the Reporting Period**

Species	2013 Survey Period												Total
	January				August				October				
	T1	T2	T7	T8	T1	T2	T7	T8	T1	T2	T7	T8	
Australian Pelican	32	4	11	3	4	57	53	12	18	56	86	1	337
Australasian Darter		2		9						1		1	13
Pied Cormorant								3					3
Little Pied Cormorant			1	1	1				1				4
Great Cormorant	4			1								1	6
Little Black Cormorant			1						3				4
Hoary-headed Grebe	3				6	4			2				15
Australasian Grebe			5										5
Black Swan				3					5	1			9
Australian Shelduck					1		4						5
Pacific Black Duck	20	6	2		4		4		15			11	62
Grey Teal	24	18	71	71	59	69	721	73	62	111	419	198	1896
Chestnut Teal													0
Water Whistling Duck				6									6
Australasian Shoveler											2		2
Pink-eared Duck							21				155		176
Hardhead			1				2						3
Australian Selduck													0
Australian Wood Duck	29		26	105	4	28	214	46	20	59	443	153	1127
Freckled Duck											8	5	13
Musk Duck							1						1
Buff-banded Rail													0
Black-tailed Native hen	3	6	414	6			5				187		621
Dusky Moorhen													0
Purple Swamphen	4		7										11
Eurasian Coot	52	30	66	60	205	387	351	97	62	70	74	113	1567
Eastern White Egret										1			1
Eastern Great Egret	1	3	2	1									7
Intermediate Egret													0
White-necked Heron	2								1				3
White-faced Heron	8	5	1	1	1	1	1		1				19
Roufous Night Heron	8	2											10
Nankeen Night-Heron													0
Glossy Ibis			8				4						12
Australian White Ibis	8	5	5									2	20
Straw-necked Ibis		1									41		42
Royal Spoonbill	1	3	3	1		1				1			10
Yellow-billed Spoonbill	5		7		3	4	3	9	3	8	6	5	53
Black Necked Stilt					3				3				6
Masked Lapwing	5	5	4	10	2		7		3	9	19	6	70
Black Fronted Dotterel	5					4	2						11
Red-kneed Dotterel			3							2			5
Silver Gull	34			3	3		26	2	4	4	8	2	86
Whiskered Tern	25	2	29	23					14	260	95		448
Gull-billed Tern													0
<b>Total</b>	<b>273</b>	<b>92</b>	<b>667</b>	<b>304</b>	<b>296</b>	<b>555</b>	<b>1419</b>	<b>242</b>	<b>217</b>	<b>587</b>	<b>1543</b>	<b>498</b>	<b>6689</b>
<b>Total Species</b>	<b>20</b>	<b>14</b>	<b>20</b>	<b>16</b>	<b>13</b>	<b>9</b>	<b>16</b>	<b>7</b>	<b>16</b>	<b>14</b>	<b>13</b>	<b>12</b>	<b>38</b>

### **August 2013**

Lake Cowal was visited on 26 and 27 August 2013. Transects 1 and 2 were surveyed on the morning of the 26th and transects 7 and 8 on the morning of the 27th. Despite recent rainfall the lake level had declined further since the January 2013 survey. Even so, the lake waters were deep enough for all transects to be surveyed. The reduced depth increased the extent of shallows around the margins of the lake reducing habitat for birds typical of deeper waters, for example diving birds such as grebes and cormorants.

This survey incorporates recommendations from the review of the Lake Cowal waterbird monitoring program (Australian Museum Business Services, 2013). So, during each transect survey data on vegetation cover were taken as well as ambient environmental data including cloud cover, wind speed and direction, air temperature, relative humidity and noise level at the beginning, and end, of each survey. The lake waters were retreating exposing mudflats which were partly colonised by herb vegetation. Inland of these mudflats exist grassy woodland with extensive weed cover.

Most birds, and the most species, were observed along transect 7 owing to the expanse of shallows – generally the most productive habitat for waterbirds - extending from the lake margin.

No colonial breeding was observed during the boat survey on August 27th. Few observations of breeding activity were made during the transect surveys: only a pair of Australian Wood Duck, with three young, observed on transect 2. Colonial breeding typically commences by October each year and so the low level of breeding activity is not unusual.

A total of 21 species (cf 30 in January 2013) were observed along transects, totalling 2512 birds, up from the 1336 birds observed in January 2013. This arrests a decline in bird richness observed on transects since August 2012 but still represents a low count relative to others this filling cycle.

The presence of large numbers of Freckled Duck in flocks is unusual at the decadal scale (observed mostly in zones B3 and B5). 400 individuals is the largest number observed in the life of this survey program and so elevates Lake Cowal as a key site for this species, at certain times (Gell, 2013b).

### **October 2013**

The final survey Lake Cowal was visited on 28 and 29 October 2013. Transects 1 and 2 were surveyed on the morning of the 26th and transects 7 and 8 on the morning of the 27th. A survey of breeding activity was made on the afternoon of the 28th. The lake level had declined further since the August 2013 survey. Even so, farm dams remained full although fewer were connected directly to the Lake. Extensive areas of shallow waters existed around the lake margins. There was little surface water across the surrounding hinterland and Lake Nerang Cowal was largely dry.

The lake waters were retreating exposing mudflats which were partly colonised by herb vegetation. Inland of these mudflats exist grassy woodland with extensive weed cover.

The bird richness observed on transects increased since August 2013 but this survey species count was the lowest for an October during this lake filling cycle.

The most common species observed continued to be Grey Teal (790 cf 922 in August) and Eurasian Coot (319 cf 1040 in August); albeit the second lowest coot numbers since August 2010. Also abundant was the Australian Wood Duck which increased further (675 cf 292 in August) to the highest numbers this filling cycle.

Numbers of cormorants and Hoary-headed Grebe remained low, while those of Australian Pelican continued to rise. Large numbers of Black-tailed Native-hen (187) were again observed on transect 7 and the number of Whiskered Tern was the highest since October 2011. The abundance of Masked Lapwing (37) was also the highest this cycle while Straw-necked Ibis were highest since January 2011. While Hardhead were absent, Pink-eared Duck returned in high numbers and Freckled Duck were recorded on transects for the first time this cycle.

In October 2013 there was no evidence of breeding activity in the areas where colonial nesting typically occurs. Few observations of breeding activity were made during the transect surveys: just a pair of Australian Wood Duck, with one young, observed on transect 2.

Climatic conditions returned to dry and so the level of Lake Cowal had fallen further since the August 2013 survey. Despite this the lake waters were deep enough for all transects to be surveyed. The reduced depth further increased the extent of shallows around the margins of the lake reducing habitat for birds typical of deeper waters (e.g. Eurasian Coot and diving birds such as cormorants and grebes). The shallow waters, particularly in transect 7, continued to provide habitat for wading birds however, in particular, the number of ducks increased to almost 60% of birds counted and Whiskered Terns increased.

Again, the highest species count was recorded on the mine site transect T1. The species recorded around the bund wall were not dissimilar to those found on the other transects. Again, many of the other species were recorded from the sanctuary to the south of the mine attesting to the value of this reserve in supporting waterbird populations. The highest number of birds was again recorded on transect 7.

Colonial breeding typically commences by October each year. However, there was no evidence of colonial nesting, and very limited evidence of any waterbird breeding activity this survey. So, low, and declining water levels inhibited breeding in what is a typical month for breeding activity (Gell, 2013c).

**Plate 5**  
**Northern Ends of Transects 1 and 7 for Waterbird Survey (October 2013)**



#### **Fauna monitoring of tailings storages and ML 1535 boundary**

Both the southern TSF and the northern TSF were active during the course of the reporting period. The NTSF was active until 17 June 2013 and then the STSF became active. The NTSF was decommissioned in June 2013 to allow for annual upstream lift project work. This included an upstream embankment raise, seepage cut-off through the Stage 3 decant causeway, and seepage cut-off down pipes around the NTSF. Fauna monitoring of the tailings storages was initiated at the time of commissioning of the TSF facilities with the twice daily fauna inspections as described in Paragraph 3.8.3.1.

Donato Environmental Services (DES) conducted a refresher training course on 30 May 2013 for the CGM Processing Plant technicians that are responsible for conducting wildlife surveys. The CGM personnel were presented with information on field survey techniques and systematic procedures for reporting observations into field data sheets. Training also included in-field observations of wildlife at active TSF and a wildlife guild identification test. DES refresher training was again conducted on 12 March 2014.

Additional to the fauna observation monitoring, bat monitoring using Anabat detectors was undertaken every evening each month during the reporting period at the active tailings facility and also at the Control site (farm homestead stock dam at 'Hillgrove' residence).

Data collected from the monitoring is stored in a database, with the information being used to assess the seasonal usage of the tailings dam, the effectiveness of hazing/deterrent techniques and to record any effects that the tailings may be having on native fauna.

Three tailings storage areas fauna usage reports were prepared by Donato Environmental Services (DES) during the reporting period being, 1 October 2012 to 31 March 2013; 1 April 2013 to 30 June 2013 and 1 July 2013 to 31 December 2013, respectively.

The main findings of the reports included:

- The cyanide discharge concentrations were below those established as a condition of operations;
- Monitoring of cyanide concentrations within the active TSF and other water bodies has been conducted frequently and at a high standard consistent with industry best practice;
- No cyanide-related wildlife mortality or effect was recorded at the TSFs;
- Considering currently accepted knowledge of cyanide toxicosis in the gold industry, the range of concentrations reported at CGM are considered benign to wildlife;
- No insectivorous bat deaths were recorded at the TSF during the current monitoring period or since systematic wildlife monitoring commenced in April 2006;
- Nocturnal surveys indicate that insectivorous bats were consistently present in the airspace above the active TSF and the control site;
- Monthly nocturnal surveying conducted at CGM represents a proactive approach to environmental monitoring and it is clearly best practice methodology employed by a gold mining operation in Australia and internationally;
- Birds were the only diurnal vertebrate wildlife recorded to visit and interact with the active TSF;
- The low cyanide concentrations recorded at the active TSF significantly reduced the risk of cyanide toxicosis to avifauna;
- The frequency of systematic wildlife surveys makes it very unlikely that cyanide-related wildlife deaths were occurring undetected;
- Rainfall patterns were not the sole influence on wildlife patterns during the reporting period; and
- Lake Cowal is considered to be a vital influence in the composition and abundance of species occurring at the CGM TSFs.

Six-monthly monitoring reports on fauna usage of the TSFs will be continued and results included in future AEMRs.

Hazing techniques were employed during the reporting period at the tailings facilities. The following different methods are utilised to deter different bird species:

- one to two radar lobe systems that detect avifauna presence at the tailings facilities;
- up to nine bird deterrent stations, activated remotely by either the radar or timer mode which broadcast bird distress calls, barking dogs, gun shots etc.;
- one to six gas cannons linked to the radar or timer-mode control station/s;
- car horns;
- solar powered scattered laser light tripod station held in safe storage to be used if required; and
- human presence.

These hazing techniques will continue to be used and monitored over the next reporting period, with new methods trialled if required.

The management measures as described in the TSMP (Barrick, 2003h) were implemented during the reporting period. Weekly visual inspections of the ML 1535 boundary fence were conducted and fence maintenance completed as necessary.

### 3.8.4 Reportable Incidents

In accordance with Development Consent Condition 3.4(a)(ii), any deaths or other incidents involving native fauna (except those attributable to physical trauma such as vehicle strike) on ML 1535 have been reported to the DTIRIS (DRE) and the EPA within 24 hours (or the next working day), and to the CEMCC as soon as practicable. All deaths or other incidents attributable to physical trauma are summarised in this report. The CEMCC requested at the meeting in December 2006 that in future they would like a summary of native fauna deaths to be provided on a quarterly basis at each meeting, rather than individual letters for each incident.

A summary of the reported native fauna deaths that occurred on ML 1535 in 2013 is provided in Table 25. Incident reports and investigations are undertaken for all native fauna deaths occurring on ML 1535 and are recorded on a site data base.

There were no alterations to any threatened fauna species reporting requirements during the reporting period.

No complaints were received relating to threatened fauna at the CGM during the reporting period.

As per 3.5.4 and 3.8.1.3 (Table 25), there was one cyanide related Silver Gull death in the Processing Plant on the 14 November 2013. The EPA, DRE and CEMCC were informed immediately by phone. There have been no cyanide related animal deaths at the CGM TSFs since operations commenced in April 2006.

### 3.8.5 Further Improvements

On-going annual training of Emergency Response and Security staff including any interested WIRES rescuers and carers from West Wyalong, will occur as required in the next reporting period. This will maintain or increase the number of staff on-site that can respond to native fauna incidents.

Further improvements in best practice avifauna deterrence will be investigated and implemented as new methods become available.

Approximately 50 mammal and bat boxes are already in position at 'Lakeside' and 'Hillgrove' and, a further 10 boxes are located on ML 1535 in the fenced forest areas. Usage of these boxes by possums, spiders, bats, galahs and other birds was observed during checks throughout 2013. A further 50 nesting/habitat boxes were manufactured locally in 2012 and are due to be installed by elevated work platform in 2014. Habitat boxes have been stored at the LCCC and shall be installed in suitable trees across 'Hillgrove' and 'Lakeside' in mid-2014.

"Beep for Birds" warning signs were installed along the bitumen access roads to the CGM in October 2010. The signs are intended to reduce the number of bird deaths on ML 1535 due to the increased number of birds in the vicinity of the ML as a result of the wet conditions experienced since mid-2010. Bird deaths on the bitumen access road of the ML remain lower than prior since the installation of the eight road signs.

## 3.9 WEEDS AND PESTS

### 3.9.1 Reporting Requirements

#### 3.9.1.1 *Development Consent*

The Land Management Plan (**LMP**) (Barrick, 2003j) was prepared in accordance with Development Consent Condition 3.10(A)(i) to provide for proper land management for all of Barrick's landholdings including the control of noxious weeds as required by the Lachlan (Riverina & Central West) Local Land Services (**LLS**) (formerly the Livestock Health and Pest Authority (**LHPA**)), Bland Shire Council (**BSC**) and DTIRIS (**DRE**). In accordance with Development Consent Condition 3.6(d)(iv) the ROMP is also required to describe measures for controlling weeds and feral pests (including both terrestrial and aquatic species) within ML 1535 and the offset areas.

In accordance with the LMP (Barrick, 2003j) and the ROMP (Barrick, 2010), general weed and pest management activities within ML 1535 and the offset areas will be reported in the AEMR. As a component of the AEMR reporting, the weed control program will be assessed for performance annually, and amended where necessary (e.g. to implement new control measures as advised by BSC or DPI [Agriculture]). Any proposed significant amendments to weed monitoring and management will be discussed with BSC.



### 3.9.1.2 *Environment Protection Licence*

Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

### 3.9.1.3 *Any Other Reporting Requirement*

There are no other relevant reporting requirements from other approvals in relation to weeds for the reporting period.

## **3.9.2 Environmental Management**

### 3.9.2.1 *Control Strategies*

In accordance with the LMP and ROMP, the control strategies for weed management on Barrick-owned land (including the offset areas) include the following:

- identification of weeds by regular and annual site inspections;
- communication with other landholders/leaseholders and regulatory authorities to keep weed management practices in line with regional weed control activities;
- mechanical removal of identified noxious weeds and/or the application of approved herbicides in authorised areas (herbicide use in wetland areas will be strictly controlled);
- implementing follow-up site inspections to determine the effectiveness of the weed control measures;
- where practicable, prevention of the establishment of new weeds on Barrick-owned land by minimising seed transport of weed species to and from the CGM through the use of a vehicle wash bay (primarily for use on agricultural and earthmoving equipment that are likely to carry weed seeds); and
- pest control activities.

The implementation of weed management strategies typically occurs according to seasonal and climatic requirements.

The pest control activities within ML 1535 and the offset areas described in the LMP and the ROMP include the following measures:

- regular property inspections to assess the status of pest populations within Barrick-owned land;
- mandatory pest control for declared pests (i.e. rabbits, pigs and wild dogs) in accordance with Pest Control Orders under the *Rural Lands Protection Act, 1998*; and
- inspections to assess the effectiveness of control measures implemented and review these if necessary.

Barrick undertakes pest control activities in conjunction with adjacent landholders for more effective pest control. This process is facilitated via consultation with local landholders and landholder groups through the CEMCC process.

The *Threat Abatement Plan for Predation by Feral Cats* (Commonwealth Department of the Environment, Water, Heritage and the Arts [DEWHA], 2008a) and the *Model Code of Practice for the Humane Control of Feral Cats* (Sharp and Saunders, 2004) will be used as a guide for the humane control of feral cats within ML 1535. The *Threat Abatement Plan for Predation by the European Red Fox* (DEWHA, 2008b) will be used to guide fox control within ML 1535.

In accordance with the LMP and ROMP, the control strategies for pest management on Barrick-owned land (including the offset areas) include those in Table 27.

**Table 27**  
**Summary of Vertebrate Pest Control Measures**

Species	Status	Method of Control <sup>2</sup>
<sup>1</sup> European Rabbit ( <i>Oryctolagus cuniculus</i> )	Declared pest	<ul style="list-style-type: none"> <li>baiting rabbits with 1080 and pindone poisoned carrot; and</li> <li>ripping of rabbit warrens.</li> </ul>
<sup>1</sup> European Red Fox ( <i>Vulpes vulpes</i> )	Nuisance animal	<ul style="list-style-type: none"> <li>fox baiting; and</li> <li>implementing a shooting programme.</li> </ul>
<sup>1</sup> Feral Cat ( <i>Felis catus</i> )	Nuisance animal	<ul style="list-style-type: none"> <li>feral cat baiting and Veterinarian euthanasure via WIRES.</li> </ul>
Feral Pig	Declared pest	<ul style="list-style-type: none"> <li>feral pig trapping.</li> </ul>
Wild Dog	Declared pest	<ul style="list-style-type: none"> <li>wild dog trapping;</li> <li>wild dog baiting with 1080; and/or</li> <li>implementing a shooting programme.</li> </ul>

Source: ROMP (Barrick, 2010)

<sup>1</sup> Recorded in the surrounding area by Cenwest Environmental Services (2009).

<sup>2</sup> NSW Livestock Health and Pest Authority (2010).

Suitable pest controls are determined in consultation with surrounding landholders, Riverina & Central West LLS and DTIRIS (DRE) prior to implementation of the pest control programme on Barrick-owned land. This assists in integrating the controls implemented on Barrick-owned land with other pest control in the local area/region.

### 3.9.2.2 Effectiveness of Control Strategies

The implementation of control strategies adequately suppressed the spread of noxious weeds and pests during the reporting period within ML 1535 and on Barrick-owned land.

Fox baiting did not occur on Barrick land during the 2013 monitoring period. 1080 Fox baiting will likely resume during 2014 when conditions are amenable. Semi-formal pest threat level dialogue was maintained with Lachlan LHPA and Central West LLS staff during the prior and current monitoring period for the observed presence of mice, foxes and locusts around Lake Cowal.

Approximately 440 mouse bait stations have been placed in and around all buildings and perimeter fences on the mining lease and Barrick-owned properties around Lake Cowal due to the mouse population increasing to plaque proportions in early-2011. Rentokil, Albury staff are contracted to restock bait stations on a fortnightly basis.

### 3.9.2.3 Variations from Proposed Control Strategies

There were no variations from the proposed control strategies during the reporting period.

During the previous reporting period, Cenwest Environmental Services was consulted in the matter of continued unwelcome nuisance numbers of Welcome Swallows in the large Mining Maintenance and Processing Warehouse Sheds. Whilst the numbers have not escalated to a significant workplace health concern the numbers continued to be monitored during 2013.

An unsuccessful Scary Man bird deterrent unit trial inside the top walkway of the Mining Maintenance Workshop Shed was decommissioned during the 2013 reporting period.

Spider spray fogging by local contractors in the same large sheds and around operations has been an effective control since 2010. This has continued in order to manage Red-back, Black and Orb spider numbers and webs.

## 3.9.3 Environmental Performance

### 3.9.3.1 Monitoring

In accordance with the LMP and the ROMP, Barrick has implemented a weed monitoring program at the CGM. Barrick-owned land including the offset areas continues to be surveyed for weeds annually. Follow-up inspections are also to be made for specific areas following the implementation of weed control measures (to assess the success of the weed controls). Follow-up inspections may also be required after control

implementation, depending on the weed species and nature of the problem. Weed monitoring is to be conducted by suitably qualified personnel from a slow moving vehicle.

Weed monitoring includes identification of:

- extent of weed occurrence (noxious or otherwise);
- details of weed distribution (i.e. locations of infested areas) and possible reasons for any infestations (e.g. a change in landuse practices);
- optimum herbicide application or physical removal timing (for implementation of controls);
- any resistance to a herbicide type or herbicide application technique (on the basis of success of previous controls); and
- identification of any new weed species that may be carried into the CGM area on vehicles accessing the site and become established near the vehicle wash-down area.

### 3.9.3.2 Performance Outcome

#### **Weed Management**

The 2013 weed survey was undertaken during December 2013 by Carnegie Natives on behalf of Barrick (Cowal) Limited. The survey involved recording the extent of weed occurrences, details of weed distribution and any new weed species infestations. Photographs, general descriptions and GPS coordinates were taken of each of the surveyed areas covering the extent of Barrick-owned land and ML 1535. Weeds of concern, those that are declared noxious in the BSC Local Government Area, and environmental weeds were targeted.

Control methods included chemical boom and spot spraying of the plants when conditions were suitable or their physical removal by manually chipping the weeds out. Weed spraying activities were carried out by a local contractor, with the measures used satisfactorily controlling any outbreaks within the site and on Barrick-owned land. During all weed control operations a registered selective herbicide was used on land above the high water mark of Lake Cowal. Some control situations required use of non-selective (knockdown) herbicides where combinations of two or more weed types were present. For weed control on the lake bed itself, physical control should be used where possible (e.g. slashing, minimal disturbance) or restrict use of herbicides registered only for use around waterways.

During 2013, CGM experienced an average winter-early spring period with monthly rainfall similar to the Wyalong Post Office (WPO) monthly average for the months of March, May and July (Table 8) assisted by June and September being significantly above the average monthly rainfall. The months of January, February, April, August, October, November and December were well below monthly average figures. Late spring and summer plant growth (including weed germination) has been limited by below average rainfall with warm weather and windy conditions combining to reduce germination of annual species and growth of perennial species.

A summary of the monitoring results from the 2012 weed survey report (Carnegie Natives, 2012) is provided below:

*Xanthium spinosum* (Bathurst Burr) is the most prevalent of the summer weeds typically growing on any disturbed soil, along roadsides, dams and around buildings. Bathurst Burr requires an ongoing control program on the ML, the adjoining properties. Areas currently requiring particular attention include the firebreaks on "Thornton", the Boneham's Lane conservation area and the Lake Cowal foreshore on all Barrick Cowal owned land. A close relative, *Xanthium occidentale* (Noogoora Burr) found on the ML along the eastern reach of the Northern Low-Flow channel and along Spring Creek on the "Lake Cowal" property appears to be controlled however, monitoring of this species must continue in these areas.

*Lycium ferocissimum* (African Boxthorn) control on the "Lake Cowal" and "Hillgrove" properties continues to reduce the prevalence of this problematic weed. During 2013 monitoring and follow-up spraying has continued on both properties timely spraying operations in March and September yielding good results. Spraying in these windows also reduces the risk of damage to desirable species due to volatilisation of the most effective chemicals used in control. All areas must continue to be monitored closely, carefully assessing kill rates due to the persistent nature of this pest. Recruitment of *Lycium ferocissimum* is persisting on the north-eastern portion of the "Hillgrove" property.

Populations of *Onopordum sp.* (Scotch Thistle) located on the ML have been reduced significantly in 2013 through strict chemical control which must be maintained as a major part of the Barrick Cowal weed control program. Small pockets of this weed continue to establish particularly on "Hillgrove" following wind dispersal of seed from primary sites.

*Marrubium vulgare* (Horehound) continues to be a target weed on the "Hillgrove" property with isolated outbreaks continuing to emerge. Monitoring for this weed must continue at this location.

*Hypericum perforatum* (St John's Wort) is a persistent problem, particularly at the Lake Cowal Grain Storage Shed and on adjacent Travelling Stock Reserve lands with current control measures containing the infestation to this area. Barrick contractors and staff from Lachlan Livestock, Health and Pest Authority (LHPA) and the Bland Shire Council (BSC) have been spraying for this weed as part of a concentrated effort to eradicate it in the shorter term.

*Sclerolaena birchii* (Galvanised Burr) prevalence has been significantly diminished as a result of Barrick's control program and the increase in groundcover due to improved seasonal conditions reducing the opportunity of bare ground for the recruitment of this pioneer species. The homestead/shed area of "Lakeside" has a concentrated outbreak requiring control during 2014.

*Proboscidea louisianica* (Purple-Flowered Devil's Claw) is a lesser problem in 2013 on the low-lying moist clay soils of the "Lake Cowal" property. Monitor and control needs to continue. *Phyla nodiflora* (Lippia) was also observed on this property at the confluence of Spring Creek and Lake Cowal. This weed presents a major concern for Lake Cowal itself as it is a vigorous weed of ephemeral wetlands without truly viable options for control. It is spread via the movement of seed and plant segments in water flows and can be transported on the feet of waterbirds.

*Centaurea solstitialis* (St. Barnaby's Thistle) continues to persist in the Southern Low-Flow channel running along the southern side of the Mine Access Road from the mine entrance to the first road bend throughout the winter months. During 2013 this area was sprayed for control and follow-up monitoring of this area is required to ensure eradication. This weed was introduced in straw which was brought in for mulching of bare soils. Future straw mulch purchases need to be restricted to suppliers of weed-free, high quality product preferably from the local area to reduce the potential for import of new weed species.

Other weeds of concern observed during the survey include:

- *Nicotiana glauca* (Tobacco Bush) at the confluence of Sandy Creek and Lake Cowal;
- *Conyza bonariensis* (Flax-Leaf Fleabane) is present across the majority of the survey area, mostly on sprayed firebreaks;
- *Centaurea melitensis* (Maltese Cockspur) is present on heavy clay soils in gilgai areas; and
- *Euphorbia sp.* (False Caper) on the roadside verge of Boneham's Lane at Lake Cowal Grain Silo area.

### **Pest Management**

During 2010, extensive control activities began to control mice populations. They were not only a visual pest (i.e. infesting work areas) but they also caused a large amount of damage, chewing through many fibre optic and other cables. Initially a small number of Talon bait stations and then Mouse-Off was used to try and control mice in offices and warehouse locations. When the mice number began to increase during daylight hours of business, Rentokil staff from Albury were engaged to promptly install an eventual 440 large bait stations using Talon XP rodenticide mouse baits in conjunction with care in maintaining a clean work environment, throughout the later part of 2010 and throughout 2011, 2012 and into 2013.

As a result, regular inspections and maintenance activities have been and will continue to be carried in an ongoing effort to contain the pest mouse populations. Live, large Black Snakes and the occasional Brown Snake have been found inside the bait boxes on multiple inspections.

A feral cat eradication program continued during 2013. Collapsible cat traps with crush end modifications (retrofitted by the West Wyalong TAFE) were purchased during 2009 and were continued to be used during the reporting period on Barrick-owned property.

Four feral cats were trapped on the mining lease in the reporting period and were taken to West Wyalong Veterinary Clinic to be assessed and euthanased.

Five Rabbits were opportunistically euthanased on site under WIRES Authority during the reporting period.

**Red Foxes**

1080 Fox baiting occurred from 27 June 2011 to end-2011. Baiting resumed May 2012 until November 2012. Due to high feed levels in the vegetated surrounding areas, no baiting was conducted during 2013 but due to a visibly increasing number of Red Foxes, baiting will likely resume during Spring 2014.

During the reporting period there were no alterations to any of the pest management requirements and the work carried out in the past few years has shown a the reduction of weeds and pests on the ML and also on the Barrick owned properties.

**3.9.4 Reportable Incidents**

The LMP and the ROMP require any incidents regarding weed and pest management to be reported in the AEMR. There were no complaints or incident reports required for weeds or pests.

**3.9.5 Further Improvements**

Review of fox, mouse and feral cat control programs will continue during the next reporting period on ML 1535 and Barrick-owned land. Rabbit baiting and warren ripping will be undertaken during the next reporting period if required, should populations be observed during regular monitoring programs.

Rentokil, Albury were contracted during the 2013 reporting period to assist Barrick in the control and eradication of pest rodent populations.

Current weed and pest monitoring will continue during the next reporting period as stated in the LMP and ROMP along with weed eradication programs across ML 1535 and Barrick-owned land.

The 2010 Lake Cowal fill event greatly reduced the area required for pest and weed control activities and could potentially concentrate pests onto Barrick owned land and reveal weed species not seen in previous years. Sustained, adaptive response weed and pest control activities will occur during the next monitoring period.

The current receding phase of lake drying exposed about six kilometres of fence line during late 2013. Fences and firebreaks were reinstated within weeks of exposure. Much of the Barrick lake floor land was shallow inundated for the 2013 reporting period.

**3.10 BLASTING****3.10.1 Reporting Requirements***3.10.1.1 Development Consent*

The modification to the CGM Development Consent (approved by the DP&I in March 2010) deleted Development Consent Condition 8.4. A revised BLMP was subsequently submitted to the Director General of the DP&I at the end of July 2010. The BLMP was revised to reflect the EPL variation (granted on 24 June 2011). The DP&I provided review comments in August 2012. The BLMP was revised to address the DP&I's comments and is currently awaiting approval.

The reporting of blasting monitoring is required by Development Consent Condition 6.3(b)(iii), which states:

- (iii) ensure that blast monitoring data is assessed regularly, and that operations are relocated, modified and/or stopped as required to ensure compliance with the relevant blast criteria;*

Development Consent Condition 3.6(a) details the blast impact assessment criteria relevant to CGM operations (as reproduced in Table 28 in Section 3.10.3).

The revised BLMP (Barrick, 2012) for the CGM requires that the AEMR reports on the following blasting related issues:

- a summary of all blast monitoring results;

- measures employed to minimise/prevent excessive blast emissions;
- blasting related complaints and amelioration measures undertaken in the event of any confirmed exceedances of blast criteria;
- review of the performance of blast control measures and the monitoring program by a suitably qualified person; and
- CEMCC decisions relating to CGM blast issues.

### 3.10.1.2 *Environment Protection Licence*

The EPL requires Barrick to undertake blast monitoring at the points identified in Licence Condition M7.

Condition R1 of the EPL requires the completion of an Annual Return comprising of a Statement of Compliance and a Monitoring and Complaints Summary at the end of each annual reporting period (i.e. the AER). Barrick submitted the Annual Return for the period 23 December 2012 to 22 December 2013 to the EPA on 20 February 2014. Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident. Condition R4.2 of the EPL requires Barrick to report any exceedances of the EPL blasting limits to the regional office of the EPA as soon as practicable after the exceedance becomes known.

Condition R4 of the EPL requires the results of the blast monitoring required by condition M7.1 to be submitted to the EPA at the end of the reporting period.

### 3.10.1.3 *Any Other Relevant Approval*

There are no other relevant reporting requirements from approvals in relation to blasting for the reporting period.

## **3.10.2 Environmental Management**

In accordance with Development Consent Condition 6.3(a) & (b), the revised BLMP and EPL Conditions L7 and M7, six blast monitors were installed at designated locations around the operation to record ground vibration and airblast overpressure. In addition, a 'control' monitor is installed at BM10 (formerly BM07), located at the main administration building.

### 3.10.2.1 *Control Strategies*

In accordance with the revised BLMP, the control strategies for blasting during the operation of the open pit include the following:

- Reducing the Maximum Instantaneous Charge (**MIC**) to lowest possible level.
- Use of crushed aggregate material for stemming in blast holes to maximise confinement of the explosives in the blast hole thereby minimising the airblast effects.
- Design of drill patterns to ensure stemming heights in the blast holes are adequate to ensure confinement of the explosives.
- Delaying or postponing blast times in unfavourable weather conditions.

Additionally Barrick has adopted a practice of spacing Pre-split and Production blasts by one to two minutes to reduce the potential for cumulative overpressure impact on the immediate surrounds of Lake Cowal. Late 2012 trialling of the covering of detonation lines with fines material did not appear to significantly reduce measured overpressure.

In accordance with Development Consent Condition 6.3(a) & (b), the revised BLMP and EPL Condition M7, airblast overpressure and ground vibration levels must be measured at nearby residences BM01, BM02 and BM03, at bird breeding areas BM04.1 and BM05 and at the general monitoring site BM06. Figure 8 shows the locations of the monitors at distances of approximately 4.5 to 9 km from the open pit.

Monitoring units located in areas that have the potential to flood have been customised so that ground vibration sensors are waterproof and airblast overpressure sensors are above the high water mark (and remained so

during the 2013 monitoring period). During early 2012, another series of rainfall events occurred which resulted in a further rise of the Lake Cowal water level and inundation of three blast monitors situated in Lake Cowal. Further improvements to the monitoring technology and height of the loggers are expected during the next reporting period.

Communication with the remote units is conducted via battery powered GSM modem fitted and recharged via solar panel. The units send data to Saros, Brisbane. All field monitoring stations are removed annually for independent off-site maintenance and calibration. Barrick previously removed the units in early February and a Saros representative re-installed them in the field in early March. A hired roving unit was maintained on-site during that time. For the past few reporting periods (since 2012), Barrick has engaged Saros to bring calibrated replacement units to Site locations and re-commission each station on the same day to minimise data loss.

### 3.10.2.2 Effectiveness of Control Strategies

The implementation of control strategies resulted in compliance with the blast impact assessment criteria (Table 28) during the reporting period. As a result, the control strategies are considered to be effective in minimising the potential impacts from blasting at the CGM. Although sixteen complaints were received during the reporting period relating to blasting (the majority of which was from one complainant)(Paragraph 4.1), monitoring results indicate that the CGM was operating in accordance with the blast impact assessment criteria defined in the Development Consent (Paragraph 3.10.3).

Notwithstanding, to improve evaluation of blast impacts on relevant privately-owned residences in the vicinity of the CGM, Barrick proposes to install a permanent blast monitor near the residence at the 'Cowel North' property (subject to approval of an EPL variation application by the EPA) during the next reporting period.

During the 2012 and 2013 reporting periods, Barrick also engaged third party consultants to conduct dilapidation surveys of relevant private residences to assist with the evaluation of potential blasting impacts from the operation of the CGM.

Barrick considers the actions and measures taken by the company have been effective in minimising/mitigating impacts from blasting at the CGM and are in accordance with the requirements of the CGM's Development Consent.

### 3.10.2.3 Variations from Proposed Control Strategies

There were no variations from the proposed control strategies.

## 3.10.3 Environmental Performance

Given the updated licence conditions, monitoring data is now divided into '*residence on privately owned land*' and '*specified sensitive locations*'. Monitoring locations BM01 (Gumbelah) and BM03 (Coniston) are categorised as '*residence on privately owned land*' and required to comply with the compliance limits specified in Condition 6.3 of the Development Consent (Table 28).. All other monitoring locations are referred to as '*specified sensitive locations*', with limits described in the BLMP.

**Table 28**  
**Blasting Impact Assessment Criteria**

<b>Location</b>	<b>Time of Blasting</b>	<b>Airblast overpressure (dB(Lin Peak))</b>	<b>Ground vibration (mm/s)</b>	<b>Allowable exceedance</b>
<i>Residence on privately owned land</i>	<i>Any time</i>	120	10	0%
	<i>Day</i>	115	5	5% of the total number of blasts over a period of 12 months
	<i>Evening</i>	105	2	
	<i>Night</i>	95	1	
	<i>Sundays and Public holidays (24 Hrs)</i>	95	1	

After extended independent monitoring and review identified no exceedances related to blasting activities at CGM, the temporary Blast Monitor (BM08) at 'Cowal North' was decommissioned and returned to Saros (26 June 2012). During the next reporting period, subject to EPL11912 variation approval, BM06 will be relocated to become BM08.1 'Cowal North'.

Administration Blast Monitor (BM07) has been moved to the east side of the E42 Pit since 09 May 2013 and re-commissioned as BM10 on a dedicated concrete pad near Pond D3. This was recommended by Saros to better define the blasting signature as the Pit becomes deeper.

Blast monitor 09 (BM09) was installed on 14 June 2012 on a 4 metre tripod in Lake Cowal on the east-west transect line between BM07 (Admin) and 'Gumbelah' (BM01).

During 26 to 27 July 2012, as a result of the inundation of Lake Cowal monitoring locations BM04, BM05 and BM06, these locations were fitted with new enhanced technology logger units atop the tripod mounts (taller mounts installed on the lake 14 - 15 June 2012).

Saros conducted a field boat based service inspection visit on 12 to 14 March 2013. Annual calibration of all fixed and roving units was performed by Saros and occurred during the period 7 to 8 October 2013, in accordance with Australian Standard 2187.1 and the manufacturer's specifications.

### **Ground Vibration**

A total of 479 blasts were fired during the period 23 December 2012 to 22 December 2013. Based on the monitoring data and blasting information available, recorded levels of ground vibration induced by blasting activities conducted at the Cowal Gold Mine were compliant with respect to the ground vibration compliance limits.

The maximum blast induced vibration level at the nearest residence was 0.30 mm/s recorded at BM03 - 'Coniston' residence on the 26 August 2013 (Saros, 2014). This level is significantly lower than compliance limit of 10 mm/s at any time.

### **Air Overpressure**

Cowal Gold Mine achieved compliance in relation to the specified airblast overpressure impact assessment criteria for the period 23 December 2012 until the 22 December 2013.

Out of a total of 479 blasts:

- No blast related events exceeded the maximum compliance level of 120dB(L);
- One blast related events exceeded the 95dB(L) level on Sundays and Public Holidays (as 95.9dB(L) at 'Gumbelah' residence on the 7 July 2013).
- Given this individual exceedance of the 95dB(L) air blast overpressure level on Sundays and Public Holidays was not more than the 5% of the total number of blasts, the CGM was in compliance with the blasting impact assessment criteria specified in Condition 6.3 of the Development Consent (Table 28).

A summary of the peak overpressure levels from individual blasts exceeding the day, evening and compliance criteria, complete with likely cause, is presented in Table 29. A detailed examination of the monitoring and blasting information was undertaken data by Saros (2014), to ascertain the peak overpressure levels recorded around the time of the specified blasts. A total of 29 events were identified as having a peak overpressure level exceeding the compliance criteria at privately-owned receivers during the reporting period.

The events have been analysed in detail to determine the likely source of overpressure. Of the 29 events that exceeded compliance levels, only 1 of these was independently determined to likely to be directly related to blasting practices and 28 of these were unable to be independently differentiated from the prevailing localised environmental factors such as wind. This has been identified by the extended durations of high overpressure readings within the 30 minute histogram blast window (Saros, 2014).

The majority of exceedances identified at blast times were related to Sunday and Public Holiday compliance limit of 95dB(L). This is to be anticipated given the Sundays' and Public Holiday's overpressure level of 95dB(L) is a significant reduction to the normal weekday and Saturday limit of 115 dB(L). It is important to note that this



20dB(L) reduction is equivalent to reducing the weekday and Saturday limit by 90% for Sunday and Public Holiday blasting (Saros, 2013).

A summary of the peak overpressure levels exceeding the compliance criteria, complete with likely cause, is presented in Table 29.

#### **3.10.4 Reportable Incidents**

During the 12 month monitoring period there was one reported incident where a unit was down for hardware issues.

- BM01- 'Gumbelah' Residence for much of January 2013.

There were 16 community complaints received related to blasting during the 2013 reporting period. A summary of the 2013 reporting year complaints is provided in Paragraph 4.1.

The CEMCC were kept informed of complaints relating to blasting overpressure during the reporting year. No additional issues or resolutions related to blasting were raised by the CEMCC during the reporting period.

#### **3.10.5 Further Improvements**

Anemometers and wind direction sensors are intended to be installed on the new enhanced loggers at each location, later during the 2014 – 2015 reporting periods. This intended to improve the determination of localised effects of weather conditions. There have been periodic issues with the new technology loggers and transmission equipment.

Under the 2012 rental agreement with Saros, incoming units (for calibration) will continue to be swapped out with 'duty' units on the same day to further minimise data loss.

During the next reporting period, subject to EPL11912 variation approval, BM06 will be relocated to become BM08.1 located near the residence on the 'Cowal North' property. BM08.1 is anticipated to improve evaluation of blast impacts on privately-owned residences in the vicinity of the CGM.

**Table 29**  
**Summary of individual blasts peak overpressure levels exceeding compliance criteria for CGM**  
**(23/12/2012 - 22/12/2013)**

Location	Date	Time	Time		Compliance Limit	Comments
			PPV (mm/s)	O'Press dB(L)		
BM03 - Coniston Residence	13/01/2013	13:20	0.09	101.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	3/03/2013	12:37	0.11	101.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	17/03/2013	12:28	0.09	100.0	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM05 – Southern Bird Breeding Area	21/03/2013	12:57	0.15	115.8	115dB(L)	Local environmental factors, unable to differentiate from background levels.
BM04.1 – Northern Bird Breeding Area	21/3/2013	12:58	0.10	115.2	115dB(L)	Local environmental factors, unable to differentiate from background levels.
BM01 - Gumbelah Residence	24/03/2013	12:26	0.11	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM01 - Gumbelah Residence	12/05/2013	12:33	0.10	102.8	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	26/05/2013	12:28	0.11	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	23/06/2013	12:57	0.07	95.7	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	23/06/2013	13:22	0.08	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM01 - Gumbelah Residence	30/06/2013	12:37	0.09	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM01 - Gumbelah Residence	07/07/2013	12:33	0.09	95.9	95dB(L) - Sundays and Public Holidays	Likely blast related.
BM01 - Gumbelah Residence	28/07/2013	13:08	0.10	101.0	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM01 – Gumbelah Residence	04/08/2013	12:38	0.09	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM01 - Gumbelah Residence	22/09/2013	12:28	0.09	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	26/09/2013	12:51	0.09	115.0	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM06 – East Lake Foreshore	26/09/2013	12:51	0.11	117.2	115dB(L)	Local environmental factors, unable to differentiate from background levels.

New EPL compliance limits with respect to residences on privately owned land, instated 24 June 2011:

- The PPV level of 5mm/s for ground vibration during the day may be exceeded for up to 5% of the total number of blasts for a period of 12 months. The level should not exceed 10mm/s at any noise sensitive location;
- The air blast overpressure level of 115dB (Linear Peak) during the day may be exceeded for up to 5% of the total number of blasts for a period of 12 months. The level should not exceed 120dB (Linear Peak) at any noise sensitive location; and
- The airblast overpressure level of 95dB (Linear Peak) on Sundays (24 hours) and Public Holidays (24 hours) may be exceeded for up to 5% of the total number of blasts for a period of 12 months.

**Table 29 (Continued)**  
**Summary of individual blasts peak overpressure levels exceeding compliance criteria for CGM**  
**(23/12/2012 - 22/12/2013)**

Location	Date	Time	Time		Compliance Limit	Comments
			PPV (mm/s)	O'Press dB(L)		
BM01 - Gumbelah Residence	6/10/2013	12:33	0.10	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	6/10/2013	12:52	0.09	98.8	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM06 – East Lake Foreshore	10/10/2013	12:30	0.09	116.9	115dB(L)	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	13/10/2013	12:34	0.10	100.0	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM06 – East Lake Foreshore	17/10/2013	12:32	0.09	117.7	115dB(L)	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	20/10/2013	12:31	0.09	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	3/11/2013	12:40	0.09	97.5	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	9/11/2013	12:44	0.09	101.0	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	24/11/2013	12:29	0.09	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	1/12/2013	13:01	0.10	95.9	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.
BM06 – East Lake Foreshore	4/12/2013	12:47	0.17	115.2	115dB(L)	Local environmental factors, unable to differentiate from background levels.
BM03 - Coniston Residence	22/12/2013	12:43	0.13	115.0	95dB(L) - Sundays and Public Holidays	Local environmental factors, unable to differentiate from background levels.

New EPL compliance limits with respect to residences on privately owned land, instated 24 June 2011:

- The PPV level of 5mm/s for ground vibration during the day may be exceeded for up to 5% of the total number of blasts for a period of 12 months. The level should not exceed 10mm/s at any noise sensitive location;
- The air blast overpressure level of 115dB (Linear Peak) during the day may be exceeded for up to 5% of the total number of blasts for a period of 12 months. The level should not exceed 120dB (Linear Peak) at any noise sensitive location; and
- The airblast overpressure level of 95dB (Linear Peak) on Sundays (24 hours) and Public Holidays (24 hours) may be exceeded for up to 5% of the total number of blasts for a period of 12 months.

### 3.11 OPERATIONAL NOISE

#### 3.11.1 Reporting Requirements

##### 3.11.1.1 Development Consent

The management and reporting of noise monitoring is required by Development Consent Condition 6.4(g), which states:

#### **Noise Management Plan**

6.4(g) *The Applicant shall prepare and implement a Noise Management Plan for the project in consultation with EPA and to the satisfaction of the Director-General. This plan must be submitted to the Director-General for approval by the end of July 2010 and include provisions to:*

- (i) *evaluate noise impacts on privately-owned residences*
- (ii) *demonstrate compliance with the noise impact assessment criteria in Table 8;*
- (iii) *implement all reasonable and feasible noise mitigation measures;*
- (iv) *investigate ways to reduce the noise generated by the project, including:*
  - *off-site road noise; and*
  - *noise levels which may result in sleep disturbance and disturbance to bird breeding behaviour; and*
- (v) *report on these investigations and the implementation and effectiveness of these measures in the AEMR.*

As described in Section 1.1.2, the modification to the CGM Development Consent (approved by the former DoP in March 2010) updated Development Consent Condition 6.4 relevant to noise. Subsequently, in accordance with Development Consent Condition 6.4(g), a revised NMP was developed for the CGM and was submitted to the Director-General of the former DoP at the end of July 2010. The DP&I provided review comments on the NMP on 14 August 2012. Barrick subsequently revised the NMP to address the DP&I's review comments and submitted the revised NMP to DP&I for approval on 24 December 2012. Barrick is currently awaiting approval of the revised NMP.

The modification to the CGM Development Consent (approved by the DP&I in March 2010) requires the management and reporting of traffic noise monitoring and truck movements in accordance with Development Consent conditions 6.4(d) and (e), which provide:

- (d) *The Applicant shall take all reasonable and feasible measures to ensure that traffic noise generated by the project does not exceed the traffic noise impact assessment criteria in Table 9.*

Table 9: Traffic noise criteria dB(A)  $L_{Aeq}$  (1 hour)

Road	Day/Evening	Night
Ungarie Road	60	55
Wamboyne Road, Blow Clear Road, Carrawandool-Warroo Road, Burcher Road, Condobolin Road, Lake Cowal Road	55	50

Note: *Traffic noise generated by the project is to be measured in accordance with the relevant procedures in EPA's Environmental Criteria for Road Traffic Noise.*

- (e) *Truck movements for material delivery purposes will be restricted as far as practicable to the day and evening periods.*

The relevant components of the former Traffic Noise Management Plan (**TNMP**) have been incorporated into the revised NMP (submitted to the Director-General of the DP&I for approval in December 2012, in accordance with Development Condition 6.4[g]). Following approval of the revised NMP, the TNMP will not be necessary.

SLR Consulting was engaged to conduct mine operating noise and traffic noise monitoring during the reporting period and in accordance with the NMP.

Noise monitoring was undertaken during the reporting period to demonstrate compliance with the noise impact assessment criteria set out in Development Consent Condition 6.4(c), which requires that noise generated by the CGM does not exceed the criteria in Table 29 below, at any residence on privately-owned land, or on more than 25 percent of privately owned land not located within Lake Cowal.

**Table 30**  
**Noise Impact Assessment Criteria dB(A) L<sub>Aeq</sub> (15minute)**

Location	Day/Evening/Night <sup>1</sup>
Bungabulla	39
Coniston	44
Cowal North	38
Gumbelah	39
Lake Cowal (non-Barrick)	38
Laurel Park	39
Mattiske	36
McLintock	41
The Glen	38
West Lea	41
All other residences	35

Notes:

- To interpret the locations referred to in Table 30, see Figure 8.
- Noise generated by the project is to be measured in accordance with the relevant requirements, and exemptions (including certain meteorological conditions), of the NSW Industrial Noise Policy.
- The noise limits do not apply if the Applicant has an agreement with the relevant owner/s of these residences/land to generate higher noise levels, and the Applicant has advised the Department of Planning in writing of the terms of this agreement.
- <sup>1</sup>Mine noise emission criteria – applicable to condition 6.3(a) of the March 2010 modified development consent

### 3.11.1.2 Environmental Protection Licence

As described in Paragraph 3.11.1.1, the modification lodged in January 2009 sought changes to the Development Consent, to contemporise the Development Consent and for consistency with the EPL and Industrial Noise Policy (INP). The application to modify the Development Consent was approved by the Minister for Planning on 11 February 2009. The NMP was revised/up-dated during 2009 to reflect the approved modifications. The revised NMP was approved on 8 April 2010.

The modification to the CGM Development Consent (approved by the DP&I in April 2010) again revised the Development Consent Conditions relating to noise. A revised NMP was subsequently submitted to the Director-General of the DP&I at the end of July 2010, in accordance with Development Consent Condition 6.4(g). The DP&I provided review comments on the NMP on 14 August 2012. Barrick subsequently revised the NMP to address the DP&I's review comments and submitted the revised NMP to DP&I for approval on 24 December 2012. Barrick is currently awaiting approval of the revised NMP.

An application to vary the EPL to reflect the modifications to the Development Consent was prepared during the 2011 reporting period and the application was approved by the DP&I on 20 June 2011.

### 3.11.1.3 Any Other Relevant Approval

There are no other relevant reporting requirements from approvals in relation to noise for the reporting period.

## 3.11.2 Environmental Management

### 3.11.2.1 Control Strategies

In accordance with the NMP, control strategies used at the CGM during the reporting period (for operational activities) utilised best management practices and the best available technology economically achievable.

#### **Best Management Practice**

Best management practices applied during the reporting period to minimise CGM noise emissions include:

- restricting movement of trucks on ridgelines and exposed haul routes where their noise can propagate over a wide area, especially at night. This means restricting night-time movement of material to areas shielded by

barriers or mounds, and reserving large-scale material movement for daytime. The LPB provides noise shielding, thereby reducing noise levels that could propagate from the open pit across Lake Cowal;

- scheduling the use of any noisy equipment during daytime;
- sighting noisy equipment behind structures that act as barriers, or at the greatest distance from the noise-sensitive area, or orienting the equipment so that noise emissions are directed away from any sensitive areas, to achieve the maximum attenuation of noise;
- where there are several noisy pieces of equipment, scheduling operations so they are used separately rather than concurrently;
- keeping equipment well maintained;
- employing 'quiet' practices when operating equipment (e.g. positioning idling trucks in appropriate areas);
- educating staff on the effects of noise and the use of quiet work practices;
- specify maximum noise/sound levels when purchasing equipment; and
- including maximum noise/sound levels in tender documents and contracts.

#### ***Best Available Technology Economically Achievable***

Best available technology economically achievable that may be applied to minimise CGM noise emissions during the reporting period include:

- adjusting reversing alarms on heavy equipment limiting acoustic range to the immediate danger area;
- minimising night time tracking of dozers on top of stockpiles;
- restricting working hours on faces closest to neighbours during wall lift project works;
- using equipment with efficient mufflers;
- damping or lining metal trays on Dump Trucks; and/or
- employing active noise control measures during normal and maintenance shutdown periods.

#### *3.11.2.2 Effectiveness of Control Strategies*

In accordance with the NMP, Barrick continued to implement the control strategies described above during the reporting period. These measures were considered effective in minimising noise emissions from the CGM, as demonstrated by the environmental performance results discussed in Paragraph 3.11.3 below.

Although two complaints were received during the reporting period relevant to operational noise (from the one complainant), results of independent third party noise monitoring indicated that the CGM was operating in accordance with the relevant Development Consent noise criteria (Section 3.11.3).

In addition to the control strategies implemented on-site, during the reporting period Barrick sought to enter Noise Mitigation Agreements with relevant landholders in accordance with procedures defined in the CGM's Development Consent. These Agreements involved Barrick agreeing to implement various measures at relevant residences to mitigate/minimise noise impacts associated with operation of the CGM. These measures included installation of air conditioning and/or double glazed windows at these residences.

Since the measures were implemented and the Agreements settled, complaints regarding operational noise have reduced. Barrick considers the actions and measures taken by the company have been effective and are in accordance with the requirements of the CGM's Development Consent.

#### *3.11.2.3 Variations from Proposed Strategies*

There were no variations from the proposed control strategies during the reporting period.

### 3.11.3 Environmental Performance

#### 3.11.3.1 Monitoring

The daytime, evening and night-time operator-attended mine operating noise surveys were conducted in February 2013 (A), and in August 2013 (B) by SLR Consulting with field assistance by the CGM Environmental Department. The survey results are presented together with the respective noise criteria in the NMP, determined in accordance with the NSW INP.

No non-compliances of the noise impact assessment criteria specified in the Development Consent were reported during the reporting period.

#### 3.11.3.2 Daytime Operator-attended Noise Survey Results

Daytime operator-attended mine operating noise surveys were conducted in February 2013 (A), and August 2013 (B). A summary of the survey results is presented in Table 31, together with the respective noise criteria.

**Table 31**  
**Daytime Noise Emission Levels  $L_{Aeq(15minute)}$**

Location	Address	Mine Contributed $L_{Aeq(15minute)}$	Mine Contributed $L_{Aeq(15minute)}$	Noise Impact Assessment Criteria <sup>4</sup> $L_{Aeq(15minute)}$
		A (dBA)	B (dBA)	
No.1	New Lake Foreshore	19, 20	36, 39	N/A <sup>3</sup>
No.2	'Coniston' Residence	<23, <22	N/A <sup>1</sup> , N/A <sup>1</sup>	44 dBA
No.3	Bird Breeding Area (South)	<18, <18	37, 37	N/A <sup>3</sup>
No.4	Bird Breeding Area (North)	<18, <18	24, 25	N/A <sup>3</sup>
No.5	'Gumbelah' Residence	<22, <22	29, 30	39 dBA
No.6	'Lake Cowal' Residence	<23, 22	N/A <sup>1</sup> , N/A <sup>1</sup>	N/A <sup>5</sup>
No. 7	'West Lea' Property	<29, 24	N/A <sup>1</sup> , N/A <sup>1</sup> , 38 <sup>4</sup>	41 dBA
No. 8	'McLintock' Property	22, 24	N/A <sup>1</sup> , N/A <sup>1</sup>	41 dBA
No. 9	"Cowan North" Residence	<23, <23	N/A <sup>1</sup> , N/A <sup>1</sup>	38 dBA

Note:

N/A<sup>1</sup> - Mine noise emission not discernible.

N/A<sup>2</sup> - No Survey Conducted. Inaccessible and/or adverse weather during test period.

N/A<sup>3</sup> - Mine noise emission criteria apply to residences only

N/A<sup>4</sup> - Digital audio Recordings Analysis

N/A<sup>5</sup> - Mine owned property

According to the Industrial Noise Policy Section 11.1.3, non-compliances with Noise Conditions states "A development will be deemed to be in non-compliance with a noise consent or licence condition if the monitored noise level is more than 2 dB above the statutory noise limit specified in the consent or licence condition". It follows that the mine noise emissions of 42 dBA and 43 dBA at location No. 7 would not be considered a non-compliance with the noise criterion of 41 dBA. Furthermore, the day-time noise level of 43 dBA coincided with a south south-easterly wind at a mean wind speed of 3.9m/s and is therefore outside the assessable weather conditions determined in accordance with the consent.

#### 3.11.3.3 Evening Operator-attended Noise Survey Results

Evening operator-attended mine operating noise surveys were conducted in February 2013 (A), and August 2013 (B). A summary of the survey results are presented in Table 32 together with the respective noise criteria.

**Table 32**  
**Evening Noise Emission Levels  $L_{Aeq(15\text{minute})}$**

Location	Address	Mine Contributed $L_{Aeq(15\text{minute})}$	Mine Contributed $L_{Aeq(15\text{minute})}$	Noise Impact Assessment Criteria <sup>4</sup> $L_{Aeq(15\text{minute})}$
		A (dBA)	B (dBA)	
No. 1	New Lake Foreshore	19, 19	36, 37	N/A <sup>3</sup>
No. 2	'Coniston' Residence	19, <19	N/A <sup>1</sup> , 26	44 dBA
No. 3	Bird Breeding Area (South)	N/A <sup>2</sup> , N/A <sup>2</sup>	N/A <sup>2</sup> , N/A <sup>2</sup>	N/A <sup>3</sup>
No. 4	Bird Breeding Area (North)	N/A <sup>2</sup> , N/A <sup>2</sup>	N/A <sup>2</sup> , N/A <sup>2</sup>	N/A <sup>3</sup>
No. 5	'Gumbelah' Residence	<23, <37	34, 34	39 dBA
No. 6	'Lake Cowal' Residence	18, 20	N/A <sup>1</sup> , <18	N/A <sup>5</sup>
No. 7	'West Lea' Property	24, 27	N/A <sup>1</sup> , N/A <sup>1</sup>	41 dBA
No. 8	'McLintock' Property	22, 23	N/A <sup>1</sup> , N/A <sup>1</sup>	41 dBA
No. 9	"Cowan North" Residence	<34, <33	N/A <sup>1</sup> , N/A <sup>1</sup>	38 dBA

Note:

N/A<sup>1</sup> - Mine noise emission not discernible.

N/A<sup>2</sup> - No Survey Conducted. Inaccessible and/or adverse weather during test period.

<sup>3</sup> - Mine noise emission criteria apply to residences only

<sup>4</sup> - Digital audio Recordings Analysis

<sup>5</sup> - Mine owned property

During the February 2013 (A), and August 2013 (B) monitoring periods, the measured evening mine noise emissions at the residential dwellings were below the applicable evening intrusive  $L_{Aeq(15\text{minute})}$  criteria

#### 3.11.3.4 Night-time Operator-attended Noise Survey Results

Night-time operator-attended mine operating noise surveys were conducted in February 2013 (A), and August 2013 (B). A summary of the survey results are presented in Table 33 together with the respective noise criteria.



**Table 33**  
**Night-time Noise Emission Levels  $L_{Aeq(15minute)}$**

Location	Address	Mine Contributed $L_{Aeq(15minute)}$	Mine Contributed $L_{Aeq(15minute)}$	Noise Emission Criteria <sup>4</sup> $L_{Aeq(15minute)}$
		A (dBA)	B (dBA)	
No.1	New Lake Foreshore	34, 22	32, 33	N/A <sup>3</sup>
No.2	'Coniston' Residence	<15, <12	29, 28	44 dBA
No.3	Bird Breeding Area (South)	N/A <sup>2</sup> , N/A <sup>2</sup>	N/A <sup>2</sup> , N/A <sup>2</sup>	N/A <sup>3</sup>
No.4	Bird Breeding Area (North)	N/A <sup>2</sup> , N/A <sup>2</sup>	N/A <sup>2</sup> , N/A <sup>2</sup>	N/A <sup>3</sup>
No.5	'Gumbelah' Residence	20, 23	35, 33	39 dBA
No.6	'Lake Cowal' Residence	28, 27	27, 27	N/A <sup>5</sup>
No. 7	'West Lea' Property	24, 23	30, 32	41 dBA
No. 8	'McLintock' Property	<25, <25	28, 28	41 dBA
No. 9	"Cowan North" Residence	16, 19	N/A <sup>1</sup> , N/A <sup>1</sup>	38 dBA

Note:

N/A<sup>1</sup> - Mine noise emission not discernible.

N/A<sup>2</sup> - No Survey Conducted. Inaccessible and/or adverse weather during test period.

<sup>3</sup> - Mine noise emission criteria apply to residences only

<sup>4</sup> - Digital audio Recordings Analysis

<sup>5</sup> - Mine owned property

During the February 2013 (A), and August 2013 (B) monitoring periods, the measured night-time mine noise emissions at the residential dwellings were below the applicable intrusive  $L_{Aeq(15minute)}$  criteria.

### 3.11.3.5 Unattended Continuous Noise Logging

Unattended continuous noise loggers were positioned at all monitoring locations from 4 to 15 February 2013 and from 14 to 29 August 2013. The loggers were used to quantify the ambient noise environment in the vicinity of CGM.

A summary of the results is presented below:

- All operator attended noise recordings in February 2013 and August 2013 were measured to be below the Consent criteria during all periods of the day at all locations monitored. Consequently, the CGM was observed to be in compliance with the relevant noise requirements during all periods of the operator-attended noise monitoring (SLR, 2013).

### 3.11.3.6 Operator-attended and Unattended Traffic Noise

In addition to the operational noise monitoring, SLR Consulting were engaged during the reporting period to conduct mine traffic noise surveys in accordance with the NMP.

The following monitoring locations were selected in the (pre-construction) Baseline Traffic Noise Assessment. These locations were and remain to be representative of the locality types which are potentially impacted along the access route between the CGM and West Wyalong. In addition, unattended continuous noise loggers were positioned at the three monitoring locations:

- TN1 140 Ungarie Road, West Wyalong (near intersection with Dumaresq Street)  
Offset distance from the road – 30 m
- TN2 “Clairview”, 56 – 86 Wamboyne Road  
Offset distance from the road – 45 m
- TN3 “Windstone”, 648 Wamboyne Road  
Offset distance from the road – 150 m

To quantify overall ambient and traffic noise levels during mine operations, operator attended traffic noise measurements were conducted at the three monitoring locations, listed above, during the morning and evening peak-traffic movement periods on 4 to 6 February 2013.

To quantify traffic volumes and determine peak traffic periods, three automatic traffic counters (ATCs) were deployed to determine overall traffic volumes, peak traffic periods as well as vehicle speeds. The ATCs were deployed for a two week period from 4 February 2013.

To accurately identify CGM vehicles, video cameras that enabled the capture of vehicle number plates were installed at five locations. The cameras were set to record videos of the pass-by traffic during morning and afternoon peak hours over three days (4 to 6 February 2013). Cameras were located at the following locations:

- TN1 140 Ungarie Road;
- TN2 50 metres south of “Clairview”, Wamboyne Road;
- TN3 “Windstone”, 648 Wamboyne Road; and
- At the two CGM entry/ exit sites.

Weather analysis was conducted in order to determine if weather conditions were a significant variable in the noise levels recorded. The analysis found that weather conditions were not a significant variable in the traffic noise levels recorded (SLR, 2013).

Traffic count data showed that the morning peak traffic period was from 0600 hours to 0730 hours, and the evening peak traffic period from 1600 hours to 1900 hours at TN1 and from 1730 hours to 1900 hours at the other two locations. The ambient LAeq (1hour) noise levels and corresponding calculated LAeq (1hour) traffic noise contribution at TN1 ‘140 Ungarie Road’ are presented in Table 34, together with the respective vehicle counts.

**Table 34**  
**Operator-attended Traffic Noise Emission Survey Results (February 2013)**  
**TN 1 - 140 Ungarie Road**

Date	Time	Mine Traffic Criteria	Traffic Counts			Traffic Noise Levels (Calculated)				Unattended (Overall)
			Total	Non-Mine	Mine	Total	Non-Mine	Mine	Mine Exceedances	
<b>Daytime Peak (1700 hours to 1900 hours)</b>										
Tuesday 5 February	1700-1800	60	155	81	74	57	54	53	-	59
	1800-1900	60	91	44	47	56	54	52	-	58
Wednesday 6 February	1700-1800	60	165	87	78	59	56	56	-	59
	1800-1900	60	85	45	40	55	51	52	-	56
Thursday 7 February	1700-1800	60	147	82	65	57	55	52	-	59
	1800-1900	60	98	61	37	56	54	51	-	58
Three-Day Average	1700-1800	60	156	83	72	58	55	54	-	59
	1800-1900	60	91	50	41	56	53	51	-	57
<b>Night-time Peak (0500 hours to 0700 hours)</b>										
Tuesday 5 February	0500-0600	55	52	12	40	54	49	52	-	54
	0600-0700	55	126	50	76	58	55	56	1	58
	0700-0800	55	76	52	24	57	55	53	-	57
Wednesday 6 February	0500-0600	55	43	10	33	53	47	52	-	53
	0600-0700	55	134	63	71	58	56	54	-	58
	0700-0800	55	96	67	29	58	56	54	-	58
Thursday 7 February	0500-0600	55	52	14	38	56	53	54	-	56
	0600-0700	55	127	57	70	57	54	54	-	57
	0700-0800	55	83	64	19	57	55	50	-	57
Three-Day Average	0500-0600	55	49	12	37	55	50	53	-	54
	0600-0700	55	129	57	72	58	55	55	-	58
	0700-0800	55	85	61	24	57	55	52	-	57

### TN1 140 Ungarie Road

The three day average calculated LAeq(1hour) mine generated traffic noise at TN1 during the daytime peak (1700 hours to 1800 hours) is 54 dBA (ie below the 60 dBA criterion). The three day average calculated LAeq(1hour) mine generated traffic noise at TN1 during the night-time peak (0600 hours to 0700 hours) is 55 dBA which meets the 55 dBA criterion.

Furthermore, dwellings located within the 37m of Ungarie Road may potentially receive traffic noise levels in excess of 55 dBA during the night-time peak hour. Based on the NMP, approximately 8 dwellings are located within 37 m from Ungarie Road. The nearest dwelling being approximately 30m from Ungarie Road where the mine generated traffic noise is likely to meet the 55 dBA criterion (SLR, 2013).

The ambient LAeq (1hour) noise levels and corresponding calculated LAeq (1hour) traffic noise contribution at TN2 'Clairview' are presented in Table 35, together with the respective vehicle counts.

**Table 35**  
**Operator-attended Traffic Noise Emission Survey Results (February 2013)**  
**TN2 - 'Clairview' Residence**

Date	Time	Mine Traffic Criteria	Traffic (identification)		Counts Mine	Traffic (Calculated)		Noise Levels		Unattended Overall
			Total	Non-Mine		Total	Non-Mine	Mine	Mine Exceedances	
<b>Day-time Peak (1700 hours to 1900 hours)</b>										
<b>Tuesday</b> <b>5 February</b>	1700-1800	55	91	21	70	52	46	50	-	-
	1800-1900	55	59	4	55	48	36	48	-	-
<b>Wednesday</b> <b>6 February</b>	1700-1800	55	84	26	58	52	47	50	-	-
	1800-1900	55	46	1	45	48	37	48	-	-
<b>Thursday</b> <b>7 February</b>	1700-1800	55	71	15	56	51	46	50	-	-
	1800-1900	55	44	5	39	48	37	48	-	-
<b>Three-Day Average</b>	1700-1800	55	82	21	61	52	47	50	-	-
	1800-1900	55	50	3	46	48	37	48	-	-
<b>Night-time Peak (0500 hours to 0700 hours)</b>										
<b>Tuesday</b> <b>5 February</b>	0500-0600	50	53	0	53	52	0	52	2	-
	0600-0700	50	79	5	74	53	40	52	2	-
	0700-0800	50	27	15	12	49	46	46	-	-
<b>Wednesday</b> <b>6 February</b>	0500-0600	50	36	1	35	49	34	49	-	-
	0600-0700	50	80	3	77	53	42	53	3	-
	0700-0800	50	45	14	31	51	48	49	-	-
<b>Thursday</b> <b>7 February</b>	0500-0600	50	41	4	37	50	41	49	-	-
	0600-0700	50	94	1	93	54	33	54	4	-
	0700-0800	50	27	3	24	49	38	48	-	-
<b>Three-Day Average</b>	0500-0600	50	43	2	42	50	37	50	-	-
	0600-0700	50	94	1	93	53	40	53	3	-
	0700-0800	55	33	11	22	50	45	48	-	-

#### TN2 'Clareview' Residence, Wamboyne Road

The three day average calculated LAeq (1hour) mine generated traffic noise at TN2 during the daytime peak (1700 hours to 1800 hours) is 50 dBA (ie below the 55 dBA criterion). The three day average calculated LAeq (1hour) mine generated traffic noise at TN2 during the night time peak (0600 hours to 0700) is 53 dBA which is moderately (3 dBA) above the 50 dBA criterion (SLR, 2013).

The ambient LAeq (1hour) noise levels and corresponding calculated LAeq (1hour) traffic noise contribution at TN3 'Windstone' are presented in Table 36, together with the respective vehicle counts.

**Table 36**  
**Operator-attended Traffic Noise Emission Survey Results (February 2013)**  
**TN3 - 'Windstone' Residence**

Date	Time	Mine Traffic Criteria	Traffic Counts (identification)			Traffic (Calculated)		Noise Levels		Unattended Overall
			Total	Non-Mine	Mine	Total	Non-Mine	Mine	Mine Exceedances	
<b>Day-time Peak (1700 hours to 1900 hours)</b>										
<b>Tuesday</b> <b>5 February</b>	1700-1800	55	91	23	68	49	43	48	-	49
	1800-1900	55	61	3	58	47	37	47	-	58
<b>Wednesday</b> <b>6 February</b>	1700-1800	55	88	27	61	47	41	45	-	47
	1800-1900	55	45	4	41	47	38	46	-	47
<b>Thursday</b> <b>7 February</b>	1700-1800	55	71	14	57	47	39	46	-	47
	1800-1900	55	47	4	43	45	33	45	-	45
<b>Three-Day Average</b>	1700-1800	55	83	21	62	48	41	47	-	48
	1800-1900	55	51	4	47	46	36	46	-	50
<b>Night-time Peak (0500 hours to 0700 hours)</b>										
<b>Tuesday</b> <b>5 February</b>	0500-0600	50	51	0	51	44	-2	44	-	44
	0600-0700	50	81	10	71	47	40	46	-	47
	0700-0800	50	26	0	26	45	0	45	-	56
<b>Wednesday</b> <b>6 February</b>	0500-0600	50	36	3	33	45	34	45	-	45
	0600-0700	50	85	2	83	49	36	49	-	49
	0700-0800	50	40	11	29	47	43	45	-	50
<b>Thursday</b> <b>7 February</b>	0500-0600	50	41	1	40	46	29	46	-	46
	0500-0600	50	92	3	89	50	34	49	-	50
	0500-0600	50	31	6	25	46	41	45	-	54
<b>Three-Day Average</b>	0500-0600	50	43	1	41	45	30	45	-	45
	0500-0600	50	92	3	89	49	37	48	-	49
	0500-0600	50	32	6	27	46	40	45	-	53

### TN3 'Windstone' Residence, Wamboyne Road

The three day average calculated LAeq (1hour) mine generated traffic noise at TN3 during the daytime peak (1700 hours to 1800 hours) is 47 dBA (ie below the 55 dBA criterion). The three day average calculated LAeq (1hour) mine generated traffic noise at TN2 during the night time peak (0600 hours to 0700) is 48 dBA which is below the 50 dBA criterion.

Furthermore, dwellings located within 64 m of Wamboyne Road may potentially receive traffic noise levels in excess of 50 dBA during the early night-time peak hour. Based on the NMP (Barrick, 2012), approximately two dwellings are located within 64 m from Wamboyne Road. The nearest dwelling being 'Clareview' (TN2) where the mine generated traffic noise has been recorded up to 4 dBA above the relevant traffic assessment criterion during the night-time peak (SLR, 2013).

Although exceedances were recorded during the traffic noise surveys, they have not coincided with complaints from the occupants of this (or any other) residence regarding traffic noise. Accordingly, the complaint validation monitoring process documented in the NMP was not enacted during the reporting period.

### Traffic Noise Agreements

Barrick entered into Traffic Noise Agreements in August 2012 with residents who may potentially be affected by traffic noise attributable to the mine traffic with the following proposal.

The Agreement letters were signed by each of the landowners notified, and the Director-General of DP&I was notified of the terms of agreement on 3 September 2012.

#### **3.11.4 Reportable Incidents**

There were three community complaints received during the reporting period relating to operational or traffic noise. Details of the relevant complaints are provided in Paragraph 4.1.

#### **3.11.5 Further Improvements**

During the next monitoring period, the annual traffic and six monthly operational noise monitoring 14 day survey periods will continue to be reviewed for optimum offset to any public holidays and thereby reflect normal road use periods.

### **3.12 VISUAL, STRAY LIGHT**

#### **3.12.1 Reporting Requirements**

##### *3.12.1.1 Development Consent*

In accordance with the Landscape Management Plan (**LSMP**) (Barrick, 2003m), the following visual issues are required to be reported in the AEMR:

- landscaping, rehabilitation and building, works and structure maintenance measures (including the reporting of any related complaints);
- contingent planting of additional screening vegetation on Barrick owned land in consultation with the CGM CEMCC on an as needs basis; and
- any additional planting on neighbouring properties if required, in consultation with the affected landholder.

As described in the currently approved CGM MOP (October 2012 to January 2014) the relevant components of the LSMP have been incorporated into the ROMP. Following approval of the ROMP by the DP&I, the LSMP will not be necessary.

In accordance with Development Consent Condition 3.6(d)(iv), the ROMP includes a description of landscaping measures that will be undertaken to minimise visual impacts of the CGM.

In addition, Development Consent Condition 6.5 requires:

*The Applicant shall take all reasonable and feasible measures, in consideration of Australian Standard AS 4282-1997 Control of the obtrusive effects of outdoor lighting, to mitigate visual and off-site impacts of the project, to the satisfaction of the Director-General.*

##### *3.12.1.2 Environment Protection Licence*

Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

##### *3.12.1.3 Any other Relevant Approval*

There are no other relevant reporting requirements from approvals in relation to landscaping and visual impact for the reporting period.

#### **3.12.2 Environmental Management**

##### *3.12.2.1 Control Strategies*

In accordance with Development Consent Condition 3.6(d)(iv), the LSMP and the ROMP, Barrick used the landscaping strategies/control measures outlined below to minimise visual impacts from the mine site.

#### ***Progressive Rehabilitation***

Progressive rehabilitation of areas of the perimeter waste emplacements and tailings storage facilities was undertaken during the reporting period to reduce the contrast between the CGM landforms and the surrounding landscape. This included progressive rehabilitation with selected grass, shrub and/or tree species.

The final void is screened from public views on Lake Cowal Road by the tailings storage facilities and waste emplacements.

#### ***Foreground Visual Screening/Vegetation Screens***

Earth mounds have been constructed on sections of the western and northern boundaries of ML 1535 to break up continuous views from Lake Cowal Road. These earth mounds and vegetation screen areas surrounding ML 1535 (including along Lake Cowal Road) have been planted with endemic plants that are compatible with the existing surrounding vegetation.

Maintenance of the vegetation screens (e.g. addition and replacement of plants, where required) will continue to be undertaken in these areas during the next reporting period. An increase in screening effect will result over time as plants continue to grow.

Visual impact mitigation measures that have been employed at CGM included landscaping and design specifically conducted for visual impact mitigation purposes. Specific landscaping strategies included:

- utilising existing vegetation as visual screens;
- planted vegetation screens around the ML 1535 boundary;
- construction of PWE, reducing visual impact of processing plant from the eastern side of Lake Cowal;
- placement of topsoil stockpiles on the southern and western sides of the STSF to break up the view from the relocated Travelling Stock Route;
- lighting design (such as directional lighting) to reduce any potential impacts of night lighting on wildlife and nearby residences; and
- selecting the colour of the processing plant buildings to blend with the adjacent landscape in accordance with the requirements of BSC.

#### ***Night Lighting***

Barrick has employed one or more of the following measures to mitigate impacts from night-lighting, where practicable:

- Scheduling of mining operations, where practicable, so that evening and night-time operations on the waste emplacements will be located on the southern waste emplacement (i.e. the lower waste emplacement) to reduce the potential for direct lighting impacts to locations north of ML 1535.
- Restriction of night-lighting to the minimum required for operations and safety requirements, where appropriate.
- Use of unidirectional lighting techniques, where practicable.

#### ***3.12.2.2 Effectiveness of Control Strategies***

In accordance with the LSMP and ROMP, the implementation of the control strategies above minimised visual impacts from mining activities of CGM.

One visual impact complaint was received on 14 June 2013 regarding intrusive night lighting. Barrick immediately responded and addressed the concern as per paragraph 4.1 and Table 39.

#### ***3.12.2.3 Variations from Proposed Control Strategies***

There were no variations from the proposed control strategies.

### 3.12.3 Environmental Performance

#### 3.12.3.1 Monitoring

In accordance with Development Consent Condition 6.5, Barrick will take all reasonable and feasible measures, in consideration of Australian Standard AS 4282-1997 *Control of the obtrusive effects of outdoor lighting*, to mitigate visual and off-site impacts of the CGM, to the satisfaction of the Director-General of the DP&I.

Table 37 provides a summary of the landscape maintenance and monitoring programme that has been undertaken at the CGM during previous reporting periods and continued during the 2013 reporting period.

**Table 37**  
**Landscape Maintenance and Monitoring Summary**

Component	Monitoring Frequency	Monitoring Method	Typical Maintenance
<b>Landscaping Works</b> <ul style="list-style-type: none"> <li>• General Inspections</li> <li>• Erosion Inspections</li> </ul>	Annually.  Following significant, high intensity rainfall events.	Visual assessment of moisture stress, plant survival, presence of weeds and erosion/ sedimentation.  Visual assessment of earth mound screening to determine if significant erosion or washouts have occurred in accordance with the ESCMP.	<ul style="list-style-type: none"> <li>• Supplementary watering if required.</li> <li>• Control of invasive weed species in accordance with the requirements of the LMP.</li> <li>• Supplementary planting of failed plants where necessary.</li> <li>• Repair any significant erosion or washout areas on earth mounds.</li> <li>• Stabilisation with Jute mesh or other materials as required.</li> <li>• Additional revegetation planting or sowing if required.</li> </ul>
<b>Buildings, Structures and Facilities</b>	Annual	Visual assessment by a suitably qualified building inspector.	<ul style="list-style-type: none"> <li>• Replace or repair items as necessary to maintain structural integrity.</li> <li>• Repaint any exterior surfaces where the finish has deteriorated.</li> </ul>
<b>Rehabilitation Works</b> <ul style="list-style-type: none"> <li>• General Inspections</li> </ul>	Annual	Monitoring in accordance with the MREMP (with reporting in the AEMR).	<ul style="list-style-type: none"> <li>• Repair any significant erosion or washout areas.</li> <li>• Control of invasive weed species in accordance with the LMP.</li> <li>• Supplementary planting or seeding of failed plants where necessary.</li> </ul>
Erosion Inspections	Following significant, high intensity rainfall events.	Visual assessment of rehabilitation works to determine if significant erosion or washouts have occurred in accordance with the ESCMP.	<ul style="list-style-type: none"> <li>• Repair any significant erosion or washout areas on earth mounds.</li> <li>• Stabilisation with Jute mesh or other materials as required.</li> <li>• Additional revegetation planting or sowing if required.</li> </ul>

#### 3.12.3.2 Performance Outcomes

Landscape maintenance and monitoring measures conducted during the reporting period included:

- general inspections of landscaping (i.e. visual screens) and rehabilitation works;
- monitoring of tree and shrub survival rates of landscape plantings; and
- erosion inspections of landscaping and rehabilitation works following periods of significant, high intensity rainfall.

As a result of this visual landscape monitoring the following maintenance activities were undertaken:

- Weed control within landscaping and rehabilitation areas by manual removal or chemical application.
- Maintenance of erosion control structures.



- Placement of native pasture hay on newly constructed TSF slopes to minimise erosion potential. Construction of the permanent buildings remaining onsite was completed early in 2006 and they are now subject to regular monitoring and maintenance by Barrick employees and contractors.

### 3.12.4 Reportable Incidents

There were no reportable incidents for the period.

### 3.12.5 Further Improvements

Landscape maintenance and monitoring will continue as summarised in Table 36, during the next reporting period. Maintenance, addition and replacement (if required) of plants within the boundary screen plantings will continue to be of high importance.

## 3.13 ABORIGINAL HERITAGE

### 3.13.1 Reporting Requirements

#### 3.13.1.1 Development Consent

The reporting of Aboriginal heritage issues is required by Development Consent Condition 8.6, which states:

*The applicant shall monitor the effectiveness of measures outlined in the archaeology and heritage management plan (condition 3.3). A summary of monitoring results shall be included in the AEMR.*

The Indigenous Archaeology and Cultural Heritage Management Plan (**IACHMP**) (Barrick, 2003n) was prepared in accordance with Development Consent Condition 3.3(b) to identify future salvage, excavation and monitoring of archaeological heritage within the CGM area prior to and during development and to address Aboriginal cultural heritage issues.

#### 3.13.1.2 Environment Protection Licence

Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

#### 3.13.1.3 Any Other Relevant Approvals

Barrick and its consultant archaeologists have obtained permits and consents under s 87 and s 90 of the *National Parks and Wildlife Act 1974* (NSW) (**NPW Act**) for CGM which include:

- Permit 1468 authorising certain archaeological works in the ML 1535 area, water pipeline area and borefield area.
- Consent 1467 authorising the destruction of Aboriginal objects (in certain circumstances) in the ML 1535 area, water pipeline area and borefield area.
- Permit 1681 authorising certain archaeological works in the relocated TSR area and road upgrade area.
- Consent 1680 authorising the destruction of Aboriginal objects (in certain circumstances) in the relocated TSR area and road upgrade area.

### 3.13.2 Environmental Management

#### 3.13.2.1 Control Strategies

The IACHMP sets out the salvage, excavation, monitoring and other management measures that have been undertaken for each of the registered archaeological sites and other Aboriginal objects within the CGM area. The management measures include strategies for registered sites and other Aboriginal objects.

In general, the strategies include: protection; investigation; collection; excavation; documentation and storage of Aboriginal objects in an on-site temporary "Keeping Place"; and collection and storage of objects during topsoil stripping and stockpiling.

There are currently eight registered sites remaining within ML 1535. Registered sites (Exposures) B, C, D, E and H are subject to ongoing conservation works including covering by geo-textile blanket and sign posting to protect the site. Should the location of these sites be proposed to be utilised, the procedure detailed in Special Condition 8 of Permit 1468 would apply after notice is provided to the Director-General of the OEH and in consultation with the local Aboriginal community.

Sites LC2, LC3 and LC4 are managed in accordance with Special Conditions 6, 12 and 13 of Permit 1468.

A summary of the management measures that have previously been undertaken for each of the registered sites identified within the AHIMS is provided in Table 38. These management measures were undertaken during the CGM construction phase. It should be noted that not all the registered sites included in the table below are located within ML 1535 or in proximity to the BCPC water supply pipeline and associated borefield.

**Table 38**  
**Summary of Major Management Measures Undertaken for Registered Sites**

Site Name	Zone and Location Relative to Currently Proposed Disturbance Areas	Condition of Permit 1468	Management Summary
Site P1	Lake Edge Ridge Zone Open Pit	Special Conditions 6, 12 and 13  Special Condition 3	Representative sample of surface Aboriginal objects collected, documented and stored at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. Collected surface Aboriginal objects to be eventually replaced.  Excavation of 3 alluvial fans within footprint of proposed open pit and Site P1. A representative sample of sub-surface Aboriginal objects to be collected, documented and stored at an onsite "Keeping Place".
Site P2	Beach Zone Open Pit	Special Condition 4	Scarred tree removed, conserved and stored or displayed at the Wiradjuri Study Centre in Condobolin.
Site LC1	Lake Edge Ridge Zone Between NWE and Open Pit	Special Conditions 6, 12 and 13  Special Condition 5	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. Collected surface Aboriginal objects to be eventually replaced.  Excavation of Site LC1. A representative sample of sub-surface Aboriginal objects collected, documented and stored at an onsite "Keeping Place".
Exposure A	Back Plain Zone Within NWE	Special Conditions 6, 12 and 13	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. All collected Aboriginal objects to be eventually replaced.
Exposure F	Back Plain Zone Within Northern Tailings Storage	Special Conditions 6, 12 and 13	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. All collected Aboriginal objects to be eventually replaced.
Exposure G	Back Plain Zone Within Northern Tailings Storage	Special Conditions 6, 12 and 13	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. All collected Aboriginal objects to be eventually replaced.

**Table 38 (Continued)**  
**Summary of Major Management Measures Undertaken for Registered Sites**

Site Name	Zone and Location Relative to Currently Proposed Disturbance Areas	Condition of Permit 1468	Management Summary
<b>Exposure I</b>	Back Plain Zone Within Northern Tailings Storage	Special Conditions 6, 12 and 13	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. All collected Aboriginal objects to be eventually replaced.
<b>Exposure J</b>	Back Plain Zone Within Northern Tailings Storage	Special Conditions 6, 12 and 13.	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. All collected Aboriginal objects to be eventually replaced.
<b>Exposure K</b>	Back Plain Zone Within Northern Tailings Storage	Special Conditions 6, 12 and 13.	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. All collected Aboriginal objects to be eventually replaced.
<b>Exposure L</b>	Back Plain Zone Within Southern Tailings Storage	Special Conditions 6, 12 and 13	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. All collected Aboriginal objects to be eventually replaced.
<b>Exposure M</b>	Back Plain Zone Within Southern Tailings Storage	Special Conditions 6, 12 and 13	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. All collected Aboriginal objects to be eventually replaced.
<b>Exposure N</b>	Back Plain Zone Within Southern Tailings Storage and close to Access Road	Special Conditions 6, 12 and 13.	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Remaining Aboriginal objects collected with the topsoil during soil stripping and temporarily stored in soil stockpiles. All collected Aboriginal objects to be eventually replaced.
<b>Site LCB9</b>	Back Plain Zone Within water pipeline area/borefield	Special Condition 7	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Excavation of test pits and extended excavation where necessary. A representative sample of sub-surface Aboriginal objects collected, documented and stored at an onsite "Keeping Place". All collected Aboriginal objects to be eventually replaced.
<b>Site LCB14</b>	Back Plain Zone Within water pipeline area/borefield	Special Condition 7	Representative sample of surface Aboriginal objects collected, documented and stored for safe-keeping at an onsite "Keeping Place". Excavation of test pits and extended excavation where necessary. A representative sample of sub-surface Aboriginal objects collected, documented and stored at an onsite "Keeping Place". All collected Aboriginal objects to be eventually replaced.
<b>Site LCB1-LCB8, LCB10-LCB13, LCB15, LCB16</b>	Back Plan Zone Within water pipeline area/borefield	Special Condition 2	No specific archaeological works required.

After: North Limited (1998); Pardoe (2002)

Management measures are not limited to registered sites. Permit 1468 and Permit 1681 authorise a range of management measures proposed in the Research Design and Study Plan for other Aboriginal objects in the CGM area that are not contained within the Registered Sites. The details of the management and mitigation measures for other Aboriginal objects is contained in the Research Design and Study Plan (Pardoe, 2002) for the CGM as amended by Permit 1468 and Permit 1681.

Activities undertaken during the 2013 reporting period include the following:

- Wiradjuri monitors from the Wiradjuri Condobolin Cultural Heritage Company (**WCCHC**) have been employed during the year on archaeological works at CGM.
- The majority of cultural heritage work continues to be surface and subsurface monitoring for topsoil removal.

Cultural heritage work has been consistently carried out since the start of construction at the CGM. Work areas were examined previously (before CGM construction works) and collections of cultural material were made in accordance with relevant approvals (see Table 37 above). The 2009 revised Ground Disturbance Procedure has led to improvements in both assessing and tracking ground disturbance on-site.

Barrick employees and contractors undertake a Cultural Heritage Induction presented by the WCCHC. These inductions are held on an as needed basis.

#### *3.13.2.2 Effectiveness of Control Strategies*

The control measures for managing and monitoring Aboriginal heritage were implemented in accordance with the IACHMP and were effective during the reporting period.

#### *3.13.2.3 Variations from Proposed Control Strategies*

There were no variations from the proposed control strategies.

### **3.13.3 Environmental Performance**

#### *3.13.3.1 Monitoring*

In accordance with the IACHMP, all areas within the Development Consent area where soil stripping and construction earthworks occur surface and subsurface surveys are carried out by Wiradjuri monitors and, where appropriate, by archaeologists, to identify "datable materials".

#### *3.13.3.2 Performance Outcomes*

In accordance with Aboriginal heritage permits and consents and IACHMP, Aboriginal heritage objects were collected prior to the commencement of all earthworks under the supervision of a qualified archaeologist and representatives of the WCCHC. Objects collected were stored in the on-site temporary "Keeping Place" during the reporting period. Archaeological analysis of these objects is ongoing.

All construction earthworks were monitored by Wiradjuri monitors and/or an archaeologist. No non-compliance issues were reported. Areas where soil stripping has taken place were inspected under the supervision of representatives of the WCCHC.

During Native Title Deed Review discussions in 2012, the Wiradjuri Condobolin Corporation identified no need for any amendments to the IACHMP.

#### **3.13.4 Reportable Incidents**

No environmental incidents or complaints were reported or received relating to Aboriginal heritage at the CGM during the reporting period.

#### **3.13.5 Further Improvements**

A Cultural Heritage Practice Guide was developed in 2013 and forms part of an Indigenous Peoples Plan being implemented at the Cowal Gold Mine. This guide provides plain English instruction to ensure all ground disturbances are managed in accordance with Aboriginal heritage permits and consents and the IACHMP. .

### 3.14 EUROPEAN HERITAGE

#### 3.14.1 Reporting Requirements

##### 3.14.1.1 Development Consent

The reporting of European heritage issues is required by Development Consent Condition 8.6 which states the applicant shall:

*The Applicant shall monitor the effectiveness of measures outlined in the archaeology and heritage management plan (condition 3.3). A summary of monitoring results shall be included in the AEMR.*

The Heritage Management Plan (**HMP**) (Barrick, 2003o) was prepared in accordance with Development Consent Condition 3.3(a).

In accordance with the HMP, the following non-indigenous heritage-related issues are required to be reported in the AEMR:

- new items of non-indigenous heritage significance identified by the Environmental Manager within ML 1535;
- new listings of non-indigenous heritage significance items on the Local Environment Plan (**LEP**) or NSW State Heritage Register within ML 1535;
- a brief overview of maintenance conducted on listed non-indigenous heritage items; and
- a summary of results from any monitoring, management and maintenance measures undertaken.

In 2006, the BSC granted Development Consent for the demolition of the 'Cowal West' Shearer's Quarters and Kitchen. Demolition was required for the construction of contained water storage D9. Demolition of the remainder of the 'Cowal West Homestead Complex' (**CWHC**) (i.e. the Homestead; Shearing [Wool] Shed and Hays shed) was approved via the March 2010 modification and was completed in October 2012.

##### 3.14.1.2 Environment Protection Licence

Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

##### 3.14.1.3 Any Other Relevant Approval

There are no other relevant reporting requirements from approvals in relation to European heritage issues for the reporting period.

#### 3.14.2 Environmental Management

##### 3.14.2.1 Control Strategies

Dismantling and relocation of the 'Cowal West' Shearing Shed to the 'Hillgrove' LCCC occurred during April 2012. Once the Shearing Shed has been reconstructed at the LCCC.

Management measures that were implemented during the reporting period prior to demolition of the CWHC included:

- reconstruction of the Cowal West Woolshed at the LCCC (see Plates 13 and 14).

An interpretive display has been established at the LCCC in consultation with the Lake Cowal Foundation (**LCF**), BSC and Bland District Historical Society (**BDHS**). The display includes maps, photographs, narrative, and fragments/elements salvaged from the CWHC to illustrate its history. Other items containing a level of local heritage significance identified in the HMP will continue to be maintained in accordance with the HMP.

#### 3.14.2.2 *Effectiveness of Control Strategies*

Reconstruction of the Cowal West Woolshed at the LCCC has been recognised by the BSC as a successful initiative in heritage protection.

#### 3.14.2.3 *Variations from Proposed Control Strategies*

There were no variations from the proposed control strategies during the reporting period.

### **3.14.3 Environmental Performance**

#### 3.14.3.1 *Monitoring*

'Cowal West' information plaques for the CWHC were fabricated in early-2009 and stored at the 'Hillgrove' LCCC facility pending further planning works at the Homestead and Shearing Quarters. Barrick consulted with the prior land owners, and the West Wyalong Historical Society regarding the content of these plaques which will be installed adjacent to any exhibit material which is planned to be housed at the nearby 'Hillgrove' LCCC facility.

#### 3.14.3.2 *Performance Outcomes*

The maintenance works carried out within the CWHC have been effective in preserving the integrity and heritage value of the buildings.

### **3.14.4 Reportable Incidents**

No environmental incidents or complaints were reported or received relating to European heritage at the CGM during the reporting period. No CEMCC issues were raised during the reporting period relating to European heritage.

### **3.14.5 Further Improvements**

No further improvements to European heritage management measures are proposed for the next reporting period.

## **3.15 SPONTANEOUS COMBUSTION**

No carbonaceous rock/material occurs in the CGM open pit or in the waste rock emplacements. As a result, spontaneous combustion has not and is not likely to occur at the CGM. Therefore, spontaneous combustion is not applicable to the CGM.

## **3.16 BUSHFIRE**

### **3.16.1 Reporting Requirements**

#### 3.16.1.1 *Development Consent*

The BMP (Barrick, 2003p) was prepared in August 2003 to establish a bushfire management strategy for the CGM that complies with Development Consent Condition 3.8. The BMP was reviewed in 2008 in accordance with the Development Consent Condition 3.2. No revisions to the BMP were considered necessary. The BMP requires the following bushfire related issues to be reported in the AEMR:

- fuel management activities undertaken in the reporting period; and
- a summary of any bushfire events that involved Barrick lands or the use of CGM on-site fire control equipment during the reporting period.

Bushfire management measures for mine site rehabilitation areas and the offset areas are also required to be detailed in the ROMP in accordance with Development Consent Condition 3.6(d)(iv). Subsequently the ROMP (Barrick, 2010) prepared during the 2010 reporting period describes bushfire preventative measures and fuel management measures for mine site rehabilitation areas and the offset areas.

#### 3.16.1.2 *Environment Protection Licence*

Condition R2 of the EPL requires Barrick to notify the EPA of incidents causing or threatening material harm to the environment as soon as practicable after Barrick becomes aware of the incident.

#### 3.16.1.3 *Any Other Relevant Approval*

There are no other relevant reporting requirements from approvals in relation to bushfire for the reporting period.

### **3.16.2 Environmental Management**

#### 3.16.2.1 *Control Strategies*

In accordance with the BMP and the ROMP, bushfire preventative control strategies for the CGM and the CGM offset areas include:

- educating employees and contractors on general fire awareness and response procedures;
- fire track (and fire break) maintenance for fire control;
- annual inspections to identify areas requiring bushfire control measures including assessment of fuel loads; and
- fuel management (e.g. hazard reduction burns) in consultation with the NSW Rural Fire Service.

In accordance with the BMP and the ROMP, fuel management control strategies for the CGM and the CGM offset areas include:

- fuel management by means other than burning; including such methods as grazing, slashing, pruning, mulching or other operations (such as ploughing, herbicide application and rolling);
- fuel management via burning where conventional fuel management strategies are inappropriate, impracticable or not successful (undertaken in consultation with relevant authorities); and
- maintaining designated firebreaks.

#### 3.16.2.2 *Effectiveness of Control Strategies*

The control strategies implemented during the reporting period are considered to be effective as demonstrated by the environmental performance outcomes (discussed in Paragraph 3.16.3 below).

#### 3.16.2.3 *Variations from Proposed Control Strategies*

There were no variations from the proposed control strategies.

### **3.16.3 Environmental Performance**

#### 3.16.3.1 *Monitoring*

In accordance with Development Consent Condition 8.1, data from the meteorological station maintained on-site was used to determine whether current weather conditions are suitable for fire management activities, and to assist in the management of bushfire fighting activities. Meteorological monitoring data is discussed in Paragraph 3.1.3.1 above.

The Kattron lightning tracking system was introduced to operations in early-2012 (replaced the obsolete Cowal Storm Vue system). The Mining Dispatch Control Room operators continually monitor and pass on alert levels between red, amber and yellow to other employee groups and the ERT until all clear conditions resume.

### 3.16.3.2 Performance Outcomes

The bushfire management measures as described in the BMP (Barrick, 2003p) and the ROMP (Barrick, 2010) were implemented at the CGM during the reporting period. Fuel management activities carried out during the reporting period included:

- the creation of firebreaks around the ML 1535 boundary by slashing, weed control spraying and grading;
- slashing of large open areas within ML 1535 that had high fuel loads;
- sustainably crash grazing areas with neighbouring farms sheep and/or cows;
- mowing and grounds maintenance of borefield stations;
- keeping all operating areas neat and tidy and with low fuel loads; and
- conducting regular inspections of the ML 1535 area to identify any significant fire risks.

Bushfire management measures and fuel management measures implemented for the offset areas will be provided in the 2013 AEMR.

The Emergency Response Team (**ERT**) currently consists of about thirty members consisting of Barrick staff members, five of which are full time Emergency Response Officers (**EROs**). The CGM Emergency Response Coordinator is now an accredited trainer with approval to train the Suppress Wildfire course from mid-2010 (currently the crews are trained to Suppress Urban Fire level).

The ERT fire fighting equipment currently consists of two Cat 7 equivalent 4WD fire tenders with a capacity of 1,000 L each, and two dedicated 1,000 L fire fighting trailers. Barrick currently has two 70,000 L water trucks, fitted with water cannons, used in mining operations and a number of contracted water trucks during TSF Wall Lift Project construction which could be used to cart water in the event of a bushfire on ML 1535.

The fire trail register was maintained during the reporting period. All-weather access tracks were established in 2010 to the DG2, BM04.1 and NO4 location and to the lake floor saline bores system to assist in fire control. Since August 2010 the majority of these tracks have been completely inundated by Lake Cowal until half began to re-emerge during late 2013. The LPB was rock covered and became an all-weather access track from March 2013 which can be used for outer Pit perimeter fast response access during summer if Lake Cowal remains full for a prolonged period.

The CGM Rescue Station houses all the ERT equipment, a clean room for bottle refilling and clothes cleaning, training facilities (smoke chamber, car rescue, fire extinguisher, ropes, hoses, breathing apparatus, etc), offices, lockers and conference room for staff, volunteer trainees and visitors.

### 3.16.4 Reportable Incidents

There was one grassfire event that occurred on Barrick-owned land that required the use of CGM on-site fire control equipment during the 2013 reporting period. It was a very short lived, small grass fire of about 200 m<sup>2</sup> caused by lightning south of the SWRE.

### 3.16.5 Further Improvements

No further improvements are proposed for the next reporting period.

## 3.17 MINE SUBSIDENCE

Mine subsidence is not applicable to the CGM.

The Cowal Gold Mine is an open pit mine (i.e. it is not an underground mine), and therefore subsidence is not a relevant matter at the CGM.



### 3.18 HYDROCARBON CONTAMINATION

#### 3.18.1 Reporting Requirements

##### 3.18.1.1 Development Consent

The HWCMP (Barrick, 2006c) has been prepared in accordance with Development Consent Condition 5.7. The HWCMP (2006c) has previously been revised to reflect results of pre-commissioning studies and requirements of the CMP on 6 March 2006.

An amendment to the HWCMP was approved by the Director-General of the DP&I in January 2008 to reflect the proposed management procedures for two new waste streams generated at the CGM, viz.: trash screen oversize waste (classified as inert waste), and hydrocarbon-impacted material (classified as solid waste following treatment in a designated bioremediation facility). The EPL was varied to reflect these amendments in July 2008.

As described in Paragraph 1.1.2 above, the HWCMP was amended to reflect the June 2009 Modification that approved the use of SMBS as an alternative cyanide destruction method. The December 2009 addendum of the HWCMP was approved by the DP&I on 10 March 2010.

In addition to the above, Barrick prepared a revised HWCMP during the 2011 reporting period. The HWCMP was updated in accordance with Development Consent Conditions 3.2 and 5.7 and revised to reflect changes in operational practices since the commencement of the CGM. The DP&I approved the revised HWCMP on 13 May 2011.

The HWCMP contains provisions for the minimisation of hydrocarbon contamination. In accordance with the HWCMP, any major or emergency spills that occur during the reporting period as well as any remedial measures that have been implemented to reduce the risk of occurrence are required to be reported in the AEMR and are provided below.

In accordance with Development Consent Condition 5.4(d):

*Within 24 hours or the next working day of any incident or potential incident with actual or potential significant off-site impacts on people, or the biophysical environment (including wildlife), a report shall be supplied to the Director-General outlining the basic facts and mitigation measures undertaken at the time. A further detailed report shall be prepared and submitted following investigations of the causes and identification of necessary additional preventative measures. The report must be submitted to the Director-General no later than 14 days after the incident or potential accident.*

The incident report should include the following information:

- location of the incident;
- person's name and contact number who discovered the incident;
- the best estimate of the time the incident occurred;
- the time the person reporting the incident and/or the organisation/company they represent became aware of the incident;
- a description of the incident;
- the suspected cause of the incident;
- the environmental harm or environmental nuisance caused, threatened or suspected to be caused by the incident; and
- actions taken to prevent further similar incidents and mitigate any environmental harm or environmental nuisance caused by the incident.

In accordance with Development Consent Condition 5.4(d):

*[Barrick] shall maintain a register of such accidents, incidents, and potential incidents. The register shall be made available for inspection at any time by the independent hazard auditor and the Director-General.*

Barrick will maintain a record of/and report on any unauthorised release of hazardous waste or chemicals to the environment.

### 3.18.1.2 *Environment Protection Licence*

The EPA is required to be notified of any spills that cause "material harm" to the environment, whereby "material harm" is defined in section 147 of the POEO Act.

### 3.18.1.3 *Any Other Relevant Approvals*

The approval for onsite remediation of hydrocarbon contaminated waste and further reuse requires that soils are sampled and assessed by external consultants for waste classification in accordance with NSW EPA (2009) *Waste Classification Guidelines: Part 1: Classifying Waste*.

## 3.18.2 **Environmental Management**

### 3.18.2.1 *Control Strategies*

Based on the principles detailed in *Leading Practice Sustainable Development Program for the Mining Industry - Hazardous Materials Management* handbook (Department of Resources, Energy and Tourism, 2009), Barrick employees and contractors have adopted a Chemical Management Strategy (**CMS**) as part of the HWCMP. This strategy allows for the management of each chemical used at the CGM.

A discussion of the primary components of the CMS is provided in the following sub-paragraphs.

Control Strategies include:

- Site wide inductions, awareness and training on Hazs Substs and Hydrocarbon spill response;
- Annual concrete bunding and tankage integrity audits;
- Area planned general inspections;
- Hazardous Substance and Dangerous Goods Register; and
- Incident reporting and follow up action items.

### ***Inventory Register***

In accordance with best practice and the CMS all raw materials/consumables brought on-site for use at the CGM are recorded in an Inventory Register which is updated and available for inspection by the appropriate authorities. Manufacturer's Safety Data Sheets (**SDSs**) for all chemicals will also be included in the Inventory Register. The CGM uses the ChemAlert 3 system for the management of SDSs of chemical/consumable on-site and to achieve site substance control.

### ***Hazardous Substance and Dangerous Goods Register (HSDGR) and Fuel and Oils Register (FOR)***

In accordance with Paragraph 6.4.1 of the EIS (North Limited, 1998) and the CMS, chemicals recorded on the Inventory Register that are designated as hazardous substances and/or dangerous goods and/or fuels and oils are included in the HSDGR and the FOR.

### ***Personnel Training***

Most if not all activities associated with hazardous consumables require the intervention or interaction of workers and management. In accordance with the CMS and HWCMP, Barrick employees and contractors are trained in:

- hazardous chemical/substance awareness;
- job hazard analysis preparation and use;
- use of Manufacturer's SDS information;
- measures to prevent accidental release;
- potential environmental impacts;
- ChemAlert 3 application and usage;
- use and maintenance of Personal Protective Equipment (**PPE**);

- emergency spill response and containment; and
- spill response and clean-up techniques.

Education and training programmes are used to instruct employees and contractors on the appropriate use of chemicals and requirement for “approved for use on-site” chemicals. The programme is also be used to distribute information on the occupational health and safety implications and potential environmental impacts of these consumables.

Employee and contractor education and training programmes continued to be provided during the reporting period. The training programmes include and are not necessarily limited to:

- induction of all company employees, contractors and first time visitors;
- training in the Job Hazard Analysis for the use of each chemical for those personnel whose work involves its use;
- specific emergency response training to suit individual work requirements; and
- ongoing refresher training programmes for key employees and contractors to improve skills and competencies as necessary.

Training also includes reinforcement by refresher courses, short ‘toolbox’ discussions, and/or routine discussion with supervisors. Records of all staff induction and environmental training are kept to assist in the identification of personnel who require ‘refresher’ training.

Operators moving or using any reagents are trained in the requirements of the material such as PPE, handling procedures and spill clean-up procedures in accordance with the HSDGR.

Specific HSDG training provided to employees during the reporting period included:

- The pocket-sized employee spill response handbook continues to be distributed across the site to all new employees or those not previously inducted.
- The Environmental Awareness Handbook also continues to be distributed to all employees and visitors during the year.

### ***Auditing of Chemical Management***

The CGM is subject to periodic audit and review. During the audit and review process CGM chemical management practices and procedures are assessed against the CMS and the HWCMP. Audit results are used to identify improvements that can be made to the site CMS procedures, if appropriate.

SAI Global conducted several days of audit training during 2011; this was the first basic audit training conducted on site for some years.

ChemAlert 3 employee training occurred 17 to 20 September 2012 and is intended to occur during the next reporting period after the change from version 3.3 to 4.0 of ChemAlert 3 is commissioned. Annual User re-licensing for the Cowal Mine with RMT, WA occurs in September.

#### ***3.18.2.2 Effectiveness of Control Strategies***

A number of minor substance spillage incidents occurred during the reporting period, however the control strategies set out in the HWCMP are considered to be effective as the spills were minor in nature and were fully contained.

The number of internally reported spills reflects the effectiveness of site awareness training sessions undertaken with more intensive oil and chemical spill training sessions.

#### ***3.18.2.3 Variations from Proposed Control Strategies***

There were no variations from the proposed control strategies during the reporting period.

### 3.18.3 Environmental Performance

#### 3.18.3.1 Monitoring

There are no specific monitoring programmes for hydrocarbons relevant to the reporting period however there are a number of preliminary spill response procedures which are discussed below. Sampling of bioremediated soil is undertaken and confirmed to be suitable prior to reuse on rehabilitation locations on-site. In addition, hydrocarbon sampling is undertaken on a quarterly basis as per SGWMBMP.

#### ***Preliminary Spill Responses***

A number of minor substance spillage incidents occurred during the reporting period and the spill response procedures outlined in the HWCMP were implemented at CGM. The CGM preliminary spill responses were implemented for the minor incidents. Impacted material was then transferred to the temporary hydrocarbon waste transfer station for bioremediation.

A Total Waste Management Service was maintained during the reporting period to handle, transport and dispose of all waste material streams generated at CGM. JR Richards & Sons, West Wyalong, have provided this service since the construction of the CGM. A number of licensed sub-contractors are coordinated by the JR Richards & Sons contract to appropriately recycle and/or dispose of the various waste streams.

#### 3.18.3.2 Performance Outcomes

As described in Paragraph 2.6 above, on-site bioremediation of site-generated hydrocarbon contaminated soils commenced in early 2009.

### 3.18.4 Reportable Incidents

There were no government reportable incidents relating to hydrocarbon spillage management during the reporting period. Barrick maintains records of loss control incident reports on any unauthorised release of hazardous waste or managed substances beyond bunded areas or to the environment.

In accordance with the HWCMP, relevant emergency services/agencies will be contacted if:

- the spill has spread or has the potential to spread beyond the boundaries of the CGM;
- it is beyond the resources of the CGM to respond to the spill;
- the available protective equipment is inadequate for dealing with the situation; or
- staff, the public or the environment is, or could potentially be placed at risk.

In accordance with the ERP/PIRMP, relevant emergency services/agencies will be contacted immediately if material environmental harm results from an incident.

The incidents that occurred during the reporting period were minor in nature and therefore not required to be reported to relevant emergency services/agencies.

### 3.18.5 Further Improvements

Whilst only minor substance spillage incident occurred during the reporting period, Barrick has continued to make additional improvements to infrastructure, systems and employee awareness about substance management and spillage prevention:

- Obsolete substances continued to be appropriately disposed of and new substances are registered for use on-site. Spillage clean up materials were disposed of appropriately;
- Continued maintenance of spill response stations. A register of bins continues to be maintained during the reporting period to facilitate content stock auditing and usage reporting;

- The Mining Hardstand truck and vehicle wash facility including the associated oily water coalescing plate separator by-product collected for off-site recycling by licensed waste management contractors;
- The Bioremediation Facility has been operational since early-2009;
- Employee spill response and environmental awareness handbooks continue to be distributed to employees (includes contractors), government regulators, CEMCC, goods suppliers, various VIP visitors, etc;
- The fuel tracking system (Banlaw) hardware was installed at all diesel dispensing stations during the 2011 reporting period. The main diesel tank bund floor has continued to be maintained;
- Barrick Regional Office introduced a Regional OHS Standard for Hazardous Materials (May 2012);
- Barrick Cowal introduced a Site Standard for Hazardous Substances and Dangerous Goods (July 2012); and
- Barrick Cowal introduced a Site Standard for Hydrocarbon performance management (July 2012).

The HSDG and hydrocarbon management measures as described in the HWCMP will continue to be maintained during the next reporting period.

### 3.19 METHANE DRAINAGE/VENTILATION

Methane drainage/ventilation is not applicable to the CGM.

The Cowal Gold Mine is an open pit mine (i.e. it is not an underground mine), and therefore does not require or involve the construction of ventilation or gas drainage infrastructure. As a result, methane drainage/ventilation is not a relevant matter to the CGM.

### 3.20 WASTE GEOCHEMISTRY

#### 3.20.1 Reporting Requirements

During annual on-site AEMR performance review meetings in 2005 and 2006, the DTIRIS (DRE) (formerly DTIRIS & DPI) [Mineral Resources] requested confirmatory test-work of waste rock geochemistry be undertaken. In their 2007 report, the IMP also recommended that Barrick continue to monitor the waste rock being removed from the open pit, to facilitate identification of potentially acid-generating material (if present) and selective placement of that material within the waste emplacements.

A description of the testwork that has been undertaken since 2007 is provided in Section 3.20.2.1.

#### 3.20.2 Environmental Management

The regional and local geology of the Endeavour 42 deposit (**E42 Deposit**), has been described by Miles, Brooker, McInnes, *et al* [1993-1998]). The complex consists of calc-alkaline to shoshonitic volcanic rocks and related sedimentary rocks deposited in a deep water environment and are unconformably overlain, in parts, by the Siluro-Devonian Manna Conglomerate. The auriferous quartz-carbonate-sulphide and carbonate-quartz-sulphide veins occur throughout the deposit and have a consistent dip of 305° and dip of 35° to the southwest. McInnes *et al* describe the gold-bearing veins as generally being associated with one of two alteration styles: ankerite-quartz-pyrite-sphalerite-chalcopryrite-galena veins, which are associated with ankerite-quartz-sericite-carbonate alteration; and quartz, potassium feldspar, pyrite, sphalerite, and chalcopryrite veins associated with the chlorite-carbonate-pyrite alteration. Oxide blankets occur at the base of tertiary transported lacustrine cover, saprolite-saprock transition and at the base of oxidation (*pers. comm*, McInnes, Freer (2007)). These flat lying blankets can be up to several hundred metres wide and 1m to 15m thick and are interpreted to have formed as a result of remobilisation of gold during weathering processes in association with water table fluctuations.

### 3.20.2.1 Control Strategies

Based on prior test work there is no indication that the E42 Deposit or the process tailings are acid forming (Environmental Geochemistry International Pty Ltd [EGi], 2004; and Geo-Environmental Management [GEM], 2009). Overall, the EGi (2004) results indicated a very low likelihood of Acid Rock Drainage (ARD) generation from waste rock, Carbon in Leach (CIL) tailings and combined primary tailings represented by the samples included in the testing programs. Therefore, no special handling requirements were indicated for ARD control at the CGM. However, operational monitoring and testing was recommended to be carried out on an occasional and as needed basis to confirm the low ARD potential of all waste types with particular focus on any unexpected rock types or alteration types which may be exposed during mining.

Detailed geochemical investigations were conducted by EGi prior to commencing mining operations at the CGM. Subsequent geochemical investigations were also conducted by EGi in 2004 and by O'Kane Consultants Pty Ltd (O'Kane) in 2008. A Tailings and Waste Rock Geochemical Assessment was also conducted as part of the E42 Modification Modified Request Environmental Assessment (Barrick, 2010) by Geo-Environmental Management Pty Limited (GEM) (2009).

Chemical groundwater data will continue to be collected as part of the groundwater monitoring programme detailed in the SGWMBMP. Leachate water quality monitoring will continue to be undertaken at the NWE, SWE and PWE external toe drain points in accordance with the EPL.

As recommended by EGi in 2004 and GEM (2009), operational monitoring and testing was carried out on an occasional and as-needed basis to confirm the low ARD potential of all waste types with particular focus on any unexpected rock types or alteration types that may be exposed during mining.

As described in Section 5, final cover material on the waste rock emplacement and tailings storage facility batters will be of low salinity to avoid the potential for saline runoff and enable satisfactory vegetation growth. It will comprise of benign rock mulch, covering the waste rock or process tailings, which will then be covered with the layer of low salinity topsoil.

In accordance with Recommendation 1 of the 2010 Sixth Annual Report of the IMP, the volume of benign, competent rock likely to be required for future rehabilitation and mine closure was calculated in 2011 based on the latest topsoil and subsoil inventory calculations; the Barrick Reclamation Cost Estimator (BRCE) model estimates; and proposed stockpiled soil resource characterisation. The volume of benign, competent waste rock anticipated to be available from future development of the open pit, is also proposed to be re-calculated during the next reporting period and used to update the materials inventory and evaluate the balance of materials available for future rehabilitation through to mine closure.

### 3.20.2.2 Effectiveness of Control Strategies

There has been no seepage from the waste rock emplacement areas and any stormwater run-off from the waste rock emplacements is captured within the ICDS. Therefore, the current control strategies implemented during the reporting period were considered adequate.

### 3.20.2.3 Variations from Proposed Control Strategies

There were no variations from the proposed control strategies during the reporting period.

## 3.20.3 Environmental Performance

The results of detailed geochemical investigations of waste rock and tailings were reported in the EIS and in subsequent environmental assessments undertaken for the CGM. The ongoing drilling and metallurgical testing carried out by Barrick during the reporting period provided the opportunity to update the geochemical database for the project and to verify the findings of previous studies by EGi (2004) and GEM (2009). Ongoing periodic field observations undertaken during the reporting period confirmed the low salinity potential of waste hard rock types mined during the reporting period.

As stated above, Barrick commissioned O'Kane in late-2007 to conduct repeat test work of the Waste (rock) Emplacement and the contents of the TSFs. O'Kane representatives visited site to obtain samples in January 2008. A report was delivered in June 2008 (O'Kane, 2008) and was provided to the DTIRIS (DRE). O'Kane

(2008) concluded that the results are generally consistent with previous investigations, which predicated that waste rock would be predominantly non-acid forming. GEM (2009) also verified these findings.

There has been no seepage from the waste (rock) emplacement areas. There has been some localised stormwater run-off in areas that are yet to undergo final rehabilitation treatment.

#### **3.20.4 Reportable Incidents**

There were no reportable incidents relating to waste geochemistry during the reporting period.

#### **3.20.5 Further Improvements**

Chemical groundwater data will continue to be collected as part of the groundwater monitoring programme detailed in the SGWMBMP. Leachate water quality monitoring will be undertaken at the northern, southern and PWE external toe drain points in accordance with the EPL if and when any seepage is detected.

As recommended during repeat external reviews (2004 - 2009), operational monitoring and testing continued to be carried out on an occasional and as-need basis to confirm the low ARD potential of all waste types with particular focus on any unexpected rock types or alteration types that may be exposed during mining.

The waste rock-topsoil cross-rip methodology has been implemented since the 2<sup>nd</sup> Lifts of the NTSF and STSF, at NWE northern, the SWE south trials, PWE east re-works (2012 - 2013) and Pond D1 Trial plots. These areas have exhibited signs of improved reclamation performance (DnA Environmental, 2012), which is a good outcome for salinity control on final slopes.

### **3.21 PUBLIC SAFETY**

#### **3.21.1 Reporting Requirements**

The following control strategies have been implemented to ensure public safety is achieved on-site:

- general site induction programme (relevant to all personnel, contractors and visitors entering Barrick-owned land);
- specific area inductions (relevant to mining, processing and geology);
- visitors induction programme;
- all Barrick employees, contractors and visitors are issued with card access identification;
- appropriate Barrick employees including contractors have undertaken a First-Aid training course;
- the perimeter of ML 1535 is fenced restricting access to site (in accordance with Development Consent Condition 2.3);
- there is 24 hour security coverage at the Main Gate (including security cameras vision around the site);
- regular security patrols are performed of the external perimeter;
- off-site locations (e.g. borefields) are securely fenced;
- contained on-site is a Emergency Response Office equipped with a fully functional First-Aid room and a commissioned site based First-Aid vehicle;
- in accordance with the BMP a fire break has been placed along the perimeter of ML 1535 and other structures of importance;
- the ERT was assembled and have been trained in fire-fighting, First-Aid response, vehicle trauma, HAZMAT, rope rescue and basic bushfire fighting;
- cyanide awareness sessions have been held for local Emergency Services groups and community groups; and
- Thirty yellow maritime special mark buoys with warning signage have been placed along the inundated ML boundary since mid-2011 to advise any potential members of the public of access restrictions.

Barrick has conducted quarterly meetings with the CEMCC during the reporting period. Hazardous substances and dangerous goods management and emergency preparedness are ongoing topics covered by updates.

#### *3.21.1.1 Effectiveness of Control Strategies*

There were no incidents relating to public safety during the reporting period, therefore the control strategies implemented during the reporting period are considered to be effective.

#### *3.21.1.2 Variations from Proposed Control Strategies*

No variations from proposed control strategies during the reporting period.

### **3.21.2 Environmental Performance**

There were no reportable incidents relating to public safety during the reporting period (see Paragraph 3.21.3 below). Therefore it is considered that the control strategies implemented above have been performing adequately to ensure public safety within ML 1535 and immediate surrounds.

### **3.21.3 Reportable Incidents**

There were no reportable incidents relating to public safety during the reporting period.

### **3.21.4 Further Improvements**

The ERT will continue to be trained in public safety preventative measures including fire-fighting, First-Aid response, vehicle trauma, HAZMAT, rope rescue and basic bushfire fighting. The ERT will attend joint training sessions with the RFS, SES, St John Ambulance, Hospital and NSW Fire and Rescue.

## **3.22 NATURAL HERITAGE**

Lake Cowal, a portion of which is located within ML 1535, is listed on the Register of the National Estate. The Lake is protected by numerous control strategies and management and mitigation measures required under the CGM's Development Consent approvals and relevant EMPs. A summary of the landscape values in the CGM area and management initiatives is provided below.

The general landscape of the CGM mining operations area is flat to very gently undulating land with occasional hills such as Wamboyne Mountain. The region supports mainly dryland agriculture with irrigation farming practised in the Jemalong/Wyldes Plains to the north-east of the Lake.

Land use surrounding the mine site is dominated by sheep and cattle grazing and grain cropping. Grazing and occasional cropping within the high water mark of the Lake has historically occurred when the lake was dry and market conditions were suitable. Irrigation farming is practised to the north-east of the Lake in the Jemalong-Wyldes Plains Irrigation District.

The game reserve previously located in ML 1535 was relocated to an area outside of ML 1535 in 2005. The travelling stock reserve was also previously relocated around the western and parts of the southern and northern boundaries of ML 1535 in 2005. The management of grazing and cropping associated with Barrick-owned lands potentially allows native plant communities to recover from 150 years of agricultural pressure. This is expected to provide enhanced terrestrial and wetland habitat opportunities for threatened herb and grass species for which grazing is a dominant threatening process, as well as fauna species. The enhancement initiatives associated within areas of Barrick-owned lands include a Remnant Vegetation Enhancement Programme, a Compensatory Wetland and the enhancement of remaining areas of wetland within ML 1535 (excluding the New Lake Foreshore). These enhancement initiatives are documented in the LMP, CWMP and ROMP. Two offset areas have also been designated on land owned by Barrick to the north and south of the CGM (Figure 19). In accordance with Development Consent Condition 3.6(a), the offset areas include offset enhancement areas and an offset revegetation area. A description of the offset areas and offset strategy is provided in Paragraph 3.7.



After decommissioning of the CGM, the modified Lake foreshore, waste rock emplacements and tailings storages are predicted to expand habitat opportunities for wetland and terrestrial flora and fauna species. The rehabilitation programme will include the revegetation of the new landforms with selected communities of native vegetation that are suitable to both the physiographic and hydrological features of each landform, whilst expanding the areas of remnant native vegetation that currently exist in the region and providing habitat opportunities for flora and fauna.

Subject to the outcomes of consultation, the Bland Creek Palaeochannel Borefield bores and associated pump stations may be transferred to regional landholders upon agreement by Barrick and in consultation with the NoW. Alternatively, the Bland Creek Palaeochannel Borefield bores and associated pump stations may be dismantled and the bores plugged and capped.

## **4 COMMUNITY RELATIONS**

Barrick recognises developing and maintaining a positive relationship with the local community is essential to running a successful mining operation. Barrick has developed a “Community Relations Strategy” designed to support the Barrick Community Relations vision of:

*“Working together with local communities for mutual long-term success”.*

Barrick has also developed a “Corporate Social Responsibility Charter”. The Charter states that at Barrick, we are committed to making a positive difference in the communities in which we live and work. Barrick strives to earn the trust of all with whom we interact, whether they be our employees, the communities where we live and work, the governments that host us, or other stakeholders with whom we engage in the sustainable development of mineral resources. The Charter guides Barrick in its conduct of business around the world, including at the Cowal Gold Mine.

In addition, Barrick has developed and implemented a Community Relations Management System (CRMS) to ensure a systemic and consistent approach to Community Relations is adopted throughout all of Barrick’s operations. The CRMS is being implemented at the Cowal Gold Mine.

### **4.1 COMMUNITY COMPLAINTS**

A community complaints line was established on 9 December 2003 and operates 24 hours per day. Complaints and/or concerns can be made by dialling (02) 6975 3454 where an operator advises the caller that they have reached the CGM Complaints Line. This number is listed in the White Pages online, West Wyalong Visitors Directory, Forbes Visitors Directory and the Condobolin Business Directory. Details of the Complaints Hotline are also advertised quarterly in the following local newspapers; The West Wyalong Advocate, The Forbes Advocate, The Condobolin Argus, and The Lachlander. Finally, the Complaints Hotline is advertised twice-yearly within the Cowal Update, community newsletter, released by Barrick and distributed to all households within West Wyalong, Forbes, and Condobolin.

When a call is made to the Complaints Hotline, the operator requests the caller’s name, the nature of their complaint/concern, and a return phone number. The information is logged along with the date and time that the call was made. A record of each call is immediately forwarded to the Barrick CGM Community Relations department via the CGPComplaints@barrick.com email. For immediate notification of complaints logged outside of regular business hours, the Community Relations Manager receives a copy of the notice to the assigned mobile phone. Upon receiving an enquiry, the Community Relations Manager conducts necessary investigations and prepares a response. The caller is contacted within 24 hours of the complaint, and notified of any action taken or proposed by Barrick.

A summary of the community complaints received during the reporting period (as required by the Development Consent) is provided in Table 39.

**Table 39**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant A)
COMPLAINT / CONCERN	Local Landholder – mentioned his concerns/complaint regarding Barrick shift bus using incorrect travel route, during an onsite meeting regarding other matters.
DATE and TIME	<b>5 February 2013 – 3:00pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. On 05/02/2013, Complainant A visited the Cowal Gold Mine and met with Barrick's Community Relations Manager to discuss a number of matters</li> <li>2. During the conversation, Complainant A mentioned that he had witnessed a Barrick shift bus travelling on Corringle Lane on 04/02/2013</li> <li>3. Complainant A stated that it was his understanding that Corringle Lane was not part of the approved routes to site for the Cowal Gold Mine</li> <li>4. Barrick Cowal's Community Relations Manager agreed with the Complainant that Corringle Lane was not part of any approved routes to site and undertook to investigate the matter and the the Complainant know of the outcome of the investigation</li> <li>5. The Community Relations Manager's investigation revealed that the bus was travelling away from site towards Condobolin. The bus was driven by a contractor driver engaged by Barrick.</li> <li>6. Barrick's Community Relations Manager arranged for the contract driving company and the drivers to be re-briefed on the approved routes for travelling to and from the Cowal Gold Mine. The contract driving company committed to ensuring the correct route would be used for future journeys.</li> <li>7. The Community Relations Manager called the Complainant at approximately 10:15am on 06/02/2013 to provide an update on the resolution of the investigation. The call was not answered so a detailed message was left on the automated answering service.</li> </ol>
DATE OF RESPONSE	6 February 2013 – 10:15am

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of West Wyalong (Complainant B)
COMPLAINT / CONCERN	Resident of West Wyalong contacted Barrick Cowal's Environment Manager directly via his home telephone to complain about a Barrick employee playing loud music, late at night, at their private residence.
DATE and TIME	<b>27 February 2013 – 11:40pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick Cowal's Environment Manager received a call on his at his home from a resident of West Wyalong complaining about a Barrick employee playing loud music at their private residence (the Barrick employee rents the home from Barrick).</li> <li>2. Barrick's Environment Manager responded by notifying the Community Relations Manager and by undertaking a visit to the area of concern in an effort to hear the problem for himself</li> <li>3. At approximately 12:00am, the Environment Manager reported that a power outage (blackout) had occurred and there was no music audible.</li> <li>4. Barrick's Community Relations representative attempted to contact the Complainant throughout the day on 28/02/2013 and received a return call at approximately 4:20pm</li> <li>5. Barrick's Community Relations Representative thanked the Complainant for returning the call and apologised on behalf of Barrick for the disturbance caused</li> <li>6. Barrick's Community Relations Representative explained that the relevant employee would be counselled on the expectations of tenants residing in Barrick-owned houses and the potential consequences of not meeting those expectations</li> <li>7. The Complainant said "they didn't want to cause trouble for anybody" but they were concerned for some of the elderly residents nearby</li> <li>8. The Complainant was provided with contact details for the Cowal Community Complaints Hotline and the Community Relations Manager. He was encouraged to use these contact details in future rather than contacting the Environment Manager at his home</li> <li>9. The relevant Barrick employee was counselled on 04/03/2013 and was issued written warning that any further breaches of the tenancy agreement with Barrick would lead to a review of the tenancy agreement.</li> </ol>
DATE OF RESPONSE	28 February 2013 – 4:15pm

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant C)
COMPLAINT / CONCERN	Local Landholder emailed Barrick Cowal's Community Relations Manager to complain about the effects of mine blasting on 23/3/2013 and 24/3/2013 and operational noise on 24/3/2013 and 25/3/2013. The Complainant also advised that they had attempted to submit their complaint via the Cowal Community Complaints Hotline and the number was not answered.
DATE and TIME	<b>24 March 2013 – 12:45pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick Cowal's Community Relations Manager responded to the email from the Complainant at 7:01am on 25/03/2013. The Community Relations Manager undertook to investigate the fault with the complaints line, provide blast monitoring results for the blasts nominated by the complainant and to provide the most recent operational noise monitoring report as soon as it is provided by Barrick's noise monitoring consultants.</li> <li>2. Barrick's Community Relations Manager sent a further email to the Complainant on 25/03/2013 at 12:55pm. The email provided blast monitoring data for the blasts mentioned by the Complainant in their original email. The monitoring data indicated the blasting conformed to the requirements of the Development consent conditions.</li> <li>3. Barrick's Community Relations Representative attempted to call the Complainant on 25/3/2013 at 1:20pm. There was no answer so Barrick's representative left a detailed message on the Complainant's automated answering service. The representative advised that an email had been sent providing the blast monitoring details for the blasts mentioned by the Complainant in their email. The Representative also referred to recent correspondence from Barrick to the Complainant's legal representative whereby Barrick reiterated its previous offer to fund noise mitigation measures at the home of the complainant. Barrick's representative invited the Complainant to call if they had any further questions or concerns.</li> <li>4. Barrick's Community Relations Representative made a further call to the Complainant on 27 March 2013 at 11:50am to follow up on the email and previous phone message. Again, there was no answer so the Representative invited the Complainant to make contact if there were any further concerns.</li> <li>5. An investigation into the fault with the Community Relations Hotline revealed that a Telstra fault had caused the Complaints Hotline not to be answered at the time of this complaint. The fault had been temporarily resolved by 5:00pm on 25/03/2012 and permanently resolved by 8:00am on 27/03/2013.</li> </ol>
DATE OF RESPONSE	25 March 2013 – 7:01am

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant C)
COMPLAINT / CONCERN	Resident of Lake Cowal contacted Barrick via the Complaints Hotline to raise concerns about the shaking caused by the blast which had taken place that day.
DATE and TIME	<b>3 April 2013 – 12:34pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. A representative of Barrick attempted to return the Complainant's call at approximately 2:35pm on 3 April 2013 however, the call was not answered so a message was left on the Complainant's automated answering service.</li> <li>2. A representative from Barrick visited the home of the Complainant on the morning of 4 April 2013. Barrick's representative was able to discuss the complainant's overall concern regarding the physical effects of blasting. Barrick's representative reiterated that Barrick would continue to operate the mine in accordance with its conditions of operations but also noted that Barrick had previously offered the complainant mitigation for noise impacts which had not yet been taken up by the complainant.</li> <li>3. Barrick's community Relations Manager emailed the complainant at approximately 4:25pm on 5 April 2013 following the other Barrick representative's visit to the Complainant on the previous day. The email included blast monitoring data for the relevant blast and confirmed that the blasting had complied with the Cowal Gold Mine's conditions of operation relevant to managing the impacts of blasting.</li> <li>4. A representative of Barrick called the complainant at 12:50pm on 8 April 2013 to ensure that the Complainant had received the aforementioned email and other recent correspondence. The Complainant confirmed that they had received that correspondence. No further questions or concerns were raised by the Complainant specific to this complaint.</li> </ol>
DATE OF RESPONSE	3 April 2013 – 2:35pm

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant C)
COMPLAINT / CONCERN	Resident of Lake Cowal contacted Barrick via the Complaints Hotline to raise concerns about the shaking caused by the blast which had taken place that day.
DATE and TIME	<b>22 April 2013 – 12:49pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. A representative of Barrick returned the Complainant's call at 12:55pm on 22 April 2013. The Complainant advised that he was not happy with the physical effect of the blast which had taken place that day. The Complainant explained that his children were outside at the time of the blast as they had heard the blast which had frightened them and caused them to run inside. Barrick's representative took note of the Complainant's remarks and reminded the Complainant that the Cowal Gold Mine's operations are undertaken in conformance with operational conditions imposed by the New South Wales Government. The Complainant expressed a view that he was not satisfied with this response. Barrick's representative explained that Barrick would continue to ensure its operations were undertaken in conformance with the conditions of operation.</li> <li>2. Barrick's Community Relations Manager wrote to the Complainant on 26 April 2013 (a copy of Barrick's letter was also sent to the Complainant via email). The letter provided clarifying information regarding an earlier offer by Barrick to provide for the installation of noise mitigation treatments at the Complainant's home. The letter also provided details regarding a temporary blast monitor which had been previously located at the complainant's home to confirm the accuracy of permanent blast monitors located in an array surrounding the mining operation. Finally, the letter provided details of blast monitoring data relevant to the blast which had taken place on 22 April 2013. The blast monitoring data confirmed that the blast had complied with the requirements of the NSW Government's Development Consent Conditions.</li> </ol>
DATE OF RESPONSE	22 April 2013 – 12:55pm

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant D)
COMPLAINT / CONCERN	Resident of Lake Cowal contacted Barrick's Community Relations Manager directly via mobile phone call regarding noise and local road dust concerns.
DATE and TIME	<b>6 May 2013 – 2:37pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Complainant D contacted Barrick's Community Relations Manager directly via mobile telephone to register concerns regarding dust caused by mine-related traffic using Corringle Lane and operational noise causing disturbance.</li> <li>2. The Community Relations Manager responded to the call by committing to distribute a site-notice to all personnel reminding them that no mine-related traffic (including personal vehicles) are to use Corringle Lane.</li> <li>3. The Community Relations Manager also asked that Complainant to consider whether the installation of noise mitigation treatments at the receptor point would assist in mitigating the concerns regarding noise.</li> <li>4. The complainant agreed that noise mitigation treatments would be a helpful solution to the concern. The Complainant undertook to supply Barrick with quotes for noise mitigation treatments.</li> <li>5. Following the discussion with the Complainant, Barrick's Community Relations Manager distributed a notice to all Barrick employees and contractors advising that use of Corringle Lane was not permitted. The notice was distributed at 10:51am on 9 May 2013.</li> <li>6. The Community Relations Manager also contacted the Bland Shire Council who, through agreement with Barrick, have undertaken to install signs at either end of Corringle Lane advising that mine-related traffic is not permitted on that road.</li> <li>7. The Community Relations Manager contacted the Complainant by telephone at approximately 9:40am on 10 May 2013 to discuss the actions taken by Barrick in response to the complaint. The Complainant acknowledged the action taken and thanked the Community Relations Manager for the update. The Complainant also noted that the local council had recently undertaken grading on Corringle Lane which had likely contributed to the increased dust.</li> </ol>
DATE OF RESPONSE	6 May 2013 – 2:37pm

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Commercial Fishing Operator (Complainant E)
COMPLAINT / CONCERN	Complainant met with Barrick's Community Relations Manager after Barrick had contacted the Complainant to advise that the Complainant's fishing equipment had been retrieved from within the section of the Mining Lease which is inundated by Lake Cowal. The Complainant advised that his complaint related to Barrick not allowing access to a section of Lake Cowal for commercial fishing and Barrick personnel interfering with set fishing equipment.
DATE and TIME	<b>10 May 2013 – 8:00am</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. On 9 May 2013, Barrick's Community Relations Manager contacted the complainant via telephone to advise that fishing equipment owned by the complainant had been retrieved by Barrick personnel from within the Mining Lease and the Complainant was welcome to pick up his equipment from the site at a convenient time. The Complainant agreed to a meeting at 8:00am on 10 May 2013 to pick up his equipment.</li> <li>2. When visiting site to pick up his equipment, the Complainant raised concerns that Barrick was preventing access to a section of Lake Cowal (the Mining Lease) and that Barrick personnel had interfered with fishing equipment in a Fishery.</li> <li>3. Barrick's Community Relations Manager responded by indicating that entire Mining Lease area is subject to active mining activity and Barrick is responsible for ensuring access to the active mining area is restricted to authorised personnel only. This includes undertaking patrols of the lease area and removing anything which have been inappropriately placed within the Mining Lease area. The Complainant was also advised that the Department of Primary Industries (Fisheries) had been made aware of the situation.</li> <li>4. The Complainant went on to indicate that the restricted access to the Mining Lease area for commercial fishers had not been made clear.</li> <li>5. Barrick's Community Relations Manager responded by saying that the inundated section of the lake was marked with buoys which state, "Mining Lease – Do Not Enter". However, Barrick's Community Relations Manager committed to write a letter to the Department of Primary Industries (Fisheries) to reiterate Barrick's position regarding unauthorised access to the inundated section of the Mining Lease.</li> <li>6. Barrick wrote to the Department of Primary Industries (Fisheries) on 20 May 2013 to formally advise of the outcome of the interaction with the Complainant and to reiterate Barrick's position regarding unauthorised access to the inundated section of the Mining Lease.</li> </ol>
DATE OF RESPONSE	10 May 2013 – 8:00am



**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of West Wyalong (Complainant F)
COMPLAINT / CONCERN	Resident of West Wyalong contacted Barrick's Community Relations Manager directly via telephone to raise concerns regarding a Barrick employee making loud noise at their home and disturbing the neighbourhood.
DATE and TIME	<b>16 May 2013 – 8:18am</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Complainant F contacted Barrick's Community Relations Manager directly via mobile telephone to register concerns regarding a Barrick employee making excessive noise at their home and causing disturbance in the neighbourhood.</li> <li>2. Barrick's Community Relations Manager asked the Complainant if they had contacted the local police regarding the matter. The Complainant responded that they had contacted the police however, given the Barrick employee is a tenant of Barrick's (the property is owned by Barrick) the matter should also be dealt with by Barrick.</li> <li>3. Barrick's Community Relations Manager apologised to the complainant for the disturbance and undertook to ensure the relevant Barrick employee received formal notice regarding the behavioural expectations of Barrick employees within the community and of tenants of Barrick properties.</li> <li>4. The relevant Barrick employee received formal notice of the matter via correspondence dated 16 May 2013 and advised that further breaches could lead to a reconsideration of the employee's tenancy agreement.</li> </ol>
DATE OF RESPONSE	16 May 2013 – 8:18am

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant C)
COMPLAINT / CONCERN	Complainant called Barrick's Community Complaints Hotline to raise concerns about vibrations caused by a blast at the Cowal Gold Mine.
DATE and TIME	<b>27 May 2013 – 11:24am</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Community Relations Manager returned the Complainant's call at approximately 11:27am on 27 May 2013. The Community Relations Manager advised that Complainant that no blast had taken place at the Cowal Gold Mine that day however one was scheduled to take place later that day at approximately 12:30pm.</li> <li>2. The Complainant responding by saying that the residents of the Complainant's home felt an effect very similar to the vibrations caused by blasting on more than one occasion that morning. The Complainant insisted that the effect must have been caused by something occurring at the Cowal Gold Mine.</li> <li>3. Barrick's Community Relations Manager undertook to review blast monitoring data from the permanent blast monitoring equipment installed around Lake Cowal to see if the reported effect could be reported.</li> <li>4. Barrick's Community Relations Manager took a further call from the Complainant at 12:01pm. The Complainant advised that the operational noise of trucks could be heard "as clear as a bell" earlier that morning but that the noise was quitter now and could not be heard. The Complainant reiterated the earlier comments regarding a two shudders which had been felt at the home that morning which were similar to the effects of blasting often felt at the home.</li> <li>5. The Community Relations Manager again committed to reviewing Blast Monitoring Data and reporting back to the Complainant.</li> <li>6. After seeking advice from Barrick's blast monitoring consultants, Barrick's Community Relations Manager wrote to the Complainant via email at 1:10pm on 28 May 2013, to advise that "no vibration or overpressure has emanated from the Cowal Gold Mine between the hours of 11:00am and 12:00pm on the 27<sup>th</sup> of May 2013."</li> <li>7. Barrick's Community Relations Manager attempted to call the Complainant at 1:12pm on 28 May 2013 to discuss the findings of the investigation into the complaint however, there was no answer so a message was left on the Complainant's automated answering service. The Complainant was invited to contact Barrick if they had any additional enquiries/concerns.</li> </ol>
DATE OF RESPONSE	27 May 2013 – 11:27am

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant A)
COMPLAINT / CONCERN	Complainant A contacted Barrick's Community Relations manager directly via telephone to raise concerns about a drover being granted permission to water cattle on Barrick-owned land adjacent to property owned by the Complainant.
DATE and TIME	<b>30 May 2013 – 8:43am</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Complainant A contacted Barrick's Community Relations manager directly via telephone to raise concerns about a drover being granted permission to water cattle on Barrick-owned land adjacent to property owned by the Complainant.</li> <li>2. Barrick's Community Relations Manager returned the Complainant's call at approximately 9:30am on 30 May 2013.</li> <li>3. The Complainant advised that he was disappointed that Barrick had granted a request from a travelling cattle drover to establish camp with a herd of cattle at Barrick's property, adjacent to the Complainant's property. The Complainant explained that putting a herd of travelling stock adjacent to his own stock creates farm management problems for him, not to mention the damage that the travelling stock will cause to the stock route if the predicted rain arrives. The Complainant believes Barrick should have at least spoken to him prior to granting the drover permission to camp at the Barrick-owned property. He would have suggested that Barrick not grant permission. The Complainant explained that there are two public campsites with dams about a day apart – the drover should be using those sites.</li> <li>4. Barrick's Community Relations Manager apologised for any disturbance caused and committed to contacting the Complainant if there were any similar requests for public access to Barrick-owned land adjacent to the Complainant's land in future.</li> <li>5. The Complainant made a further call to Barrick's Community Relations Manager at 10:00am on 1 June 2013 to express his frustration that the drover was still present in the area adjacent to his property. The Complainant said the only reason the drover was still present was because he had good access to water via Barrick's property and that access should now be denied and the drover encouraged to move on. Barrick's Community Relations Manager undertook to take immediate action and get back to the complainant.</li> <li>6. Barrick's Community Relations Manager returned the Complainant's call at 10:50am on 1 June 2013 to advise that the drover had now been told to remove his cattle from the Barrick-owned land. The Complainant was reminded that Barrick had no authority to force the drover to move from the public Travelling Stock Route. The Complainant thanked Barrick's Community Relations Manager for the action taken.</li> </ol>
DATE OF RESPONSE	30 May 2013 – 9:30am

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant A)
COMPLAINT / CONCERN	Complainant raised a concern regarding Barrick's temporary lighting arrangements during a meeting with Barrick's Environment Manager.
DATE and TIME	<b>14 June 2013 – 1:00pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. During a meeting to discuss other matters, Complainant A raised his concerns regarding the visual effects of Barrick's temporary lighting arrangements with Barrick's Environment Manager. The Environment Manager undertook to raise the issue with Barrick's Community Relations Department.</li> <li>2. Barrick's Community Relations Manager call the Complainant at 2:19pm on 14 June 2013 to discuss the matter. The Complainant advised that lights from the mine had recently been shining through the lounge room window at night time.</li> <li>3. Barrick's Community Relations Manager undertook to make arrangements to have the temporary lighting adjusted to resolve the Complainant's concerns. The Complainant was invited to contact the Community Relations Manager directly that evening if the concerns had not been addressed.</li> <li>4. Barrick's Community Relations Manager called the Complainant at 12:13pm on 17 June 2013 to enquire as to whether the Complainant was satisfied that the lighting arrangement had been adjusted to resolve the concerns. The Complainant advised that the problem had been resolved and thanked the Community Relations Manager for the action taken.</li> </ol>
DATE OF RESPONSE	14 June 2013 – 2:19pm

DETAILS	Resident of Lake Cowal (Complainant C)
COMPLAINT / CONCERN	Complainant C placed a call with Barrick's Community Complaints Hotline regarding the effects of blasting which had taken place that day.
DATE and TIME	<b>18 June 2013 – 12:53pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Community Relations Officer returned the Complainant's call at 1:06pm on 18 June 2013. The Complainant advised that he was concerned about the effects of blasting that day which had occurred at approximately 12:50pm.</li> <li>2. Barrick's Community Relations Officer undertook to pass the Complainant's details to Barrick's Community Relations Manager and arrange for blast monitoring data to be provided to the Complainant.</li> <li>3. Barrick's Community Relations Manager wrote to the Complainant at 9:49am on 20 June 2013 to provide blast monitoring data for the blast which occurred on 18 June 2013. The information provided included advice that the monitoring data indicated that the blast which took place on 18 June 2013 conformed to the Development Consent Criteria set by the NSW Government for the Cowal Gold Mine. The Complainant was also reminded of their right to seek an independent review of Barrick's compliance with Development Consent Conditions via the Director-General of the Department of Planning and Infrastructure.</li> </ol>
DATE OF RESPONSE	18 June 2013 – 1:06pm

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal, (Complainant A)
COMPLAINT / CONCERN	Local Landholder – called the CGM Community Relations Manager directly regarding blasting activities.
DATE and TIME	<b>25 July 2013 – 1:49pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick Cowal Gold Mine's Community Relations Manager received a call from the Complainant at approximately 1:49pm on Thursday, 25 July 2013.</li> <li>2. During the call, the Complainant mentioned that the blast which had occurred earlier that day was particularly noticeable. The Community Relations Manager encouraged the Complainant to register his concern as a formal complaint and the Complainant agreed. The Community Relations Manager undertook to review blast monitoring data from the day's blasting activities and pass on that data to the Complainant. The Complainant agreed with the proposed approach.</li> <li>3. Barrick's Community Relations Manager emailed the Complainant at approximately 10:24am on 29 January 2013 to provide details of the blasting activities relevant to the Complainant's enquiry. The Community Relations Manager advised within the email that blasting activities on 25 July 2013 were well within the Blasting Impact Assessment Criteria set out in the Development Consent Conditions for the Cowal Gold Mine. Blast monitoring data for 25 July 2013 was also provided to the Complainant within the email.</li> <li>4. The Community Relations Manager placed a call to the Complainant at approximately 10:26am on 29 January 2013. The Community Relations Manager explained to the Complainant that he had sent a summary of blast monitoring data via email which confirmed that the blast which took place on 25 July 2013 conformed to the requirements of the Blast Impact Assessment Criteria set out in the Development Consent Conditions for the Cowal Gold Mine. The complainant had no further questions regarding the matter.</li> </ol>
DATE OF RESPONSE	25 July 2013

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant B)
COMPLAINT / CONCERN	Local Landholder – called the Cowal Community Complaints Hotline regarding blasting activities.
DATE and TIME	<b>26 July 2013 – 12:55pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick Cowal Gold Mine's Community Relations Manager emailed the Complainant at approximately 10:04am on 29 July 2013 to follow up on the Complainant's enquiry. The email included blast monitoring data from 26 July 2013 which confirmed that the day's blasting activities had conformed to the requirements of the Blast Impact Assessment Criteria set out in the Development Consent Conditions for the Cowal Gold Mine.</li> <li>2. The Community Relations Manager called the Complainant at approximately 10:42am on 29 July 2013 to following up on the abovementioned email and to ensure the Complainant had no further questions or concerns. The Community Relations Manager explained that the blasting activity on 26 July had conformed to the requirements of the Blast Impact Assessment Criteria set out in the Development Consent Conditions for the Cowal Gold Mine. The Complainant raised no further questions or concerns regarding the matter.</li> </ol>
DATE OF RESPONSE	29 July 2013.

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Commercial Fishing Operator (Complainant C)
COMPLAINT / CONCERN	Commercial Fishing Operator – complained via telephone that fishing equipment had been removed by Barrick personnel
DATE and TIME	<b>31 July 2013 – 5:05pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick Cowal Gold Mine’s Senior Community Relations Advisor called the Complainant at 5:05pm on 31 July 2013 to advise that a number of yabby pots had been located within the Cowal Gold Mine Mining Lease and that the equipment was available for collection from Barrick.</li> <li>2. The Complainant raised concern that the equipment had been commercially set fishing equipment and Barrick personnel had committed an offence by removing the equipment.</li> <li>3. The Complainant sent an email to Barrick’s representative at approximately 9:06am on 1 August 2013 formalising his complaint that his equipment had been removed by Barrick personnel and requesting additional information regarding the matter.</li> <li>4. Barrick’s Senior Community Relations Advisor responded to the Complainant’s email at approximately 10:49am on 1 August 2013. The email advised that the Complainant’s equipment had been retrieved by Barrick personnel as it had been improperly placed within the Cowal Gold Mine Mining Lease. The Complainant was also advised that The Department of Primary Industries (Fisheries) could be contacted by the Complainant if he had further concerns regarding his rights as a commercial fishing operator.</li> <li>5. Barrick’s Senior Community Relations Advisor attempted to contact the Complainant via telephone at 2:35pm on 6 August 2013 however there was no answer. Barrick’s representative left a message enquiring as to whether the Complainant had identified a convenient time to collect his fishing equipment.</li> <li>6. Barrick’s Senior Community Relations Advisor called the Complainant at 3:48pm on 7 August 2013 to enquire as to whether he had identified a convenient time to collect his equipment. The Complainant advised that he would not be collecting the equipment and that he would instead arrange for either representatives of the NSW Police or the Department of Primary Industries (Fisheries) to collect the equipment.</li> <li>7. Barrick’s Community Relations Manager emailed the Complainant at approximately 4:37pm on 14 August 2013 attaching a letter. The letter referred to Barrick’s previous requests that the Complainant cease setting yabby pots within the Barrick Cowal mining lease. The letter then provided details of equipment which had been collected from within the mining lease on 31 July 2013. The letter explained that, by unlawfully entering the mining lease, the Complainant would be potentially exposing himself and possibly others to a serious risk of harm. Barrick reiterated its request that the Complainant not enter the Cowal Gold Mine mining lease for any purpose. The letter concluded that Barrick considered the Complainant’s entry of the mining lease to be a trespass and potentially a breach of applicable safety legislation. A copy of the letter was also provided to the Department of Primary Industries (Fisheries).</li> <li>8. Barrick’s Senior Community Relations Advisor emailed the Complainant at 4:30pm on 20 November 2013 reminding the Complainant that he was still welcome to make arrangements to collect his equipment from Barrick. No response was received.</li> </ol>
DATE OF RESPONSE	31 July 2013

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal (Complainant D)
COMPLAINT / CONCERN	Local Landholder – called the CGM Complaints Line regarding blasting activities
DATE and TIME	<b>1 August 2013 – 1:53pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Senior Community Relations Advisor attempted to call the Complainant at approximately 4:00pm on 1 August 2013 however, there was no answer. Barrick's Representative left a message stating that no blasting activity had taken place during the time described by the Complainant rather, blasting had taken place earlier that day. Barrick's representative said that, despite the fact that no blast had taken place at the time described by the Complainant, Barrick would arrange for a review of blast monitoring data for that day and that the data could be emailed to the Complainant.</li> <li>2. The Complainant contacted Barrick again via the Community Complaints Hotline and explained that they did not have access to email and instead, could the blast monitoring data be faxed.</li> <li>3. Barrick's Community Relations Manager sent a letter to the Complainant via fax on 2 August 2013. The letter explained that no blast had taken place at the time described by the complainant rather, blasting had occurred more than one hour earlier. The letter advised that blast monitoring had revealed no overpressure or vibration emanating from the Cowal Gold Mine within the half-hour window of the Complainant's enquiry.</li> <li>4. The Senior Community Relations Advisor called the Complainant at 3:15pm on 5 August 2013 in an effort to confirm that the Complainant had received the abovementioned letter via fax. The Complainant confirmed that they had received the correspondence. The Complainant wanted to know what the noise was that they had heard/felt. Barrick's representative said that they did not know and that the effects of blasting were immediate and would not be delayed by over an hour. The Complainant was invited to make further contact if they had any additional questions or concerns.</li> </ol>
DATE OF RESPONSE	1 August 2013



**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal, (Complainant A)
COMPLAINT / CONCERN	Local Landholder – during a telephone conversation with the Cowal Gold Mine's Community Relations Manager, the Complainant raised concerns regarding the impacts of blasting during the previous week.
DATE and TIME	<b>7 August 2013 – 1:25pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. The Community Relations Manager called the Complainant at approximately 1:25pm on 7 August 2013 to discuss a separate matter. During the conversation, the Complainant mentioned that the impacts of blasting had been significantly more noticeable during the previous week. The Community Relations Manager undertook to review blast monitoring data for the period described by the Complainant and get back in touch to discuss further.</li> <li>2. The Community Relations Manager emailed the Complainant at 2:16pm on 8 August 2013 and provided blast monitoring data for the period 27 July to 4 August 2013. The data demonstrated that all blasting activities had conformed to the requirements of the Blast Impact Assessment Criteria set out in the Development Consent Conditions for the Cowal Gold Mine.</li> <li>3. The Complainant raised no further concerns regarding the matter during subsequent engagements or via correspondence.</li> </ol>
DATE OF RESPONSE	7 August 2013
DETAILS	Resident of Lake Cowal, (Complainant B)
COMPLAINT / CONCERN	Local Landholder – called the CGM Complaints Line regarding blasting
DATE and TIME	<b>10 August 2013 – 12:37pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. During a telephone conversation with the Complainant on 12 August 2013 at approximately 11:00am, the Community Relations Manager confirmed that he had received the Complainant's enquiry regarding blasting on 10 August and that blast monitoring data from that day would be sent via email later that day to confirm whether the blasting activity had complied with the Cowal Gold Mine's Development Consent Conditions.</li> <li>2. The Community Relations Manager emailed the Complainant at approximately 4:39pm on 12 August 2013 and provided blast monitoring data for the blasting activity which took place on 10 August 2013. The email confirmed that the blasting activity had conformed to the requirements of the Blast Impact Assessment Criteria as articulated in the Development Consent Conditions for the Cowal Gold Mine.</li> <li>3. No further questions or concerns were raised by the Complainant during subsequent conversations or in correspondence.</li> </ol>
DATE OF RESPONSE	12 August 2013

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal, (Complainant B)
COMPLAINT / CONCERN	Local Landholder – called the CGM Complaints Line regarding blasting
DATE and TIME	<b>12 August 2013 – 12:37pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. The Community Relations Manager emailed the Complainant at 10:28am on 13 August 2013 and provided blast monitoring data for the blasting activity on 12 August. The email confirmed that the blasting activity had conformed to the requirements of the Blast Impact Assessment Criteria as described in the Development Consent Conditions for the Cowal Gold Mine.</li> <li>2. No further questions or concerns were raised by the Complainant during subsequent conversations or in correspondence.</li> </ol>
DATE OF RESPONSE	13 August 2013

DETAILS	Resident of Lake Cowal, (Complainant B)
COMPLAINT / CONCERN	Local Landholder – called the CGM Complaints Line regarding blasting
DATE and TIME	<b>15 August 2013 – 12:35pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Community Relations Manager emailed the Complainant at 4:15pm on 16 August 2013 and provided blast monitoring data from the blasting activities on 15 August. The monitoring data confirmed that the blasting activities conformed to the requirements of the Blast Impact Assessment Criteria as described in the Development Consent Conditions for the Cowal Gold Mine.</li> <li>2. No further questions or concerns were raised by the Complainant during subsequent conversations or in correspondence.</li> </ol>
DATE OF RESPONSE	16 August 2013

DETAILS	Resident of Lake Cowal, (Complainant A)
COMPLAINT / CONCERN	Local Landholder – complained about blasting activity during a conversation with a Barrick representative
DATE and TIME	<b>6 September 2013 – 5:42pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Community Relations Manager emailed the Complainant at approximately 1:17pm on 9 September 2013 and provided blast monitoring data from 6 September. The blast monitoring data confirmed that the blasting activities had conformed to the requirements of the Blast Impact Assessment Criteria as described in the Development Consent Conditions for the Cowal Gold Mine.</li> <li>2. The Community Relations manager called the Complainants at approximately 2:20pm on 10 September 2013 to follow-up on the abovementioned email. The Complainant thanked the Barrick representative for the call and for sending the information via email.</li> </ol>
DATE OF RESPONSE	9 September 2013

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal, (Complainant B)
COMPLAINT / CONCERN	Local Landholder – called the CGM Complaints Line regarding blasting
DATE and TIME	<b>10 September 2013 – 12:57pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick Cowal Gold Mine's Community Relations Officer attempted to call the Complainants at 2:16pm on 10/09/2013. There was no answer so a message was left with the automated messaging service to advise that an email would be sent to the Complainant with details of blast monitoring undertaken for the relevant blast which prompted the complaint. The Community Relations Manager invited the Complainant to contact him directly if there were any further questions or concerns.</li> <li>2. The Community Relations Manager sent an email to the Complainant at 2:26pm on 11/09/2013 providing a summary table of blast monitoring undertaken on 10/09/2013. The blast monitoring data provided by Barrick's third-party blast monitoring consultants indicated that the blasting undertaken on 10/09/2013 conformed to the blast impact assessment criteria set out in the operation's Development Consent Conditions.</li> </ol>
DATE OF RESPONSE	10 September 2013

DETAILS	Resident of Lake Cowal, (Complainant B)
COMPLAINT / CONCERN	Local Landholder – called the CGM Complaints Line regarding operational noise
DATE and TIME	<b>29 September 2013 – 9:23am</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Community Relations Manager emailed the Complainant at 10:31am on 30 September 2013. The email provided details of noise monitoring activities undertaken by Barrick at the Cowal Gold Mine. The email explained that the most recent noise monitoring undertaken by a third-party consultant, including at the Complainant's home, revealed that the Cowal Gold Mine's operational noise emissions conformed to the requirements of the operation's Development Consent Conditions.</li> <li>2. In the abovementioned email, the Complainant was also advised that they may elect to as the Director-General of the Department of Planning and Infrastructure in writing for an independent review of the impacts of the Cowal Gold Mine on their land. Contact details for the Department of Planning and Infrastructure were provided.</li> <li>3. The email included an update on the process of agreeing to a Noise Mitigation Deed between Barrick and the Complainant. A Noise Mitigation Deed has been subsequently finalised in accordance with the Development Consent Conditions for the Cowal Gold Mine.</li> <li>4. Barrick's Senior Community Relations Advisor attempted to call the Complainant at approximately 3:15pm on 30 September 2013 however there was no answer. A message was left advising that the Barrick representative was calling to check that the Complainant had received the abovementioned email inviting the Complainant to make contact if they had any further questions or concerns.</li> </ol>
DATE OF RESPONSE	30 September 2013

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal, (Complainant B)
COMPLAINT / CONCERN	Local Landholder – called the CGM Complaints Line regarding blasting
DATE and TIME	<b>11 October 2013 – 12:35pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Community Relations Manager emailed the Complainant at approximately 11:01am on 14 October 2013 and provided blast monitoring data for the blasting activities relevant to the Complainant's enquiry. The blast monitoring data revealed that the blasting activities had conformed to the requirements of the Blast Impact Assessment Criteria as described in the Development Consent Conditions for the Cowal Gold Mine.</li> <li>2. The Complainant was advised that if, despite the abovementioned advice, they consider that the Cowal Gold Mine is exceeding the impact assessment criteria for blasting (or any other impact) then they may ask the Director-General of the Department of Planning and Infrastructure in writing for an independent review of the impacts of the Cowal Gold Mine on the property. Contact details for the Department of Planning and Infrastructure were provided.</li> <li>3. No further questions or concerns were raised by the Complainant during subsequent conversations or in correspondence.</li> </ol>
DATE OF RESPONSE	14 October 2013

DETAILS	Resident of Lake Cowal, (Complainant B)
COMPLAINT / CONCERN	Local Landholder – called the CGM Complaints Line regarding operational noise
DATE and TIME	<b>15 October 2013 – 6:50am</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Senior Community Relations Advisor attempted to call the Complainant at approximately 9:15am on 15 October 2013. The Barrick representative left a message inviting the Complainant to call back to discuss the complaint they had lodged earlier that morning regarding operational noise.</li> <li>2. The Complainant returned the Barrick representative's call at approximately 8:15am on 16 October 2013. The Barrick representative enquired as to whether the Complainant had received the most recent operational noise monitoring report which had previously been sent to the Complainant. The Complainant confirmed that they had received that report. Barrick's representative explained that the most recent noise monitoring report had revealed that Barrick's operational noise output had conformed to the requirements of the relevant Development Consent Conditions. Barrick's representative suggest that if, despite the abovementioned advice, the Complainant considers that the Cowal Gold Mine is exceeding the impact assessment criteria for noise (or any other impact) then they may ask the Director-General of the Department of Planning and Infrastructure in writing for an independent review of the impacts of the Cowal Gold Mine on the Complainant's land.</li> <li>3. Barrick's representative also provided updated information to the Complainant regarding the progress toward the finalisation of a Noise Mitigation Agreement between the Complainant and Barrick. A Noise Mitigation Agreement was subsequently finalised.</li> </ol>
DATE OF RESPONSE	15 October 2013

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal, (Complainant E)
COMPLAINT / CONCERN	Local Landholder – complained about unauthorised access to their property by Barrick personnel/contractors
DATE and TIME	<b>29 October 2013 – 10:25am</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. The Complainant attempted to call Barrick's Environment Manager at approximately 10:25am on 29 October 2013 and left a message on the automated answering service asking that the call be returned.</li> <li>2. Barrick's Community Relations Manager returned the Complainant's call at approximately 10:56am on 29 October however, there was no answer so a message was left and the Complainant was invited to return the Barrick representative's call.</li> <li>3. The Complainant returned the Barrick representative's call at approximately 12:20pm on 29 October and advised that he was concerned that he had witnessed two vehicles on his property that day. He recognised the first as being a Barrick employee undertaking the usual monthly dust monitoring activities on his property however, he was unfamiliar with the second vehicle and its male occupants following closely behind. The Complainant was concerned that he didn't recognise the visitors in the second vehicle and he felt he should at least be introduced to new visitors to his property. The Community Relations Manager undertook to investigate the matter and call the Complainant back.</li> <li>4. The Community Relations Manager called the Complainant again at approximately 1:03pm on 29 October and explained that the visitors in the second vehicle were representatives of Barrick's weed spraying contractors who were visiting to be shown the location of the dust gauge in case any weed control requirements at that location came up in the future. Barrick's representative went on to explain that he had discussed the Complainant's concerns with the Barrick contract manager and explained that in future, any new visitors to the property should first be introduced to the Complainant via prior appointment. The Complainant agreed with the proposed approach to managing site visits in future and no further questions or concerns were raised.</li> </ol>
DATE OF RESPONSE	29 October 2013

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Community member, (Complainant F)
COMPLAINT / CONCERN	Community Member – called the CGM general reception desk regarding the driving behaviour of a person he suspected of being a mine employee
DATE and TIME	<b>9 November 2013 – 11:05am</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Community Relations Manager returned the Complainant's call at approximately 1:53pm on 9 November 2013 and asked that the Complainant relay his concerns. The Complainant explained that they had been travelling along Wamboyne Road, Lake Cowal at approximately 9:30am when a private vehicle travelling down Blow Clear Road, appearing to be travelling away from the Cowal Gold Mine, failed to give way at the intersection (near the Telstra Exchange). The Complainant advised that a collision at high speed would have certainly occurred if he had been closer to the intersection (he was approximately 200 metres from the intersection). The Complainant said the driver should have slowed given there is a Give Way sign on Blow Clear Road at this intersection. The Complainant described the vehicle as a silver single cab ute. After some discussion, Barrick's representative told the Complainant that he would arrange for tapes of the Barrick car park to be reviewed in an effort to identify whether the vehicle was one which left the Cowal Gold Mine around that time.</li> <li>2. Barrick's representative called the Complainant again at 2:47pm on 09/11/2013 to advise that Barrick had reviewed recording of the car park at the Cowal Gold Mine between 8:00am and 10:00am that day and no vehicle matching the description provided by the Complainant had come or gone from the mine that day. The Complainant said he thought he knew who the driver was and that it was an employee of the Cowal Gold Mine. The Complainant advised that it was his intention to contact the police and report the dangerous driving behaviour. Barrick's representative advised that they thought that would be a good option given that the driver was operating a privately owned vehicle in their own private capacity. Barrick's representative also advised that a notice to employees and contractors would be distributed reminding them to abide by the road rules. No further questions or concerns were raised by the Complainant.</li> </ol>
DATE OF RESPONSE	9 November 2013

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Resident of Lake Cowal, (Complainant B)
COMPLAINT / CONCERN	Local Landholder – called the CGM Complaints Line regarding blasting
DATE and TIME	<b>1 December 2013 – 1:03pm</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Community Relations Manager emailed the Complainant at approximately 1:43pm on 2 December 2013. The email included the details of blast monitoring data from 1 December which indicated that the blasting activity from that day conformed to the requirements of the Blast Impact Assessment Criteria as described in the Development Consent Conditions for the Cowal Gold Mine.</li> <li>2. The Complainant was also advised in the email that if, despite the abovementioned advice, they consider that the Cowal Gold Mine is exceeding the impact assessment criteria for blasting (or any other impact) then they may ask the Director-General of the Department of Planning and Infrastructure in writing for an independent review of impacts of the Cowal Gold Mine on their land. Contact details for the Department of Planning and Infrastructure were provided.</li> <li>3. Further to the abovementioned information provided in the email, a copy of recent correspondence was also attached wherein Barrick agrees to relocate a blast monitor to the Complainant's property per an earlier request from the Complainant. An access agreement for the Complainant's consideration was included in the correspondence. The Complainant was yet to respond to that correspondence.</li> <li>4. Barrick's Senior Community Relations Advisor attempted to call the Complainant at 11:02am on 3 December 2013 however there was no answer. The Barrick representative left a message saying that he wanted to confirm that the complainant had received the abovementioned email and correspondence. The Complainant was invited to call the Barrick representative back if they had any additional questions or concerns.</li> </ol>
DATE OF RESPONSE	2 December 2013

**Table 39 (Continued)**  
**Summary of Community Complaints during the Reporting Period**

DETAILS	Community Member, (Complainant G)
COMPLAINT / CONCERN	Community Member – called the CGM Complaints Line regarding the driving behaviour of a person he suspected of being a mine employee
DATE and TIME	<b>17 December 2013 – 6:41am</b>
OUTCOME	<ol style="list-style-type: none"> <li>1. Barrick's Senior Community Relations Advisor attempted to return the Complainant's call at approximately 11:50am on 17 December 2013 however the call was not answered. A message was left inviting the Complainant to return the Barrick representative's call.</li> <li>2. A further attempt to call the Complainant was made at approximately 9:05am on 18 December 2013 however there was no answer. Again, Barrick's representative invited the Complainant to return the call.</li> <li>3. The Complainant returned the Barrick Representative's call at approximately 9:30am on 18 December and provided a detailed description of a private vehicle driving dangerously on public roads. The Complainant explained that he – by chance – visited the same petrol station in West Wyalong as the alleged dangerous driver. During the conversation with the driver, the Complainant was able to confirm that the driver was an employee of Barrick however, no name was provided.</li> <li>4. Barrick's representative advised the Complainant that Barrick would attempt to identify the driver and discuss road and community safety. The Complainant raised no further questions or concerns.</li> </ol>
DATE OF RESPONSE	17 December 2013



## 4.2 COMMUNITY LIAISON

### ***Community Environmental Monitoring and Consultative Committee***

Barrick established a CEMCC prior to commencement of construction works, in accordance with the Development Consent Condition 8.7(i). The CEMCC monitors compliance with conditions of the Development Consent and other matters relevant to the operation of the mine.

During the reporting period, Barrick conducted quarterly meetings with the CEMCC.

The CEMCC quarterly meetings during the reporting period occurred on 5 March, 5 June, 11 September, and 4 December 2013. The CEMCC meets on-site or in local communities, undertakes regular inspections, reviews environmental and audit reports and discusses any incidents or complaints that may have been registered. The CEMCC members are an active conduit between local communities and the CGM. Minutes are taken from each meeting and published in the local library and also on BSC and Lachlan Shire Council websites (see Appendix D).

### ***Community Information Newsletters***

The "Cowan Update" is the CGM external newsletter that was released regularly during the construction and start-up phase of the project (2003 to August 2006). A publication of the Cowan Update was released June 2013 following an earlier edition which had been released in December 2012/January 2013. Copies of the Cowan Update community newsletter are distributed to all households in the Bland, Lachlan and Forbes Shires. It is scheduled that the Cowan Update will be published every six months with the next edition due in July 2014.

### ***Other Community Involvement***

Barrick extended invitations to numerous community groups to visit the CGM for presentations and site visits. Site visits were undertaken by a number of groups during the reporting period including:

- Bland, Forbes and Lachlan Shire Councils;
- Wiradjuri Condobolin Corporation;
- local farmers;
- various community and charity groups from neighbouring towns and villages;
- various primary and secondary schools;
- employee family visits: and
- community visit day for community members of Bland, Forbes & Lachlan Shires

Community and Family visit days are conducted annually with up to 600 people in attendance over the two days. In addition, the Cowan Gold Mine regularly hosts school and community group visits. Stakeholder meetings are carried out on-site or in the local community depending upon the group and topic. These meetings can consist of 3 to 20 people, for example:

- CEMCC meetings (which are held quarterly);
- Local landholders and local community and charitable groups: and
- Local Government and State agency meetings.

Barrick also attended several off-site presentations involving the community including:

- local community and charitable groups;
- Wiradjuri Condobolin Corporation
- Lachlan, Bland and Forbes Shire Councils; and
- Local secondary schools.

### ***Wiradjuri Condobolin Community Liaison***

Barrick works with the Wiradjuri Condobolin Community through the WCC and a number of formal committees:

- the Cowal Project Coordinating Committee (**CPCC**); and
- the Employment, Training and Business Committee (**ETBC**), which meets with the WCC on a regular basis.

Barrick has committed to provide employment opportunities for Wiradjuri people on-site and has developed an Indigenous Peoples Plan to improve engagement opportunities for Indigenous People in the Barrick Cowal workforce. The Wiradjuri Traineeship Program was implemented in early 2010 with the introduction of a Business Administration Traineeship and a Store Warehousing Traineeship, both traineeships were successfully filled.

WCC was awarded the offices and facilities cleaning contract in February 2007, which is a further 12 employees. WCC were also successful in tendering for the CGM's freight and logistics contract in 2009.

During the reporting period the WCCHC has provided archaeological monitoring services on-site. Monitoring has been carried out on an as needs basis.

Barrick employees and contractors continued to attend Cultural Heritage Inductions presented by the WCCHC during the reporting period.

Through the ETBC, Barrick and the WCC have continued to award Scholarships to Wiradjuri students moving into University studies. Since the Scholarship program commenced in 2004 a total of 28 scholarships have been awarded. During the reporting period 5 Wiradjuri scholarships were awarded.

In addition to Wiradjuri support, Barrick continues to support students in the Bland, Lachlan and Forbes Shires and offers the "Endeavour" Scholarship program. In collaboration with local senior schools, Barrick has reviewed the structure of the Endeavour Scholarship program, ensuring it meets the needs and aspirations of Barrick and local students. This review led to local schools distributing over \$20,000 worth of scholarships and bursaries from Barrick in 2013.

### ***Barrick Donations***

Barrick has continued to support numerous donation, sponsorships and partnerships to a variety of local schools, annual events, charity and not for profit groups, community infrastructure and town advancement groups. Barrick again made substantial contributions to the community during this reporting period.

Barrick operates two schemes to facilitate financial contributions to the community. The Cowal Partnering Program (**CPP**) and the Barrick Buddies (**BB**) Program, both programs were established in 2006 and both programs will continue to operate during the next reporting period.

The BB Program offers \$250 to successful employee volunteers, completing 25 or more hours of service to a charity, sporting or community group per annum. The employee presents the funds to their nominated group. The BB Program promotes community involvement amongst the work force.

Barrick allocated more than \$170,000 of funds to via the CPP and Barrick Buddies Programs during 2013.

### ***The Lake Cowal Foundation Limited***

The Lake Cowal Foundation (**LCF**) continues to grow into an important local independent "Environmental Trust". The Foundation is actively supported financially and in-kind by CGM. The LCF Board meet as required, some meetings are held via teleconference.

In addition to housing the LCCC on Barrick owned property 'Hillgrove', Barrick has also provided the LCF with considerable freehold property to undertake conservation and research projects. Barrick also provides secretariat services to the LCF.

The LCF has now been involved in approximately 32 conservation projects in the Lake Cowal region and has developed a relationship with 34 project partners, including:

- numerous local land owners and managers;
- Lachlan Catchment Management Authority;
- EPA, National Landcare Program, Natural Heritage Trust, Environmental Trust, Greening Australia and DPI (Fisheries);
- Forbes, Lachlan, Weddin, Temora and Bland Shire Councils, and Condobolin, Forbes and Young Pastures Protection Boards;
- Charles Sturt University, CSIRO, Western Research Institute, Western Institute of TAFE and West Wyalong High School; and
- numerous local bodies such as the West Wyalong Anglers and Gardening Clubs.

Some of the projects that the LCF have completed or are involved in include:

- the restocking of Bland and Sandy Creeks with native fingerlings;
- Lake Cowal and Bland Creek revegetation projects;
- Bland Creek Catchment Incentives Grants Project that has combined contributions of approximately \$5 million;
- a Natural Sequence Farming project which aims to reconnect the hydrologic function of the ten kilometre Spring Creek with its floodplain;
- collaborative research with CSIRO Plant Industry into native grassland population dynamics;
- Pasture Re-establishment Trials and Pasture Cropping Trials;
- the LCCC; and
- seed collection, assessment of remnant vegetation and establishment of a herbarium.

The LCF continues to be an important organisation with conservation, pastoral, community, government, educational and mining groups working collaboratively together to achieve considerable outcomes for the Lake Cowal region.

## 5 REHABILITATION REPORT

### 5.1 BUILDINGS

No buildings were renovated or removed from ML 1535 during the reporting period.

### 5.2 REHABILITATION OF DISTURBED LAND

A chronological summary of the rehabilitation of the CGM undertaken to date is provided below.

A total of 22 ha were prepared for rehabilitation works during the 2008 reporting period (Figure 4) on the southern portion of the SWE and on the STSF. A large trial plot was established on the southern outer batter of the SWE by the end of September 2009 to conduct rehabilitation trial work consistent with the on-site learnings from the inside east pit wall trials. Of the 100 tube stock trees planted across the topsoil plots in the SWE trial area in December 2010 there was no survival. Direct seeding was trialled in October 2011 just prior to a significant rainfall event (dry winter). DnA Environmental conducted testing of soil profile nutrients and root penetration for previous eucalyptus planting survivors during surveys in late-2012. Weeping Myall (*Acacia pendula*), have regenerated fairly well in amongst the grasses, weeds and shrubs cover on the topsoil trial portions at the end of the 2012 reporting period.

The 8ha of the outer slopes of the 2<sup>nd</sup> Lift of the NTSF were rehabilitated using the rock-topsoil method during 2009. North and south side trial plots were constructed on the lower slopes of the NTSF by the end of September 2009 in response to comments from the IMP. Independent evaluation and monitoring by DnA Environmental of the outcomes of NTSF and SWE trial plot treatment covers for waste rock was ongoing during the reporting period. The outcomes of the rehabilitation trials to date are described in Paragraph 5.4.

The rock-topsoil cross-rip rehabilitation method used in the 2<sup>nd</sup> Lift of NTSF was applied to a designated trial area on the northern slopes of the western extension to NWE (adjacent to Pond D1) after agreement to extend the trial was received from DTIRIS (DRE) on 6 January 2010. About 2 ha had been treated with gypsum and a further 6 ha was in progress by the end of the 2010 reporting period. Substantial re-shaping works were required adjacent Pond D1 during 2010 and 2011 to facilitate the establishment of the Pond D1 north trial plot area.

The rehabilitation activities undertaken during the reporting period were consistent with the principles and objectives described in the MOP (2011 – 2012 and 2012 – 2014). As described in the 2012 to 2014 MOP, the cover system concept for the final landform batters will be revised based on the results of rehabilitation cover treatment trials conducted to date. The concept would include using a rock mulch-topsoil cover on the batter slopes and include cross-ripping with approximately 10 t/ha gypsum. The concept (based on CGM rehabilitation trial outcomes) is considered in accordance with CGM rehabilitation principles and objectives presented in the EIS.

Approximately 6 ha of the 3<sup>rd</sup> Lift of the STSF was rehabilitated during the reporting period using the waste rock – topsoil cross-rip method with wheaten straw used to protect the northern slope from the harsher conditions in the times between rains. During late-2011 and into early-2012, 8 ha of the 3<sup>rd</sup> Lift of the NTSF was also rehabilitated using the waste rock – topsoil cross-rip method with gypsum at 10 t/ha.

During late-2012 to early-2013, 8 ha of the 4<sup>th</sup> Lift of the NTSF was rehabilitation using the waste rock – topsoil cross-rip method and with gypsum at least 10 t/ha.

During November – December 2011 the foreshore of the LPB was rock armoured given the forecast of a wet start to 2012. The Lift above the LPB received all the stripped waste rock – topsoil layer from the proposed Pond D1 north trial area (fresher, more homogenous topsoil was required for the replicate trial plots to be of value). A number of large gullies toward the southern end of the first Lift above the LPB were dozed out and re-packed, and then covered with waste rock – topsoil cross-ripped with gypsum at 10 t/ha as added protection.

The soil stockpile characterisation programme undertaken by McKenzie Soil Management and Carnegie Natives, commenced during the prior reporting period, and concluded during the 2013 reporting period. As per Barrick MOP (October 2012 – January 2014), soil resource characterisation has begun to allow Barrick to better define the quality and volume of soil resources present and inform rehabilitation efforts now and into the future. The CGM MOP (2014 – 2016) will describe how higher salinity subsoil and topsoil stockpiles will be ameliorated by gypsum treatment.

During late-2012 to early-2013, approximately 6 ha of the 4<sup>th</sup> Lift of the STSF was rehabilitation using the waste rock – topsoil cross-rip method and with gypsum at least 10 t/ha. Clean wheaten straw was applied to the northern face from end-March 2013 for plant growth protection against the hotter aspect conditions. The west facing outer batter of the 4<sup>th</sup> lift of STSF was also armoured with clean wheaten straw during 2013.

Table 39 provides details of the nature of disturbance, area and rehabilitation status for areas that have been disturbed prior to and during the reporting period.

Rehabilitation works were carried out in the following areas during the reporting period:

- PWE - re-shaped 2<sup>nd</sup> and 3<sup>rd</sup> Lifts of the outside southern and eastern sections;
- NWE – North Wall (extension of Pond D1 rock – topsoil method trials on north-eastern side);
- SWE – South Wall (rock – topsoil trial plots) ongoing monitoring of the direct seeding of November 2011;
- SWE – south wall corner by Pond D4 re-shaped ready for rocking and topsoiling in early 2014;
- Temporary and Lake Protection Bund - road and weed maintenance;
- De-silted the southern UCD lowflow diversion channel sediment basin at end of 2013;
- STSF – Walls (various trials, repairs on north lower wall, and rock - topsoil method on 4<sup>th</sup> Lift); and
- NTSF – Walls (various trials and rock - topsoil method maintenance on 3<sup>rd</sup> Lift).

Topsoil and subsoil stockpiles were relocated from the NWRE Millers Crusher area during late 2012, to allow for construction of the waste emplacement basal layer ahead of waste rock emplacement during the 2013 reporting period.

All disturbed areas/structures had temporary erosion and sediment control measures implemented during construction in accordance with the EIS and ESCP. Control measures included temporary sediment traps, sediment filters, diversion banks and silt fences. Further detail of erosion and sediment control measures for these areas/structures is described in Paragraph 3.2.2 and presented in the ESCP.

### ***Perimeter Waste Emplacement***

The PWE has been constructed to approximately RL 223 m and surrounds the pit to the north, east and south (Figure 3). The emplacement occupies an area of approximately 60 ha. It forms part of the series of embankments (i.e. Temporary Isolation Bund and Lake Protection Bund) between the open pit and Lake Cowal. The emplacement elevation has been designed to reduce potential noise and light impacts of mining and processing on the surrounding environment.

As per the January 2009 s96(1A) Modification, the PWE bund wall to the north-east of the open pit was reduced in height to maintain geotechnical performance during vertical advancement of the pit floor. This cut reshaped the inside eastern pit wall from June 2009 and removed the northern half of the earlier rehabilitation trial plots in mid-March 2010. The 1<sup>st</sup> eastern Lift of the PWE was repaired using the rock – topsoil method with gypsum at 10 t/ha along the full length whilst rock armouring of the outer face of the LPB was conducted from November 2011.

In early 2012, before the Lake Cowal fill event of March, the first Lift above the LPB access road and the lower face in the TIB-LPB (wave break), was retreated by repairs with the waste rock, topsoil and gypsum methodology.

During 2013, the remaining portions of the eastern side of the PWE will be retreated using the same method. No tube stocks have been planted due to the dry end of 2012 and start to 2013. The late 2011 direct seeding trial works at the SWE are yet to mature enough to warrant independent consultant review on the effectiveness of the applied mix.

**Table 40**  
**Nature of Disturbance and Rehabilitation Status of Disturbed Land at the end of the Reporting Period**

Disturbed Area	Nature of Disturbance				Area (ha) (approximate)	Rehabilitation Status
	Vegetation Cleared	Topsoil and Subsoil Stripped	Earthworks	Construction Works Status*		
NTSF						
• Floor	✓	✓	✓	Complete	168	Not yet rehabilitated
• Starter embankment	✓	✓	✓	Complete	15	Shaped and covered
• Upstream lift	✓	✓	✓	Commenced	20	Rock-topsoil cover
STSF						
• Floor	✓	✓	✓	Complete	156	Not yet rehabilitated
• Starter embankment	✓	✓	✓	Complete	15	Shaped and covered
• Downstream lift	✓	✓	✓	Complete	24	Some sections shaped and covered
• Upstream lift	✓	✓	✓	Commenced	18	Rock-topsoil cover
Open Pit	✓	✓	✓	Commenced	107	Not yet rehabilitated
PWE	✓	✓	✓	Commenced	60	Southern section shaped and covered
NWE (excluding outer batters)	✓	✓	✓	Commenced	230	Not yet rehabilitated
SWE (excluding outer batters)	✓	✓	✓	Commenced	140	Southern section shaped
NWE and SWE outer batters	✓	✓	✓	Commenced	20	Some sections shaped and covered
Ore Stockpiles	✓	✓	✓	Commenced	58	Not yet rehabilitated
Tailings service corridor	✓	✓	✓	Complete	5	Not yet rehabilitated
Soil stockpiles	✓	✓	✓	Commenced	125	Not yet rehabilitated
Processing plant (including contained water storages D5 and D6)	✓	✓	✓	Complete	20	Not yet rehabilitated
Mining Hardstand (including workshop and fuel farm)	✓	✓	✓	Complete	8	Not yet rehabilitated
Internal mine access road	✓	✓	✓	Complete	8	Not yet rehabilitated
Contained water storages D1 and D4	✓	✓	✓	Complete	5	Not yet rehabilitated
Contained water storages D2, D3, D8A and D8B	✓	✓	✓	Complete	11	Not yet rehabilitated

\* Construction works status refers to earthworks, excavations and/or emplacement of material.

**Table 40 (Continued)**  
**Nature of Disturbance and Rehabilitation Status of Land under Rehabilitation at the end of the Reporting Period**

Disturbed Area	Nature of Disturbance				Area (ha) (approximately)	Rehabilitation Status
	Vegetation Cleared	Topsoil and Subsoil Stripped	Earthworks	Construction Works Status*		
Contained Water Storage D9	✓	✓	✓	Complete	13	Not yet rehabilitated
Stilling basin and outfall	✓	✓	✓	Complete	1	Not yet rehabilitated
Temporary tank and holding pond for bore field water	✓	✓	✓	Complete	<1	Not yet rehabilitated
Mine dewatering bores	✓	N/A	✓	Complete	<1	Not yet rehabilitated
Minor internal roads and haul roads	✓	✓	✓	Commenced	40	Not yet rehabilitated
Temporary laydown areas	✓	✓	✓	Complete	1	Not yet rehabilitated
Exploration Geology office	✓	✓	✓	Complete	1	Not yet rehabilitated
Administration office	✓	✓	✓	Complete	1	Not yet rehabilitated
Temporary administration office	✓	✓	✓	Complete	1	Not yet rehabilitated
Borrow pit within NWE	✓	✓	✓	Complete	10	Not yet rehabilitated
ML 1535 perimeter fence	✓	N/A	✓	Complete	<1	Not yet rehabilitated
Magazine compound	✓	✓	✓	Complete	2	Not yet rehabilitated
Temporary isolation bund	✓	✓	✓	Complete	10	Shaped and covered
Lake protection bund	✓	✓	✓	Complete	10	Shaped and covered
Up-catchment diversion system	✓	✓	✓	Complete	2	Rehabilitated and under maintenance
Internal catchment drainage system (permanent catchment divide)	✓	✓	✓	Complete	2	Rehabilitated and under maintenance
BCPC water supply pipeline	✓	✓	✓	Complete	2	Not yet rehabilitated
Saline groundwater supply borefield and associated pipeline	N/A	✓	✓	Commenced	10	Not yet rehabilitated
Boart Longyear office	✓	✓	✓	Complete	1	Not yet rehabilitated
Bioremediation area	✓	✓	✓	Complete	1	Not yet rehabilitated
Waste management yard	✓	✓	✓	Complete	1	Not yet rehabilitated
TSF construction compound	✓	✓	✓	Complete	1	Not yet rehabilitated

N/A: Not applicable

\* Construction works status refers to earthworks, excavations and/or emplacement of material.

A summary of the construction and rehabilitation measures relevant to the PWE is provided below.

#### *Physical and Chemical Characteristics of Emplaced Material Relevant to Rehabilitation*

Material within the perimeter waste rock emplacement consists primarily of oxide waste rock. Oxide waste rock will be typically saline and non-acid forming silty clayey rock fill. This material will break down following track rolling/compaction and will most likely form a material of medium to low permeability.

#### *Method of Land Shaping*

The perimeter waste rock emplacement has been constructed in approximately 5m to 10m lifts with land shaping and rehabilitation works to be undertaken progressively during run-of-mine operations.

#### *Characteristics of Cover Material*

As described above, based on rehabilitation trial results to date, the cover material of the waste emplacement batters likely to provide stable landforms and successful revegetation performance includes a rock mulch topsoil cover treatment. As a result, areas of the PWE have been reshaped and covered using this cover system.

#### *Thicknesses of Cover Layers and Methods of Laying and Compaction*

The cover system concept includes approximately 0.25 m deep layer of rock mulch, cross-rippled with 10 t/ha gypsum and a layer of 0.25 m topsoil. Topsoil will be transferred from soil stockpiles or directly from newly stripped areas and be spread using tractors, dozers and scrapers.

#### *Drainage and Erosion Control*

Batter drainage will be affected by the use of wide reverse-graded berms every 5m vertical height. The berms will diffusely grade inwards and the surfaces be kept as rough as possible to maximise absorption. This will have the effect of absorbing and storing rainfall in all but extreme events (in which case, runoff will longitudinally fall along the berms to be held for absorption by a series of depressions constructed every 50m – 100m in the reverse-grading berms). This minimises the use of artificial drainage structures on the batters. Drainage on the top surfaces of the emplacement will be similarly managed via a series of small shallow basins (depressions) and deep cover of high absorption capacity. The use of depressions is aimed at maximising internal drainage without creating permanent ponding during normal and heavy rainfall events. The reverse-graded berms will be progressively installed as the lifts are constructed.

In-field observations of slope response to heavy rainfall during the 2008 reporting period prompted a review of the risks associated with proposed methods of rehabilitation. The large-scale trial area on northern slopes of the NWE is being constructed to assess the performance of various treatments associated with the rock mulch/topsoil cover systems.

#### *Final Landform Profile and Slopes*

A typical section through the perimeter waste rock emplacement and lake isolation system is shown in Figure 20. Typical slopes of the perimeter waste rock emplacement will be 1(V):5(H) (Figure 20).

#### *Soil Treatment*

Soils to be used in rehabilitation are treated with gypsum where necessary. Gypsum will be spread over the waste rock by tractor spreader before topsoiling as areas become available. It is anticipated that a rate of 10 t/ha will be used. A scientific trial using six different types of mulch was initiated in 2006 with full results forming the basis of a thesis by an ANU honours student during the 2008 reporting period. An ANU PhD student continued investigations into soil treatment and plant species combinations for optimum rehabilitation during the 2010 and 2011 reporting periods. This work is discussed further in Paragraph 5.4.

Additionally, as a component of the soil treatment soil characterisation works, gypsum application rates for the stockpiles have been prepared by McKenzie Soil Management (2013) and are detailed in their *Cowan Gold Mine Soil Stockpile Characterisation Report*.



### *Revegetation Species and Methods for Establishment*

Top surfaces of the emplacements and outer batters will be revegetated following placement of topsoil with native and introduced grasses. Barrick is still reviewing options for the PWE with continued poor growth during dry 2012 conditions. The results of the 2<sup>nd</sup> Lift of NTSF and the SWE trial plots suggest that no seeding is necessary when using the new rock mulch-topsoil method. As discussed in Section 5.4, early observations of the surface treatments (e.g. rock mulch) trials on the outer batters of the waste rock emplacements are positive (i.e. landforms are stable and vegetation is establishing within the rock mulch) and indicate that this cover treatment is likely to provide for successful rehabilitation of mine landforms at the CGM (Barrick, 2011). 3<sup>rd</sup> Lifts of the STSF and NTSF have also been conducted using waste rock – topsoil method using gypsum at 10 t/ha and wheaten straw along the northern face and are demonstrating similar trends.

Long-term rehabilitation of the waste rock emplacement will be informed by the results of the rehabilitation trials carried out over the mine life and would include the progressive re-establishment of woodland community species with the planting/seeding of local native grasses, shrubs and trees.

### *Extent to which Agreed Rehabilitation Outcomes and Landuse Have Been Met*

The proposed progressive rehabilitation of the perimeter waste rock emplacement is in accordance with rehabilitation concepts presented in the EIS. Further rehabilitation of the emplacement will be undertaken to achieve final rehabilitation outcomes and other subsequent environmental approvals in accordance with the EIS.

### *Maintenance Activities/Requirements*

Visual monitoring of revegetated landforms including the perimeter waste rock emplacement will be conducted to ensure vegetation is establishing and to determine the need for any maintenance and/or contingency measures (such as the requirement for supplementary plantings, erosion control and weed control). The early 2012 and mid 2013 rehabilitation works are subject to ongoing independent consultant review of effectiveness.

### ***Northern and Southern Waste Rock Emplacements – Outer Batters***

The NWE will be constructed to approximately 266 m AHD and will occupy an area of approximately 230 ha northwest of the pit. The SWE will be constructed to approximately 250 m AHD and will occupy an area of approximately 140 ha southwest of the pit (in accordance with the modification of the Development Consent on 10 March 2010).

### *Physical and Chemical Characteristics of Emplaced Material Relevant to Rehabilitation*

Material within the northern and southern waste rock emplacements predominantly consists of primary waste rock and a minor proportion of oxide waste rock.

### *Method of Land Shaping*

The waste rock emplacements will be constructed in lifts with land shaping and rehabilitation works to be undertaken progressively during run-of-mine operations. Land shaping will be carried out by graders and dozers and will involve the construction of drainage and erosion and sediment control features.

During the 2008 reporting period, a 22ha portion of the southern wall of the SWE was shaped to be used for a rehabilitation trial area. During the 2009 reporting period, a series of large trial rehabilitation plots were established in this area to assess the erosion potential of various cover treatments (Plate 10 below).

The 22ha portion of SWE was re-shaped and extended by about 10ha by dozer during 2012. The area immediately adjacent the intake to Pond D4 was rocked and shaped at the end of the 2012 year.

Topsoil-rocking and gypsum ripping for the majority of the outer batters of the SWE is scheduled to occur during 2014. The same equipment will be scheduled to complete the NWE northern topsoil-rock ripping during 2014.

#### *Characteristics of Cover Material*

The waste emplacement outer batter cover material will be of low salinity to avoid the potential for saline runoff and enable satisfactory vegetation growth. The cover system concept for the NWE and SWE batters will be the same as applied to PWE described earlier in this section.

#### *Thicknesses of Cover Layers and Methods of Laying and Compaction*

The cover system concept for the NWE and SWE batters will be the same as applied to PWE described earlier in this section.

#### *Drainage and Erosion Control*

Batter drainage will be the same as applied to PWE described earlier in this section.

#### *Final Landform Profile and Slopes*

A typical section through the waste rock emplacement is shown in Figure 21. Typical slopes of the waste rock emplacements will be 1(V):5(H).

#### *Soil Treatment*

Soils to be used will be the same as applied to PWE described earlier in this section.

#### *Revegetation Species and Methods for Establishment*

Outer batters of the emplacements will be the same as applied to PWE described earlier in this section.

In November 2011 a direct seeding application of local provenance stock was applied to the topsoil plots of the SWE south trial area. Plate 11 provides a visual summary of the varieties of treated native seed that was broadcast.

DnA Environmental conducted surveys of nutrient in soil profile and tree root penetration tracking through the SWE south trial plots (as per Independent Monitoring Panel recommendation (2011 report)). The results of DnA Environmental's survey is provided in Paragraph 5.4.

#### *Extent to which Agreed Rehabilitation Outcomes and Landuse Have Been Met*

The proposed progressive rehabilitation of the waste rock emplacements is in accordance with rehabilitation concepts presented in the EIS and the currently approved Cowal Gold Mine Modified Request Environmental Assessment (Barrick, 2009) Further rehabilitation of the emplacements will be undertaken to achieve final rehabilitation outcomes and landuse in accordance with the EIS.

#### *Maintenance Activities/Requirements*

Visual monitoring of revegetated landforms including the northern and southern waste rock emplacements will be conducted to ensure vegetation is establishing and to determine the need for any maintenance and/or contingency measures (such as the requirement for supplementary plantings, erosion control and weed control).

#### **Temporary Isolation Bund and Lake Protection Bund**

The temporary isolation bund was designed to control water inflow to the open pit development area from the lake during construction of the lake protection bund (Figure 20). This structure was designed with a short-term function, however, the bund will remain until stability of the PWE is assured. The permanent lake protection bund is a low permeability embankment to prevent water inflow from the lake into the open pit development area over the life of the mine and in the longer term.

*Physical and Chemical Characteristics of Emplaced Material Relevant to Rehabilitation*

The Australian National University (ANU) Honours project (Paragraph 5.4) undertaken during 2006 indicated that the soil was potentially dispersive. Amelioration with gypsum was undertaken in August 2006 at a rate of 5 t/ha tractor spread over the surface area of the Lake Protection Bund.

In early 2012, before the Lake Cowal fill event of March, the first Lift above the LPB access road and the lower face in the TIB-LPB (wave break), was reshaped and treated with the waste rock, topsoil and gypsum methodology.

Since the inundation of the TIB in March 2012 by the Lake Cowal flood event, there has been significant growth of native plants on the east face of the TIB due to the continued availability of water. The east face of the LPB was adequate to withstand wave action during the flood until the water receded back below the top of the TIB in July 2012.

**Plate 6**  
**TIB – Eastern Face Native Re-growth**



*Method of Land Shaping*

The temporary isolation bund was constructed to RL 206.5m, has a crest length of 3,170m and reaches a height of 2m in the centre of the arc. Approximately 180,000m<sup>3</sup> of fill was required for construction. Settlement analysis undertaken by SNC Lavalin (SNC Lavalin, 2004) indicated the subsurface formation is typically well consolidated and any settlement is likely to cease soon after completion of the construction period. Prior to commencement of construction and, in accordance with the EIS, a silt fence was erected to provide the lake protection from any sediment laden runoff. Prior to the placement of fill, the upper approximate 300mm of topsoil was stripped from the footprint area of the bund and stored for later rehabilitation of the bund. The bund was constructed in short sections with placement and compaction of the fill section in 0.3m lifts. Following construction of the bund to its final height the structure was shaped and the side slopes were flattened to slopes of 4(H):1(V) on the mine side and 5(H):1(V) on the lake side (Barrick, 2007). Further details on rehabilitation of the structure are provided in Paragraph 4 of the 2012 – 2014 MOP (Barrick, 2012).

The lake protection bund has been constructed to its final height of RL 208.35m. The structure was built as a two-zone earthfill embankment and meets specific engineering criteria for compaction to ensure that required compaction densities are achieved. The bund has a crest length of 4,200m and approximately 500,000m<sup>3</sup> of fill was used for construction. Prior to construction, the upper 300mm of topsoil and loose clay sediment material were stripped and stored for future rehabilitation of the bund. A cut-off section a further 1.7m deep was constructed as a means of even further reducing the expected minimal seepage under the bund system.

Placement and compaction of the fill section was conducted in 0.3m lifts. Following construction of the bund to its final height, the structure was shaped and the lake side slope flattened to 5(H):1(V) (Barrick, 2010). Further details on rehabilitation of the structure are provided in the 2012 - 2014 MOP (Barrick, 2012).

Short-term heavy rain during the 2011 reporting period lead to degradation and temporary closure of the lake protection bund access road. The first lift of the LPB outer slope was repaired using the rock-topsoil method and gypsum at 10 t/ha from November 2011 after the north-east outer slopes of the NWE were shaped up and rock – topsoil treated for the Pond D1 north trials. The top of the LPB was covered in a 0.5 m layer of course crushed waste rock with a fines finish in March 2012 and the road is now an all weather access.

#### *Characteristics of Cover Material*

The cover material will be of low salinity to avoid the potential for saline runoff and enable satisfactory vegetation growth.

#### *Thicknesses of Cover Layers and Methods of Laying and Compaction*

Prior to the placement of fill, the upper approximate 300mm of topsoil was stripped from the footprint area of the bund and stored for later rehabilitation of the bund.

#### *Drainage and Erosion Control*

Incidental rainfall runoff from the LPB outer face is held by the temporary isolation bund.

#### *Final Landform Profile and Slopes*

A typical section through the perimeter waste rock emplacement and lake isolation system is shown on Figure 20. Typical slopes of the perimeter waste rock emplacement and lake protection bund will be 1(V):5(H) (Figure 20).

#### *Soil Treatment*

Soils used in rehabilitation have been treated with gypsum. Gypsum had previously tractor spread over the topsoiled surface of the LPB a rate of 5 t/ha.

#### *Revegetation Species and Methods for Establishment*

The New Lake Foreshore will continue to be opportunistically revegetated (subject to seasonal conditions) using native seedlings (propagated on-site or obtained from a supplier) and direct seeding.

#### *Extent to which Agreed Rehabilitation Outcomes and Landuse Have Been Met*

During the prior 2years there was no additional revegetation work undertaken on the LPB. The 2010 rains and wet start to 2011 appears to have increased cover marginally, however, the cessation of traffic along the top of the bund by placement of log stocks was the main contributor to growth (G Pearson 2011, *pers. comm.*). The Lake Fill placed water against the TIB from August 2010 and water sat between the TIB and LPB for all of the recent reporting period.

#### *Maintenance Activities/Requirements*

Barrick proposes to raise the height TIB by 0.5 metre when Lake Cowal recedes to a suitably safe distance from the toe of the TIB. These works would be undertaken in consultation with DTIRIS-DRE when necessary.

Visual monitoring of revegetated landforms including the bunds will continue to be conducted to ensure vegetation is establishing and to determine the need for any maintenance and/or contingency measures (such as the requirement for supplementary plantings, erosion control and weed control). Vegetation monitoring of the new lake foreshore was undertaken during the reporting period.

There were no variations in activities undertaken from those proposed in the MOP.

### ***Northern and Southern Tailings Storage Facility – Starter Embankments and Lifts***

The tailings storage facilities are located 3.4km west of the Lake shoreline. Starter embankments have been progressively raised throughout the mine life with tailings disposal alternating between each facility. The STSF starter embankment was completed and the facility was commissioned in May 2006 for disposal of oxide tailings. The NTSF starter embankment was completed and the dam commissioned in April 2007 for disposal of sulphide tailings. The STSF required a downstream and upstream lift to meet geotechnical design concerns for the oxide layer and was commissioned in mid-2008. The NTSF received a 2nd Lift in 2009 and was commissioned in late-2009. The 3<sup>rd</sup> Lift (2<sup>nd</sup> augmentation) of the STSF was in progress from late-2009 until mid-2010 and used the waste rock – topsoil cross-rip method with 10 tonnes of gypsum per ha and wheaten straw mulch was also applied along the northern and western faces. Repairs were made along the original un-rocked lower Lift face using the waste rock – topsoil method with straw after gully erosion occurred on them in several places in 2011 and 2012 years.

Approximately 8 ha of the outer slopes of the 2<sup>nd</sup> Lift of the NTSF was rehabilitated using the trial waste rock-topsoil cross-rip method during 2009. North and south side trial plots were constructed on the lower slopes of the NTSF by end-September 2009 after written approval was received from the DP&I in response to supporting comments from the Lake Cowal IMP. Rock ribbons, woodchips, rock-topsoil, rock mulch and straw rehabilitation trials of outer slopes of the STSF occurred from February to October 2009. Outer slope rehabilitation trials on the initial lift walls of the NTSF during the same period consisted of biosolids, bioremediation solids, straw and rock mulch and rock-topsoil and were completed by October 2009. Monitoring of these trials continued during the reporting period. The 3<sup>rd</sup> Lift of the NTSF was rehabilitated using the waste rock – topsoil method and 10 tonnes gypsum / ha from late-2011 until early-2012.

The 4<sup>th</sup> Lift (3<sup>rd</sup> augmentation) of the STSF occurred from mid-2012 until end-2012 (a MOP (2011-2012) variation was sought for this activity). The 4<sup>th</sup> Lift of the NTSF will commence in late-2013. Rehabilitation of the outer batter occurred late-2013 using the rock, topsoil, gypsum and wheaten straw armour methodology.

#### *Physical and Chemical Characteristics of Emplaced Material Relevant to Rehabilitation*

Material used in the construction of the tailings storage facilities starter embankments includes soft oxide waste rock and clays. Results of recent and past geochemical testing indicate that oxide waste rock will be typically saline and non-acid forming silty clayey rock fill. Clays excavated from within the tailings storage footprints are expected to be stable with low permeability and high strength when compacted (North Limited, 1998).

Soils to be used in rehabilitation will be treated with gypsum by tractor spreading 10 t/ha in the waste rock before topsoiling.

#### *Method of Land Shaping*

The cover system concept for the tailings storage facility batters has also been updated to include rock mulch and topsoil and would be consistent with the updated concept for the waste emplacement batter cover system.

#### *Characteristics of Cover Material*

The characteristics of the cover materials is the same as applied to the WREs.

#### *Thicknesses of Cover Layers and Methods of Laying and Compaction*

Similar to the proposed waste rock emplacement cover system, the proposed thickness of the rock mulch layer would be 0.25 m followed by a 0.25 m thick layer of topsoil.

The cover system for the top surfaces of TSFs will be conducted according to a mine closure plan and would include capping and shallow-medium root depth species.

#### *Final Landform Profile and Slopes*

The final landform profile for the tailings facility starter embankments is shown in Figure 22. Typical slopes of the downstream rehabilitation zone will be 1(V):5(H).

### *Soil Treatment*

Soils to be used in rehabilitation will be treated with gypsum where necessary.

### *Revegetation Species and Methods for Establishment*

The downstream rehabilitation zone will be ripped and seeded. Revegetation species will include native and introduced grasses. As a result of the hay mulching on the northern wall of the NTSF in previous years, germination of annual grass species and groundcover was generally quite good compared to the untreated eastern wall. No additional seeding took place on the NTSF or STSF starter embankments during the reporting period.

As discussed in Paragraph 5.4, early observations of the surface treatments (e.g. rock mulch) trials on the outer batters of the tailings storages are positive (i.e. landforms are stable and vegetation is establishing within the rock mulch) and indicate that this cover treatment is likely to provide for successful rehabilitation of mine landforms at the CGM (Barrick, 2011).

### *Extent to which Agreed Rehabilitation Outcomes and Landuse Have Been Met*

The proposed progressive rehabilitation of the walls of the NTSF and STSF starter embankments is in accordance with rehabilitation concepts presented in the EIS and subsequently in proposed preliminary EA MOD11 (late-2013). Further rehabilitation of the embankments will be undertaken to optimise rehabilitation outcomes and landuse in accordance with the EIS. The short term rehabilitation objectives for the NTSF are to establish good groundcover using native and exotic pasture species. The long-term rehabilitation of the tailings storages will include the re-establishment of woodland communities and will commence following the cessation of tailings deposition.

The existing rehabilitation trials on the tailings storage facilities involving various mulch treatments and native species combinations continued to be monitored during the reporting period in accordance with Recommendations 2 and 3 of the Sixth Annual Report of the IMP. Results from rehabilitation trials established on the tailings storage facilities are detailed in Paragraph 5.4.

### *Maintenance Activities/Requirements*

Visual monitoring of revegetated landforms including the NTSF and STSF starter embankments will be conducted to ensure vegetation is establishing and to determine the need for any maintenance and/or contingency measures (such as the requirement for supplementary plantings, erosion control and weed control). A 1 ha area was prepared for a small biosolids trial during the 2009-2010 reporting period. The intent of the trial was to assess the benefit of using biosolids with mulch for rehabilitation works. The trial showed best results for 45 tonnes per hectare application rate reducing to negligible growth at 15 tonnes per hectare. A monoculture of a grass appeared to flourish in this area and therefore biosolids is not being pursued as a rehabilitation tool at this time (G Pearson 2011, *pers. comm.*).

Any emergent deeper rooted species that germinate in the walls of the TSF structures continued to be poisoned by stump paste with glyphosate. As per ongoing Cowal Mine TSF fauna protection practices, no trees shall be encouraged to grow until after the final capping is completed on the TSFs.

### **Contained Water Storage D9**

The D9 water storage facility occupies an area of approximately 13 hectares and has an operational maximum volume of 690 Million Litres (ML).

### *Physical and Chemical Characteristics of Emplaced Material Relevant to Rehabilitation*

Rehabilitation of the water storage will be undertaken to optimise rehabilitation outcomes and land use in accordance with the EIS.

### *Method of Land Shaping*

The water storage was constructed as a “turkey’s nest” type of dam with no direct catchment external to its perimeter embankment. The dam has a nominal fill height of 8 Metres (m) and a nominal cut depth of approximately 2 m. Freeboard for a 1 in 100 year Annual Recurrence Interval (ARI) 48 hour rainfall event will be maintained in the storage.

#### *Characteristics of Cover Material*

The embankment cover material will be of low salinity to avoid the potential for saline runoff and enable satisfactory vegetation growth. The embankments will be covered with rock mulch-topsoil cover system.

#### *Thicknesses of Cover Layers and Methods of Laying and Compaction*

Topsoil that had been stripped from the footprint of the dam was used to cover the outer batters of the facility with a depth of 250 mm using an excavator.

#### *Drainage and Erosion Control*

The outer walls drain to the adjacent stormwater Pond D8B.

#### *Final Landform Profile and Slopes*

The outer slopes of Pond D9 were topsoiled and are sloping at about 1 (V): 4 (H).

#### *Soil Treatment*

Soils to be used in rehabilitation will be treated with gypsum where necessary.

#### *Revegetation Species and Methods for Establishment*

Outer batters of the storage was revegetated following placement of topsoil with native and introduced grasses.

#### *Extent to which Agreed Rehabilitation Outcomes and Landuse Have Been Met*

The rehabilitation on the embankments of Pond D9 did not exhibit any useful surface growth on the northern face and much of the western face during the recent decade of drought. The wet start to 2011 resulted in good growth on all faces except the north. Consequently re-ripping and straw mulching of the northern face was conducted during the 2011 reporting period. Rehabilitation of the storage will be undertaken to achieve final rehabilitation outcomes and landuse in accordance with the EIS. The east, south and west walls of Pond D9 were dozed to remove small surface gullies and thatch armoured with clean wheaten straw during 2011. There has been no further erosion and cover remains good on these slopes. During 2012, the north-eastern corner was lightly ripped and bladed by dozer and then covered in clean wheaten straw thatch manually (machinery access restrictions by design top edge).

#### *Maintenance Activities/Requirements*

Visual monitoring of revegetated landforms including Pond D9 continued be conducted during the reporting period to ensure vegetation is establishing and to determine the need for any maintenance and/or contingency measures (such as the requirement for supplementary plantings, erosion control and weed control).

#### **Boundary Amenity Plantings**

No additional tubestock was planted during the reporting period.

### **5.3 OTHER INFRASTRUCTURE**

No other rehabilitation activities were conducted during the reporting period further to those described above.

## 5.4 REHABILITATION TRIALS AND RESEARCH

Since 2008, Barrick has commissioned numerous specialists/expert personnel to work with mine and University personnel on the following issues relevant to the rehabilitation/stabilisation of landforms at the CGM:

- Geo-Environmental Management Pty Ltd – review of erosion control and restoration strategies for the Lake Protection Bund, Waste Rock Emplacement and Tailings Storage Facilities. Specifically, the investigation of the geochemical suitability of rock armouring on the outer batters of the mine landforms.
- Landloch – completion of a surface materials assessment and review of rehabilitation strategies and landform design. Specifically, investigation and recommendations regarding erosion control, landform design and the suitability of different treatment materials (e.g. rock mulching).
- Gilbert and Associates – assessment and revision of the rehabilitation and water management concepts, particularly in regard to erosion control and water management on the top surfaces of the mine landforms.
- Australian National University – ongoing trials and research relevant to revegetation and alternative surface treatment measures (e.g. mulch) that will assist in the refinement of revegetation objectives. Additional research into topsoil resources and investigation into optimal topsoil amendment rates (i.e. gypsum treatment) and fertiliser treatments.
- DnA Environmental - design of rehabilitation monitoring methodology and trial design and to determine a set of completion criteria that complies with and is consistent with conditions specified with Management Plans and approval documents and relevant NSW legislation, policies and best practice guidelines.
- McKenzie Soil Management – sampling and characterisation of the CGM's stockpiled soil resources to inform the most appropriate soil treatment measures to improve the soil stocks for rehabilitation use.
- Carnegie Natives - design of rehabilitation monitoring methodology and revegetation tube trial design to assist in informing CGM's rehabilitation programme.
- The results of the abovementioned investigations will be used to inform the progressive rehabilitation/stabilisation of mine landforms at the CGM. Other specialists/expert personnel experienced in dealing with the rehabilitation issues relevant to the CGM (e.g. AECOM formerly URS Corporation, Principal GSS Environmental and the Lake Cowal Foundation) will continue to be engaged where necessary as rehabilitation progresses.

A detailed description of the monitoring results of the new lake foreshore revegetation trials, tailings storage facility and waste rock emplacement revegetation trials, offset areas monitoring and completion criteria establishment by DnA Environmental (2011 - 2013) is provided below.

### ***Rehabilitation Monitoring Methodology and Determination of Completion Criteria: Ecosystem Sustainability***

DnA Environmental was engaged by Barrick in 2011 to design a monitoring methodology and determine a set of rehabilitation completion criteria for the CGM. The primary objective of the monitoring of rehabilitation areas and trials was to establish an annual rehabilitation monitoring program and develop an set of completion criteria that complies and is consistent with conditions of the CGM's approval documents and management plans and aligns with the then applicable DTIRIS (DRE) (2011) *Rehabilitation and Environmental Management Plan Guidelines Consultation Draft V2.0 June 2010*. DnA Environmental subsequently prepared the 2011 report *Rehabilitation monitoring methodology & determination of completion criteria: Ecosystem sustainability*. A description of the monitoring programme and methodology is provided below.

The CGM's monitoring programme aims to establish clearly defined, repeatable and consistent methodologies for monitoring changes in various aspects of ecosystem stability, recovery and long-term sustainability. The process included:

- Establishing a range of relevant reference sites to compare and track the progress of rehabilitation areas and inherent ecosystem function;
- Selecting a range of suitable reference sites that reflect the desired final land use, biodiversity targets, historical disturbances and local community expectations; and



- Undertaking a monitoring program that provides simple and reliable information that indicates positive recovery trends or rapid detection of rehabilitation failure.

The objective behind the use of reference sites is to set the benchmark for rehabilitation success or at least provide a target to achieve. To account for variations in ecosystems across the landscape, each vegetation community is best represented in triplicate. In 2010, there was difficulty in selecting three reference sites for each of the four broad vegetation community types. This was largely due to the lack of suitable area of remnant vegetation in the near vicinity of the mine and due to flooding of some the Lake Cowal Environment.

The broad rehabilitation vegetation communities used within part of this program include those associated with:

- Lake: Woodlands occurring within the lake and lake foreshores (RL 205 – 220m) = 2 sites (one 2010 site inaccessible; one new site established);
- Slopes: Woodland occurring on flat to gently undulating slopes (RL 210 – 225m) = 2 sites;
- Hills: Woodlands occurring on low ridges, hills and elevated land (RL 220 – 245m) = 3 sites; and
- Grass: Cleared native grasslands, predominantly occurring on flat to gently undulating slopes (RL 210 – 225m) = 2 sites.

The resultant number of revegetation monitoring sites established during 2011 was nine. Monitoring during spring aims to capture a more accurate representation of species present in the area. Numerous areas have already undergone some rehabilitation, which will be progressive over the life of the mine.

Results of the DnA Environmental report '*2012 Rehabilitation Monitoring Report*' are described below.

A new approach to rehabilitation and environmental management accountability, including rehabilitation monitoring and completion criteria was drafted and released for consultation by the DITRIS (DnA Environmental, 2011e). The DTIRIS draft guidelines indicate that in order to receive closure sign-off of rehabilitation, it will be necessary to demonstrate that selected performance indicators (or criteria) have reached their established completion criteria or that a satisfactory successional trajectory has been established that will result in a self-sustainable ecosystem. The draft approach includes five major stages of ecosystem development as demonstrated below, by which a set of performance indicators or criteria will need to be monitored and either be equivalent to or exceed those assessed for the reference sites (DnA Environmental, 2011e):

- Landform establishment;
- Growth medium development;
- Ecosystem establishment;
- Ecosystem development; and
- Ecosystem sustainability.

The CGM monitoring methodology was developed in accordance with the DTIRIS-DRE draft guidelines and adopts a standard and simple procedure that can be easily replicated over any vegetation community or revegetation area and importantly results in a system that essentially compares like with like (DnA environmental, 2011e). The methodology used includes a combination of Landscape Function Analysis (LFA), accredited soil analyses and various measurements of ecosystem diversity and habitat values (DnA Environmental, 2011e). For a full description of rehabilitation methodology, refer to the DnA Environmental report titled '*Rehabilitation monitoring methodology & determination of completion criteria: Ecosystem sustainability*'.

The DTIRIS-DRE new MOP Guidelines supersedes the draft 2011 guidelines. Therefore, Barrick will continue to work with DnA Environmental to revise the CGM's monitoring methodology in accordance with the DTIRIS-DRE's new guidelines.

### ***New Lake Foreshore Revegetation Trials***

There have been significant changes occurring on the new lake foreshore area since 2005. The sites have been progressing and are beginning to stabilise despite extreme climatic conditions. The ponded water within the temporary bund has become well established with a variety of aquatic species which have largely colonised from

the soil seed bank. There continues to be active erosion derived from the unvegetated slope and poor drainage construction of the perimeter waste emplacement above the permanent lake protection bund. Despite some remedial earthworks being undertaken during 2011, numerous active gullies remain along the foreshore bunds and will require further amelioration.

Two six year old lake foreshore rehabilitation sites (CWT2 and CWT3) have demonstrated a dramatic improvement in ecological function, but remain short of meeting LFA completion targets. Increasing trends in ecosystem function at these sites can be attributed to increasing cover of vegetative materials including litter and annual and perennial plants.

One lake foreshore rehabilitation site (CWT6) has been significantly affected by wave action eroding almost half of the site, estimated to be in the order of 10m from the original foreshore area. Despite increasing vegetation cover, it appears that the sodic soils are particularly susceptible to waves from the lake. Rock lining may be required to halt further deterioration of the lake foreshore area.

### ***Tailings Dam Walls Revegetation Trials***

The northern and southern tailings storage facility walls have been the focus of additional rehabilitation trials, implemented during 2009. A variety of treatments were setup with a full description provided in the report "2010 Cowal Rehabilitation Monitoring Report" (DnA Environmental, 2011c).


NTSF01 (rock mulch + topsoil on northern TSF) appeared to be more stable and functional compared to other rehabilitation sites in 2010 however there was a significant improvement in NTSF02 (topsoil + wheaten hay on northern TSF) in 2011. Both sites on the northern TSF now have very similar LFA indices for infiltration and nutrient cycling capacity to the grassland reference sites, but remained lower in stability. NTSF01 (rock ribbon + wheaten hay) has demonstrated a decline in overall ecological function and continues to fall well short of meeting LFA targets.

Major changes occurring within the rehabilitation areas in 2011 and 2012 included increased perennial ground cover and typically increased levels of litter cover due to the abundance of annual plants which have colonised the sites.

Sites situated on the NTSF have performed relatively well, but are still considered immature and have further ecological development to undertake. It has been noted in treatments using wheaten hay, the hay was often applied in far greater depths than required, limiting the establishment of plants.

For future rehabilitation, recommendations include applying locally harvested native pasture hay bearing mature seeds immediately onto newly prepared rehabilitation areas, rather than using wheaten hay. Improved analysis of spoil materials prior to use in rehabilitation programs is also required to improve the condition of the growing mediums.

**Plate 7**  
**STSF and NTSF Wall Rehabilitation**



Source: DnA Environmental, 2010

### **Southern Offset**

Two reference sites were established in the southern offset area resembling woodlands occurring on low ridges, hills and elevated land (RL 220 – 245). These communities are dominated by *Eucalyptus dwyeri*, *Acacia doratoxylon*, *Callitris endlicheri* and *E. sideroxylon* on the rockier ridge tops and intergraded with *E. populnea*, *E. microcarpa* and *Callitris glaucophylla* woodlands on the lower parts of the slope. The reference sites that form the revegetation benchmarks and completion targets are named “RHill01” and “RHill02”.

The southern offset area contained a high diversity of ground cover plants and while many of these were exotic annual species or colonising plants, the majority were native species which were increasing in numbers. Exotic species had declined in 2011 and this trend is expected to continue provided there is limited disturbance. The sites were demonstrating additional successional recovery with the further development of vegetative cover and soils surface crusting, increasing abundance of cryptogams, increased soil coherency and reduced erosion and deposition.

Soil properties remained within the local or desirable levels and no adverse soil chemistry was apparent from the soil test results with the exception of increased ESP in Offest02 indicating the soils may have a tendency to disperse. There was a lack of tree and shrub species as well associated structure and habitat requirements indicating these monitoring sites currently fall short of the completion targets. Continual rehabilitation of these sites should show an improvement in Key Performance Indicators (KPIs) providing appropriate species and densities are implemented. As the completion criteria have been derived from the adjacent Hill communities, revegetation activities should aim to replicate these community types (DnA Environmental, 2013c).

AMBS conducted a flora survey and mapping of the CGM and its surrounds (including the offset areas) in April 2012. The results of the survey and mapping are included in this AEMR in Paragraph 3.7.3.1.

### **Northern Offset Woodland revegetation**

Two monitoring sites (Offset03 and Offset04) were established in the northern offset area prior to rehabilitation. The established sites were chosen to resemble *Acacia pendula* – *Casuarina cristata* woodlands occurring on flat to gently undulating slopes. These sites were compared to reference sites RSlope01 and RSlope02.

The northern offset area continued to be a diverse environment and despite a reduction in total floristic diversity, it maintained a high diversity of ground cover plants and was dominated by native plants. The sites were demonstrating positive successional recovery with improved ground cover and in terms of ecological function, both sites were within ranges provided by the woodland slope reference sites. The water filled gilgais were a particularly important feature in these sites in 2010 and while they were dry this year they continued to provide topographic relief and additional habitat features, resulting in a relatively high floral diversity. The sites were similar in composition to the reference sites however they contained slightly more exotic species and lacked a population of shrubs.

The soils differed considerably between the two sites with some significant changes having occurred over the past year. Most primary soil characteristics were similar to the reference sites in 2011 with the exception of low nitrates. Most changes in soil chemistry were attributed to the variable topographic relief provided by the gilgais landscape in combination with high rainfall throughout 2011 and at the start of 2012.

DnA Environmental recommended that as part of the rehabilitation process that deep ripping is not undertaken due to the occurrence of potentially highly sodic soils, gilgais, and the high species richness. Deep ripping may compromise the ecological function and high conservation significance of the site. Any rehabilitation that is to occur should aim to replicate the associated reference sites, taking care to replicate the structure and future habitat requirements of these communities (DnA Environmental, 2013c).

AMBS conducted a flora survey and mapping of the CGM and its surrounds (including the offset areas) in April 2012. The results of the survey and mapping are included in this AEMR in Paragraph 3.7.3.1.

### **Southern Waste Emplacement rehabilitation trials**

These trials were established on the south side of the Southern Waste Emplacement (**SWE**) in late 2009 to examine the benefits of rehabilitating slopes with long continuous slopes compared to a three tiered battered slope, with and without different mulching treatments. A variety of treatments were setup with a full description provided in the DnA Environmental report from 2011 titled *2010 Cowal Rehabilitation Monitoring Report*.

A preliminary assessment was undertaken during March 2010 by DnA Environmental (initial assessment not formal) and minimal difference was observed between the sub soil and no subsoil treatments. Differences between slope types were also minimal but more rilling had occurred on the single continuous slope. Mulch treatments showed more promising stabilising cover (rock and hay) and during this initial assessment there was little vegetative cover. Woodchips provided excellent stabilising cover but seemed to inhibit the growth of vegetation. The rock and topsoil and topsoil only treatments contained the highest establishment of plants, but site stability was questionable.

Whilst the treatments were not subjected to rigorous statistical analysis the results of the 2010 monitoring showed that there was little difference in ecosystem function or plant cover and diversity whether subsoil was applied or not, but there may have been some slight advantage in using a subsoil treatment. There was also little difference between continuous slopes or 3-tiered reverse graded batters except for more rilling in the straight slope. Other observations include some additional erosion control within the reverse graded batter, as a temporary alluvial fan had developed within some of the sub-treatments. Other advantages of the 3-tiered slope include shorter slopes and better and safer access for ongoing revegetation and maintenance activities (DnA Environmental, 2011c).

The better performing sites in terms of ecological sustainability and similarity to the native grassland reference sites were found to be those with a topsoil application. Rock mulch as a treatment (in shallow depths to allow for plant growth) also provides stability in the case of extreme climatic events. As a result, in order to prevent erosion from occurring before the plants have become well established, a light application of rock, woodchips or preferably native pasture hay will provide temporary and critical soil surface protection and erosion control in the initial site establishment phase (DnA Environmental, 2011c).

As with all rehabilitation sites at Cowal, the ability to meet completion targets will depend on the capacity of native perennial plants to drive the ecological functions of the site. Whilst at this stage the sites contain a high number of weedy species, these species are part of the successional process and provide important ground cover and assist in the development of the microbial and nutrient recycling processes. On the other hand, these two sites contained a good representation of native species which are expected to set seed and become more abundant over time.

The SWE South trials were established to examine the benefits of rehabilitating slopes with long continuous slopes compared to a three tiered battered slope, with and without different mulching treatments. The layout of the trial is shown above. The growth rate on the southern aspect has been observed to be higher than the sunny northern aspect (hotter and drier). The trials were constructed in September 2009 as follows using an 8m wide D9 dozer blade as a spacing guide:

- Subsoil (with and without);
- Slope (3 tiered 1:3 battered, single continuous slope);
- Rock mulch (R);
- Rock mulch + woodchips (R+Wc);
- Rock + topsoil + woodchips (R+T+Wc);
- Rock + topsoil (R+T);
- Topsoil (T); and
- Control or No treatment (C).

In 2012, DnA Environmental excavated soil from around the root zone of four tubestock which were planted in 2010 to determine if the seedling roots were able to penetrate through the waste rock layers and to what depth they had reached within a two year growing period. The seedlings were relatively small for being two years old and of the four, two seedlings were spindly and chlorosed which may be the result of their condition when they were first planted (they may have been tall and spindly tubestock in the first place) but this may also be partially reflected in the dry seasonal conditions experienced throughout most of 2011 and 2012, despite flooding during summer in both years. It appears however that the seedlings had well developed root systems that easily penetrated down through the different combinations of topsoil, subsoil and oxide layers, with one major exception in tree 4, where the roots abruptly terminated, reduced in size and/or changed direction when they entered into the oxide layer. While the oxide layers were typically very strongly alkaline and extremely saline and had high levels of sulfur and arsenic in all excavation holes the tree roots appeared to have penetrated into this layer in three of the four excavation holes. Therefore DnA Environmental did not find any consistent and conclusive evidence that suggests that the seedling roots do not or cannot penetrate any of the strata used in this rehabilitation site.

DnA will be consulted for a progress review on the performance of these trials in 2014. Direct seeding may have produced a suitable number of seedlings in the next few years to assist future rehabilitation (Plate 9).

**Plate 8  
SWE – Southern Slope Trial Plots**

October 2009



March 2010



July 2011



October 2012



January 2013



May 2014



No Subsoil											Subsoil												
3 tiered Batter (1:3)						Single continuous slope (1:5)					Single continuous slope (1:5)					3 tiered Batter (1:3)							
R	R+W <sub>c</sub>	R,T+W <sub>c</sub>	R+T	T	C	R	R+W <sub>c</sub>	R,T+W <sub>c</sub>	R+T	T	C	R	R+W <sub>c</sub>	R,T+W <sub>c</sub>	R+T	T	C	R	R+W <sub>c</sub>	R,T+W <sub>c</sub>	R+T	T	C



**Plate 9**  
**SWE – Southern Slope Trial Direct Seeding Mix**



**Plate 10**  
**Weeping Myall (*A. Pendula*) Re-growth from topsoil SWE Southern Slope Trials**



## **5.5 DEVELOPMENT OF THE FINAL REHABILITATION PLAN**

Proposed rehabilitation outcomes have been continuously developed throughout the CGM approval process. The EIS, the currently approved Cowal Gold Mine Modified Request Environmental Assessment (Barrick, 2009) and the CGM's ROMP detail the final rehabilitation philosophy and objectives for the CGM as well as the proposed rehabilitation programme and final landform and revegetation concepts.

Subsequent to the EIS approval a series of management plans were developed in accordance with Development Consent Conditions. The CWMP, FFMP, LSMP and ROMP further developed rehabilitation concepts presented in the EIS. The following stakeholders were consulted during preparation of these plans:

- EPA;
- DTIRIS (DRE);
- OEH

- DPI - Fisheries;
- NoW;
- Lake Cowal Landowners Association;
- Lake Cowal Foundation;
- DP&I; and
- BSC.

Results of consultation undertaken with the abovementioned stakeholders were incorporated into the management plans where relevant.

In accordance with the EIS and subsequent to the commencement of mining operations, consultation with respect to the detail of the concepts will be commenced as part of an ongoing process (in accordance with the Mining Rehabilitation and Environmental Management Process (MREMP) throughout the life of the CGM. The final rehabilitation concepts have been developed and are described in the ROMP. Rehabilitation will continue to be iterative and based on results of rehabilitation trials and formulated in consultation with DTIRIS (DRE) and other relevant stakeholders. A Final Rehabilitation Plan (FRP) will be included in the CGM Mine Closure Plan.

Table 41 provides a summary of rehabilitation activities at the CGM during the reporting period. The table includes details of rehabilitation at the start of the reporting period and estimated for the next report.

**Table 41  
Rehabilitation Summary**

	Area Affected/Rehabilitated (hectares)		
	Previous Report	Current Report	Next Report (estimated)
<b>A MINE LEASE AREA</b>			
A1 Mine Lease(s) Area	2,650	2,650	2,650
<b>B DISTURBED AREAS</b>			
B1 Infrastructure Area <sup>1</sup>	350	355	359
B2 Active Mining Area <sup>2</sup>	107	107	107
B3 Waste Emplacements <sup>3</sup>	342	342	342
B4 Tailings Emplacements	369	369	369
B5 Shaped Waste Emplacement <sup>4</sup>	87	96	127
<b>ALL DISTURBED AREAS<sup>5</sup></b>	1,255	1,269	1,295
<b>C REHABILITATION PROGRESS</b>			
C1 Total Rehabilitated Area <sup>6</sup>	110	118	153
<b>D REHABILITATION ON SLOPES</b>			
D1 10 – 18 Degrees	110	118	153
D2 Greater than 18 Degrees	0	0	0
<b>E SURFACE OF REHABILITATED LAND</b>			
E1 Pasture and Grasses	151	151	151
E2 Native Forest/Ecosystems	38	38	38
E3 Plantations and Crops	0	0	0
E4 Other	0	0	0

<sup>1</sup> Includes areas such as ore and soil stockpiles, contained water storages, processing plant and roads.

<sup>2</sup> Open pit area.

<sup>3</sup> Areas of waste emplacements yet to be shaped and rehabilitated.

<sup>4</sup> Areas of waste emplacements that have been shaped and rehabilitated.

<sup>5</sup> Includes any area that has been disturbed by mining activities. This value includes the Total Rehabilitation Area presented in C1.

<sup>6</sup> Any areas that have been rehabilitated including areas of waste emplacements and tailings storage facilities progressively shaped and rehabilitated.

Table 42 gives a summary of the maintenance works carried out on rehabilitated land over the reporting period. Also summarised are planned works to be undertaken during the next reporting period.



**Table 42  
Maintenance Activities on Rehabilitated Land**

Nature of Treatment	Area Treated (ha)		Comments/Control Strategies/Treatment Detail
	Report Period	Next Period	
Additional erosion control works	2	10	The reverse-graded berms that were constructed at the top of the Lake Protection Bund were reshaped during the reporting period to remove sediment build up and improve their effectiveness in minimising runoff from the PWE. Maintenance of the road on the top of the Lake Protection Bund was also undertaken.
Re-covering	45	50	The 3 <sup>rd</sup> Lift of NTSF was treated by rock-topsoil during early-2012. The 4 <sup>th</sup> Lift (3 <sup>rd</sup> augmentation) of STSF was treated by rock-topsoil during late-2012. The 4 <sup>th</sup> Lift of the NTSF will require outer batter rehabilitation works during late-2013. The Pond D1 end of the NWE was re-shaped after the rock bars were re-shaped in the Northern Diversion Channel during 2012 to early-2013. The Pond D4 end and the south side of the SWE was re-shaped and the Southern Lowflow Diversion Channel and settlement basin were cleaned out and re-shaped during 2012 and the start of 2013. PWE works will occur during 2013 and 2014. SWRE and NWRE shaping and rehabilitation covers works are scheduled for 2014 and 2015, respectively. Inside the PWE south is being completed in 2014 (grey lake sediments requiring re-shaping, gypsum and waste rock addition).
Soil treatment	0	0	Despite field sampling testwork indicating a need for higher gypsum dose (above 10t/ha), and extended treatment times, no area has presently been approved for the treatment of the relevant site subsoil and topsoil stocks.
Treatment/Management	100	20	Slashing and grading of firebreaks was undertaken during the reporting period. It is expected that the same activities will undertaken in the next reporting period. Lake Fill event has covered the lake fire trails for now.
Re-seeding/Replanting	0	4	The southern slope of the SWE was seeded during October 2011. There was no replanting of any trees and shrubs in any area. The southern Lake edge of the PWRE was scheduled to have native tubestock planted in late-2013 however, weather conditions didn't permit that.
Adversely affected by weeds	500	300	<i>Xanthium spinosum</i> (Bathurst Burr), <i>Sclerolaena birchii</i> (Galvanised Burr) <i>Ibicella lutea</i> (Devil's Claw) and <i>L ferrocissimum</i> (African Boxthorn) were treated by spot spraying with chemical or by manual removal. Infestations were mainly in isolated low lying areas that held enough moisture long enough for germination. Lake Fill event has covered all of the 'Lakeside' control areas since August 2010 until steady re-emergence in late-2013.
Feral animal control	2,650	2,650	Feral animal control activities were undertaken during the reporting period. Activities included fox and rabbit baiting on ML 1535 and parts of Barrick-owned land, and feral cat trapping.

## 6 ACTIVITIES PROPOSED FOR THE NEXT AEMR PERIOD

Mining and landform rehabilitation activities will continue to be undertaken in the next AEMR period in accordance with the Development Consent, the MOP, EMPs and other approvals.

Operational activities will include the continuation of mining and mineral processing during the next reporting period.

### 6.1 ENVIRONMENTAL MANAGEMENT TARGETS AND STRATEGIES FOR THE NEXT YEAR

The management strategies set out in the CGM EMPs prepared to date would continue to be implemented during the next reporting period in order to meet the objectives and targets described in the EMPs. A summary of the management targets and objectives, as set out in the EMPs for the next reporting year is provided in Table 43.

In accordance with Development Consent Condition 3.2. a 5-yearly review and update of all CGM EMPs will be undertaken in 2014 and the outcomes documented in the 2014 AEMR.

**Table 43**  
**Summary of Environmental Targets and Management Strategies for the Next Reporting Year**

Environmental Management Plan	Objectives/Targets (for next reporting period)	General Management Strategies
BLMP	<ul style="list-style-type: none"> <li>Optimisation of blasts by Geotechnical personnel.</li> <li>Maintain network during continued Lake Fill.</li> <li>Continue to work with near neighbours and CGM Community Relations and adjust programme resources as required.</li> </ul>	<ul style="list-style-type: none"> <li>Blasting in accordance with the identified criteria.</li> <li>Maintain monitoring network and Cowal Saros Blast Hub external services.</li> <li>Remedial measures in events which exceed blast criteria or disturb birdlife.</li> <li>Install new meteorological sensors equipment on the new generation blast loggers of 2012.</li> <li>Vary EPL11912 condition M7.1. Relocate BM06 (east Lake) to 'Cowan North' (old BM08). Becomes location BM08.1.</li> <li>Ongoing consultation with affected landholders as required.</li> </ul>
BMP	<ul style="list-style-type: none"> <li>Conduct staff training and drills.</li> <li>Maintain the available fire trails across seasons from / to ML1535 Gates and Barrick farmland during through to post Lake Fill.</li> </ul>	<ul style="list-style-type: none"> <li>Maintenance of Emergency Response Procedures.</li> <li>Reduction of bushfire threat and protection of assets at risk after fuel growth period.</li> </ul>
CWMP	<ul style="list-style-type: none"> <li>Continue weed and pest control.</li> </ul>	<ul style="list-style-type: none"> <li>Prevention of grazing stock entry.</li> <li>Frog surveys – annual/ bi-annual (rain/ heat).</li> <li>Natural regeneration of native plants.</li> <li>Limitation of vehicular access.</li> <li>Improvement of habitats for wildlife.</li> <li>2016 Lake Cowal fish survey (receding) – if the lake is full.</li> </ul>
DMP	<ul style="list-style-type: none"> <li>Continued use of Petro Tac on light roads.</li> <li>Continue NMI and ALS use of CGM bulk dust standard (2011).</li> <li>Continue learning from Uni of Sydney Thesis of Ryan, 2012 (plant uptake) and Anning (in-situ tracking As using pXRF).</li> <li>Maintain network during continued Lake Fill.</li> <li>Observe trends DG14 in lake floor (moved DG8 'Hillgrove' to ML location n-e of E42 Pit between Site 52 and DG 5 (as per Cattle, 2012)). Became in-Lake ML location DG14.</li> </ul>	<ul style="list-style-type: none"> <li>Reduction/control of dust emissions.</li> <li>The University of Sydney will continue to advise Barrick personnel on the dust sampling methodology, to reduce the likelihood of sample contamination via the incorrect implementation of sampling techniques.</li> <li>Evaluate use of original and 2012 taller tripod gauges in Lake Cowal for duplicates with gauge campaigns of up to quarterly duration to further investigate high Cu and Zn assays.</li> </ul>

**Table 43 (Continued)**  
**Summary of Environmental Targets and Management Strategies for the Next Reporting Year**

Environmental Management Plan	Objectives/Targets (for next reporting period)	General Management Strategies
HMP	<ul style="list-style-type: none"> <li>• Advise the relevant stakeholders that Cowal Mine has no remaining HMP items of interest. Request removal of HMP.</li> <li>• Post information plaques at proposed LCCC Museum if Barrick proceed with Shearing Shed component of section 75W approvals.</li> </ul>	<ul style="list-style-type: none"> <li>• Maintenance of stored items.</li> <li>• Weed and pest control around items.</li> <li>• Fire control around stored items Shed.</li> <li>• Surface water control, basal layer.</li> <li>• Relocation to LCCC museum area.</li> <li>• maintenance of 'Cowan West' Shearing Shed at LCCC (opened on 19 April 2013) .</li> </ul>
ESCP	<ul style="list-style-type: none"> <li>• Continue event based structure inspections.</li> <li>• Enhance the southern portion of the UCDS through repair and strengthening of erosion control structures. Clear sediment from UCDS south front basin.</li> <li>• Conduct annual peer risk review.</li> <li>• Reclamation Standard compliance.</li> </ul>	<ul style="list-style-type: none"> <li>• Effective control of sediment and salinity migration.</li> <li>• Maintain lake floor/ edge access fire trail and planned general inspections of assets after lake Fill event.</li> <li>• Maintenance of downstream (Lake) water quality.</li> <li>• Ongoing approval use for the rock-topsoil method using independent review and amended MOP, EMPs, DC modification, etc.</li> </ul>
CMP	<ul style="list-style-type: none"> <li>• Continued cyanide management.</li> <li>• Continue use of SMBS system and maintain Caro's Acid preparedness.</li> <li>• Maintain TSF auto-sampler to the concrete bunded tailings slurry pumping hopper area.</li> <li>• Independent audit ICMI Code - fourth triennial re-certification was posted at start 2014.</li> </ul>	<ul style="list-style-type: none"> <li>• Maintain strategy of excellence in environmental management of installed facilities, process water streams, on-site reagent storage, use and emergency preparedness.</li> <li>• Implement engineering design solution for repeat, aggressive corrosion at sulphuric acid sump and continue maintenance program for the SMBS area.</li> <li>• Maintain full compliance status with the ICMI Code.</li> </ul>
FFMP	<ul style="list-style-type: none"> <li>• Continue NSW WIRES training for employees.</li> <li>• Relocate wildlife as required.</li> <li>• Continue maintenance of TSF and Pond D6 bird deterrent system and fences.</li> <li>• Continue control of vermin and noxious weeds.</li> <li>• Approval and implementation of ROMP.</li> </ul>	<ul style="list-style-type: none"> <li>• Remnant vegetation enhancement programme.</li> <li>• Vegetation clearance protocol.</li> <li>• Weed management and pest control.</li> <li>• Protection of flora and fauna threatened species located within the CGM.</li> <li>• Additional bird and bat nesting boxes and hollows at 'Hillgrove' and 'Lakeside' trees.</li> </ul>
HWCMP	<ul style="list-style-type: none"> <li>• Continue appropriate transport, handling, disposal, and recycling of wastes.</li> <li>• Maintain steel drum crusher and cardboard bailer operations.</li> <li>• Ongoing ICMI Cyanide Code full compliance – operational phase.</li> <li>• Appropriate responses to spillages.</li> <li>• Ongoing use and management of bioremediation area.</li> <li>• Audit and maintain emergency preparedness oil &amp; chemical spill kits.</li> </ul>	<ul style="list-style-type: none"> <li>• Substances Inventory Register (IR).</li> <li>• Distribution of revised employee environmental awareness handbook and spill training.</li> <li>• Emergency preparedness contingency.</li> <li>• Root cause analysis of spill incidents with action programs to eliminate.</li> <li>• Enhanced employee use of upgraded Chernalert III system software features.</li> <li>• Observe independent review of waste rock geochemistry as a portion of the Application for s75W Extension approval.</li> </ul>
IACHMP	<ul style="list-style-type: none"> <li>• Continued assessment of areas as per IACHMP prior to soil stripping.</li> <li>• Revised IACHMP – include GDP process.</li> </ul>	<ul style="list-style-type: none"> <li>• Protection/Management of sites within the CGM area.</li> <li>• Dissemination of cultural heritage information and offsets.</li> </ul>

**Table 43 (Continued)**  
**Summary of Environmental Targets and Management Strategies for the Next Reporting Year**

Environmental Management Plan	Objectives/Targets (for next reporting period)	General Management Strategies
LMP	<ul style="list-style-type: none"> <li>Continue control of vermin and noxious weeds.</li> <li>Maintain ML boundary buoys (Plate 6).</li> <li>Approval and implementation of the ROMP.</li> <li>Review the draft Lachlan River Floodplain MP (January 2011) and incorporate as required.</li> </ul>	<ul style="list-style-type: none"> <li>Pasture and remnant vegetation management.</li> <li>Weed management and pest control.</li> <li>Farm Planning.</li> </ul>
Monitoring Programme for Detection of any Movement of Lake Protection Bund, Water Storage and Tailings Structures and Pit/Void Walls	<ul style="list-style-type: none"> <li>Maintain monuments inspection frequency of TSF walls.</li> <li>Maintain Pond structure inspections.</li> <li>Raise height of TIB by 0.5 m when Lake Cowal recedes to safer distance from the TIB.</li> </ul>	<ul style="list-style-type: none"> <li>Detection of any movement of the Lake Protection Bund, water storage and tailings structures, and pit/void walls.</li> <li>Effective responses to any detected movement.</li> </ul>
LSMP	<ul style="list-style-type: none"> <li>Continued building inspections.</li> <li>Ongoing visual assessments.</li> <li>Approval and implementation of the ROMP.</li> </ul>	<ul style="list-style-type: none"> <li>Blending of structures with the surrounding landscape as far as possible.</li> <li>Establishment of shrubs and trees in accordance with the requirements of BSC.</li> <li>Effective maintenance of landscapes and buildings.</li> </ul>
SSMP	<ul style="list-style-type: none"> <li>Continue soil stockpile management.</li> <li>Update database as required.</li> </ul>	<ul style="list-style-type: none"> <li>Continue McKenzie survey of site rehabilitation stockpiles qualities.</li> <li>Conduct a LiDAR aerial 3-D <math>\pm</math> 0.1 survey of site stockpiles in early 2016.</li> <li>Continued use of ArcGIS as a management tool.</li> <li>Effective scheduling and management of soil stripping operations.</li> </ul>
SWMP	<ul style="list-style-type: none"> <li>Maintain monitoring and reporting of open pit dewatering system.</li> <li>Continue process water management.</li> <li>Water Conservation Standard compliance.</li> </ul>	<ul style="list-style-type: none"> <li>Prevent the quality of any surface water (including waters within Lake Cowal) and groundwater being degraded.</li> <li>Effective management of the quantity of surface water and groundwater generated within the CGM area.</li> <li>Effective amelioration of potential impacts to surface water and groundwater.</li> </ul>
SWGMBMP	<ul style="list-style-type: none"> <li>Ongoing use of approved revised SWGMBMP.</li> </ul>	<ul style="list-style-type: none"> <li>Detection of any adverse affects to surface water, groundwater, and/or biology.</li> <li>Effective responses to any detected adverse affects.</li> <li>Re-stocking Lake with native fish should Lake levels rise enough in future years.</li> <li>2016 Lake Cowal fish survey - receding.</li> </ul>
NMP (including traffic noise)	<ul style="list-style-type: none"> <li>Continue employee awareness.</li> <li>Continued monitoring in accordance with NMP.</li> </ul>	<ul style="list-style-type: none"> <li>Prevention of adverse mine operational noise.</li> <li>Ongoing development of bund walls and waste rock emplacements.</li> <li>Prevention of adverse mine traffic noise.</li> <li>Ongoing consultation with affected landholders as required.</li> <li>Complaint response and dispute resolution procedures.</li> </ul>
TSMP	<ul style="list-style-type: none"> <li>Develop species-specific plans as required.</li> <li>Conduct surveys for threatened species as required</li> <li>Biodiversity Conservation Standard compliance.</li> </ul>	<ul style="list-style-type: none"> <li>Ensure the viability of a local population of a threatened species is not put at risk by the CGM.</li> <li>Species-specific management plans.</li> </ul>

**Table 43 (Continued)**  
**Summary of Environmental Targets and Management Strategies for the Next Reporting Year**

<b>Environmental Management Plan</b>	<b>Objectives/Targets (for next reporting period)</b>	<b>General Management Strategies</b>
Implementation Plan to Protect Fauna from Interactions with the Tailings Storage Facilities	<ul style="list-style-type: none"> <li>Continue monthly bat monitoring</li> <li>Conduct daily routine inspection and monitoring of fauna, process, tailings discharge, surface water and groundwater.</li> <li>Investigate use of LRAD noise gun/s for recalcitrant visitors to TSF beaches.</li> </ul>	<ul style="list-style-type: none"> <li>Prevent fauna and avifauna use of operational tailings storage facilities.</li> <li>Maintain TSF perimeter fencing and avifauna deterrents.</li> <li>TSF Operations and Maintenance Plan.</li> <li>Maintain readiness for end of current Lake Fill.</li> </ul>
MOP (October 2012 –January 2014) extended until 31 January 2015 (pending MOD11 approvals process)	<ul style="list-style-type: none"> <li>Schedule Mine development.</li> <li>Continue progressive landscape and rehabilitation management.</li> </ul>	<ul style="list-style-type: none"> <li>Soil stripping scheduling.</li> <li>Soil stockpile management – amelioration options. Continue to prevent the contamination of surrounding land whilst working towards setting phased completion criteria.</li> <li>Mine waste rock emplacements.</li> <li>Closure and decommissioning plan.</li> <li>Life of Mine Plan.</li> <li>TSF Operations and Maintenance Plan.</li> <li>Next draft MOP ready (June 2014).</li> </ul>
THMS	<ul style="list-style-type: none"> <li>Maintain arrangements for THMS.</li> <li>Continue emergency preparedness contingency with external services.</li> <li>Use of inland road and/or other emergency routing as required (e.g. 2011-12 Flooding).</li> </ul>	<ul style="list-style-type: none"> <li>Employee awareness training.</li> <li>On-site facilities inspection and maintenance.</li> <li>Contract management.</li> <li>Emergency preparedness.</li> </ul>
ROMP	<ul style="list-style-type: none"> <li>Approval and implementation of the ROMP.</li> </ul>	<ul style="list-style-type: none"> <li>Mine site rehabilitation management.</li> <li>Offset areas management.</li> <li>Establish mechanism for long-term security of the offset areas (i.e. draft VPA, May 2014).</li> </ul>

### **Environmental Management System**

Barrick will continue development of the CGM EMS in accordance with corporate standards during the next reporting period. Risk-based management of significant environmental aspects by ongoing management review and employee involvement in site wide planned general inspections will continue during the next reporting period.

Barrick has five (5) environmental standards and the core EMS standard:

- Closure;
- Water Conservation;
- Tailings Facility Design;
- Climate Change; and
- Incident Reporting and Investigation.

Internal and external review of compliance to these standards is ongoing across Barrick operations.

The CGM underwent both Preliminary and Stage 1 EMS audits during the 2012 reporting year. The CGM passed a Stage 2 ISO 14001 external audit by ERM-CVS on 28 February 2013 and was recommended for certification which occurred 12 June 2013 (UKAS Certificate 495 ; *Mining and Ore Processing Operations and Support Services for Gold and Silver production*). Cowan Mine's second six-monthly surveillance audit as an ISO 14001 certified site will occur 27-30 October 2014.

**Plate 11**  
**New Shallower Draught Environmental Patrol Boat (March 2014).**



**Plate 12**  
**Southern Waste Rock Emplacement South Side (May 2014).**



**Plate 13**  
**Original south face of the 'Cowal West' Shearing Shed (2005 - 2012).**



**Plate 14**  
**Refurbished 'Cowal West' Shearing Shed (April 2013).**





## 7 REFERENCES

- Australian and New Zealand Environment and Conservation Council and Agriculture and Resource Management Council of Australia and New Zealand (ANZECC and ARMCANZ) (2000) *National Water Quality Management Strategy No. 4: Australian Guidelines for Water Fresh and Marine Water Quality Monitoring and Reporting Vol 1 & 2*.
- Australian Geological Survey (2000) *Forbes 1:250 000 Geological Sheet – Explanatory Notes 2<sup>nd</sup> edition SI55-7*. Mineral Resources – Geological Survey of New South Wales. ISBN 0 642-39837-2 Commonwealth of Australia.
- Australian Museum Business Services (2012) *Cowel Gold Mine and Surrounds Flora Survey*.
- Barrick Australia Limited (2003a) *Cowel Gold Project Soil Stripping Management Plan*.
- Barrick Australia Limited (2003b) *Cowel Gold Project Site Water Management Plan*.
- Barrick Australia Limited (2003c) *Cowel Gold Project Dust Management Plan*.
- Barrick Australia Limited (2003d) *Cowel Gold Project Erosion and Sediment Control Management Plan*.
- Barrick Australia Limited (2003e) *Cowel Gold Project Surface Water, Groundwater, Meteorological and Biological Monitoring Programme*.
- Barrick Australia Limited (2003f) *Cowel Gold Project Lake Protection Bund, Water Storage and Tailings Structures and Pit-Void Walls Monitoring Programme*.
- Barrick Australia Limited (2003g) *Cowel Gold Project Flora and Fauna Management Plan*.
- Barrick Australia Limited (2003h) *Cowel Gold Project Threatened Species Management Protocol*.
- Barrick Australia Limited (2003i) *Cowel Gold Project Compensatory Wetland Management Plan*.
- Barrick Australia Limited (2003j) *Cowel Gold Project Land Management Plan*.
- Barrick Australia Limited (2003m) *Cowel Gold Project Landscape Management Plan*.
- Barrick Australia Limited (2003n) *Cowel Gold Project Indigenous Archaeology and Cultural Heritage Management Plan*.
- Barrick Australia Limited (2003o) *Cowel Gold Project Heritage Management Plan*.
- Barrick Australia Limited (2003p) *Cowel Gold Project Bushfire Management Plan*.
- Barrick Australia Limited (2005e) *Cowel Gold Project Implementation Plan to Protect Fauna from Interactions with the Tailings Storage Facilities*.
- Barrick Australia Limited (2006c) *Cowel Gold Project Hazardous Waste and Chemical Management Plan*.
- Barrick Australia Limited (2006e) *Cowel Gold Project Cyanide Management Plan*.
- Barrick Australia Limited (2006f) *Cowel Gold Project Mining Operations Plan*.
- Barrick Australia Limited (2007) *Cowel Gold Project Mining Operations Plan*.
- Barrick (Cowel) Limited (2009) *Cowel Gold Project Mining Operations Plan*.
- Barrick Australia Limited (2009) *Cowel Gold Project Surface Water, Groundwater, Meteorological and Biological Monitoring Programme – Mine Operations*.



- Barrick Australia Limited (2012) *Cowal Gold Project Blast Management Plan*.
- Barrick Australia Limited (2010) Modified Request Environmental Assessment.
- Barrick (Cowal) Limited (2011) *Cowal Gold Project Mining Operations Plan*.
- Barrick (Cowal) Limited (2012) *2012-2014 Mining Operations Plan*.
- Barrick (Cowal) Limited (2013) *Addendum to the Surface Water, Groundwater, Meteorological and Biological Monitoring Programme – Mine Operations*.
- Carnegie Natives (2011) *Cowal Gold Mine Annual Weed Survey*.
- Carnegie Natives (2012) *Cowal Gold Mine Annual Weed Survey*.
- Cattle, S. (2012) *Interpretation and Discussion of 2011 Air Quality Monitoring Results Cowal Gold Project*.  
University of Sydney.
- Cattle, S. (2013) *Interpretation and Discussion of 2012 Air Quality Monitoring Results Cowal Gold Project*.  
University of Sydney.
- Cattle, S. (2014) *Interpretation and Discussion of 2013 Air Quality Monitoring Results Cowal Gold Project*.  
University of Sydney.
- Genwest Environmental Services (2009) *Cowal Gold Mine E42 Modification – Modified Request Fauna Assessment*.
- Coffey Geotechnics (2009a) *Cowal Gold Mine – Groundwater Monitoring Review 2008*. Report No. GEOTLCOV21910AE-AB.
- Coffey Geotechnics (2009b) *Cowal Gold Mine Groundwater Level Investigation*. Report No. GEOTLCOV21910AF-AB.
- Coffey Geotechnics (2011) *Cowal Gold Mine Groundwater Monitoring Review 2011*.
- Coffey Geotechnics (2013) *Cowal Gold Mine Groundwater Monitoring Review 2012*.
- Coffey Geotechnics (2014) *Cowal Gold Mine Groundwater Monitoring Review 2013*.
- Department of Resources, Energy and Tourism (2009) *Leading Practice Sustainable Development Program for the Mining Industry - Hazardous Materials Management Handbook*.
- Department of the Environment, Water Heritage and the Arts (2008a) *Threat Abatement Plan for Predation by Feral Cats*.
- Department of the Environment, Water Heritage and the Arts (2008b) *Threat Abatement Plan for Predation by the European Red Fox*.
- Department of Trade and Investment, Regional Infrastructure and Services (Department of Mineral Resources) (2006) *Guidelines and Format for Preparation of an Annual Environmental Management Report*.
- Department of Trade and Investment, Regional Infrastructure and Services (2011) *Rehabilitation and Environmental Management Plan Guidelines Consultation Draft V2.0 June 2010*.
- Donato Environmental Services (2007) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: April 2007 to September 2007*.
- Donato Environmental Services (2008) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: October 2007 to March 2008*.

Donato Environmental Services (2008) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: April 2008 to September 2008.*

Donato Environmental Services (2009) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: October 2008 to March 2009.*

Donato Environmental Services (2010) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: April 2009 to September 2009.*

Donato Environmental Services (2010) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: October 2009 to March 2010.*

Donato Environmental Services (2011) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: April 2010 to September 2010.*

Donato Environmental Services (2011) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: October 2010 to March 2011.*

Donato Environmental Services (2011) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: April 2011 to September 2011.*

Donato Environmental Services (2012) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: October 2011 to March 2012*

Donato Environmental Services (2012) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: April 2012 to September 2012.*

Donato Environmental Services (2013) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: October 2012 to March 2013*

Donato Environmental Services (2013) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: April 2013 to June 2013.*

Donato Environmental Services (2014) *Seasonal Wildlife Use Patterns of the Cowal Gold Mine Tailings Facility: July 2013 to December 2013.*

DnA Environmental (2009) 2009 Weed Survey & Farm Management Report.

DnA Environmental (2010) Cowal Gold Mine Rehabilitation Trials: Preliminary Assessment March 2010.

DnA Environmental (2011a) 2010 *Austral pillwort* survey.

DnA Environmental (2011b) 2010 *Compensatory Wetland Regeneration Monitoring Results.*

DnA Environmental (2011c) 2010 *Rehabilitation Monitoring Report.*

DnA Environmental (2011d) 2010 *Remnant Vegetation Enhancement Program: 2010 monitoring results.*

DnA Environmental(2011e) *Rehabilitation monitoring methodology & determination of completion criteria: Ecosystem sustainability.*

DnA Environmental (2012)

DnA Environmental (2012a) 2011 *Austral pillwort* survey.

DnA Environmental (2012b) 2011 *Compensatory Wetland Regeneration Monitoring Results.*

DnA Environmental(2012c) 2011 *Rehabilitation Monitoring Report.*

- DnA Environmental (2012d) 2011 *Remnant Vegetation Enhancement Program: 2011 monitoring results*.
- DnA Environmental (2013)
- DnA Environmental (2013a) 2012 *Austral pillwort survey*.
- DnA Environmental (2013b) 2012 *Compensatory Wetland Regeneration Monitoring Results*.
- DnA Environmental(2013c) 2012 Rehabilitation Monitoring Report.
- DnA Environmental (2013d) 2012 *Remnant Vegetation Enhancement Program: 2012 monitoring results*.
- DnA Environmental (2014)
- DnA Environmental (2014a) 2013 *Austral pillwort survey*.
- DnA Environmental (2014b) 2013 *Compensatory Wetland Regeneration Monitoring Results*.
- DnA Environmental(2014c) 2013 Rehabilitation Monitoring Report.
- DnA Environmental (2014d) 2013 *Remnant Vegetation Enhancement Program: 2013 monitoring results*.
- Environment Australia (1997) *Best Practice in Environmental Management in Mining*.
- Environment Protection Authority (2008) *Waste Classification Guidelines*.
- Environmental Geochemistry International Pty Ltd (2004) *CGP Geochemical Assessment of Waste Rock and Process Tailings*.
- Environmetrics Australia Pty Ltd (2008) *Review of Statistical Aspects of Cowal Gold Mine Operations Monitoring Program*.
- FloraSearch (2008). *Cowal Gold Mine E42 Modification Flora Assessment*. Report No. HAL-26.
- frc environmental (2012). *Cowal Compensatory Wetland Habitat and Fish Investigation*. Ref 101209.
- Gell (2012c) *Lake Cowal Waterbird Monitoring Survey Progress Report – October 2012*.
- Gell (2013a) *Lake Cowal Waterbird Monitoring Survey Progress Report – January 2013*.
- Gell (2013b) *Lake Cowal Waterbird Monitoring Survey Progress Report – August 2013*.
- Gell (2013c) *Lake Cowal Waterbird Monitoring Survey Progress Report – October 2013*.
- Geo Environmental Management (2009) *Cowal Gold Mine E42 Modification – Modified Request – Tailings and Waste Rock Geochemical Assessment*.
- Hawkes, G. E. (1998) *Hydrogeology of the Proposed Lake Cowal Gold Mine NSW*, MSc Thesis, University of Technology Sydney.
- Heggies (2009). *Cowal Gold Project Traffic Noise Monitoring January 2010*. Report No. 10-4111-R9 Traffic.
- Heggies (2009). *Cowal Gold Project Mine Operation Noise Monitoring January 2009*. Report No. 10-4111-R9 Mine.
- Heggies (2009). *Cowal Gold Project Mine Operation Noise Monitoring July 2009*. Report No. 10-4111-R10 Mine
- Heggies (2010). *Cowal Gold Project Traffic Noise Monitoring January 2010*. Report No. 10-4111-R11 Traffic.

- Heggies (2010). *Cowal Gold Project Mine Operation Noise Monitoring January 2010*. Report No. 10-4111-R11 Mine.
- Heggies (2010). *Cowal Gold Project Mine Operation Noise Monitoring July 2010*. Report No. 10-4111-R12 Mine.
- Lyons *et al.* (2000) *The Cowra - Yass Province*. Geoscience Australia.
- NEPC (1999) *National Environment Protection (Assessment of Site Contamination) Measure*.
- North Limited (1998) *Cowal Gold Project – Environmental Impact Statement*. Report prepared by Resource Strategies Pty Ltd.
- NSR Environmental Consultants (1995) *Lake Cowal Gold Project Environmental Impact Statement*.
- NSW Agriculture and CMPS&F (1996) *Environmental Guidelines for the Assessment and Cleanup of Cattle Tick Dip Sites for Residential Purposes*.
- NSW Agriculture (2003) *Draft Vertebrate Pest Control Manual*.
- NSW Livestock, Health and Pest Authority (2010) *Controlling Pests on your Land*.
- Miles, Brooker, McInnes, *et al* [1993-1998]
- McInnes, P., Freer, L. (2007). *The Cowal Gold Corridor – Opening Other Doors*. Barrick Gold of Australia.
- McInnes, P., Miles, I., Radclyffe, D., and Brooker, M. (1998) Endeavour 42 (E42) gold deposit, Lake Cowal; in Berkman D A, Mackenzie D H (Ed.s), 1998 *Geology of Australian & Papua New Guinean Mineral Deposits The AusIMM, Melbourne Mono 22 pp 581-586*.
- McKenzie Soil Management and Carnegie Natives (2012) *Preliminary Soil Characterisation Report – ‘Subsoil 02’ and ‘Topsoil 02’*.
- McMahon, D.M. (2012) *Surface Water and Sediment Sampling and Analysis 2011, Lake Cowal NSW*.
- McMahon, D.M. (2013) *Surface Water and Sediment Sampling and Analysis 2012, Lake Cowal NSW*.
- McMahon, D.M. (2014) *Surface Water and Sediment Sampling and Analysis 2013, Lake Cowal NSW*.
- O’Kane Consultants Pty Limited (O’Kane) (2008) *Waste Rock Geochemical Infill Programme Cowal Gold Mine*.
- Pardoe, C. (2002) *Supplementary Archaeological Survey of Part of the Proposed Borefield and Pipeline for the Cowal Gold Project, Lake Cowal, NSW - Draft Report*.
- Parsons Brinkerhoff (2005) *Fire Safety Study, Cowal Gold Project*.
- Parsons Brinkerhoff (2007), *Parsons Cowal Gold Project – Preliminary Hydrogeochemical Review of the Groundwater System*. Report prepared by Edward Oldmeadow for Barrick Australia Ltd.
- Pinnacle Risk Management (2004) *A Preliminary Hazard Analysis, Transport of Hazardous Materials Study, Hazard and Operability Study Report, Cowal Gold Project*.
- Pinnacle Risk Management (2005) *Fire Safety Study, Cowal Gold Project*.
- Ryan, A and Cattle, S (2010) *Understanding the local pedological and ecological impacts of dust emitted from Cowal Gold Mine*. University of Sydney. 19th World Congress of Soil Science, Soil Solutions for a Changing World, Brisbane.
- Saros (Australia) Pty Ltd (2010). *2009 review of Blast Monitoring Results*.

- Saros (Australia) Pty Ltd (2011). *2010 review of Blast Monitoring Results*.
- Saros (Australia) Pty Ltd (2012). *2011 review of Blast Monitoring Results*.
- Saros (Australia) Pty Ltd (2013). *2012 review of Blast Monitoring Results*.
- Saros (Australia) Pty Ltd (2014). *2013 review of Blast Monitoring Results*.
- SLR Consulting Australia Pty Ltd (2012) *Cowal Gold Project Traffic Noise Monitoring January 2012*.
- SLR Consulting Australia Pty Ltd (2012) *Cowal Gold Project Mine Operation Noise Monitoring January 2012*.
- SLR Consulting Australia Pty Ltd (2012) *Cowal Gold Project Mine Operation Noise Monitoring July 2012*.
- SLR Consulting Australia Pty Ltd (2013) *Cowal Gold Project Traffic Noise Monitoring January 2013*.
- SLR Consulting Australia Pty Ltd (2013) *Cowal Gold Project Mine Operation Noise Monitoring January 2013*.
- SLR Consulting Australia Pty Ltd (2013) *Cowal Gold Project Mine Operation Noise Monitoring July 2013*.
- Smits J (2008) The Effectiveness of different mulches in mine rehabilitation: short-term effects on the surface stability and the conditions for plant growth, Cowal Gold Mine, NSW. Honours, ANU.
- SNC Cavalin (2004) *Lake Bund Final Design Report Lake Protection System Design*.
- Summerfield D (2006) Mulch and cover crops in stabilising sloping rehabilitation areas at Cowal Gold Project, West Wyalong, NSW. Honours, ANU.
- Tsoar and Pye (1987) *Dust Transport and the Question of Desert Loess Formation*. Sedimentology 34, 139-153.
- University of Ballarat (2010a) Gell, P. Lake Cowal Waterbird Monitoring Survey Progress Report January 2010
- University of Ballarat (2010b) Gell, P. Lake Cowal Waterbird Monitoring Survey Progress Report August 2010
- University of Ballarat (2010c) Gell, P. Lake Cowal Waterbird Monitoring Survey Progress Report October 2010
- University of Ballarat (2011a) Gell, P. Lake Cowal Waterbird Monitoring Survey Progress Report January 2011
- University of Ballarat (2011b) Gell, P. Lake Cowal Waterbird Monitoring Survey Progress Report August 2011
- University of Ballarat (2012a) Gell, P. Lake Cowal Waterbird Monitoring Survey Progress Report October 2011
- University of Ballarat (2012b) Gell, P. *Lake Cowal Waterbird Monitoring Survey Progress Report – August 2012*.
- University of Sydney (2010) *Interpretation and Discussion of 2009 Dust Monitoring Results, Cowal Gold Project*. Report prepared by Dr. Stephen Cattle for Barrick (Cowal) Limited.
- University of Sydney (2011) *Interpretation and Discussion of 2010 Dust Monitoring Results, Cowal Gold Project*. Report prepared by Dr. Stephen Cattle for Barrick (Cowal) Limited.
- University of Sydney (2012) *Interpretation and Discussion of 2011 Dust Monitoring Results, Cowal Gold Project*. Report prepared by Dr. Stephen Cattle for Barrick (Cowal) Limited.
- University of Sydney (2013) *Interpretation and Discussion of 2012 Dust Monitoring Results, Cowal Gold Project*. Report prepared by Dr. Stephen Cattle for Barrick (Cowal) Limited.

## 8 GLOSSARY OF TERMS

<b>AER</b>	Annual Environmental Return (EPA)
<b>AEMR</b>	Annual Environmental Management Report (DTIRIS [DRE] coordinated for DP&I and other regulators)
<b>ANZECC</b>	Australian New Zealand Environmental Conservation Council
<b>ARD</b>	Acid Rock Drainage
<b>ARMCANZ</b>	Agriculture and Resource Management Council of Australia and New Zealand
<b>ARI</b>	Annual Recurrence Interval
<b>ASWAT</b>	Aggregate Stability in Water
<b>AWS</b>	Automatic Weather Station
<b>BB</b>	Barrick Buddies
<b>BCPC</b>	Bland Creek Paleochannel
<b>BDHS</b>	Bland District Historical Society
<b>BLMP</b>	Blast Management Plan
<b>BMP</b>	Bushfire Management Plan
<b>BSC</b>	Bland Shire Council
<b>CEMCC</b>	Community Environmental Monitoring & Consultative Committee
<b>CGM</b>	Cowan Gold Mine
<b>CHESSE</b>	Community Relations, Health, Environmental, Safety and Security
<b>CIL</b>	Carbon in Leach
<b>CLM</b>	Contaminated Land Management
<b>CMP</b>	Cyanide Management Plan
<b>CMS</b>	Chemical Management Strategy
<b>CPCC</b>	Cowan Project Coordinating Committee (WCC - Barrick)
<b>CWHC</b>	Cowan Partnering Program
<b>CRMA</b>	Cowan Risk Management Application
<b>CSIRO</b>	Commonwealth Scientific and Industrial Research Organisation
<b>CW</b>	Compensatory Wetland
<b>CWHC</b>	Cowan West Homestead Complex
<b>CWMP</b>	Compensatory Wetland Management Plan
<b>DMP</b>	Department of Mines & Petroleum
<b>DP&amp;I</b>	Department of Planning and Infrastructure
<b>DECCW</b>	Department of Environment, Climate Change and Water (now EPA)
<b>DII</b>	Department of Industry and Investment - Minerals Resources (DTIRIS)
<b>DPI</b>	Department of Primary Industries – Agriculture, Fisheries
<b>DTIRIS-MR</b>	Department of Trade, Investment and Regional Infrastructure Services – Mineral Resources
<b>DSC</b>	Dams Safety Committee
<b>EA</b>	Environmental Assessment
<b>EC</b>	Electrical Conductivity
<b>EEC</b>	Ecologically Endangered Community
<b>EFA</b>	Ecosystem Function Analysis
<b>EIS</b>	Environmental Impact Statement
<b>EMP</b>	Environmental Management Plan
<b>EMS</b>	Environmental Management System
<b>EMSS</b>	Environmental Management System Standards
<b>EPA</b>	Environment Protection Authority
<b>EPL</b>	Environment Protection License
<b>ERO</b>	Emergency Response Officer
<b>ERP</b>	Emergency Response Plan (see PIRMP)
<b>ERT</b>	Emergency Response Team
<b>ESCP</b>	Erosion and Sediment Control Program
<b>ESB</b>	Eastern Saline Borefield
<b>ESCMP</b>	Erosion and Sediment Control Management Plan
<b>ETBC</b>	Employment Training Business Council (WCC – Barrick)
<b>FFMP</b>	Flora and Fauna Management Plan
<b>FOR</b>	Fuel and Oils Register
<b>FRP</b>	Final Rehabilitation Plan
<b>GDP</b>	Ground Disturbance Protocol

<b>GEM</b>	Geo-Environmental Management
<b>GFZ</b>	Gilmore Fault Zone
<b>HMP</b>	Heritage Management Plan
<b>HSR</b>	Hazardous Substances Register
<b>HWCMP</b>	Hazardous Waste and Chemical Management Plan
<b>HSDG</b>	Hazardous Substances and Dangerous Goods
<b>HSDGR</b>	Hazardous Substances and Dangerous Goods Register
<b>IACHMP</b>	Indigenous Archaeology and Cultural Heritage Management Plan
<b>ICMC</b>	International Cyanide Management Institute Code for Cyanide Management
<b>IEA</b>	Independent Environmental Audit
<b>IMP</b>	Independent Monitoring Panel
<b>INP</b>	Industrial Noise Policy
<b>ISO 14001</b>	International Standards Organisation – Best Practice Environmental Management Standard
<b>KPI</b>	Key Performance Indicator
<b>LCCC</b>	Lake Cowal Conservation Centre
<b>LCF</b>	Lake Cowal Foundation
<b>LCMA</b>	Lachlan Catchment Management Authority. Now reformed as LLS.
<b>LEP</b>	Local Environment Plan
<b>LHPA</b>	Livestock Health and Pest Authority – now LLS (formerly RLPB).
<b>LiDAR</b>	Light detection and ranging. High-speed aerial laser pulses to generate 3-D shot (3-D ± 0.1 m).
<b>LOR</b>	Limit of Reporting
<b>LPB</b>	Lake Protection Bund
<b>LPMBP</b>	Monitoring Programme for Lake Protection Bund, Water Storage and Tailings Structures and Pit-Void Walls
<b>LFA</b>	Landscape Function Analysis
<b>LLS</b>	Local Land Service. Late 2013 replacement of LHPA, LCMA and DPI-Agriculture entities. Lake Cowal sits across the LLS Riverina & LLS Central-west zones (roughly on a north-south line).
<b>LMP</b>	Land Management Plan
<b>LSMP</b>	Landscape Management Plan
<b>MIC</b>	Maximum Instantaneous Charge
<b>ML</b>	Mega Litres = 1 Million Litres
<b>m</b>	metres
<b>ML</b>	Mining Lease
<b>MOP</b>	Mining Operations Plan
<b>MSDS</b>	Material Safety Data Sheet
<b>NAF</b>	Non Acid Forming (rock acid forming potential)
<b>NGER</b>	Australia's National Greenhouse and Energy Reporting Scheme
<b>NMP</b>	Noise Management Plan
<b>NoW</b>	New South Wales Office of Water (formerly DWE within OEH - EPA).
<b>NPI</b>	National Pollutant Inventory
<b>NPWS</b>	National Park and Wildlife Service
<b>NSWFR</b>	NSW Fire and Rescue (formerly NSW Fire Brigade)
<b>NTSF</b>	Northern Tailings Storage Facility
<b>NWRE</b>	Northern Waste (rock) Emplacement
<b>OEH</b>	Office of Environment and Heritage
<b>OSCAR</b>	Australian Online System for Comprehensive Activity Reporting
<b>PIRMP</b>	Pollution Incident Response Management Plan (see ERP)
<b>PPE</b>	Personal Protective Equipment
<b>PRA</b>	Preliminary Risk Assessment
<b>PWRE</b>	Perimeter Waste (rock) Emplacement
<b>RAB</b>	Rotary Air Blast
<b>Registered Site</b>	Registered Site (NSW) NPW Act
<b>RFS</b>	NSW Rural Fire Service
<b>RIMS</b>	Barrick Responsibility Information Management System
<b>RL</b>	Relative Level metres
<b>ROMP</b>	Rehabilitation and Offset Management Plan
<b>RVEP</b>	Revegetation Enhancement Project
<b>SDS</b>	Manufacturer's Safety Data Sheet
<b>SMBS</b>	Sodium metabisulphite (cyanide destruct reagent replacing Caro's Acid)
<b>SOE</b>	State of the Environment

<b>SOI</b>	Southern Oscillation Index
<b>SSMP</b>	Soil Stripping Management Plan
<b>STSF</b>	Southern Tailings Storage Facility
<b>SWRE</b>	Southern Waste (rock) Emplacement
<b>SWGMBMP</b>	Surface Water, Groundwater, Meteorological and Biological Monitoring Programme
<b>SWMP</b>	Site Water Management Plan
<b>THMS</b>	Transport of Hazardous Materials Study
<b>TIB</b>	Temporary Isolation Bund
<b>TNMP</b>	Traffic Noise Management Plan
<b>TSF</b>	Tailings Storage Facility
<b>TSMP</b>	Threatened Species Management Protocol
<b>TSMS</b>	Threatened Species Management Strategy
<b>TSP</b>	Total Suspended Particulates
<b>TSR</b>	Travelling Stock Route
<b>UCDS</b>	Up Catchment Diversion System
<b>VCP</b>	Vegetation Clearance Permit
<b>VCP</b>	Vegetation Clearance Protocol
<b>VPA</b>	Voluntary Planning Agreement
<b>WAD</b>	Weak Acid Dissociated
<b>WCC</b>	Wiradjuri Condobolin Corporation
<b>WCCHC</b>	Wiradjuri Condobolin Cultural Heritage Company
<b>WIRES</b>	Wildlife Information Rescue and Education Service